

**BREAKING THE TENSION: DEVELOPMENT AND INVESTIGATION OF A  
CENTRIFUGAL TENSIONED METASTABLE FLUID DETECTOR SYSTEM**

A Thesis

by

MATTHEW ALAN SOLOM

Submitted to the Office of Graduate Studies of  
Texas A&M University  
in partial fulfillment of the requirements for the degree of

MASTER OF SCIENCE

Approved by:

Chair of Committee,	Karen Vierow
Committee Members,	Leslie A. Braby
	James T. White
Head of Department,	Yassin Hassan

December 2012

Major Subject: Nuclear Engineering

Copyright 2012 Matthew Alan Solom

## ABSTRACT

The current knowledge of the performance characteristics of Centrifugal Tensioned Metastable Fluid Detectors is limited. While a theoretical treatment and experience with bubble chambers may be applied with some degree of success, they are no substitute for experimental and operational knowledge of real CTMFD systems. This research, as with other investigations into CTMFD systems in the past, applies theory and simulations. In addition, however, an experiment was conducted that for the first time attempts to determine the threshold energy for triggering a CTMFD system in a controlled manner.

A CTMFD system works in a manner similar to classic bubble chambers. A liquid is brought to an unstable state in which it is favorable to form a volume of vapor; using centrifugal techniques similar to those employed in a Briggs apparatus, the pressure in the sensitive region can be brought to extremely low values, placing the liquid in a tensile state. In such states, the energy necessary to cause the formation of macroscopic bubbles can be vanishingly small, depending on the degree of tension. When such bubbles form in a CTMFD, if they have a size bigger than a critical value, they will grow until a large vapor column forms in the sensitive region of the CTMFD.

The experiment developed for this research employed a carefully-controlled laser to fire pulses of known energies into the sensitive region of a CTMFD. By varying the laser power, the threshold values for the triggering energy of a CTMFD can be found.

The experiment and simulation demonstrated the ability of the facilities to test CTMFD systems and the potential to extract their operational characteristics. The experiment showed a certain viability for the technique of laser-induced cavitation in a seeded fluid, and demonstrated some of the associated limitations as well. In addition, the CFD framework developed here can be used to cross-compare experimental results with computer simulations as well as with the theoretical models developed for this research.

## **DEDICATION**

*For my grandparents.*

## **ACKNOWLEDGEMENTS**

I would like my advisor, Dr. Karen Vierow, for making this research possible. Her help, support, and above all, patience, enabled me to complete this work. I would also like to thank the other members of my committee, Dr. Leslie A. Braby and Dr. James T. White, for their help and insightful discussions on the mechanics behind the experiment.

I am also very grateful to the other members of the Laboratory for Nuclear Heat Transfer Systems, past and present, for the myriad of ways they assisted. Oren Draznin, Wes Cullum, Brad Beeny, Andrew Dercher, and Patrick McDermott were instrumental in assembling the experimental facilities. In addition, Dr. Kevin Hogan introduced me to CFD and was extremely helpful in the early stages of the CFD model development.

I would also like to thank Dr. R. Cable Kurwitz and the Nuclear Power Institute at Texas A&M University. Their support enabled me to continue after funding for this research disappeared.

## NOMENCLATURE

ATMFD	Acoustic Tensioned Metastable Fluid Detector
CAD	Computer-Aided Design
CFD	Computational Fluid Mechanics
CTMFD	Centrifugal Tensioned Metastable Fluid Detector
HEU	Highly Enriched Uranium
IR	Infrared
LED	Light Emitting Diode
P	Pressure
PWM	Pulse Width Modulation
r	Radius
R	Gas Constant
SNM	Special Nuclear Material
T	Temperature
TMFD	Tensioned Metastable Fluid Detector
WIMP	Weakly Interacting Massive Particle

## TABLE OF CONTENTS

	Page
ABSTRACT .....	ii
DEDICATION .....	iv
ACKNOWLEDGEMENTS .....	v
NOMENCLATURE .....	vi
TABLE OF CONTENTS .....	vii
LIST OF FIGURES .....	x
LIST OF TABLES .....	xiv
1. INTRODUCTION .....	1
1.1. Problem Statement .....	5
1.2. Technical Approach .....	5
1.3. Thesis Overview .....	6
2. BACKGROUND AND THEORY .....	8
2.1. Bubble Theory .....	8
2.1.1. Limits of Quasi-Static Stability .....	10
2.1.2. Energetics .....	13
2.1.3. Acoustic Dynamics .....	15
2.1.4. Cavitation Damage .....	17
2.2. Nucleation Theory .....	18
2.2.1. Heterogeneous Nucleation .....	18
2.2.2. Homogeneous Nucleation .....	20
2.3. Tensile Fluids .....	25
2.4. Bubble Chambers .....	28
2.5. Tensioned Metastable Fluid Detector Systems .....	30
3. EXPERIMENTAL WORK .....	36
3.1. Experimental Background Theory .....	37
3.1.1. Pulse Width Modulation .....	46
3.1.2. RS-232 .....	47

3.1.3.	Optics .....	50
3.2.	Experimental Equipment.....	52
3.2.1.	Containment Box.....	57
3.2.2.	Containment Box Interlock.....	60
3.2.3.	CTMFD Hardware .....	61
3.2.4.	CTMFD Test Sections.....	64
3.2.5.	Speed Sensor .....	68
3.2.6.	Cavitation Sensor .....	69
3.2.7.	Signal Inverter .....	71
3.2.8.	Speed Controller Electronics Unit.....	72
3.2.9.	RS-232 Isolator and Power Supply .....	76
3.2.10.	Laser System and Optical Assemblies.....	78
3.2.11.	Laser Interlock System .....	81
3.2.12.	Pulse Generator.....	83
3.2.13.	Oscilloscope.....	85
3.2.14.	High Speed Camera .....	85
3.2.15.	Data Acquisition and Control System .....	86
3.2.16.	SpeedControl Software.....	86
3.3.	Fluid Choice and Seeding .....	96
3.4.	Experimental Procedures.....	97
3.4.1.	Pre-Operation Procedures .....	97
3.4.2.	Data Operation Procedures.....	99
3.4.3.	Shutdown Procedures .....	104
3.4.4.	High-Speed Camera Notes .....	104
3.5.	Experimental Results.....	105
3.5.1.	High Speed Visualization.....	106
3.5.2.	First Fill.....	116
3.5.3.	Second Fill.....	118
3.5.4.	Third Fill .....	121
3.5.5.	Fourth Fill.....	122
3.5.6.	Discussion and Analysis.....	124
4.	COMPUTATIONAL FLUID DYNAMICS WORK .....	130
4.1.	CFD Simulation.....	131
4.2.	CFD Results .....	141
5.	CONCLUSIONS.....	150
5.1.	Key Findings .....	151
5.2.	Future Work .....	151
	REFERENCES.....	153
	APPENDIX A .....	156



APPENDIX B .....	193
APPENDIX C .....	355

## LIST OF FIGURES

	Page
Figure 1: van der Waals Isotherms [1] .....	22
Figure 2: PV Diagram [6].....	24
Figure 3: CTMFD Concept [5].....	32
Figure 4: Triggered CTMFD .....	33
Figure 5: Experimental Concept .....	38
Figure 6: Energy Requirements for Bubble Formation.....	44
Figure 7: Fluence Requirements for Bubble Formation.....	44
Figure 8: New Laser Room .....	53
Figure 9: CTMFD Experimental Facility.....	54
Figure 10: CTMFD Experiment with Open Enclosure .....	55
Figure 11: Close-Up of the Mounted Test Section .....	56
Figure 12: CTMFD Setup .....	62
Figure 13: Assembled Test Section A.....	65
Figure 14: Test Section A Glassware .....	66
Figure 15: Flat-Bottomed Glassware .....	67
Figure 16: Controller Output Waveform.....	74
Figure 17: Laser and Mirror on Platform .....	80
Figure 18: Main SpeedControl Window .....	88
Figure 19: Before the Pulse .....	107

Figure 20: Firing the Pulse .....	108
Figure 21: 1 ms Post-Pulse.....	108
Figure 22: 2 ms Post-Pulse.....	109
Figure 23: 3 ms Post-Pulse.....	110
Figure 24: 4 ms Post-Pulse.....	110
Figure 25: 5 ms Post-Pulse.....	111
Figure 26: 6 ms Post-Pulse.....	111
Figure 27: 7 ms Post-Pulse.....	112
Figure 28: 9 ms Post-Pulse.....	113
Figure 29: 11 ms Post-Pulse.....	113
Figure 30: 16 ms Post-Pulse.....	114
Figure 31: 21 ms Post-Pulse.....	115
Figure 32: 41 ms Post-Pulse.....	115
Figure 33: 191 ms Post-Pulse.....	116
Figure 34: First Fill .....	118
Figure 35: Fill 2 Data .....	119
Figure 36: Fill 3 Chart.....	122
Figure 37: Fourth Fill Data.....	124
Figure 38: All Collected Data .....	126
Figure 39: 6 $\mu$ s Pulse Data .....	127
Figure 40: Comparison with Expected Trend .....	128
Figure 41: CAD model for CFD .....	132

Figure 42: Model Dimensions (mm), Front .....	133
Figure 43: Model Dimensions (mm), Top .....	134
Figure 44: Model Dimensions (mm), Side.....	134
Figure 45: CFD Mesh.....	135
Figure 46: Initial Fill Example .....	136
Figure 47: CFD Pressure Drop.....	145
Figure 48: CFD $\Delta P$ Fractions.....	146
Figure 49: Lab-Frame Velocity Distribution .....	147
Figure 50: Pressure Distribution .....	148
Figure 51: Containment Box Interlock Schematic .....	158
Figure 52: Speed Sensor Schematic .....	160
Figure 53: Speed Sensor Adapter Schematic .....	161
Figure 54: Cavitation Sensor Schematic .....	163
Figure 55: Signal Inverter Schematic.....	165
Figure 56: Speed Controller Electronics Overview .....	167
Figure 57: Master Power Subassembly .....	168
Figure 58: Fault Detector Subassembly .....	169
Figure 59: Isolator Subassembly .....	170
Figure 60: Phase Detector Subassembly .....	171
Figure 61: Trigger Subassembly .....	172
Figure 62: Waveform Adapter Subassembly .....	173
Figure 63: Serial Port Isolator Overview .....	177

Figure 64: Power Supply Subassembly.....	178
Figure 65: Buffer A-B Subassembly.....	179
Figure 66: Buffer C-D Subassembly.....	180
Figure 67: Buffer E-F Subassembly.....	181
Figure 68: Buffer G-H Subassembly.....	182
Figure 69: Laser Interlock System Overview .....	185
Figure 70: Interlock Light 1 Subassembly.....	186
Figure 71: Interlock Light 2 Subassembly.....	187
Figure 72: Interlock Light Flasher Controller Subassembly.....	188
Figure 73: Interlock 12V Supply Subassembly.....	188
Figure 74: Interlock Door and Buttons Subassembly .....	189
Figure 75: Pulse Generator Schematic .....	192

## LIST OF TABLES

	Page
Table 1: Properties of Acetone [21] .....	43
Table 2: Antoine Parameters for Acetone [22] .....	43
Table 3: Data from the First Pulse Series .....	117
Table 4: Data from the Second Pulse Series .....	120
Table 5: Data from the Third Pulse Series .....	121
Table 6: Data from the Fourth Pulse Series .....	123
Table 7: Meshing Information .....	137
Table 8: Physics Conditions .....	139
Table 9: Other Conditions .....	140
Table 10: CFD Ramp-Up .....	142
Table 11: Post-Ramp Values .....	143
Table 12: Long-Term Values .....	144
Table 13: Containment Box Interlock Components .....	159
Table 14: Speed Sensor Components .....	161
Table 15: Speed Sensor Adapter Components .....	162
Table 16: Cavitation Sensor Components .....	164
Table 17: Signal Inverter Components .....	165
Table 18: Speed Controller Components, Part 1 .....	174
Table 19: Speed Controller Components, Part 2 .....	175

Table 20: Serial Port Isolator Components, Part 1 .....	183
Table 21: Serial Port Isolator Components, Part 2 .....	184
Table 22: Laser Interlock System Components .....	190
Table 23: Pulse Generator Components .....	191

## 1. INTRODUCTION

Detection of highly enriched uranium (HEU) and other special nuclear materials (SNM) can be made difficult through shielding and low intrinsic radioactivity signatures of the potential material. In addition, current detectors designed for use at domestic points of entry (for the detection of smuggled SNM) tend to be large and expensive affairs with limited usefulness. The development of an inexpensive, high-performance, and portable system would therefore greatly help the detection effort and enhance the deterrence of such activities.

A novel detector based on metastable tensioned fluids has promising characteristics that would facilitate detection of SNM in an active-interrogation environment. The detectors can be fabricated out of common, inexpensive materials, and be scaled from relatively small, portable units to large, fixed detectors by simply enlarging the tensioned fluid chamber. The threshold for detection can be adjusted by changing the degree of tension present in the fluid, allowing for the sensitivity to radiation to be easily adjusted.

There are two major classes of tensioned metastable fluid detectors currently under investigation to achieve this. One design uses a piezoelectric transducer to induce acoustic waves in a sensitive resonant region. This results in periods of high pressure at the peak of the waveform and potentially significant degrees of tension during the troughs. The detector therefore has an intrinsic duty cycle and will have a minimum



insensitive period regardless of the particle flux. Such a system is an acoustic tensioned metastable fluid detector (ATMFD).

The second design achieves a tensile state in the sensitive region through centrifugal means. A specially crafted assembly containing the fluid is rotated around its centerline at a very high rate. Due to the design of the apparatus, the result can be a significant degree of tension in the fluid at the centerline and for the region surrounding it. While the pressure in the sensitive region will vary by the distance from the centerline, it can be essentially time-independent. This eliminates the insensitive periods inherent in the ATMFD. However, this centrifugal tensioned metastable fluid detector (CTMFD) has the drawback of being essentially a single-shot device; once the tension is broken, the device needs to be stopped and restarted to re-tension the fluid. This results in dead times on the order of tens of seconds. Such a protracted period of insensitivity makes the device useless for high-flux fields within the device's sensitive range; however, it is much less important when the field is extremely weak and detection of the presence of the field takes priority over quantification of the flux.

While the conditions the fluids experience may be considered exotic, the fluids themselves need not be. The devices can be designed to use Freon, acetone, or even water. They take advantage of the tendency of liquids to adhere to the walls of their containers if the composition is compatible (adhesive forces), for individual molecules to be attracted to each other (cohesive forces), and for the liquid to remain largely incompressible. The combination of those properties allow for tensile stresses to be applied to liquids far in excess of thermodynamic stability. In fact, liquids can be

tensioned well beyond the point where the absolute pressure within them is less than zero [1]. Some liquids have remarkable limits on the amount of tension they can endure; benzene has been measured to -150 bar [2], and water has been measured to -1400 bar with a theoretical limit of -1400 to -2000 bar [3].

The ability of liquids to tolerate significant amounts of tension may seem surprising at first, but it is a known phenomenon. In fact, it is not a rare phenomenon in nature. Plants are known to take advantage of it; -15 atm can be found in the sap of redwoods, while -80 atm have been measured in creosote bushes [4].

In such tensile states, the liquids are not stable and tend to separate into liquid + vapor. However, this is limited when there are no nucleation sites available. These may be surface irregularities, suspended 'motes' in the liquid, dissolved gases, or anything else that would encourage bubble formation and growth beyond the critical size. If appropriate nucleation sites are not available, cavitation will not occur and the liquid will remain a liquid, although unstable. Increasing the degree of tension in the liquid makes it easier to destabilize and cavitate, and by increasing it far enough either the adhesive or the cohesive forces maintaining the liquid as such will be overcome and it will cavitate. Within that range, the minimum required energy for an event to result in cavitation becomes very small. Depending on the liquid, at some point the localized energy deposited by a single incident nuclear particle is enough to nucleate a bubble larger than the critical size, and it will continue to grow until the new liquid + vapor mixture reaches thermodynamic equilibrium [5]. Given enough of a tensioned liquid with even a modest

cross-section, one could build a detector based on the cavitation of the liquid. This is not unlike the classic bubble chamber, which uses superheated liquid as its working fluid.

From bubble theory, one can easily determine the energy required to grow or shrink a spherical bubble from one radius to another if the vapor and liquid pressures are known along with the surface tension of the interface. Any of the aforementioned irregularities in the liquid may provide an effective ‘bubble’ that can be incited to grow by local energy deposition. However, it is unclear to what extent a liquid’s properties may be affected by a metastable tensile state and how influential random microscale events may be; simple application of thermodynamics and bubble theory may be insufficient for the realization of the energetics involved in a cavitation event. Experimentation is necessary to gather sufficient data on the events and to develop empirical relationships governing cavitation events.

Such experiments can be conducted by providing known energies to liquids with known tensions. This may be done by focusing a laser pulse to a small region of fairly uniform tension in a liquid and observing potential cavitation events. By adjusting the laser’s properties (pulse energy, size of the region of highly focused beam energy, etc.) one can construct the relationship between energy deposition and liquid tension for laser induced cavitation.

## **1.1. PROBLEM STATEMENT**

The broad goal of this research is the characterization of a CTMFD system through the use of:

- Theory
- An experiment utilizing laser-induced cavitation
- Computational Fluid Dynamics (CFD)

At present, there is insufficient knowledge of the behavior of fluids in real (rather than ideal) CTMFD systems to adequately characterize their responses and to optimize such systems. This research attempts to provide some of the necessary steps to address that lack of knowledge.

## **1.2. TECHNICAL APPROACH**

The broad goals of this research can be broken into the following facets:

1. To design, construct, and operate an experimental facility for the evaluation of CTMFD systems and the collection of tensioned liquid data
2. To explore the use of laser-induced cavitation as an experimental technique
3. To investigate the energetics of a CTMFD system
4. To develop a CFD framework for modeling a CTMFD system

This research will examine tensioned liquids to increase the knowledge of metastable fluids and their behaviors in dynamic systems. An improved understanding of tensioned fluids can lead to new types of nuclear detectors based on their unique properties. Although there have been a number of experiments performed in order to determine the limiting values of tension in liquids, other properties have not been as thoroughly probed. The utility of laser-induced cavitation will also be examined as an experimental technique.

### **1.3. THESIS OVERVIEW**

This thesis describes a multi-faceted research project, and is organized to give each facet its own section. The first section is a simple introduction. The second section provides background on TMFD systems as well as some information on the related bubble detectors. It also provides the theoretical underpinnings for CTMFD systems in discussions of tensile liquids, bubble theory, and nucleation theory.

The third section contains the largest effort in this research: the development and early operation of CTMFD experimental facilities. It is subdivided to give details on its operational theory, including discussions on Gaussian optics, RS-232 interfaces, and Pulse Width Modulation. Each component is described; many of them were designed and built specifically for this experiment. The operation of the facility is described as well, and discussion of the first set of results is included.

The fourth section describes the Computational Fluid Dynamics framework developed for this research. While the goals of this particular model are relatively

modest, it provides a foundation on which to base further research. As with the experiment, a discussion of the first set of results is included.

Any conclusions that can be drawn are discussed in the fifth section. It brings together the earlier discussions, draws conclusions, and makes recommendations for further work. Finally, the Appendices provide details that do not fit well into the main text; this includes circuit schematics, diagrams, and source code listings.

## **2. BACKGROUND AND THEORY**

The theoretical framework for the characterization of TMFD systems has much in common with that of more traditional bubble-based detectors. They all place their working fluids in metastable states, and experience cavitation events when incident particles deposit sufficient energy in the fluid. As a result, bubble theory and nucleation theory are key to the understanding of all such systems. While these systems may all be considered superheated, they arrive at that superheat from various methods. TMFD systems achieve it by placing the liquid in a negative pressure state, so both the limits of superheat and the overall limits of tension must be considered. Methods of energy deposition are important as well, but are considered beyond the scope of work.

The key theoretical underpinnings for TMFD systems considered for this scope of work are bubble theory and nucleation theory. An understanding of tensile fluids is important as well, as is the application of such theoretical frameworks in TMFD systems and more conventional bubble detectors.

### **2.1. BUBBLE THEORY**

For the sake of this thesis, simple bubble theory will be applied. Bubbles will be assumed to be spherical and in a quasi-static state; this allows the analysis to proceed in a simple and straightforward manner.

A spherical gas bubble at steady state in a liquid has a relationship between the inner and outer pressure that is based on the bubble radius and surface tension as given below [6].

$$P_B - P_L = \frac{2\sigma}{r} \quad (1)$$

It is clear from Eq. (1) that the internal pressure of the bubble is greater than the pressure of the bulk liquid surrounding it, and that the difference is more pronounced in small bubbles than in large ones. It also suggests that, for a given set of constant pressures, there is one specific stable bubble radius; at a smaller radius, surface tension will dominate and the bubble will begin to collapse while the opposite is true for a larger radius. It should be noted that the pressure for the bubble is the total pressure inside it; there may be several different components to the bubble's contents, and they may make a difference in the behavior of the bubble. If a component will not dissolve or diffuse away, its partial pressure will vary with bubble size and temperature, and will not be constant.

At equilibrium, the bubble will contain a partial pressure of the surrounding liquid in its vapor state as determined by the temperature of the liquid. It would also contain partial pressures of gases that are dissolved in the liquid as determined by their solubility characteristics. It may also have amounts of relatively insoluble gases contributing. Much of the distinction between the soluble and insoluble gases depends on the dynamics of the system of interest; for rapid changes in short time scales, many gases may behave as insoluble gases, but would be expected to maintain equilibrium concentrations on longer time scales or when changes are slower.



### 2.1.1. Limits of Quasi-Static Stability

When more information is needed, one can turn to the formulae for bubble dynamics. In general, the Rayleigh-Plesset Equation [6] is the traditional formula used for spherical bubble dynamics Eq. (2).

$$\frac{P_B - P_L}{\rho_L} = r\ddot{r} + \frac{3}{2}\dot{r}^2 + \frac{4v_L}{r}\dot{r} + \frac{2\sigma}{\rho_L r} \quad (2)$$

While Eq. (2) can be used for simple bubble dynamics, it can also be used to gain insight into static and quasi-static conditions. If one takes a bubble at equilibrium and perturbs it, one can determine if that equilibrium point is stable or unstable. Depending on the gases within the bubble, it may have more than one equilibrium radius. In modeling bubble dynamics, one may consider the bubble a two-component system: the vapor from the surrounding liquid, and an insoluble gas. By applying that to the Rayleigh-Plesset Equation and by using a small perturbation to shift it slightly off-equilibrium, one can determine the following:

$$P_B = P_v + P_g \quad (3)$$

$$\frac{P_v + P_g - P_L}{\rho_L} - \frac{2\sigma}{\rho_L r} = r\ddot{r} + \frac{3}{2}\dot{r}^2 + \frac{4v_L}{r}\dot{r} \quad (4)$$

$$P_g = \frac{nRT}{\frac{4}{3}\pi r^3} = \frac{3nRT}{4\pi r^3} \quad (5)$$

$$P_v - P_L + \frac{3nRT}{4\pi r^3} - \frac{2\sigma}{r} = \rho_L \left( r\ddot{r} + \frac{3}{2}\dot{r}^2 + \frac{4v_L}{r}\dot{r} \right) \quad (6)$$

$$P_v - P_L = \Delta P, \frac{3nRT}{4\pi r^3} - \frac{2\sigma}{r} = f, \rho_L \left( r\ddot{r} + \frac{3}{2}\dot{r}^2 + \frac{4v_L}{r}\dot{r} \right) = g \quad (7)$$

$$\Delta P + f = g \quad (8)$$

At equilibrium,  $g=0$ . That gives a relationship between the equilibrium bubble size and the local conditions as Eqs. (9) and (10):

$$\Delta P + f = 0; P_v - P_L + \frac{3nRT}{4\pi r^3} - \frac{2\sigma}{r} = 0 \quad (9)$$

$$(P_v - P_L)r^3 - 2\sigma r^2 + \frac{3nRT}{4\pi} = 0 \quad (10)$$

Solving for the roots of Eq. (10) gives equilibrium radii. One interesting thing to note is the situation in which the liquid and vapor pressures are equal and the system is in equilibrium:

$$-2\sigma r^2 + \frac{3nRT}{4\pi} = 0 \quad (11)$$

$$r = \sqrt{\frac{3nRT}{8\sigma\pi}} \quad (12)$$

When  $r$  is greater than the value in Eq. (12),  $f$  will always be negative. Below that,  $f$  will be positive. In the limit as  $r$  gets arbitrarily large,  $f$  will approach zero. It will have a minimum in the same place as  $\Delta P + f$  as given by Eqs. (13) through (16):

$$\frac{d}{dr}(\Delta P + f) = 0 = \frac{df}{dr} = \frac{d}{dr} \left( \frac{3nRT}{4\pi r^3} - \frac{2\sigma}{r} \right) \quad (13)$$

$$0 = -3 \frac{3nRT}{4\pi r^4} + \frac{2\sigma}{r^2} \quad (14)$$

$$\frac{9nRT}{4\pi} = 2\sigma r^2 \quad (15)$$

$$r = \sqrt{\frac{9nRT}{8\pi\sigma}} \quad (16)$$

Equation (16) is known as the Blake critical radius [6]. On both sides,  $f$  will increase monotonically the further away from this radius a bubble is. When  $\Delta P$  is greater than zero, the vapor pressure of the liquid is greater than the bulk liquid pressure, and the surface tension of the bubble is responsible for maintaining it. Plugging the Blake critical radius in to  $f$  gives a minimum value:

$$\frac{3nRT}{4\pi \left( \sqrt{\frac{9nRT}{8\pi\sigma}} \right)^3} - \frac{2\sigma}{\sqrt{\frac{9nRT}{8\pi\sigma}}} = f_{\min} = -\sqrt{\frac{128\pi\sigma^3}{81nRT}} \quad (17)$$

As a result of Eq. (17), if  $\Delta P$  is greater in magnitude than  $f_{\min}$  and opposite in sign, then  $g$  will always be positive and equilibrium will not be achieved. Conversely, if  $\Delta P$  is less than zero, there will be one equilibrium radius. However, if  $\Delta P$  is between zero and the negative of  $f_{\min}$ , then there will be two equilibrium radii, one on each side of the Blake critical radius.

The end result is the determination of an upper limit of stability; for equilibrium bubbles with smaller radii than the Blake critical radius, a small perturbation will result in the bubble returning to its equilibrium state. If the equilibrium radius is greater than this limit, it is unstable; a small perturbation will lead to increasing deviations from the original state. This is due to the monotonically increasing nature of  $f$  away from the Blake critical radius; if the larger bubble is perturbed,  $g$  will end up having the same sign

as the perturbation and the bubble will change size with positive feedback. On the other side of the Blake critical radius, however,  $g$  will have the opposite sign as the direction of the perturbation and it will oppose the change [6]. If  $\Delta P$  is less than zero, however, the bubble will be unconditionally stable, as the sign of  $g$  will always be opposed to the direction of bubble size deviation. Of course, the preceding analysis assumed that the bubble is spherical, isothermal, and quasi-static.

From Eq. (16), it is clear that any bubble composed entirely of the vapor of the surrounding liquid will not be in a stable equilibrium state, as the critical radius of such a bubble is zero. If it has any deviation from its equilibrium size, it will either grow explosively or implode. It should also be noted that even with a nonzero quantity of insoluble gases in a bubble, the surrounding liquid can be placed under tension without affecting the stability of the bubble if it is small enough; surface tension forces can be sufficient to override a negative pressure in the surrounding liquid. Therefore, a liquid may survive being placed under tension without completely removing existing bubbles.

### **2.1.2. Energetics**

It takes energy to grow a bubble in size. The necessary amount of work to grow a bubble quasi-statically (such that inertial and viscous effects can be ignored) can be easily calculated by integrating from  $r_1$  to  $r_2$ , which accounts for the PV-work done at the bubble boundary. In addition, the change in energy of the bubble's contents must also be accounted for; it may not be an adiabatic process. In a growing bubble, a certain amount of the surrounding liquid will evaporate and fill the bubble to maintain a

constant partial pressure. The gases may also absorb heat from the surroundings if the process is isothermal. These relationships are expressed in Eqs. (18) through (25):

$$W_{PV} = \int_{r_1}^{r_2} \left[ (P_L - P_v) + \frac{2\sigma}{r} \right] 4\pi r^2 dr \quad (18)$$

If the bubble grows from nothing to the critical radius with a constant internal vapor pressure, Eq. (18) can calculate the net energy necessary, resulting in Eq. (19) [6]:

$$W_{CR} = \frac{16\pi\sigma^3}{3(P_v - P_L)^2} \quad (19)$$

This reflection of the work may not give the entire picture; it excludes the latent heat of vaporization for the vapor and some of the work done by it. Taking more into account results in Eqs. (18) to (23). They assume that a bubble is grown from an essentially zero size sphere of initial liquid (which vaporizes) to a vapor-filled bubble at the equilibrium radius, and that the volume of liquid vaporized is negligible compared to the final bubble volume. Heat is not exchanged between the growing bubble and its surroundings; it only does PV work on them. The necessary energy to supply to that initial bit of liquid is then given by Eq. (20).

$$E_{Bubble} = W_{PV,L} + Q_{vap} \quad (20)$$

$$W_{PV,L} = \int_0^{r_c} \left( P_L + \frac{2\sigma}{r} \right) 4\pi r^2 dr = 4\pi r_c^2 \left( \frac{P_L}{3} r_c + \sigma \right) \quad (21)$$

$$Q_{vap} = nh_{vap} \quad (22)$$

$$n = \frac{4\pi P_v r_c^3}{3RT} \quad (23)$$

In Eq. (22), the latent heat of vaporization should be expressed in a per mole basis, allowing a simple application of the Ideal Gas Law in the calculation.

$$E_{bubble} = 4\pi r_c^2 \left( \frac{P_L}{3} r_c + \sigma \right) + \frac{4\pi P_v r_c^3}{3RT} h_{vap} \quad (24)$$

$$E_{bubble} = \frac{16\pi\sigma^3}{3(P_v - P_L)^3} \left[ P_v \left( 3 + \frac{h_{vap}}{RT} \right) - P_L \right] \quad (25)$$

Substitution of the critical equilibrium radius into Eq. (24) results in the value given in Eq. (25). The values expressed in Eqs. (18) through (25) reflect reversible processes; if there is an irreversible component or energy loss, it must also be taken into account. In addition, they say nothing about the source or availability of the energy. For this, some discussion of bubble nucleation is necessary.

### 2.1.3. Acoustic Dynamics

Although the primary focus of this research involves static methods (constant rotation rates and pressure fields, etc.), some discussion of more dynamic behavior is in order. As a common experimental technique for the investigation of cavitation and tensile liquids involves acoustic waves, some consideration of their effects on bubble stability is worth mentioning.

One important aspect of bubbles exposed to acoustic waves is their behavior approximating a damped oscillator if the pressure wave's amplitude is low. This gives rise to a resonance frequency for the bubble, which is approximated in Eq. (26) [7]. In it,  $\eta$  is the shear viscosity and  $\kappa$  is the polytropic index, while  $r_0$  is the equilibrium bubble radius and  $P_0$  is the constant term in the external pressure oscillation.

$$\omega_0 = \frac{1}{r_0 \sqrt{\rho}} \sqrt{3\kappa \left( P_0 + \frac{2\sigma}{r_0} - P_v \right) - \frac{2\sigma}{r_0} + P_v - \frac{4\eta^2}{\rho r_0^2}} \quad (26)$$

In the undamped case, expressions for the resonance frequency and bubble radius can be seen in Eqs. (27) and (28) [8].

$$\rho \omega_r^2 r_0^2 = 3\gamma \left( P_0 + \frac{2\sigma}{r_0} \right) - \frac{2\sigma}{r_0} \quad (27)$$

$$\Delta r = \begin{cases} \frac{P_A}{\rho r_0 (\omega_r^2 - \omega^2)} \left[ \sin(\omega t) - \frac{\omega}{\omega_r} \sin(\omega_r t) \right] & \omega \neq \omega_r \\ \frac{P_A}{2\rho r_0 \omega^2} [\sin(\omega t) - \omega t \cos(\omega t)] & \omega = \omega_r \end{cases} \quad (28)$$

Another important relationship for bubbles exposed to pressure oscillations is the limit of stability for such systems. In cases where gas diffusion can play a role, an expression for the amplitude limit can be seen as Eq. (29) [8], where  $\delta$  is a damping factor, the gas concentrations are  $C_0$  at saturation and  $C_\infty$  in the bulk liquid, and  $\beta$  is the fraction of the resonance frequency.

$$\left( \frac{\Delta P}{P_0} \right)^2 = \frac{3}{2} \left( \frac{1 + \frac{2\sigma}{r_0 P_0} - \frac{C_\infty}{C_0}}{1 + \frac{2\sigma}{r_0 P_0}} \right) \left[ (1 - \beta^2)^2 + \beta^2 \delta^2 \right] \quad (29)$$

$$\delta = \frac{P_0}{\rho \omega^2 r_0^2} \quad (30)$$

$$\beta = \frac{\omega}{\omega_r} = \sqrt{\frac{\rho \omega^2 r^2}{3\gamma P_0}} \quad (31)$$

A simpler, alternate expression for the value in Eq. (29) can be seen when the concentration of gas dissolved in the liquid ( $C_\infty$ ) is equal to its saturation value ( $C_0$ ), and the damping factor is zero. It then can be approximated as Eq. (32) [8].

$$\left(\frac{\Delta P}{P_0}\right)^2 = \frac{3\gamma\sigma}{r_0 P_0} \frac{(1-\beta^2)^2}{\left(1-\frac{\beta^2}{8}\right)} \quad (32)$$

#### 2.1.4. Cavitation Damage

Bubble growth may be more relevant to this research, but the collapse of bubbles bears mentioning as well. Whether the source of nucleation is heterogeneous or homogenous, the appearance of bubbles in liquid may pose challenges to engineers. In transient conditions, the bubbles may only exist for moments and can collapse quickly and violently. Such collapsing bubbles can have powerful effects; they may produce local high-amplitude shock waves and microjets [6]. Heating in the collapsing bubble may result in sonoluminescence. Incandescence and thermochemical reactions have been suggested as mechanisms for light emission from collapsing bubbles, but the phenomenon is not fully understood [7]. In fact, it has been suggested that collapsing bubbles can get hot enough to allow for thermonuclear reactions [5], although that position is not widely accepted.

In any case, if any objects are near violently collapsing bubbles, they may experience cavitation damage. Such damage has been observed on boat propellers, and all sorts of hydraulic equipment are susceptible. It is a limiting condition for pump operation, and is the cause of the Tarbela tunnel collapse in Pakistan in 1974 [1].



Therefore, it is a concern to those working on equipment that can be put into such an environment.

## **2.2. NUCLEATION THEORY**

Bubble nucleation will occur preferentially where discontinuities exist in the liquid that provide weak spots [9]. This can be observed in the simple case of boiling a pot of water on a stove; the bubbles will largely form where the water meets the heated part of the pot. If that surface is scuffed or has other imperfections, those sites themselves can be observed to be active sources of steam bubbles [9]. This is exacerbated by the local thermal conditions; the water in the immediate vicinity of the heated part of the pot will tend to be hotter than the bulk liquid, and may be fairly superheated. That encourages additional nucleation in those regions.

If such nucleation sites are not available, a liquid will be able to survive a significant amount of superheat without boiling. This can be seen by placing a smooth mug of relatively pure water in a microwave oven [10]. If the conditions are right, the water may be heated well above its boiling point without actually boiling. If it is then removed from the microwave oven, it can be hazardous; the introduction of nucleation sites may lead to sudden vigorous boiling that can cause injury [10].

### **2.2.1. Heterogeneous Nucleation**

The discontinuities necessary for heterogeneous bubble nucleation in a liquid can be provided by the liquid's container. The container wall itself not only provides a discontinuity, but may also provide locations where gases can become trapped. If there are crevices in the wall, gas can easily be retained in them when the container is filled

with liquid. Under the right conditions, a stable equilibrium can be achieved. If the pressure is reduced, the trapped gas can expand and may release bubbles into the bulk liquid. Such trapped gas can be eliminated by pressurizing the liquid to pressures on the order of 1000 bar and holding there for half an hour or more; this forces the gas to dissolve into the liquid [1].

Rough container walls are not the only locations that one may find gas-storing crevices. Motes (particles, often specks of dirt or dust) and contaminants suspended in the liquid are also prime locations for gas-trapping crevices. In addition, if the suspended particles encounter each other, bubbles can form through tribonucleation [1].

It is possible for gas trapped in such crevices to remain in the crevice instead of dissolving into the liquid. If the wall does not get perfectly wetted and the contact angle is correct, it can reduce the gas pressure in the crevice to that of the equilibrium pressure from the gas already dissolved in the liquid. Changes in the solubility of additional gas or in the liquid pressure can upset this equilibrium.

Surface tension and geometry are not the only ways to keep gas bubbles from dissolving out into the liquid. In fact, small bubbles of gas may stay dispersed in the liquid without vanishing. Such bubbles are an additional source of weaknesses in the liquid, and their persistence was unexpected. It is now thought that even trace amounts of an organic contaminant in the liquid is sufficient to form a sort of skin around the edges of microbubbles, limiting the diffusion of gas into the liquid [6].

### 2.2.2. Homogeneous Nucleation

When heterogeneous nucleation is limited, homogenous nucleation may dominate the formation of vapor bubbles. Given a critical radius, there is a finite probability that a bubble will randomly form within a set time period. Since the rate of bubble formation is generally expressed as being proportional to Eq. (34) [6], the rate of formation of bubbles in a mole of tensile liquid can be given as Eq. (36) [11]. This can be adjusted to give the limit of tension when a bubble forms in a mole of tensile liquid as a function of time as in Eq. (37); in practice, this relationship can be simplified to Eq. (38) [11]. Other analyses use the critical temperature in Eq. (33), and it is generally accepted that when  $Gb < 11.5$ , cavitation is assured [6].

$$Gb = \frac{W_{cr}}{kT} \quad (33)$$

$$J = J_0 e^{-Gb} \quad (34)$$

$$J_0 = N \sqrt{\frac{2\sigma}{\pi m}} \quad (35)$$

$$\frac{dn}{dt} = \frac{NkT}{h} \exp\left(-\frac{\Delta f_0^* + W_{\max}}{kT}\right) = \frac{NkT}{h} \exp\left(-\frac{\Delta f_0^* + \frac{16\pi\sigma^3}{3P^2}}{kT}\right) \quad (36)$$

$$P_t = -\sqrt{\frac{16\pi}{3} \frac{\sigma^3}{kT \ln\left(\frac{NkTt}{h}\right) - \Delta f_0^*}} \quad (37)$$

$$P_t = - \sqrt{\frac{16\pi}{3kT} \frac{\sigma^3}{\ln\left(\frac{NkT}{h}\right)}} \quad (38)$$

Such nucleation has the practical effect of limiting the tensile strengths of liquids. The tensile strength of a liquid can be estimated by envisioning the intermolecular spaces as existing vapor bubbles and determining the tension in the liquid that would cause those bubbles to grow. Unfortunately, such an estimate would be incorrect, frequently missing the mark by several orders of magnitude. It would, however, give results comparable to those obtained by using compressibility moduli [6]. A better, although still inaccurate, estimate can be made by application of the van der Waals Equation, shown as Eq. (39) [1].

$$\left(P + \frac{a}{V^2}\right)(V - b) = RT \quad (39)$$

Tracing an isotherm in the van der Waals Equation reveals a minimum pressure in the curve, which is the limiting low pressure at that temperature [1]. Example isotherms are shown in Figure 1. Additionally, there is a local maxima in the curve which represents the greatest pressure a supercooled vapor can survive without condensing. By following the minimum pressure at differing temperatures, one can generate the liquid spinodal curve. Likewise, tracing the location of the local maximum, one can arrive at the vapor spinodal curve. These curves meet at the critical point, and only exist below it [6]. When the saturation curve is overlaid on the spinodal curves, one can see the ranges of the supercooled vapor and superheated liquid. The area between the saturation curve and the spinodal curves on a PV-diagram are the metastable

states for the supercooled vapor and superheated liquid. Since they are not stable, disturbances in those states can cause a transition from a single-phase system (liquid or vapor) to a two-phase system (liquid + vapor).




Figure 1: van der Waals Isotherms [1]

Formally, a thermodynamic spinode is defined in Eq. (40) [12]. The spinode exists where, in an isotherm, the partial derivative of the pressure with respect to the volume of the material is zero.

$$\left(\frac{\partial P}{\partial V}\right)_T = 0 \quad (40)$$

In reality, there are deviations from the forms of the spinodal lines given by the van der Waals Equation; an example curve is given in Figure 2. On a P-T plot, as the temperature decreases away from the critical point, the liquid spinodal line is expected to decrease monotonically, but this may not be the case for water. Water, a material known for behaving in non-ideal manners, is thought to be especially deviant along its liquid spinodal line, and may not exhibit monotonic behavior [13]. Furthermore, it is not achievable in practice to bring a metastable fluid all the way to its spinodal limit. The closer to the limit one approaches, the more likely it is for a random disturbance to cause nucleation and form a two-phase system.




Figure 2: PV Diagram [6]

Homogenous nucleation theory can give an insight into practical limits to metastable states. Given a critical radius for a vapor bubble, there is a non-zero probability that a vapor bubble at least that large will spontaneously coalesce in a given time for a volume of metastable liquid. The closer to the spinodal limits one approaches, the shorter the waiting time becomes for the random nucleation of a critical-sized

bubble. Ultimately, a metastable liquid cannot exist as such beyond the spinodal limits, and nucleation is assured.

### **2.3. TENSILE FLUIDS**

Much like solids, liquids are able to withstand being "stretched," or placed under a degree of tension. At first glance, this may seem a bit strange; when the pressure above a liquid drops below its vapor pressure, it may begin to boil. Indeed, this can be observed by heating a pot of water on a stove; once the water's temperature is high enough, its vapor pressure is equal to the pressure of the surrounding air and the pot will begin to boil. This is a well-known phenomenon; the boiling point of water is common knowledge, and boiling water is a part of everyday life.

However, it is not always the case that hot water at or above its boiling point will end up boiling. A mug of water heated in a microwave oven may remain as a liquid well above its boiling point; this is known as a superheated liquid, and can give an unlucky observer a close and personal demonstration of superheated water flashing to steam [10]. Such a situation demonstrates two things: liquids can exist as liquids above their boiling points, and such superheated conditions are not necessarily stable. A superheated liquid, therefore, is metastable; it can exist in such a state, but if it experiences a sufficient disturbance, it will move toward its stable equilibrium state.

The reason for this is simple: each molecule of the liquid has some attractive and repulsive forces between it and its neighbors, and the attractive forces can be quite large; these forces are large enough that liquids can be considered to be incompressible. The attractive forces between molecules in the liquid are called cohesive forces, and the



attractive forces between the liquid and its container are called adhesive forces. At fluid interfaces, these forces are agglomerated and called the surface tension.

At the boiling point, the cohesive forces in a liquid can be great enough to prevent bulk boiling, and it readily occurs only at weak points within the fluid. These weak points can be provided by bubbles, suspended particles, contaminants or other such discontinuities.

One result of this is the ability to maintain liquids in superheated or other metastable states. In fact, it can be such a powerful effect that liquids can be maintained in metastable states where their vapor pressures are much greater than the total pressure in the liquid; the total pressure in the liquid can even drop below zero, putting the liquid in a tensioned rather than compressed state.

The degree of tension that a metastable tensioned liquid can survive can be surprisingly high. For example, by 1951 benzene had been brought down to -150 bar, aniline had been brought down to -300 bar, and chloroform had been brought down to -317 bar [2]. Water in particular can survive a remarkable degree of tension; it has been tested to be metastable at pressures less than -1400 bar, with a theoretical limit between -1400 bar and -2000 bar [3]. Limits on tension can be approximated based on overcoming the attractive forces between individual molecules [6]; however, this method tends to overestimate the magnitude of the tensile limits by several orders. Better estimates can be determined by application of nucleation theory [6].

Modern studies of tension in liquids began in the 19th Century; Euler predicted the presence of tensile stresses in moving liquids in 1754 [1]. François Donny in the

1840s experimented with vacuum pumps and sulfuric acid in U-tubes, producing mild tensions in the liquid. Soon afterward, Berthelot in the 1850s was able to induce tension at 50 atm in water using an instrument that now bears his name: the Berthelot tube [1]. A Berthelot tube is a sealed cylinder filled with liquid and a small portion of air. The tube is heated, and the liquid expands until there is no room left for the air, which then dissolves in the liquid. The tube is then cooled, and tension builds up in the liquid until the tension breaks, and some of the air comes out of solution as bubbles. There is also a slight increase in the volume of the tube from just before the breaking of the tension to afterwards; this is used to help determine the degree of tension at that point [1]. Then, in the late 19th Century, Reynolds experimented with centrifugal means for tensioning liquids [1].

While tensile liquids at first glance seem to be a laboratory curiosity or limited to transient situations due to their metastability, they do appear in nature. In the 1890s, it was proposed that tension in the sap of tall trees enabled it to be lifted to the top; a vacuum pump cannot lift water anywhere near 100-m above ground, which is a height achieved by redwoods [4]. Using a balancing pressure technique, the pressure in the xylem at the top of an 82-m redwood was measured to be less than -15 atm. Haplophytes ranged from -35 to -60 atm, and a creosote bush was found with a pressure lower and -80 atm in the xylem. Mistletoe was found to have significantly lower pressures than its host, often by 10 to 20 atm [4]. The balancing pressure technique has been compared to other methods with mixed results. Experiments using modified pressure probes frequently do not agree with the high degree of tension found by the

balancing pressure method. However, centrifugal methods have been found to agree with the balancing pressure method [14].

## **2.4. BUBBLE CHAMBERS**

The idea that nuclear particles can nucleate bubbles, and that such a process can be used as a detector, is not new. Glaser experimented with superheated diethyl ether in the early 1950s, and found that it would erupt in boiling much quicker when in the presence of ionizing radiation than in the absence of radiation [15]. From those early experiments, the early bubble chambers were developed and their theories of operation determined. Fluids such as liquid hydrogen and liquid propane were used with high fractions of superheat; a liquid hydrogen bubble chamber operating at 27 K has a superheat of nearly 7 K (with a boiling point of 20.3 K at atmospheric pressure, this is more than 1/3 greater than the boiling point), and can have a bubble nucleated by a local deposition of 4.08 eV [16].

Those systems would be operated on a cycle; the detector would be decompressed to a very superheated state in which the liquid would be very sensitive to deposited energy. Incident particles would leave tracks made of bubbles, which would be photographed. Then a fast compression would bring the liquid back to a stable state in which it would not be sensitive. Then the cycle repeats, with a decompression down to very superheated states [17]. Such devices had drawbacks resulting from the severe amounts of superheat applied to the working liquid, and the sensitive period could only last a few moments [17]. They eventually disappeared from common use, but were not completely forgotten. The COUPP (Chicagoland Observatory for Underground Particle

Physics) experiments have shown a renewed interest in similar devices for the detection of Weakly Interacting Massive Particles (WIMPs). The superheat is more moderate, and the fluid is different ( $\text{CF}_3\text{I}$ ). The COUPP experiments have had a degree of success taking the sensitive period for the system from moments to indefinitely long periods [17].

Other modern takes on superheated liquids include emulsion-based devices. Small droplets of superheated liquid are suspended in an inert matrix; the two fluids are immiscible and cannot mix. Deposition of sufficient energy can result in the formation of a vapor bubble within a suspended droplet; the entire droplet may completely flash to vapor. Such devices have been used as neutron detectors, but are also sensitive to heavy charged particles [18].

While traditional bubble-based detectors involve superheat at positive pressures, speculation on devices very much like modern acoustic TMFD systems goes back at least to 1965. Bertolotti, Sette, and Wanderlingh considered the use of ultrasonic pressure waves in resonant chambers to grow microbubbles left behind by incident nuclear particles. If microbubbles were to dissipate slowly and accumulate as the result of energy deposition from incident radiation, induced ultrasonic cavitation might be able to reveal a spectrum of energy deposition long after the passage of the depositing particles [19]. While the descriptions they gave are too limited to draw conclusions about their work, the system described appears to have a remarkable amount in common with more modern ATMFD designs.

## **2.5. TENSIONED METASTABLE FLUID DETECTOR SYSTEMS**

A novel take on the classic bubble chamber for detecting nuclear particles is the Tensioned Metastable Fluid Detector (TMFD). In such systems, a liquid is placed under tension to create a sensitive zone. The idea is that nuclear particles incident in the sensitive zone may deposit enough energy in the liquid to nucleate a bubble larger than the local critical size, at which point the bubble will continue to grow until some external limit is reached. Depending on the fluid properties and the degree of tension, the necessary deposited energy from such a particle can be quite small. The fluid need not be exotic; selection of the fluid may be a part of the design optimization process. This depends on the type, energy, and flux of particles to detect, as well as outside factors such as cost and availability.

There are two main methods for achieving the necessary tensile state in the liquid, and these methods define the class of TMFD systems. Both methods are deceptively simple. One method uses transducers to induce acoustic waves in the detection fluid; such systems are Acoustic TMFD (ATMFD) systems. The second method rotates a special assembly rapidly around an axis so that centrifugal effects create a tensile region in the vicinity of the axis of rotation; this method is used in Centrifugal TMFD (CTMFD) systems.

Both ATMFD and CTMFD systems can be made of commodity hardware and have no requirement for exotic or expensive materials; even prototype systems can be relatively inexpensive to design and construct. They can also be scaled from very small


systems to much larger ones. This may be simpler for an ATMFD than for a CTMFD, as the CTMFD must rotate the entire detection assembly.

In an ATMFD, a resonant chamber is filled with a chosen detection fluid. Piezoelectric transducers are used to induce acoustic waves in the fluid with a large amplitude. At the peaks of the acoustic waves, the pressure can be very high in the surrounding fluid; it is unlikely to be sensitive to incoming nuclear particles in this part of the cycle. The pressure will drop with the wave, and near the troughs the pressure in the surrounding liquid can be very low; given a great enough amplitude, the troughs can place the local liquid in a tensile state. At that time, the surrounding liquid can be sensitive to incoming particles. During this period, if incident particles deposit enough energy, cavitation events can occur and the resulting bubbles can quickly grow. However, when the pressure rises, the bubble growth will be arrested. The period of high pressure can cause the bubbles to violently collapse; the resulting click and pops may be audible, and cavitation luminescence may be observed. If the ATMFD is instrumented, the time and location of collapsing bubbles can be determined to help characterize the incoming flux. While the sensitivity of the detector is time and position-dependent, it can handle numerous simultaneous events and can operate continuously.

A CTMFD is similar to devices used by Briggs experimenting with tensile liquids [1] [20]. The heart of a CTMFD is the specially-shaped detection assembly. It has a bulb at the bottom along the axis of rotation; this region contains the tensioned liquid. From the top of the bulb, two tubes extend up and out radially, then bend back toward each other, meeting again along the axis of rotation some distance above the


bulb. The tubes trace a roughly diamond-shaped area above the bulb [5]. In operation, the bulb and tubes will be filled with liquid to a point above the 'elbows' in the tubes where they bend back toward each other above the bulb, but not all the way to where they meet. This is important; when the assembly is rotated, the tension at the centerline depends on how far out from the axis of rotation the liquid is filled to.

When the detection assembly in a CTMFD system is rotated rapidly about its axis, the pressure in the centerline depends on three primary things: the density of the liquid, the rotation rate, and the radial distance to the centerline from the top of the liquid fill. The pressure at the air-liquid interface (the assembly is open at the top) provides a necessary reference. Away from the centerline, the pressure in the liquid depends on the radial position. An illustration of the CTMFD concept is given in Figure 3.



**Figure 3: CTMFD Concept [5]**

During operation in a CTMFD system, the assembly is typically rotated at a constant rate. As a result, the pressure field in the liquid is essentially time-independent. It is also very predictable. However, cavitation events are not detected in the same manner as in an ATMFD, and this provides a limit on the performance of a CTMFD system. When a bubble that is larger than the critical size is formed, it quickly grows and merges with any other nearby bubbles. Because there is no pulse of high pressure, the bubble's growth will not be arrested by it and it will not collapse. Instead, it moves to the centerline and grows into a vapor column in the bulb; the growth is finally stopped by the increase in pressure brought by the displaced liquid pushed up into the tubes above the bulb. An illustration of this is shown in Figure 4. Here, a “triggered” CTMFD is one that has, in operation, experienced a critical cavitation event and as a result has a stable vapor column formed in the bulb.



**Figure 4: Triggered CTMFD**



The formation of a vapor column will break the tension in the liquid; the vapor column can shrink and grow to balance the pressures. Therefore, a CTMFD is essentially a single-shot detector. Once the vapor column forms, it does not disappear. Instead, the rotation must be stopped. At that point, the vapor column will shrink to a much smaller bubble or disappear entirely. Whatever bubble remains must be allowed to migrate up through the tubes and out to the interface between the liquid and air in the upper part of the assembly. Otherwise, when the assembly is returned to speed, the bubble will regrow into the vapor column. The stop-restart sequence can take tens of seconds, so a CTMFD is not suitable for high detection-rate environments.

One of the more interesting features of a TMFD is the potential ability to reveal the directionality of incoming particles. If an incoming particle does not lose too much of its energy in an encounter in the fluid, does not deflect far from its original course, and has sufficient distance between induced nucleation events, the formation of bubbles from the high-energy depositions from the particle can provide a track for the particle. With high capture speeds and sufficient resolution, such tracks can be recorded and be used to determine the direction from which the particles were coming.

The idea behind a CTMFD is displayed in Figure 3. The main driver behind the pressure gradient is the differing fill levels in the upper and lower arms during rotation. Since the gas above the liquid is generally going to be much less dense, the pressure developed by it is going to be significantly less in the upper arms than that developed by the liquid in the lower arms. So long as the liquid adheres to the walls of the container and does not develop bubbles, the liquid will remain trapped in the lower arms and bulb.

Assuming incompressibility and neglecting gravity, the pressure drop from one radial position to another in the liquid is easily calculated as is done in Eq. (41). If it is assumed that at the liquid-gas interface the pressure  $P_{amb}$  is equal to the outside pressure, then one can approximate the centerline pressure in the bulb from the liquid's density, rotation rate, fill level, and ambient pressure as in Eq. (42) [5].

$$\Delta P = - \int_{r_1}^{r_2} 4\rho\pi^2 f^2 r dr \quad (41)$$

$$-P_{centerline} \approx 2\rho\pi^2 f^2 r_{amb}^2 - P_{amb} \quad (42)$$

While both physical demonstrations and computer simulations of CTMFD systems have been performed [5], there is a current lack of hard experimental data in such systems. In particular, the threshold deposition energies for triggering a CTMFD have not been experimentally verified. Theory and computer simulations are wonderful tools, but they cannot completely replace experimental testing and verification.

### 3. EXPERIMENTAL WORK


An experimental CTMFD system was designed and constructed with the goal of examining the energetics of a CTMFD system. In order to do this, it takes a CTMFD system and attempts to induce cavitation by depositing energy in the working fluid with laser pulses. The laser pulses are at known intensities and durations, and focused near the centerline in the CTMFD. The laser power starts of low, and then grows sequentially in order to find the minimum threshold power necessary to induce cavitation and the formation of a vapor column in the CTMFD.

The goals of this experiment were to examine the threshold energy for the formation of a vapor column in a seeded CTMFD with pressures in the -1 atm to -5 atm range. The liquid was acetone, and the seeding material was printer toner. A side-goal of this is to demonstrate the ability to successfully assemble a CTMFD system using standard, inexpensive parts and components. While most of the electrical systems were not off-the-shelf pieces of equipment, they use standard and relatively inexpensive components (transistors, diodes, op-amps, etc.) that a serious electronics hobbyist may be familiar with. Some circuits were made of components found entirely in local RadioShack retailers. However, there were some exceptions. The CTMFD test section used glassware that was custom-built by an experienced glassblower, and is not something that can be readily found or assembled from commercial products. In addition, the laser system's cost dwarfed that of the other pieces of equipment.

The design and construction of the experimental facilities involved a major effort. While the particular goals of this experiment are somewhat limited, the now-existing facilities provide a framework for further tests without the need to develop completely new facilities; they can largely be used as-is.

### **3.1. EXPERIMENTAL BACKGROUND THEORY**

The idea behind the experiment is simple: operate a CTMFD in a known configuration, and focus pulses of known laser energy into a spot in the immediate vicinity of the centerline of the CTMFD, and see whether or not it forms a vapor column. If one did not form, the laser pulse energy would be increased until a threshold energy was found that did result in such a formation. With the optical system in place, the energy concentration at the focus point could be estimated, and with properties such as the Beer-Lambert coefficients, the total energy absorbed at that point could also be estimated. Using a calculation based off of the rotation rate, fill level, and density of the liquid under examination, a relationship could be drawn between the operating centerline pressure and the minimum deposition energy needed for the formation of the vapor column.



**Figure 5: Experimental Concept**

The size of the laser spot would not be varied; only the pulse power and duration would be. In a ramp test, the duration would be preset, and the pulse power would be the only thing varied. Since the laser spot was expected to be much larger than the critical radius of a vapor bubble in the tensile liquid, much of the deposited energy would be wasted; only a fraction would be used to nucleate the critical bubble.

The minimum reversible energy for the formation of a bubble of with a critical radius is given from Bubble Theory as Eq. (19); Eq. (25) may also be applied. An irreversible term can be added as well to describe off-equilibrium energy losses, but that is not done here. The entirety of this energy must be deposited in the immediate vicinity of the growing bubble. If this area is limited to a sphere the size of the condensed liquid

that would be the vapor fill of a critical bubble, the energy arrives in the form of a photon flux, and a known fraction of the flux incident on the circle defined by the projection of the liquid sphere into two dimensions, then, using the time duration of the flux, an estimate of the laser energy can be made by following Eqs. (43) through (54).

$$A_{dep} = \pi r_{condensed}^2 \quad (43)$$

$$r_{condensed} = \sqrt[3]{\frac{3}{4\pi} V_{condensed}} \quad (44)$$

$$V_{condensed} = \frac{m_L}{\rho_L} = \frac{nM_L}{\rho_L} = \frac{M_L}{\rho_L} \frac{P_v V_{crit}}{RT} \quad (45)$$

$$V_{crit} = \frac{4}{3} \pi r_c^3 = \frac{4\pi}{3} \left( \frac{2\sigma}{P_v - P_L} \right)^3 \quad (46)$$

$$V_{condensed} = \frac{M_L}{\rho_L} \frac{P_v}{RT} \frac{4\pi}{3} \left( \frac{2\sigma}{P_v - P_L} \right)^3 \quad (47)$$

$$r_{condensed} = \sqrt[3]{\frac{M_L P_v}{\rho_L RT} \left( \frac{2\sigma}{P_v - P_L} \right)} \quad (48)$$

$$A_{dep} = \pi \left( \frac{M_L P_v}{\rho_L RT} \right)^{2/3} \left( \frac{2\sigma}{P_v - P_L} \right)^2 \quad (49)$$

$$\Phi = \frac{Energy}{Area} \quad (50)$$

$$\Phi_{CR} = \frac{W_{CR}}{A_{dep}} = \frac{\left( \frac{16\pi\sigma^3}{3(P_v - P_L)^2} \right)}{\pi \left( \frac{M_L P_v}{\rho_L RT} \right)^{2/3} \left( \frac{2\sigma}{P_v - P_L} \right)^2} \quad (51)$$

$$\Phi_{CR} = \frac{\left( \frac{16\sigma^3}{3(P_v - P_L)^2} \right)}{\left( \frac{M_L P_v}{\rho_L RT} \right)^{2/3} \left( \frac{2\sigma}{P_v - P_L} \right)^2} = \left( \frac{\rho_L RT}{M_L P_v} \right)^{2/3} \left( \frac{4\sigma}{3} \right) \quad (52)$$

$$\Phi_{bubble} = \frac{E_{bubble}}{A_{dep}} = \frac{16\pi\sigma^3}{3(P_v - P_L)^3} \left[ P_v \left( 3 + \frac{h_{vap}}{RT} \right) - P_L \right]}{\pi \left( \frac{M_L P_v}{\rho_L RT} \right)^{2/3} \left( \frac{2\sigma}{P_v - P_L} \right)^2} \quad (53)$$

$$\Phi_{bubble} = \left( \frac{\rho_L RT}{M_L P_v} \right)^{2/3} \left( \frac{4\sigma}{3} \right) \left[ \frac{P_v \left( 3 + \frac{h_{vap}}{RT} \right) - P_L}{P_v - P_L} \right] \quad (54)$$

$$\Phi = \frac{P_{Laser} t_{Pulse}}{A_{focus}} \quad (55)$$

It should be noted that  $M_L$  is the molar mass of the liquid. The equations make the assumption that the bubble will form at the laser focus point, that the entirety of the laser fluence is available for bubble formation at that point, and that the liquid conditions are sufficiently far from the spinodal limits that their influence on the energy requirement is small. They also need the laser focus area to be greater than the bubble's energy deposition area. In addition, the pressure in the liquid needs to be below the liquid's vapor pressure.

This adds up to a constant value in Eq. (52); it followed the use of the critical energy, Eq. (19), from nucleation theory. A separate treatment uses the total energy for

bubble formation from Eq. (25), resulting in Eq. (54). In the limit as the liquid pressure gets arbitrarily negative, it asymptotically approaches the value given in Eq. (52).

It also ignores the effects of irreversible processes, thermal conductivity in the fluid (which can be significant in the time and length scales under consideration), and any sort of activation energy necessary for the event. It also assumes that incident radiant energy would be converted to ordinary heat, but this may not be the case. The effects of thermal conductivity can be limited by using a sufficiently short pulse period, if the laser is sufficiently powerful to emit the requisite energy in such a short period.

As for the activation energy, it may be possible to define a limit on its value from examination of relevant fluid properties. If the necessary activation energy is greater than the energy necessary to grow a bubble to the critical size, then delivery of the full bubble growth energy may not be sufficient to nucleate the bubble; the necessary energy would then depend on delivering the full amount of activation energy. It may be possible to place a limit on the activation energy by determining how much energy it would take to heat the volume of liquid under consideration (that necessary to fill a bubble of the critical radius at the vapor pressure of the bulk liquid) to the liquid spinodal limit at the operating CTMFD centerline pressure. Past the spinodal limit, nucleation is assured. If the spinodal limit at the operating pressure is unknown, one may use the liquid's critical temperature instead as a conservative limit; the spinodal limits do not exist past the critical point [6]. At the critical point, each molecule has enough energy to separate from all the other molecules, and the surface tension drops to zero [6]; the distinction between the liquid and vapor fluid phases disappears. This



estimate is shown in Eq. (58); if it is greater than Eq. (54), then the process may be dominated by the activation energy, but this is not expected to be the case. The estimated activation energy is expected to be a severe overestimate.

$$E_{act} < m_{condensed} c_p (T_{lim} - T) \quad (56)$$

$$E_{act} < \frac{4\pi}{3} \rho_L r_{condensed}^3 c_p (T_{lim} - T) \quad (57)$$

$$E_{act} < \frac{4\pi}{3} c_p (T_{lim} - T) \frac{M_L P_v}{RT} \left( \frac{2\sigma}{P_v - P_L} \right)^3 \quad (58)$$

As an example, the values for acetone at 25° C are given below. The properties for acetone are listed in Table 1 [21] and Table 2 [22]. The data in Table 2 is used in the Antoine Equation [22] to determine the vapor pressure at a given temperature; the Antoine Equation is given in Eq. (59). With those parameters, the vapor pressure of acetone at 25° C would be 30.6 kPa. The resulting plots of the necessary bubble formation energy and the laser fluence are given in Figure 6 and Figure 7. While in the plots, the activation energy dominates for pressures above about -6 bar, the activation energy term is meant to be little more than an upper bound rather than a best estimate.

**Table 1: Properties of Acetone [21]**


Boiling Point	56.05° C
Surface Tension	0.02272 N/m
Thermal Conductivity	0.161 W/m-K
Density	784.5 kg/m <sup>3</sup>
Viscosity	3.06E-4 Pa-s
Heat Capacity	126.3 J/mol-K
Latent Heat of Fusion	29.1 kJ/mol at 56.05° C 30.99 kJ/mol at 25° C
Molar Mass	56.08 g/mol
Critical Temperature	508.1 K
Critical Pressure	4.7 MPa

$$\log_{10}(P) = A - \frac{B}{T + C} \quad (59)$$


Equation (59) uses the parameters given in Table 2 to determine the vapor pressure of acetone within the range of the given parameters. This can be used, along with the properties in Table 1 and the energy relationships in Eqs.(19), (25), (49), (50), (52), (54), and (58), to produce the curves shown in Figure 6 and Figure 7.

**Table 2: Antoine Parameters for Acetone [22]**

[P]	bar
A	4.42488
B	1312.253
C	-32.445
Range	259.16 K to 507.6 K



**Figure 6: Energy Requirements for Bubble Formation**



**Figure 7: Fluence Requirements for Bubble Formation**

Unfortunately, things are rarely as simple as the calculations behind Figure 6 and Figure 7. In this experiment, the working fluid was not a single, homogenous liquid. In order to ease the energy requirements for successfully inducing cavitation and forming a vapor column, solid 'seed' particles were mixed in with the liquid. These provided two benefits: weak points in the liquid to reduce the necessary localized energy deposition, and a much greater absorption of energy to help localize additional energy deposition from a given laser pulse. They are widely dispersed so as to limit the extra absorption in the beam path before the focus point, but are intended to be close enough together to assure that seed particles will be present in the region of high energy intensity within the depth of focus. While these may be true, their presence introduces new phenomena and additional complexity.

The particles chosen were black toner particles from a Dell™ Color Laser Printer 3110cn. If they are assumed to be made entirely of carbon black, they would have a density of  $1.887 \text{ g/cm}^3$  [23], which is significantly more than that of acetone. Even when they would remain in suspension under ordinary conditions, it is possible that they may not when exposed to sufficient operational periods in a CTMFD. They may come out of suspension as a result of severe centrifugation. For example, at 200 rps and 5 mm out from the centerline, the centripetal acceleration is more than  $7,895 \text{ m/s}^2$ , which is nearly 805 times the acceleration due to gravity at the surface of the Earth. In addition, they do not have a uniform size, but have a potentially wide size distribution. They also introduce an added thermal sink at the point of greatest laser energy absorption; the energy directed to heating the toner particles will reduce the amount going to heating the

acetone. The particles, under the immense sudden heat load, may catastrophically deform, break apart, melt, or undergo other interesting thermochemical changes. This can lead to the formation of vapor columns that are less directly connected to the properties and energetics of the bulk acetone and have more to do with phenomena primarily occurring in the seed particles themselves. At present, it is unknown what kind of effects to expect.

A discussion of the theory behind the CTMFD experiment would be incomplete without mentioning some of the theoretical underpinnings behind the support equipment. This includes Pulse Width Modulation, RS-232, and some relevant optical theory.

### **3.1.1. Pulse Width Modulation**

There are situations where it is useful to represent analog signals in digital circuits. This can be achieved by sampling the signal at regular intervals and encoding it into a more suitable form, making sure that the sampling frequency is high enough to capture all the important variations in the original signal. One common encoding technique is Pulse Width Modulation, which "represents a signal by using pulses of constant amplitude but variable widths" [24]. A simple PWM signal operates on a fixed frequency; as a result, the meaningful width of each pulse is limited to a maximum of the period of the PWM frequency. Therefore, a simple PWM signal is a square wave where the widths of the peaks are varied in relation to the encoded information. The fraction of time in which the signal is high rather than low is known as its duty cycle [25], and has a simple relationship with the original signal. If, for example, the original signal was at 75% of its limit, the corresponding duty cycle of the PWM signal would also be 75%. If

the original signal dropped to 25% of its limit, the corresponding duty cycle of the PWM signal would drop to 25% as well.

When a PWM is passed through a low-pass filter, the output is a reconstruction of the original signal that was encoded with PWM. So long as the original signal does not get too close to its upper or lower limits, the reconstructed signal will match the original signal [24].

PWM is commonly used in power conversion circuits; the digital logic helps enhance the efficiency of those circuits [25]. It can also be expanded beyond simple bi-state logic to three or more levels, depending on the application; for example, a three-level PWM signal might have voltage states of +1, 0, and -1 V [24].

PWM variants can be used in circuits that are not strictly digital. For example, an ordinary thyristor-based dimmer switch [26] typically trims the early part of each half-cycle in an AC line; the 'pulse' is the remaining part of the sine wave in the latter part of each half-cycle downstream of the dimmer switch.

### **3.1.2. RS-232**

RS-232 ("Recommended Standard 232") is a standard that defines a type of serial communication interface commonly found on computers and associated equipment. It defines what has become the traditional 'serial port' found on PC-compatible computers since the original IBM PC. The standard itself predates the IBM PC. It is a robust interface that can tolerate abuse, and is relatively simple to interface with in software. In addition, user-mode software in Microsoft ® Windows™ operating systems are given a

remarkable degree of control over the hardware itself; direct software control of the 'control lines' is permitted. This makes it an attractive interface for a variety of uses.

In RS-232 standards, there are two device types: Data Terminal Equipment (DTE) and Data Circuit-terminating Equipment (DCE) [27]. The DTE would typically be a computer or other terminal, while the DCE would be a modem or printer connected to the computer's serial port; the DTE connects to the DCE in standard setups. The standards also define a full set of 25 pins, however, it is common for many of the pins to be absent from an interface. There are recommended uses for all the pins, but many of them are allowed to be used as seen fit by hardware and software developers.

In RS-232 systems using the DE-9 style interconnects (most PC serial ports are such), there are 8 signal lines and one ground line. The ground is a common signal ground for both sides. Instead of using a 'balanced' 4 input and 4 outputs lines, there are 3 lines signaling in one direction and 5 in the other. Which set is input and which is output then depends on the device type. This is not to be confused with 'unbalanced' electrical circuits; however, RS-232 is unbalanced electrically as well.

The DTE has 3 signals as its output: Data Terminal Ready (DTR), Request To Send (RTS), and Transmit Data (TxD or TD). Those signals are input signals on the DCE. The DCE, then, has 5 output signals: Data Carrier Detect (DCD), Data Set Ready (DSR), Ring Indicator (RI), Clear To Send (CTS), and Received Data (RxD or RD) [27]. Apart from the data lines TxD and RxD, the other 'control lines' have meanings or operations that are largely defined by software; user-mode software can easily take direct control of the state of the control lines.

The RS-232 standards also define voltages for the interface. Compliant devices are required to be able to have any of their pins shorted to each other or to ground without damage. The signal lines are also required to be able to handle having +/- 25 V applied, again without damage. However, the signals are required to be between +/- 5 V and +/- 15 V at the source; the receiving end allows the minimum to drop to +/- 3 V.

The region between -3 V and +3 V is undefined. Valid signals are therefore between -15 V and -3 V, and between +3 V and +15 V with respect to ground. For most of the signals, positive voltages reflect a logical 1, and in RS-232 documentation this state may also be called "true," "on," "asserted," or "mark." Negative signals, then, reflect a logical 0. Other terms for that state include "false," "off," "not asserted," and "space." The control lines follow such logic, but the data (TxD and RxD) do not; the data lines use inverted logic, where a negative voltage reflects a logical 1 and a positive voltage reflects a logical 0. The data lines also do not allow for the type of user-defined functionality that the control lines do.

Valid signals are not allowed to linger in the -3 V to +3 V zone; they are only allowed to be there when transitioning from one state to another. This wide voltage gap between defined states gives a degree of noise immunity to the system

The RS-232 standard also define limits on such characteristics as the rate of change for signal voltages (the slew rate) and the maximum data rate. However, it is common for these limits to be ignored in modern systems in order to allow for faster communication speeds.



### 3.1.3. Optics

In many materials, certain wavelengths of light can travel relatively unimpeded, while others may be absorbed in the material. It may also experience various types of scattering, and can reflect off of the material's interfaces. Some wavelengths may even cause the material to fluoresce. In the case of simple absorption, quantification of the absorption is simple and straightforward. The fractional change in intensity of light over a distance through the material depends on the material's properties and the distance traversed. This relationship is known as the Beer-Lambert Law, and the absorption parameter is known as the Beer-Lambert coefficient [28]. The equations are given in Eqs. (60) and (61). Attention should be paid to the symbols in use in these equations. While  $I$  represents the intensity and  $N$  the density,  $\sigma$  is NOT the surface tension; instead, it represents a cross section for interaction in Eqs. (60) and (61).

$$dI = -\sigma N I dx \quad (60)$$

$$\frac{I}{I_0} = e^{-\sigma N x} \quad (61)$$

If the primary interest is in energy absorption around a specified depth, that is relatively easy to compute. For example, if the region of interest is between  $x$  and  $x + y$  in some medium, then the fractional absorption in that region can be given by Eq. (62).

$$f_{abs} = \frac{I_x - I_{x+y}}{I_0} = e^{-\sigma N x} (1 - e^{-\sigma N y}) \quad (62)$$

This works for a homogenous absorbing medium, and may be applied to Eq. (55) or any of the other fluence equations. In those cases, the distance  $y$  would be on the order of the diameter of the sphere of to-be-vaporized liquid. If there are discontinuities,

things are a bit different. If the medium is largely transparent but has highly absorbing bits scattered throughout it, then most of the energy may be deposited at the absorbing sites rather than in the bulk medium. If the medium is transparent enough, and the absorbing sites have great enough absorption parameters, then the incident intensity on an individual site will be approximately the initial intensity, and it may absorb roughly all the incident energy. Therefore, the local absorption fraction could approach 1.

The clearest way to think about the Beer-Lambert dropoff in intensity is to think of following a laser beam through a medium; the further along the beam, the weaker it gets. This is not entirely due to absorption, however; even a well-collimated beam will spread out with distance. Laser systems commonly emit a beam that can be described by how close it is to having a Gaussian profile. A good laser will have its beam be very close to one of the modes of a Gaussian profile. With a Gaussian profile, the major parameters used to describe a beam are its diameter and divergence (the angle at which the beam spreads out). Both of those can be affected by optics in the beam's path.

If a lens is placed in the path of a coherent Gaussian beam, simple ray optics calculations are insufficient to describe the beam's characteristics after the lens. While it would seem that a beam could be focused down to an infinitesimally small spot by using a quality convex lens with a good laser, this is not the case. First, the absolute minimum spot size is determined by the wavelength of the light ( $\lambda$ ). In addition, a Gaussian beam will not focus to a point; there is a minimum spot diameter ( $\omega_0$ ) determined by the beam's diameter immediately before entering the lens ( $D$ ) and the divergence of the

beam after the lens, which is related to the focal length of the lens ( $F$ ). This relationship is given in Eq. (63) [29].

$$2\omega_0 = \left(\frac{4\lambda}{\pi}\right)\left(\frac{F}{D}\right) \quad (63)$$

$$DOF = \left(\frac{8\lambda}{\pi}\right)\left(\frac{F}{D}\right)^2 \quad (64)$$

The region in which the beam is close to its minimum size at the focus point has a finite and easily determined size. This so-called depth of focus, given in Eq. (64) [29], is the range centered around the beam waist at which point the beam width is  $\sqrt{2}$  times as wide as the beam waist. It should be noted that Eqs. (63) and (64) are approximations of the Gaussian parameters that work for relatively small focal lengths.

### **3.2. EXPERIMENTAL EQUIPMENT**


The experimental setup was constructed in the Nuclear Heat Transfer Systems Laboratory at the Riverside annex to Texas A&M University. Walls were constructed in the lab to create a room for the experiment, and the room was provided with an appropriate interlock system for the Class IIIb laser used in the experiment. A photograph of the new room can be seen in Figure 8. Like the walls, most of the equipment used in the experiment were custom-built.

Schematics for all of the custom electrical equipment built for this research are given in Appendix A. Similarly, the source code for the SpeedControl application developed to operate the facility is given in Appendix B.



**Figure 8: New Laser Room**

The experiment has a small glass CTMFD test section assembly attached to a rotating shaft, which is connected to a rotary tool; the shaft and CTMFD were custom-built, while the rotary tool is a standard power tool available at hardware stores. They in turn are mounted to an off-the-shelf Dremel ® stand using scrap wood and hose clamps. The system is instrumented with a custom-built IR speed sensor and optical cavitation sensor, while the speed is controlled by connecting the rotary tool to a custom-built controller. Much of this can be seen in Figure 9.




**Figure 9: CTMFD Experimental Facility**

In Figure 9, most of the key components in the experiment can be seen. On the left, somewhat cut off, are the computer system and oscilloscope. On the same platform, one can see the RS-232 isolator (bottom), the cavitation sensor box (sitting on the RS-232 isolator), and the pulse generator (nondescript box next to the oscilloscope with various wires). Mounted on the containment box are the box interlock (middle), speed controller electronics (top), laser interlock emergency stop button (red button on the right), and the experiment (inside). The high speed camera is visible on the bottom, as is the optical platform. The laser is hidden from view; it can be seen in the bottom in Figure 10.



**Figure 10: CTMFD Experiment with Open Enclosure**

There are optics that focus the laser (an off-the-shelf system) to a point within the CTMFD test section. A close-up showing the relation between the focusing lens, test section and cavitation sensor is shown in Figure 11. While some of these electrical and optical components are outside, the mechanical components are housed in a heavy containment box. The containment box is interlocked with custom electronics for safety reasons, and is separated from the laser and optical mounts to reduce the transmission of vibrations to the optical assemblies.



**Figure 11: Close-Up of the Mounted Test Section**

The speed sensor, cavitation sensor, speed controller, and laser head are connected to a custom central power supply and RS-232 interface through applicable adapters. In addition, the laser head interfaces with the room interlock system and the pulse generator circuit, both of which were custom-built. The pulse generator circuit, in turn, connects to the RS-232 interface as well as an oscilloscope. The oscilloscope and RS-232 interface connect to a desktop computer system for data acquisition and control. While the computer and its operating system are off-the-shelf commodities, the data acquisition and control software had to be written from scratch in a major development effort.

RS-232 serial communication was used in the experiment, but not all signals were used as one might expect from standard RS-232 systems. However, an RS-232 serial port on PC hardware is flexible; in addition to the standard text transmission and simple logic states, loosely-applied pulse width modulation was used (see Sections 3.1.2 and 3.1.1). Details for each of the components involved in the experiment can be found in Sections 3.2.1 through 3.2.16.

The above setup works well when calibrated. However, there are phenomena that it cannot monitor that still garner interest. To gain insight into the dynamics of the formation of the vapor column, a high speed camera was employed. However, due to operational difficulties, it is not a standard instrument in the experiment. It was only used in dedicated runs to collect high speed video of the cavitation events and the rapid growth of the bubbles into vapor columns.

### **3.2.1. Containment Box**

The containment box is an important part of the experiment. Not only does it provide physical support to its contents, it also serves as a major component in the experiment's safety systems. It is more than just a large, heavy assembly of wood, plastic, and metal.

Physically, the containment box is built up from a lower 2' x 4' platform made of plywood and 2x4 boards. From the platform, two similarly-sized regions are formed: the experimental area, and a secondary area. Both are rectangular volumes sitting on the platform with 2x4 framing. It rises about 3' above the platform. The experimental area



is separated from the secondary area by a plywood wall. The remaining four sides of the experimental area are covered by 0.25" polycarbonate windows.

The thick polycarbonate was chosen to ensure safety in the event of catastrophic failure in the experimental area. As the rotary tool is capable of speeds in excess of 35,000 rpm (>583 rotations/sec), ensuring safety became a central concern. At that speed, a device attached to the rotary tool extending out to a radius of just 5 cm would have a tangential velocity greater than 183 m/s at the edge. While it was expected that such speeds would not be readily attained, even much slower speeds could still pose a serious threat. The 0.25" of polycarbonate was deemed necessary to prevent the escape of projectiles from a failed test section. Should a catastrophic failure occur, the plywood and polycarbonate enclosure will keep the operator from catastrophically merging with the failed test section.

While providing physical protection, polycarbonate also provides clear, scratch-resistant window for observing the experiment in progress. Since the front, top, and left and right sides have the large polycarbonate windows, there is a large choice of angles to view the experiment from.

In addition to the windows, the front and top are hinged such that they can be rotated up as a unit and flipped over the top of the secondary area; it swings open. This provides a free and clear opening to the experimental area, with unobstructed access from the front and above. The side windows remain in place. When the access is closed, a lever arm can be rotated into place that will lock the front and top in the closed

position. The interlock on the box senses the position of both the access and the locking arm, so that attempts to open the box will result in power being cut from the experiment.

The interlock is mounted to the box, on the wall in the secondary area. Aside from the frame and the floor and wall to the experimental area, the secondary area is open to the air. In addition to the interlock for the box, the speed control unit is also mounted to the wall. Two switches are mounted between the interlock and speed control units; these turn on and off the outlets in the experimental area. One switch turns the regulated power (the speed control line) on and off, while the other switch controls raw 120 VAC in the experimental area for accessories such as lights.

The wires for power and sensors are fed through penetrations in the plywood wall in the back of the experimental area into gang boxes on the inside. The AC power lines (both regulated and unregulated) are attached to outlets in the experimental area to supply power to the rotary tool and the experimental area's lights. The wires for the speed sensor and cavitation sensor heads go through a separate penetration into a gang box with a cover in place. They then go through small openings in the box to reach their respective pieces of equipment.

In addition to the interior electrical boxes, there is a horizontal support board near the top of the experimental area. This holds a fluorescent light that illuminates the interior of the experimental area; the light plugs into the unregulated AC socket. The support board also allows the Dremel ® stand to be secured at its top, restricting wobble when the experiment is running. This has the side effect of making the experiment louder and transmitting additional vibration to the containment box from the experiment.

The floor of the experimental area has two major penetrations; both can be seen in Figure 11. One allows the optical support rod to enter the area and support the lens without being attached to the vibration-laden containment box. The second penetration is directly below where the test section is mounted to the shaft; this allows the laser beam to enter the experimental area and be focused into the test section. It is a relatively large and unobstructed penetration, but it is positioned such that it is extremely unlikely for shrapnel from a catastrophically failed experiment to traverse, bounce off something on the other side, and cause injury to persons in the vicinity.

The entire containment box is mounted on feet, one at each of its four corners. This elevates the system several inches above the ground. Each of the feet has a thick rubber strip glued to its bottom; this is intended to reduce the amount of vibration that can be transmitted to the floor beneath the containment box. There is sufficient room underneath the containment box to provide space for the laser head and optical assemblies.

### **3.2.2. Containment Box Interlock**

The interlock on the experiment's containment box was the first circuit to be designed and constructed. It was recognized early on that hazardous conditions would exist near the operating experiment, and that some physical separation between experimenter and experiment would be a prudent measure in order to keep the two from becoming one. While the box itself works when procedures are strictly followed, it is a good practice to include the interlock to help enforce safe practices. Should the box be opened, the interlock acts as a 'kill switch' and cuts the power from the box, shutting

down the rotary tool and quickly slowing the rotation down to zero. It does not, however, affect the operation of the laser.

The containment box interlock centers around two relays. The detector relays is connected to two microswitches on the experiment: one on the door itself, and a second one in series with the first on the locking arm. If the door or locking arm is opened to give physical access to the experiment, the detection circuit is opened and the detector relay opens. In addition, the second (downstream power) relay opens, cutting off power to the experiment. This allows separation of the low and high voltage sides of the circuit and maintains the circuit status -- when the containment box is closed and latched, the interlock will not automatically reconnect power to the experiment.


The interlock circuit displays its current status via indicator LEDs, and requires manual 'arming' of the system. Two buttons serve that purpose: one to arm the system, and one to manually trip it. When the 'arming' button is pushed, the system will only arm if the containment box is closed and latched, and if the 'trip' button is not concurrently pushed. Otherwise, the interlock will not connect power to the downstream components, even while the 'arm' button is held down.

In addition to providing an interlock to the containment box, the interlock circuit can serve as a source of +12VDC power. However, it is not used with the current experimental setup.

### **3.2.3. CTMFD Hardware**

The rotary tool is a Craftsman ® Rotary Tool Model 572610950. It has a maximum rotation rate of 35,000 rpm, and is rated to consume 1.15 Amps at 120VAC.

For the experiment, it plugs into the controlled socket inside the containment box, and has its switch set on high. It is mounted near the top of a fully-extended Dremel® stand, which is mounted inside the containment box at its base on the platform and at the top where the vertical rod meets the support board. This can be seen in Figure 12.



**Figure 12: CTMFD Setup**

The rotary tool attaches to a short 3 mm diameter by 60 mm length rod that has a pinhole at the far end. This rod is inserted into the receptacle for it in the main shaft, and the two are secured by passing a clip through their pinholes.

The main shaft itself is made up of several pieces. The top piece (7.96 mm diameter by 71 mm long) was cut from a paper feeding shaft in an older HP ® Deskjet™ 648C printer. A hole was drilled axially into the center of one end to insert the attaching rod for the rotary tool. A second, smaller hole was drilled through the side at the same end to allow a locking pin or clip to be inserted through the corresponding hole in the attaching rod when it is inserted and aligned. The opposite end has interlocking teeth cut into it to match a similar set on the lower portion.

The lower portion of the main shaft connects to the upper portion using sets of interlocking teeth cut into the mating surfaces, adhesive glue, and a plastic sleeve cut from paper feed wheels in the same inkjet printer that the main shaft came from (both parts were cut from the same rod). The sleeve covers the joint between the upper and lower portion, and everything is held together by the glue. It extends from the joint 36 mm down to the top of a pipe, traversing most of the length of the pipe.

Below the joint, the lower portion of the main shaft was wrapped in an even layering of aluminum tape and inserted into the center of a 0.25" SCHD 40 SS304 pipe with a length of 150 mm. They were secured together with epoxy. This expanded main shaft is marked using aluminum and black electrical tape running axially down the central portion; this allows for the speed sensor to see an alternating light and dark surface as the shaft rotates.

The expanded main shaft was then mounted to two high speed ball bearings, one near each end. The gap between the inner surface of each bearing and the outer surface of the pipe was filled with tape and epoxy for a permanent mount when the shaft was inserted into the outer housing.

The outer housing is made of 1" SCHD 80 PVC pipe cut to fit. Appropriate gaps were cut to hold the high speed bearings in place, and scrap PVC was used to make a mount at the top for clips to secure the upper high speed bearing in place. A hole was cut in the center of the housing for the speed sensor to view the rotating shaft inside.

The housing and shaft assembly was mounted vertically to the Dremel® stand and held in the correct position using wood blocks, rubber hose used as a cushion/gasket, and worm gear hose clamps. A piece of aluminum was cut and mounted to the wood support blocks and is used to support the speed sensor; it is taped into place aimed into the hole in the shaft housing.

At the bottom of the shaft, an SS304 pipe bushing for 0.25" to 0.5" SCHD 80 was securely threaded onto the 0.25" pipe. The bushing is the interface between the main shaft and the test section assemblies; the test section assemblies are replaceable and can quickly and easily be threaded onto the bushing.

#### **3.2.4. CTMFD Test Sections**

The test sections are made up of two primary components bonded together by epoxy: a mount and the CTMFD glassware. The mount is a 0.5" SCHD 80 PVC pipe coupler with two slots cut in one end on opposite sides. These slots allow the glass test section to be inserted into the mount while its arms extend out through the slots. Care is


taken to ensure an adequate alignment between the mount's center of rotation and the center of the bulb on the glassware, and the two components are then epoxied securely together. The mount threads onto the bushing on the bottom of the rotational shaft, allowing for quick and easy test section swaps. An assembled CTMFD test section can be seen in Figure 13.



**Figure 13: Assembled Test Section A**




The glassware is a small CTMFD made of 1 mm thick borosilicate. It has a bulb at the bottom, from which two opposing tubes extend out the top. The tubes extend out a distance, then have bends that angle them back toward the centerline of the bulb, still angled upward. They meet and rejoin each other a short distance above the top of the bulb, at which point they form a vertical tube. These arms, from where they leave the bulb to where they rejoin, form a diamond-shaped area between them. This can be clearly seen in Figure 14.



**Figure 14: Test Section A Glassware**

There are two major configurations for the glassware: a bulb with a hemispherical bottom, and a bulb with a flat bottom. The hemispherical-bottom bulbs match designs used elsewhere [5], while the flat bottom bulbs present a surface that should not have seriously unpredictable lensing effects. This should allow for better focusing of the laser beam to a point within the bulb than is possible with the highly curved hemispherically-bottomed bulbs. A flat-bottomed bulb can be seen in Figure 15.



**Figure 15: Flat-Bottomed Glassware**

The hemispherically-bottomed bulbs have the following nominal dimensions: 15 mm diameter by ~30 mm total height in the bulb. The inner width for the diamond-shaped region is between 60 and 65 mm, with an outer width between 74 and 80 mm. The inner height of that area is on the order of 18 to 20 mm. The flat-bottomed bulbs have the following dimensions: a cylinder of 15 mm in diameter and a height of 31 mm. The flat-bottomed bulbs were not used for the testing in this thesis.

### **3.2.5. Speed Sensor**

The speed sensor is a relatively simple circuit; it is essentially an optical tachometer. It consists of three major parts: a sensor head, a control unit, and a signal adapter. Each part is separated and placed in its own enclosure with cables connecting the parts.

The sensor head consists of an enclosure mounted near the shaft of the experiment. The shaft is divided radially into two regions: a dark half and a reflective half. This was done by applying black electrical tape and aluminum tape along the shaft; when it rotates, it alternates between the black and reflective surfaces being presented to the sensor head. The sensor head itself has an infrared LED and an infrared photodiode. The IR LED illuminates the rotating shaft, while the IR photodiode is used to transform the amount of reflected radiation into a voltage. That voltage is fed back to the control unit.

The control unit feeds the voltage from the sensor head into an op-amp, which is used as a comparator. It differentiates between the light and dark regions on the shaft by comparing the sensor output voltage to a tunable reference voltage. This reference

voltage is developed as part of the calibration of the sensor. To aid in this, two visible LEDs are included and connected to the output signal: a red LED indicating a low state, and a green LED indicating a high state. The reference voltage itself comes from a potentiometer connected to a knob. This is adjusted to determine the threshold between high and low output states for both the reflective and dark regions on the shaft; it is then positioned midway between the two limits to provide maximum noise immunity on either side. When properly operating, the control unit outputs a square-wave signal at the frequency of rotation. A high output state corresponds to the reflective side of the shaft being in view of the sensor, while the low state corresponds to the dark side of the shaft. At constant speeds, the times spent in the high state and low state should be similar.

The third enclosure, the signal adapter, was a later modification to the circuit. As the speed sensor was designed and constructed early on, before the DAQ design was fully worked out, it resulted in an output signal that was not compatible with the final system. The signal adapter takes the square wave from the control unit and changes the signal voltage levels to those compatible with RS-232 systems. With the adapter in place, the signal (still a square wave at the frequency of rotation) can be used directly in RS-232 control lines.

### **3.2.6. Cavitation Sensor**

The cavitation sensor was designed to be very similar to the speed sensor. Originally, it used an almost identical circuit based around an IR LED and photodiode. There were only two differences: it did not need a signal adapter, and the sensor unit

was split into two units. The IR LED was in one small enclosure, and the photodiode was in the other small enclosure. This was intended to allow for flexibility in placing the units as well as the ability to pick up direct rather than reflected IR radiation from the IR LED.

However, the original design proved difficult to get working in practice. As a result, some minor modifications were made. The IR LED and IR photodiode were replaced with visible-spectrum optoelectronic components; a red LED was substituted for the original IR LED, and a CdS photocell replaced the original IR photodiode. While CdS photocells have much slower response times than photodiodes generally do, that is not a problem with the current experimental setup.

The cavitation sensor works by illuminating the bulb in the test section with the red LED. When it is filled with a largely transparent fluid, certain lensing effects will come into play. When there is no vapor column in the bulb, only liquid, the bulb will tend to concentrate the light from the LED on the opposite side of the bulb. This bright spot is where the photocell is placed. When cavitation occurs and a vapor column forms, the concentration of light on the photocell is reduced. If the vapor column is wide enough, almost all of the light originally concentrated on the photocell will be scattered elsewhere, and the photocell will see darkness.

The cavitation sensor is mounted on wood blocks secured to the lower platform inside the containment box. They are aligned and aimed at each other, with the bulb of the test section in between them.

The cavitation sensor is calibrated in essentially the same manner as the speed sensor. It has a knob and indicator LEDs on the control unit that function the same way they do in the speed sensor. The knob is turned until the thresholds are found for both the case where a vapor column exists and the case where it does not. The knob is then adjusted to a point between the two thresholds. Alignment beforehand is necessary. It should be noted that additional care must be taken with the cavitation sensor. Not only does the setpoint have a tendency to drift, but it also has a high degree of sensitivity to interference from light sources. Ambient illumination changes the setpoint, and care must be taken that changes in the illumination levels are not enough to impair operation of the sensor during testing. Sufficient brightness may even prevent the sensor from operating at all, regardless of the setpoint.

It should be noted that the signal that the cavitation sensor outputs is inverted; when the design was changed, the meanings of 'high' and 'low' output states were swapped. As a result, a separate signal inverter was assembled and connected to the output of the cavitation sensor.

### **3.2.7. Signal Inverter**

The signal inverter is a very simple circuit centered around an op-amp used as a comparator. It was built as a result of the way the cavitation sensor operates, but it is an independent device that can be easily connected and disconnected from any of the binary state signals used in the experiment.

The signal inverter takes an RS-232 signal and reverses its polarity. Therefore, if the input is 'high' then the output will be 'low,' and vice versa. It can be useful for

dealing with changes in the meanings of the high and low states that are not accounted for elsewhere in the setup. It is currently used to address the change in the meaning of the output signal from the cavitation sensor.

### **3.2.8. Speed Controller Electronics Unit**


The speed controller unit has two largely separate functional circuits. The first circuit is a protection system designed to detect faults in the power line. It will disconnect the hot, neutral, and ground lines in the event of a polarity reversal or other wiring fault in the electric source. As such faults have been discovered in the wiring at Riverside in the past, this protection was determined to be warranted. Since the upstream interlock chassis is metal, its ground was connected to the protection circuit as well to prevent shocks in the case of a hot-ground reversal.

The second circuit uses a form of pulse width modulation to control the speed of the attached rotary tool. This output is the same as that of a conventional dimmer switch. As the AC voltage and current cross zero, the silicon controlled rectifiers in the circuit return to their non-conductive state. Then, after a period determined by the timer and control signal, a signal is applied to the silicon controlled rectifiers and they transition to a fully conductive state. Even when the signal is removed, they remain in the conductive state until the current through them falls below a threshold value. The signal, however, is maintained until a short period before the incoming AC voltage crosses zero.

The product is a modified AC wave where the early parts of both the positive and negative cycle are cut off and remain at zero. This is a characteristic waveform for SCR

and TRIAC circuits, and constitutes a low-frequency variant of pulse width modulation where each pulse is the 1/120 second period where the input voltage swings sinusoidally from zero to its peak (either positive or negative) and then back to zero. By removing parts of the waveform in this manner, the output power can be controlled. It works well for incandescent light bulbs, but not all circuits can accept it. CFLs that are not specially designed for dimmer switch operation, for example, will not tolerate it. However, by trial and error, it was found that the rotary tool employed for this experiment was compatible with such a method of power control. Controlling the input power for the rotary tool translates well into a speed control. An example of the waveform output by the controller electronics is given in Figure 16; it was set near the mid-level, so roughly the first half of the AC sinusoid half-cycle is dropped. It should be noted that the oscilloscope in the photograph is not the one used for laser pulse measurements.





**Figure 16: Controller Output Waveform**

The speed controller has two options for managing the output levels: a control knob and an external input that accepts a modulated input signal at RS-232 voltages. There is a switch to select between the two. When the knob is used for manual control, it presents a control voltage from the position of the knob's potentiometer to an op-amp used as a comparator. The other signal comes from the timing circuit. The timing circuit uses a rectifier bridge and Zener-based voltage reference along with an op-amp to determine when the incoming AC voltage is near zero. When the voltage is not near zero, the op-amp sends a signal to a series of transistors that will charge a capacitor to reflect the AC phase angle. When the AC voltage swings back to zero, the op-amp (used

as a simple comparator) switches from a high output state to a low one, which triggers the transistors to quickly drain the timing capacitor. Therefore, the voltage across the capacitor is determined by the progression through each AC half-period.

When the voltage across the timing capacitor is greater than the reference voltage, another op-amp (again used as a comparator) sends a trigger signal to the driver circuit that fires the SCRs.

The second input option uses an external signal to generate a reference voltage to compare to the timing capacitor level. The external signal is connected to an op-amp, once again used as a simple comparator. The output from the op-amp will therefore be either high or low. This signal is fed into a simple RC-circuit that acts as a sort of low-pass filter. With a high-frequency input signal fed into the op-amp, the capacitor in the RC-circuit will trend toward an average value based on the time that the signal is high vs. the time that the signal is low. The higher the frequency, the lower the 'ripple' voltage across the capacitor will be and the closer the voltage will remain to the average. This can be thought of as a form of a digital-to-analog convertor; an input logic signal will be converted to an average value based on the time at either level, with a wide input frequency tolerance.

This wide input frequency tolerance is the result of the high RC time constant used in the circuit's design; the time constant is 2.2 seconds. The design called for such a high time constant to reduce the effects of poor timing control in the input signal; glitches and jitter will be readily filtered out. However, it does have the resulting effect of slowing down the response time to legitimate signal changes. The 'stroke time' for

changing from zero to full power is several seconds, which was deemed to be acceptable. Controllable speed fluctuations in the rotary tool were assumed to not need a faster response than was given by the speed control circuitry.

### **3.2.9. RS-232 Isolator and Power Supply**

The main interface between the computer and the rest of the experiment is the RS-232 serial port isolator and +/- 15VDC power supply. It provides the necessary DC power to the sensors, signal inverter, and pulse generator. In addition, it provides connections to the RS-232 serial port on the computer.

The power supply for the isolator is a simple design. It uses a toroidal transformer to provide a reduced input voltage into the regulators and LC filtering to smooth out the output power. Rectifiers, inductors, and capacitors connected to the transformer provide positive and negative unregulated voltages with respect to ground as input to the regulators. The regulators are simple one-component linear regulators: an LM7812 on the positive rail and an LM7912 on the negative rail. Zener diodes and capacitors are used to adjust the ground reference voltage, giving +/- 15V regulated output. An additional set of filter capacitors are used immediately downstream of the regulators.

The serial port isolator circuit does not fully isolate the DTE from the DCE side [29]; the ground line is common to both sides and simple op-amp circuits are used rather than a fully independent optoisolator system. Four dual op-amp ICs are used, bringing the number of op-amps to 8, one for each signal line on the DE-9 connector. The heart of each signal isolator is identical.

On power-up, the default signal on each signal line is negative in the absence of an RS-232 signal. If an existing signal is removed after power-up, then the output of that line is maintained at the last input value (positive or negative). The op-amps are used as comparators, and positive feedback is used to help enforce a policy of either positive or negative output when the isolator has power.

According to RS-232 standards, the voltage range centered around ground - 3 V to + 3 V is a sort of 'dead zone' to help with noise immunity [27]. Signals are only allowed to exist in that range when changing states. Therefore, the isolator circuits were designed to maintain their current state until the input signal fully crosses that voltage region. At that point, it is clear that the input has changed states and the output will change to match it, aided by positive feedback.

For this experiment, the computer is treated rather conventionally as DTE, and the experiment's electronics are the DCE. Therefore, the isolators take 3 inputs from the computer side and output them to the experiment, while 5 inputs are taken from the experiment and directed to the computer. Not every signal line is used in the experiment; while all 3 outputs from the DTE are used, only 3 of the 5 inputs to the DTE are connected to the experiment. This leaves some room for additional connections in the future.

The computer is connected to the isolator with a standard 9-pin serial cable. The experiment then connects easily to the isolator using the banana jacks on the back. In addition to the 8 sets of banana jacks for the RS-232 signal lines (the signal line and a

ground connector), a 3-plug banana jack is there to conveniently supply +15VDC, ground, and -15VDC.

### **3.2.10. Laser System and Optical Assemblies**

The laser system is a Coherent Cube 405-100C. It is a 100 mW Class IIIb diode laser with a nominal wavelength of 403 nm. It consists of the laser head, power adapter, heat sink and fan, keyswitch, and associated cabling.

The laser can connect to a computer via its USB port or through an RS-232 serial port; it only uses the TxD, RxD, and signal ground lines. Computer control over RS-232 is straightforward; it uses a documented command set that lends itself to easy automated control.

The laser also operates in several modes. In pure CW mode, the beam power can be controlled by issuing commands from a computer. It also offers two modes for a modulated beam: an analog power control option that allows modulation at up to 350 kHz, and an external TTL control for digital modulation up to 150 MHz. In digital pulse mode, the power is set externally and the beam is turned on or off based on the TTL state (high or low). Rise and fall times are less than 2 ns. The delay from signal to laser turn-on is 16 ns, and the fall delay is 15 ns [30].

The laser head is connected to the pulse generator through its SMB connector. It also connects to TxD, RxD, and a signal ground on the RS-232 isolator. In addition, it has two connections to the laser interlock system. The interlock loop is connected through the keyswitch. The interlock's flasher circuitry is connected to the appropriate terminals wired to the laser head. In addition to the interlock circuitry, the laser has a

shutter build into the laser head that will prevent laser radiation from escaping the laser head when closed.

The laser head is bolted down to the heat sink and fan assembly. Without the heat sink and fan, the laser will quickly overheat and may be damaged. The connected laser and cooler assembly is itself mounted to a stage that allows lateral translation, which greatly assists in beam alignment. The stage in turn is mounted to a platform made of plywood and 2x4s. The platform is bolted down to the lab floor with a thick rubber gasket between it and the floor to help resist the transmission of vibrations from the floor to the platform. The containment box is placed over and around this optical platform, but they are not attached to each other; the containment box's feet stand on rubber next to the platform, not on it. This was an attempt to keep as much vibration as possible from transmitting through the containment box to the optics.



**Figure 17: Laser and Mirror on Platform**

In addition to the laser assembly, an optical component assembly is mounted on a stage to the optical platform. This is shown in Figure 17. The component assembly consists of a vertically mounted support rod which rises into the containment box along with mirror and lens assemblies and their associated support arms. The mirror assembly consists of a first surface mirror on an adjustable mirror mount extended on a horizontal support arm that attaches to the vertical support arm with a connector. The mirror is positioned below the containment box laser penetration and angled to reflect the laser beam up through the penetration and into the test section. A plano-convex lens is positioned in the beam path to bring the beam to a focus within the test section; it is held

in a lens mount attached to a horizontal support rod which is mounted near the top of the vertical support rod. The lens is closely below the test section; this part of the assembly is inside the containment box.

### **3.2.11. Laser Interlock System**

The laser interlock system is designed to address the laser safety requirements when used in conjunction with the corresponding circuitry built in to the laser system. It complements the built-in circuits in the laser head by providing the required warning lamps and interlock circuitry. When the interlock is tripped, the laser will stop firing.

The interlock system consists of the main interlock panel, the two warning lamps, the two emergency stop buttons, the door open sensors, and the associated interconnects. The circuit designs were based on schematics provided by Dr. Leslie A. Braby for an X-Ray system interlock.

The design uses relays to open and close the interlock loop based on the system status. On powering up, which requires a key, the system will not be armed. Both the inside and outside warning lamps will activate at half power. There are three separate interlock circuits in the panel. In order to operate the laser, all three must be in the 'armed' state. Two of the circuits are self-triggering; they only come into play if the warning lamps have burned out bulbs. If either the inside or outside warning lamp is burned out, the corresponding circuit will trip and an indicator LED will light up until the situation is rectified.

In order to arm the third circuit, the door must be closed and both emergency stop buttons must be pulled out to the 'ready' position. Then the 'arm' button on the



panel must be pushed. If the door is open or either emergency stop button is pushed, the circuit will not arm and will remain in the 'tripped' stat. If the power is turned off, the door is opened, or an emergency stop button is pushed, it will immediately enter the tripped state and the corresponding indicator LED will illuminate.

The laser system expects the external interlock to provide a short between the appropriate contacts to indicate that the interlock system is armed and ready; it is tripped when the connection is opened. Therefore, when any of the interlock circuits trip, their respective relays will open, breaking the connection and giving an open circuit on the interlock line of the laser. Since the interlock circuits are connected in series, only one will need to open to open the circuit to the laser.

The interlock system is also designed to accept an 'active' signal from the laser head. When this signal is present, the interlock system will engage the flasher circuitry. Then the warning lamps will flash; they will alternate between half and full power instead of maintaining a constant half-power brightness. This can provide an additional safety check; if the lamps are flashing but the interlock is tripped, then something is wrong.

The interlock panel itself is locked and requires a key to gain access to the internal wiring. In addition, the wiring to the lamps and buttons is enclosed in flexible metal conduit. This is meant to discourage unauthorized personnel from tampering with the interlock wiring. The conduit is shared by the room lighting; however, its power branches off at the point where the power cord enters the interlock panel.

### 3.2.12. Pulse Generator

The pulse generator is designed to send a pulse signal to the laser upon receiving a triggering RS-232 signal. The pulse signal is meant to be much more controlled than the signal coming from the computer system. When the laser is in pulse mode, it accepts TTL signals through its SMB connector modulated at frequencies up to 150 MHz. The pulse generator outputs such a TTL-compatible signal through its BNC coupler, which is connected to the laser via a BNC-SMB adapter.

The trigger signal coming into the pulse generator should be at least 2 microseconds in duration. This does not pose a problem. However, the triggering signal may be in the high state arbitrarily long; its duration and timing are poorly controlled due to the nature of the control software and the computer system. The circuit was therefore designed to work properly in this situation. It uses an op-amp as a comparator on the input to transform the RS-232 voltages into something more in line with TTL signals, and then passes the output from the op-amp into a simple RC-based high-pass filter. The signal passing through the filter is very short, on the order of 1 to 2 microseconds, and can be used as a triggering signal in an NE555 timing circuit.

The NE555 is a ubiquitous, low-cost precision timer IC. When two NE555 timers are placed on a single IC, the product is the NE556 dual timer. Both the NE555 and NE556 come in a number of variants. The timer used in the pulse generator was a RadioShack LM556 that was on hand at the time of assembly. It has the capability of directly driving TTL circuitry, can source or sink up to 200 mA [31], and can do timing down to microseconds.

Only one of the timers in the LM556 is used in the pulse generator, and it is used in monostable (single-shot) mode. This means that the timer must be triggered separately for each output pulse; it does not run as an oscillator. The duration of the output pulse is determined by the values of a resistor and capacitor connected to the IC. The capacitor used in the pulse generator has a fixed value, while the resistor is a potentiometer connected to a knob. This allows the duration of the pulse to be easily changed and set for the experiment. The output pulse can therefore be set from about 4 to around 120 microseconds by rotating the knob.

The pulse generator also includes connectors meant for use in observing the output pulse. This makes connecting an oscilloscope to the system a simple task. One connector connects through a 1000-ohm resistor to the output pin on the timer, and another connects through a 1000-ohm resistor to the output line downstream of the impedance-matching resistor. The laser head and coupling cables are nominally a 50-ohm impedance system, and therefore the pulse generator should have its output impedance matched to that. However, there are other considerations as well. Tolerable signal voltage and short circuit protection were considered in the design, and so the impedance match is somewhat less than perfect. Nevertheless, the degree of imperfection is not considered to be much of an issue at the operating frequencies in the experiment.

### **3.2.13. Oscilloscope**

The oscilloscope used in the experiment is a Tektronix ® TDS 2014C with Tektronix TPP0201 probes. It nominally responds to frequencies up to 100 MHz, and has four independent channels for input.

The oscilloscope can communicate with a PC using its built-in USB interface. It comes with a limited software suite, but its use is not restricted to the included software. The oscilloscope uses the VISA (Virtual Instrument Software Architecture) software interfaces and a documented command set. This allows custom software to communicate with the oscilloscope. However, such software has not been developed for this experiment; the oscilloscope was used as a stand-alone piece of lab equipment, and the results were manually read and recorded.

### **3.2.14. High Speed Camera**

The high speed camera used to capture the high-speed footage of the experiment is an IDT X-Stream™ VISION XS-4. It has 2 GB of onboard memory and can capture grayscale images. Its resolution is 512 x 512, and at that resolution can capture up to 5,145 frames/second; at certain lower resolutions, it can capture more. It uses a USB interface to the computer system, which runs IDT X-Vision version 1.13.01 for saving the footage and controlling the camera.

The lens used for the camera is a Nikon Micro-Nikkor ® 55mm f/2.8 lens, attached via a Nikon ® F-C Mount Lens Adapter. The entire assembly was mounted to a platform independent of the experiment, and is outside one of the containment box. It is aimed through one of the windows and focused on the bulb in the test section.

### **3.2.15. Data Acquisition and Control System**

The computer used in the experiment is a Dell ® OptiPlex™ 745. It is used for data acquisition and for control of the experiment through the SpeedControl software developed specifically for those tasks. While the system is not meant for high-performance, it does have suitable characteristics for use in the experiment.

It has 2 GB of RAM and, more importantly, a 2.4 GHz Intel ® Core 2 Duo™ CPU E6600. The multi-core characteristic is important; the SpeedControl software is multithreaded and one of the threads uses a full CPU core as long as the program is running. This is due to its practice of polling the serial port for high-speed observation and control; the main thread cannot afford to sleep (give up large parts of its timeslice while the CPU does other things). The presence of a second CPU core gives the other threads and other background tasks system resources in which to execute, largely without interfering with the time-critical thread.

The system runs Microsoft ® Windows™ XP with Service Pack 3 and is regularly updated. Since Windows™ XP is a preemptive multitasking system, some care needed to be taken in the development of the control and data acquisition software to ensure that time-critical operations do in fact occur in a timely manner, and that the preemptions that do occur are properly taken into account.

### **3.2.16. SpeedControl Software**

The SpeedControl software provides an integrated package for performing the functions of instrumentation, control, and data acquisition for the experiment. It performs low-level control for the experiment and automates a number of higher-level

functions. It includes a User's Guide; this document can be accessed any time the SpeedControl software is running by clicking on the 'Help' button.


A significant development effort went into making the SpeedControl software functional. It was written in Microsoft ® Visual Basic™ 2005 Express as a .Net™ 2.0 application. It does make direct use of certain Win32 API calls, so its cross-platform compatibility is somewhat limited. It requires a computer running Microsoft ® Windows™ 2000 or higher with .Net 2.0™ installed. It also requires more than one CPU core in order to run properly, and benefits greatly from faster CPU performance. The presence of at least one serial port is required as well.

#### *3.2.16.1. Using the SpeedControl Software*

Upon launch, the User is presented with a loader screen. This lets the User select the port(s) for use with the speed controller and the laser system if present; it can be the same port as the speed controller. It is also where the User selects the output logfile, giving the option of appending or replacing any existing file of the same name and location. In addition, the choice for the type of speed measurement calculations is made in the loader screen.

Once the selections are made, the program launches the necessary threads in its startup process. Once all the appropriate threads have been launched and the initialization sequence completes, the software will enter its running mode. The User is presented with a split window that gives options for speed control and laser firing sequences, with a glimpse at the logfile output and laser I/O; this window is presented in

Figure 18. In this mode, the main execution thread will consume as many CPU cycles as it can on one CPU core.



**Figure 18: Main SpeedControl Window**

In the main operating mode, the software will monitor the experiment's speed, cavitation status, and will record data received through the serial port used for the experiment; if the laser is set to jointly use the port, it will be acknowledged upon reception of transmitted data. The software will also work to maintain the set speed, signal laser pulses as appropriate, and transmit the appropriate data to the laser head. In addition, the software logs the relevant data and maintains a user interface with current information.

From the User Interface window, the User can easily monitor the status of the experiment. In addition, simple controls are provided for the user-adjustable options available at runtime. Speed control is accomplished on the left side of the window; the User simply types in a value for the speed in rotations per second in the appropriate box and clicks on 'Set' beneath it to set the value. The User can also change the program's actions when cavitation is detected (continuing, stopping, or pausing and resuming) and a pause duration if the cavitation action is set to pause and resume the rotation of the test section. The User can also click 'Start' to start running the experiment; it then gets grayed out and the 'Stop' button is activated. Pressing 'Stop' halts the experiment and terminates laser pulsing.

If the software is running with the laser control enabled, such controls can be accessed on the right hand side of the window. An estimated duration of the pulse can be entered directly, as can the time delay between pulses. These new values are not set until the User clicks on the 'Set' button in the laser control area. Additional control and options can be accessed via their relevant buttons. Text commands can be sent directly to the laser head through the window brought up when the User clicks on the 'Send Command to Laser' button. A manual pulse can be issued through the window brought up when the User clicks on the 'Fire Pulse...' button. It also allows the User to change the starting power for automatic pulsing by setting the power for the manual pulse and closing the manual pulse window.



The User can also insert a comment into the logfile by clicking on the 'Insert Comment' button in the main window and typing in the comment. The nearby 'Help' button brings up the User's Guide, and the 'End' button will exit the program.

#### *3.2.16.2. SpeedControl Software Architecture*

The software manages to do much of its operation in its main thread. In the main operating mode, it loops endlessly without sleeping. This is so that it can get timing issues handled as well as it possibly can. It does, however, allow certain cooperative OS functions time at the end of each loop executed. It uses an elevated priority state to help ensure that timing is not thrown too far off by preemptive OS functions. Timing is critical in the main thread because it directly handles the logic states of the input sensors and directly controls the output states, which can have a desirable update or monitoring frequency on the order of thousands of times each second; the timeslices in Windows do not have sufficient granularity to properly handle sub-millisecond sleep intervals.

The main loop of the main thread does a number of things in each loop. This includes

- Clock functions for precision timing and the detection of significant 'dead'/preempted times
- Reading the input state for speed and cavitation sensor, and processing the information
- Setting the speed control pin as appropriate

- Processing the Laser Fire Control Sequence, which can override speed control values, issues commands to the laser head, and controls the status of the fire control pin on the serial port
- Determines if enough time has elapsed for the less-frequent tasks to be executed
- Allowing Windows to process certain events without fully releasing the timeslice

The less-frequent tasks include

- Speed logging
- Reading and Writing data to and from the serial port data buffers
- Updating the User Interface
- Collecting User-Controlled values
- Additional speed control calculations
  - Predicting the speed in the near future with simple linear regression
  - Determining if the speed is within tolerance limits
  - Determining a time fraction for the speed control pin to be in the 'high' state
- Processing certain delays

The speed measurement is based around a simple tachometer concept: counting how frequently the light and dark regions on the main shaft go past the speed sensor.

Every time the software determines that the sensor changed state (light to dark or dark to light), the appropriate counter is incremented. In addition, it uses a sort of 'running average' scheme using exponential decay to keep the transition count and live time up to date. If a significant 'dead' period is detected (a missing chunk of time long enough to mask two or more transitions at the current speed), that time period is removed from consideration for the speed calculation if the 'Advanced Timing Feature' is enabled. The speed determined in the calculation is logged at a minimum frequency, when certain events take place (laser firing, entering or leaving the tolerance ranges), and when the speed has had a significant change from its last recorded value.

Determination of the cavitation status is simpler than the speed calculation. It looks for a signal from the cavitation sensor of a minimum duration (to eliminate spurious signals) to determine whether or not a vapor column has formed in the bulb of the test section. If the minimum duration requirement is met, the cavitation state is considered to be 'true' and the event is logged.

Management of the speed control output state grew from a relatively simple and straightforward method to a more complex set of calculations. On its face, the concept is still simple: the pin should be in a 'high' state for a determined fraction of the time, and in the 'low' state for the remainder of the time. This is meant to occur on very short timescales so that this signal gets converted to an analog voltage on a capacitor in the controller electronics with little ripple; it is much like Pulse Width Modulation at variable frequencies. This control fraction is set with a simple concept: raise the value when the speed is low, and reduce it when the speed is high. However, the method of

achieving this simple concept became somewhat complex before a working solution was developed.

The solution required a degree of responsiveness to random fluctuations and at the same time have the speed remain stable. In practice, making the system more responsive produced odd behavior; oscillations were seen, and the speed could swing rapidly and uncontrollably from zero to full speed. Reining in the oscillations reduced the responsiveness of the system, and random fluctuations in the speed would end up dominating; the speed would never completely approach the desired value.

To address those issues, the calculations for determining the speed control fraction take several variables into account. One is a prediction of what the speed will be in the near future. Another is a running average of the control level as an analog to the voltage across the control capacitor in the speed controller electronics. In addition, 'dead' times are taken into account. Such periods can result in significant deviations in the output; the actual output fraction can differ greatly from the desired fraction. These deviations are detected and incorporated into the value of the fraction for the next time period. However, a simple calculation does remain at the core of the determination of the output fraction: the change in the fraction is equal to the sum of the speed deviation multiplied by a coefficient and the cube of the speed deviation multiplied by another coefficient. The coefficients are such that the cubic term comes to dominate when the difference between desired and measured speed is very high; otherwise, the linear term dominates.

The values for the speed control fraction are used for a fraction of a second before they are updated. Within their use period, the speed control output is high if the fraction to that point is lower than desired; it gets set low if the time fraction is greater than desired. Precision timing is therefore critical for proper control of the speed control signal.

The Laser Fire Control sequence addresses and automates key parts of the experimental procedure. It takes the procedure to adjust and fire each pulse and breaks that procedure down into a series of 'stages' where each stage takes certain actions and will only proceed to the next stage once certain criteria are met. It can take a large number of cycles through each execution loop for the criteria for moving on to the next stage to be fulfilled; a stage can take an arbitrarily long time to complete. Therefore, the software was designed so that the code in each stage would not halt the loop's execution. For example, a stage that consists of a delay for a certain amount of time will simply compare the system clock to a timer value each time the main loop is executed. If insufficient time has passed since the timer was started, the software will return to executing the main loop without advancing to the next stage. When the timer value has expired, the software will execute the following stage the next time through the main loop.

The concept for the firing sequence is simple: halt the rotation of the test section, adjust the laser power, bring the test section back up to speed, issue a laser pulse, and finalize the sequence. There are a series of delays in that sequence to ensure that everything happens in the correct order. If, for example, the laser processed its power

setting command slowly and power was changed after the test section started rotating again, it might cause an inadvertent cavitation event. This is because the laser emits radiation while it is adjusting its power in pulse mode.

The sequence for a 'manual pulse' is essentially as described above. An 'automatic pulse' is similar, but does have several notable differences. An automatic pulse sequence, when cavitation is detected, will end. In addition, after the laser power is adjusted and it returns to speed, more than one shot will be fired. The software will pulse the laser three times at that particular power with a delay between shots.

Afterward, there is a delay to see if a vapor column develops. Then, if no vapor column develops, the laser power is incremented by 1 mW and the sequence starts over. This repeats until the firing sequence is interrupted by cavitation, a timeout, user intervention, or the next pulse power exceeds the laser's capabilities. In this manner, the software automates the experiment. It ramps up the laser pulse power until it finds the power necessary to induce cavitation in a test section rotating at its set speed with its particular fluid fill parameters.

The threads that the SpeedControl software executes, other than the main thread, have somewhat mundane tasks. One thread takes the information to log from a buffer and writes that data to a logfile. Another one acts as an intermediary between the main thread and the User; it controls the user interface and communicates information back and forth between the main thread and the UI window. An additional thread only runs during startup with laser control activated; it sends the initialization sequence to the laser head. In addition, if the laser port is active but set to be different from the main serial

port, its I/O will be handed off to another thread. There is also an underlying monitor thread that only plays a role during program startup and shutdown, and when threads terminate unexpectedly. It launches the relevant threads at startup, periodically checks to make sure they are running during the main operation loop, and attempts to close resources gracefully on shutdown or when things go awry.

### **3.3. FLUID CHOICE AND SEEDING**

The liquid used in this experiment was hardware-store grade acetone. While it is understood that such a grade of acetone may be full of impurities, that is not expected to be one of the primary sources of error in the experiment. The acetone is seeded, and the seeding material is expected to override any impurities that may be present in such low-grade acetone.

The original intent was to use a pure liquid without any seeding material. This would encourage the use of Eq. (62) to determine localized energy deposition in the liquid. However, early testing suggested that the laser system was not powerful enough to deposit sufficient localized energy in the tensioned acetone to guarantee an induced cavitation event and the subsequent formation of a vapor column. Therefore, a material was needed that could, when mixed with the acetone, provide weak points within the liquid in order to seed the nucleation of bubbles and enhance the local energy absorption of the liquid. Black toner from a used toner cartridge was found, through trial and error, to have some suitable characteristics.

The toner had small particles that would readily disperse into the acetone, and a significant fraction appeared to stay in suspension for long periods of time. It also

absorbed significant fractions of the incident visible light; as 403 nm is nominally within the visible spectrum, it was thought to provide excellent local absorption and could then transfer the absorbed radiant energy to its surrounding fluid. Since the toner appeared to disperse in the acetone as a suspension rather than by dissolving, the energy absorption should be highly localized to the suspended particles rather than evenly dispersed in the acetone.

Such a combination was thought to be helpful; the particles would provide local weaknesses in the liquid, as the adhesive forces were expected to be less than cohesive forces in the acetone. In addition, the laser energy would be preferentially available to those weak areas, as the absorption by the toner particles (appearing black to the eye) is much greater than that of acetone, which is transparent. As a result, it was expected that this would decrease the demand for laser power in the experiment. However, it may provide a major source of error, and discourages the use of Eq. (62). As a result, it was assumed that all (or at least a constant fraction of) the absorbed laser energy would be made available at the interface between the toner particles and bulk acetone, encouraging the direct use of the fluence equations with a simple scaling coefficient.

### **3.4. EXPERIMENTAL PROCEDURES**

The performance of an experiment can be broken roughly into three distinct phases: Pre-Operation, Operation, and Shutdown.

#### **3.4.1. Pre-Operation Procedures**

The Pre-Operation procedures are largely independent of data runs. They involve certain systems checks and preparations.



1. Prepare bulk test solutions for future use
  - a. Measure the mass of each component
  - b. Mix and store them in CLEAN, AIRTIGHT containers
  - c. Ensure the containers are properly labeled
2. Check the functionality of the laser interlock system according to the Standard Operating Procedures for the laser system
3. Power on the RS-232 isolator and check that the speed sensor calibration is good. If not, adjust the calibration knob
4. Don the protective laser goggles
5. Prepare the room for the laser interlock to be armed
6. Open the shutter on the laser
7. Power on the laser
8. Open the control software provided by the laser vendor
9. Adjust the laser to low-power (less than 5 mW) CW; do not turn on the beam
10. Arm the interlock system and enable the beam
11. Check the rough alignment of the beam with an index card or something functionally similar. It should be directed toward the location of the bulb in the bottom of the test sections; if it is far off, perform a rough alignment.
12. Disable beam emission and shut down the laser.

### 3.4.2. Data Operation Procedures

These procedures come immediately after the Pre-Operation Procedures, and may be repeated several times for a day of data collection.

1. Select the test section for use and clean it. This may be difficult to accomplish.
2. Clean the syringe that will be used to handle the fluid.
3. Choose a fluid solution prepared previously in the Pre-Operation Procedures. If necessary, agitate the solution to ensure dispersal of anything that may have settled out.
4. Withdraw a sufficient amount of solution to fill the clean test section using the clean syringe
5. Fill the test section incompletely; the fluid should be in the upper arms but filled no further than the outer edge of the PVC mount.
6. Mount the filled test section onto the experiment's main rotational shaft; record the bulb and fill fluid used.
7. Making sure that the protective laser goggles are worn, power on the laser.
8. Using the vendor's control software, set the laser to low power ( $< 5 \text{ mW}$ ) and check the fine alignment. This is easiest to accomplish if the test fluid fluoresces; the hardware-store grade acetone does
  - a. The focus of the beam should be near the center of the bulb, along the axis of rotation, which may not match the bulb centerline.

- b. Close the box, power on and arm the box interlock, power on the speed controller and set the switches to manual control.
  - c. Adjust the rotation rate to a low speed, but high enough to visually determine the axis of rotation.
  - d. Ensure that the focus does correspond to a point along the axis of rotation sufficiently far above the bottom of the bulb that cavitation events will not be generated there. Adjust if necessary
  - e. The alignment should work for several tests using the same test section; it should not be tweaked needlessly
9. Adjust the calibration of the cavitation sensor
- a. Making sure that there is no vapor column in the bulb, find the knob position for the threshold between “detected” and “not detected.” The test section should be rotating at a low rate for this. Note the position of the knob.
  - b. Ramp up the speed and induce cavitation (this may require use of the laser; the vendor’s software can be of assistance).
  - c. Reduce the speed until the vapor column in the bulb is very small.
  - d. Adjust the calibration knob on the cavitation sensor to find the threshold position for detection of a vapor column; note the position of the knob.
  - e. Set the position of the calibration knob on the speed sensor to halfway between the two thresholds just determined

- f. NOTE: since the sensor uses a photocell and incident light passing through the test section to determine its state, extraneous or changing illumination may interfere with its correct operation. It may also have trouble if the liquid absorbs significant amounts of light in the red frequencies.
- g. Set the rotation rate back to zero.

10. Degas the fluid in the test section

- a. Check to see if the fluid can maintain the maximum rotation rate deliverable without forming a vapor column by ramping up the speed to its limit.
- b. If a vapor column forms, stop the rotation, allow the gas bubble to escape, and repeat the ramp test until a vapor column no longer appears at the maximum rotation rate.
- c. Ramp the speed up to its maximum value.
- d. Briefly set the laser power to 100 % in CW mode using the vendor's software. Once a vapor column forms, set the power to zero
- e. Slow down the speed until the vapor column is little more than a bubble in the bulb
- f. Maintain this condition for a few minutes to attempt to diffuse any gas remaining in the liquid out to the vapor column, which should be largely the vapor of the liquid rather than dissolved gas.

- g. Repeat as necessary
  - h. Stop the rotation
11. Exit the laser vendor's control software
  12. Determine a pulse duration to be used for the subsequent tests
    - a. Disable laser emission.
    - b. With the oscilloscope attached to the pulse generator's output, feed a square wave into the input of the pulse generator that is compatible with RS-232 voltages and signaling.
    - c. Adjust the timer knob on the pulse generator until the pulses it outputs match the desired pulse duration.
    - d. Reconnect the pulse generator to the appropriate serial port line
  13. Make sure the laser is powered on
  14. Start the SpeedControl software, and set its initial parameters
  15. Once finished starting up, make sure that the software is set to not control the speed.
  16. Switch the electronic speed controller over to external input for speed control.
  17. Perform a test sequence.
    - a. Using a micrometer, measure the distance between the menisci in the arms of the test section. Record the value.
    - b. Close the box and arm its interlock.

- c. Set the initial laser pulse power and duration in the SpeedControl software, and enable automatic pulsing. The initial laser pulse power need not be zero if it is known that cavitation will not occur below certain values.
- d. Set the desired rotation rate in the SpeedControl software, and set the control to stop once cavitation is detected.
- e. Start the control, and allow it to automatically perform its test sequences.
  - i. First, the program will stop the rotation and calibrate the laser pulse power.
  - ii. Then, the test section is brought back up to its desired speed.
  - iii. Up to three pulses are issued to the laser
  - iv. If no vapor column forms, the laser power is incremented, the speed brought to zero, and this sequence is repeated
  - v. If a vapor column forms, then the speed is brought to zero and the sequence ends.
- f. Upon a successful cavitation event, determine the measured duration of the pulse issued to the laser from the pulse generator. Record this value.

- g. Check the logfile and determine the rotation rate at the time the critical pulse was issued; record this value as well as the laser power for the pulse.
18. Perform additional test sequences as necessary and desired.
  19. Once a test section has been filled with the testing fluid, it should not be topped off; it should be completely drained and rinsed before refilling.

### **3.4.3. Shutdown Procedures**

These procedures are primarily for the end-of-the-testing-day cleanup.

1. Set the speed controller to manual and adjust it to zero.
2. Power off all the systems that were used, except the laser interlock.
3. Once the laser has been powered off, close the shutter on the laser head.
4. Power off the laser interlock. The laser goggles can now be removed.
5. Dispose of the used testing fluids as necessary.
6. Backup the saved test data.

### **3.4.4. High-Speed Camera Notes**

When a high-speed camera run is performed, it is much like a normal test. However, some additional “juggling” is involved. Before running the test, it should be aimed and configured in its software for the appropriate framerate, resolution, etc. It may be necessary to provide additional illumination; care should be taken to ensure this does not interfere with the cavitation sensor.

Since the camera has limited onboard memory, it cannot be run for the entirety of the test sequence. Instead, the user must carefully watch the indicators on the

SpeedControl software in the background while in the X-Vision software. Shortly before a laser pulse is issued, the user must trigger high speed acquisition from the X-Vision software. Depending on the settings, it may be necessary to do this for each pulse. Once a cavitation event has been detected, the user can save the high speed acquisition to the DAQ computer in a variety of formats.

Due to the lack of high-speed camera support in the SpeedControl software, it is recommended that it only be used in special runs. The recommendation is that instead of doing a ramp in laser energy to find the cavitation threshold, it be deliberately set WELL ABOVE the cavitation threshold to ensure a video capture of the event and the formation of the vapor column.

### **3.5. EXPERIMENTAL RESULTS**

Several tests were successfully performed with the existing experimental setup. One successful high speed camera run was recorded, and four separate fluid fills were done for threshold data runs. All runs used the same test section, recorded as Bulb A. The four threshold data runs drew from the same mixture of acetone and toner, recorded as Mixture A. However, due to particulate settling, they may not have had identical fills. In addition, the high speed camera run used an uncharacterized toner/acetone mixture.

The common acetone/toner mixture is relatively clear. The dispersed particles do not do much to darken the mixture, except when they settle out. The original mixture used 145.0028 g of acetone, into which was mixed 0.10919 g of collected toner particles. This amounts to a ratio of 0.753 mg toner per g acetone. However, the larger and heavier toner particles do not remain suspended long, while the very smallest ones




should remain in suspension indefinitely. Indeed, it was seen that the largest of particles never fully dispersed into the liquid, and instead quickly settled onto the bottom of the container. Over the course of hours to days after agitating the mixture and subsequently allowing it to stand undisturbed, additional particles were seen to have settled out on the bottom of the container. However, the liquid never regained its complete original clarity, indicating that some material had not come out of suspension/solution.

### **3.5.1. High Speed Visualization**


This test was intended solely to provide visualization of a cavitation event and the early evolution of a vapor column. As such, the particulate concentration was not determined, and neither was the operating centerline tension; it is estimated as having been around  $-2 \text{ atm} \pm 1 \text{ atm}$  based on an apparent mid-level liquid fill. It operated at 200 rps, and the recording framerate was 1000 fps.

The state before and during the laser pulse can be seen in Figure 19 and Figure 20, respectively. A small white dot appears, and a vapor column grows out from there. The subsequent formation and stabilization of the vapor column is shown proceeding in time in Figure 21, Figure 22, Figure 23, Figure 24, Figure 25, Figure 26, Figure 27, Figure 28, Figure 29, Figure 30, Figure 31, Figure 32, and Figure 33. They show the state of the bulb at 1, 2, 3, 4, 5, 6, 7, 9, 11, 16, 21, 41, and 191 ms after the laser pulse, respectively.




**Figure 19: Before the Pulse**


One thing that should be recognized is the presence of reflections from the light sources for the camera. They can be seen in all the high-speed captures, and should not be confused with the phenomena of interest, especially in Figure 20. The bright reflections in Figure 20 are very much like those in Figure 19, occurring primarily in the bottom right and top left of the bulb; less prominent reflections occur elsewhere. The spot in Figure 20 slightly to the left of the bottom center of the bulb, however, is not a reflection and is unlikely to be a camera artifact; it is in the same location as the growing disturbance in Figure 21.



**Figure 20: Firing the Pulse**




**Figure 21: 1 ms Post-Pulse**



**Figure 22: 2 ms Post-Pulse**


In Figure 21 and Figure 22, it can be seen that there is a rapidly expanding region in the bottom of the bulb growing out from the initial spot. This region begins to take shape in Figure 23 and Figure 24 as a column in the bulb. However, it is still in its initial growth phase; momentum expands it past its long-term (stable) boundaries. The approximate stable boundaries can be seen in the image taken 191 ms after the laser pulse.




**Figure 23: 3 ms Post-Pulse**



**Figure 24: 4 ms Post-Pulse**



**Figure 25: 5 ms Post-Pulse**




**Figure 26: 6 ms Post-Pulse**


In Figure 25 and Figure 26, the initial growth phase of the vapor column is winding down, and it shifts back towards its eventual steady-state conditions. However, as seen in Figure 27 and Figure 28, it has a chaotic period of acceleration to undergo. The liquid at the edge of the new vapor column was originally in the vicinity of the centerline, and had a low tangential velocity. When the liquid moves out to a new radius, its tangential velocity is essentially unchanged, and it needs to accelerate to the appropriate in order to match the angular velocity of the system. This acceleration of liquid in the bulb results in some chaotic disturbances.



**Figure 27: 7 ms Post-Pulse**




**Figure 28: 9 ms Post-Pulse**



**Figure 29: 11 ms Post-Pulse**





**Figure 30: 16 ms Post-Pulse**


Figure 29 and Figure 30 show the largely formed vapor column, but the chaos of acceleration is still present. After some time, as seen in Figure 31 and Figure 32, the chaos dies down. Within 16 ms, the vapor column is essentially in its steady state. Vibrations in the equipment play a major role in the remaining chaotic behavior.



**Figure 31: 21 ms Post-Pulse**



**Figure 32: 41 ms Post-Pulse**



**Figure 33: 191 ms Post-Pulse**

As seen in Figure 32 and Figure 33, the vapor column after 191 ms is not much different from the vapor column 41 ms after the laser pulse. The steady-state situation can continue with few changes for large periods of time. Long-term, the primary causes of deviations from the steady-state vapor column would include fluctuations in the rotation rate, vibrations/deformations, and the slow disappearance of acetone out the top of the test section as it evaporates out to the atmosphere at large. This occurs on time scales much larger than those used for testing.


### **3.5.2. First Fill**

The first fill was used for a series of 50- $\mu$ s pulses at 180 rps. In all, 28 threshold tests were successfully completed before the fill was depleted to a level at which it could

not ramp up to speed without the formation of a vapor column. The results are given in Table 3.

**Table 3: Data from the First Pulse Series**

Test Number	Fill Diameter (mm)	Power (mW)	Pulse Duration ( $\mu$ s)	Speed (rps)	Centerline Pressure (Pa)	Pulse Energy (J)
1	38.83	42	50.4	178.196	-8.40E+04	2.12E-06
2	39.24	42	50.4	180.5	-9.29E+04	2.12E-06
3	40.07	56	50.4	180.88	-1.02E+05	2.82E-06
4	40.45	47	50.4	181.04	-1.06E+05	2.37E-06
5	41.22	51	50	180.12	-1.12E+05	2.55E-06
6	41.73	43	50	180.83	-1.19E+05	2.15E-06
7	42.72	55	50	182.97	-1.35E+05	2.75E-06
8	44.17	43	50	179.91	-1.43E+05	2.15E-06
9	45.1	50	50	180.38	-1.55E+05	2.50E-06
10	45.72	47	50	180.89	-1.63E+05	2.35E-06
11	46.25	52	50	180.89	-1.70E+05	2.60E-06
12	46.8	46	50	182.31	-1.80E+05	2.30E-06
13	46.98	56	50	181.59	-1.80E+05	2.80E-06
14	47.2	50	50	180.88	-1.81E+05	2.50E-06
15	47.95	55	50	179.96	-1.87E+05	2.75E-06
16	48.61	57	50	178.77	-1.91E+05	2.85E-06
17	49.43	51	50	181.28	-2.10E+05	2.55E-06
18	50.21	47	50	181.48	-2.20E+05	2.35E-06
19	50.85	46	50	182.68	-2.33E+05	2.30E-06
20	51.5	41	50	180.69	-2.34E+05	2.05E-06
21	51.8	56	50	181.71	-2.42E+05	2.80E-06
22	52.52	54	50	179.99	-2.45E+05	2.70E-06
23	53.6	51	50	181.07	-2.63E+05	2.55E-06
24	54.09	49	50	181.51	-2.72E+05	2.45E-06
25	55.03	53	50	179.96	-2.78E+05	2.65E-06
26	56.4	56	50	181.21	-3.03E+05	2.80E-06
27	58.76	54	50	181.51	-3.39E+05	2.70E-06
28	63.86	46	50	182.21	-4.23E+05	2.30E-06




**Figure 34: First Fill**

The information in Table 3 is represented graphically in Figure 34. As one can see, there is plenty of scatter in the data. In addition, whatever trend there may be is hidden by that noise. It would appear that the trend is essentially flat. This can be the result of thermal diffusion effects. If the pulse is not short enough, significant amounts of the deposited energy can diffuse away instead of contributing to bubble nucleation; the diffusing energy may be so large as to completely mask any underlying trend in the required energy threshold.

### 3.5.3. Second Fill

The second fill was used for a series of 6- $\mu$ s pulses at 210 rps. In all, 20 threshold tests were completed before the fill was depleted to a level at which it could

not ramp up to speed without the formation of a vapor column. However, one test was of unusable quality, and an additional four are of questionable quality.



**Figure 35: Fill 2 Data**

Table 4 lists the data collected in this sequence, and it is presented graphically in Figure 35 with all problem points included; each of the questionable points has a red arrow pointing to it in the figure. Once again, there is a significant amount of noise in the gathered data which may interfere with the determination of a trend. However, the early values appear to hint at one, trending towards lower energy with decreasing pressure.

**Table 4: Data from the Second Pulse Series**

Test #	Fill Diameter (mm)	Power (mW)	Pulse Duration ( $\mu$ s)	Speed (rps)	Centerline Pressure (Pa)	Pulse Energy (J)	Note
1	37.44	79	5.92	208.18	-1.34E+05	4.68E-07	
2	38.14	74	5.92	213.05	-1.54E+05	4.38E-07	
3	38.44	74	5.92	210.43	-1.52E+05	4.38E-07	
4	38.93	71	5.92	211.5	-1.61E+05	4.20E-07	
5	39.41	65	5.92	212.45	-1.70E+05	3.85E-07	Very first shot
6	39.68	66	5.92	210.05	-1.68E+05	3.91E-07	
7	40.51	68	5.92	212.29	-1.85E+05	4.03E-07	
8	41.27	62	5.92	210.55	-1.91E+05	3.67E-07	
9	41.91	78	5.92	212.09	-2.05E+05	4.62E-07	
10	42.54	85	5.88	211.06	-2.11E+05	5.00E-07	
11	44	61	5.92	211.32	-2.33E+05	3.61E-07	
12	45.66	65	5.92	214.03	-2.68E+05	3.85E-07	
13	46	74	5.92	210.51	-2.62E+05	4.38E-07	
14	46.8	59	5.92	209.66	-2.71E+05	3.49E-07	3rd shot at first power
15	47.53	80	5.92	208.91	-2.80E+05	4.74E-07	
16	48.44	65	5.92	213.51	-3.13E+05	3.85E-07	
17	49.57	64	5.92	211.22	-3.23E+05	3.79E-07	
18	51.99	85	5.88	211.96	-3.69E+05	5.00E-07	Possible seed depletion
19	58.01	67	5.88	210.42	-4.75E+05	3.94E-07	Possible seed depletion
20	64.89	85	5.88	211.45	-6.28E+05	5.00E-07	Possible seed depletion

### 3.5.4. Third Fill


The third fill was used for a series of 6- $\mu$ s pulses at 180 rps. In all, 4 threshold tests were completed before the fill was depleted to a level at which it could not ramp up to speed without the formation of a vapor column. However, the first test ramped all the way to the limit of the laser's power without forming a vapor column; as a result, some of the liquid was removed to start the next ramp at significantly increased tension. These tests appear to have experienced relatively violent transients, as the other 180 rps tests did not seem to remove as much fluid from the test section as these tests did in the 54 to 57 mm fill range. The results are given in Table 5.

**Table 5: Data from the Third Pulse Series**

Test #	Fill Diameter (mm)	Power (mW)	Pulse Duration ( $\mu$ s)	Speed (rps)	Centerline Pressure (Pa)	Pulse Energy (J)	Note
1	41.24	(none)					Liquid removed afterward
2	54.66	82	5.96	181.06	-2.78E+05	4.887E-07	
3	56.47	82	5.96	182.88	-3.12E+05	4.887E-07	
4	61.63	80	5.96	180.8	-3.79E+05	4.768E-07	

The data given in Table 5 is presented graphically in Figure 36. While there does appear to be a slight downward trend, there are only three points. Given the noise experienced by the other tests, it is surprising that there was so much consistency in this series. However, there are too few points to make a good determination of a trend with any confidence from these points alone.





**Figure 36: Fill 3 Chart**

### 3.5.5. Fourth Fill


The fourth fill was used for a series of 6-μs pulses at 180 rps. In all, 19 threshold tests were completed before the fill was depleted to a level at which it could not ramp up to speed without the formation of a vapor column. However, the last test ramped all the way to the limit of the laser’s power without forming a vapor column. In addition, the three tests previous to it had questionable qualities. All the data can be seen in Table 6; as it was the second fill of the day, it did not begin with test one. The third fill was performed immediately prior to this one.

**Table 6: Data from the Fourth Pulse Series**

Test #	Fill Diameter (mm)	Power (mW)	Pulse Duration ( $\mu$ s)	Speed (rps)	Centerline Pressure (Pa)	Pulse Energy (J)	Note
5	46.71	94	5.96	181.69	-1.78E+05	5.602E-07	
6	47.21	82	5.96	182.09	-1.85E+05	4.887E-07	
7	47.82	96	5.96	180.27	-1.86E+05	5.722E-07	
8	48.46	83	5.92	180.47	-1.95E+05	4.914E-07	
9	49.26	82	5.92	182.08	-2.10E+05	4.854E-07	
10	49.51	84	5.92	179.91	-2.06E+05	4.973E-07	
11	49.9	76	5.92	180.21	-2.12E+05	4.499E-07	
12	50.48	95	5.92	178.93	-2.15E+05	5.624E-07	
13	51.2	78	5.92	182.21	-2.36E+05	4.618E-07	
14	52.07	95	5.92	181.72	-2.45E+05	5.624E-07	
15	52.85	84	5.92	180.67	-2.52E+05	4.973E-07	
16	53.39	82	5.92	179.46	-2.54E+05	4.854E-07	
17	53.76	73	5.92	180.81	-2.64E+05	4.322E-07	
18	54.24	82	5.92	180	-2.68E+05	4.854E-07	
19	55.05	75	5.92	182.38	-2.89E+05	4.44E-07	
20	55.95	70	5.92	181.75	-2.99E+05	4.144E-07	2nd shot at first power
21	56.64	65	5.92	180.43	-3.03E+05	3.848E-07	3rd shot at first power
22	58.62	83	5.92	183.02	-3.44E+05	4.914E-07	Possible seed depletion
23	63.07	(none)					Possible seed depletion

The values from Table 6 are presented in Figure 37. Out of all the fill sequences, this one reveals the strongest trend. However, if all the questionable points are removed (indicated by red arrows in the figure), it becomes less apparent. In addition, the final test in the sequence did not end with the formation of a vapor column. This could be the

result of seed depletion. As the toner particles at this point had been experiencing significant centrifuging effects, it would not be surprising that enough would come out of solution to cause issues. It did appear that at the end of the test, some toner had caked out along the outermost points in the elbows of the test section, but it was not determined how much toner had actually undergone that.




**Figure 37: Fourth Fill Data**

### 3.5.6. Discussion and Analysis


A collection of every test is charted in Figure 38 to compare the results. Each series is provided a different marker. By casual examination, it is clear that the 50

microsecond pulse data does not match the 6 microsecond pulse data at all. As there is a factor of more than 8 between their time scales, it is suspected that they are phenomenologically different. On the longer time scales, transient heat flow becomes more significant and may dominate the process. It is also possible that the motion of the seed particles comes into play in this time scale; they have more time to move into and out of the laser beam. In addition, since the total average pulse energy in the 50 microsecond tests is on the order of five times as great as that of the 6 microsecond tests, it is possible that the cavitation events may not be restricted to the zone of high power density near the focus point. They may happen elsewhere along the beam. This would only be expected to happen in the situation where seed particles are scarce, and the only way to deposit energy into the seed particles is to expand the applicable range. Such effects probably do play a role; it appears that seed depletion is an issue with many of the tests.




**Figure 38: All Collected Data**

When the 6-microsecond pulse data seen in Figure 38 appears without the 50-microsecond data, the differences between the tests becomes more pronounced. This is shown in Figure 39. Much of this may depend on variations in the initial fill; as particles may settle out of solution, even using the same solution at different times (as was done here) does not guarantee consistency between tests. In addition, the mounting is expected to be slightly different between tests. While care was taken to thread the test section onto the shaft consistently across fills, some variation is unavoidable.



**Figure 39: 6  $\mu$ s Pulse Data**

One bit of information that was largely neglected was the fluid temperature. While it was assumed that variations in it would not be significant, that may not be entirely true. The laser lab has limited air conditioning, and the containment box prevents most airflow. After prolonged periods of operation, the room warms up noticeably, and the air in the containment box seems much warmer. This should be no surprise; the rotary tool can use significant amounts of power and it is an enclosed space.



**Figure 40: Comparison with Expected Trend**

A comparison with the expected trend is shown in Figure 40 for the 6 microsecond pulse data. The questionable points were removed from the comparison, and the trend is that given by Eq. (54) using a scaling coefficient of  $1.10E-7$ . It is not a curve fit or regression analysis; it is simply there for comparison purposes. The scatter in the data makes such a fit questionable at best; the results appear to neither confirm nor deny the expected trend. The 50 microsecond pulse data, however, appears to be essentially flat and would therefore tend to fit a scaled Eq. (52) rather than a scaled Eq. (54).

The comparison with the trend from Eq. (54) is important. It directly relates the experimental data to the energetics developed from the analysis of Bubble Theory. If future results show a poor fit to the trend, then Eq. (54) did not adequately capture the relevant phenomena. If future results do follow the trend, then the next step would be the development of the proper scaling coefficients. From there, one could determine the energy deposition characteristics that would be useful for full optimization of CTMFD systems.



#### 4. COMPUTATIONAL FLUID DYNAMICS WORK

Computational Fluid Dynamics simulations can be very useful in the study of fluid systems. With advances in modern computing systems and CFD software, reasonable simulations can be performed on a wide variety of systems in decent amounts of time. In addition, modern tools allow the workload to be spread across several computer systems, reducing the computational demand on any one node. This allows for large, complex simulations to be performed even on commodity hardware.

CFD codes solve the equations of fluid mechanics in a discretized, numerical manner. An important step in a CFD simulation is the conversion of the flow geometry into a computational domain. In this process, a continuum of locations is divided into a finite number of places known as vertices, surfaces, and cells [32]. The flow conditions in each cell can then be described by a set number of parameters; the specific parameters in question are determined by the particular simulation. For example, in laminar simulations, turbulence parameters would not be included.

A CFD simulation needs more than just a mesh. Initial conditions are important, as are wall and boundary conditions. The entry/exit conditions need to be given, and the fluids themselves need to be defined (i.e., parameters like viscosity and density). In addition, the simulation models need to be chosen and their parameters defined. Turbulence models can be used, or flows can be forced into the laminar or inviscid regimes. If time dependence is not an issue, a steady-state simulation can be performed. Any applicable extra conditions -- motions in the reference frame, for instance, should


be determined as well. Stopping conditions such as time and convergence criteria should also be given.

When all the necessary conditions are provided and the simulation started, the solver steps through the calculations in an iterative manner. It applies the discretized forms of the fluids equations to the mesh and conditions, and solves them in a numerical rather than symbolic manner. Ideally, each iteration will rapidly bring the computed solution closer to the true one. Generally, a surrogate for the deviation from the true to the calculated solution is the residual in the computation (the difference between succeeding iterations; the exact meaning may vary from code to code). When the residual is very low, there is not a significant change in the computed solution from iteration to iteration, and the computed solution is said to have converged on that value. There may be several levels of convergence, not all of which may be accessible to the end user. If the calculation is transient, then the solver would proceed on to the next time step upon meeting the convergence criteria or iteration limits set by the user. If the residuals remain large, the solution is not converging and may instead diverge. That can quickly lead to nonphysical results and overflow errors, and should be avoided. Refinements to the mesh or other inputs can frequently be used to remedy such a situation.

#### **4.1. CFD SIMULATION**


The CFD simulation of a CTMFD was performed in CD-adapco ® Star-CCM+ 5.02.009, which uses finite volume computational techniques [32]. It ran on an ad-hoc Cluster of Workstations, each running a 64-bit version of Microsoft ® Windows™ (the

main node runs Windows Vista ®, while all the others run Windows™ 7) and the Win64 version of the MPICH2 v. 1.2.1p1 parallel computing library. The computers were connected via a Gigabit Ethernet network with Jumbo Frames enabled. The main node has a dual Intel ® Xeon™ 5520 CPU with a total of 8 physical cores and a total of 6 GB RAM. Each of the workers has 2 GB of RAM, but they have different processors. One has an Intel ® Core 2 Duo™ E7200, a second has an Intel ® Core 2 Duo™ E6700, and the third has a dual Xeon™ 3.2 (Nocona); the third node was largely used for offloading file storage.




**Figure 41: CAD model for CFD**

The simulation used a model of a small CTMFD developed in SolidWorks™, exported in the IGES format, and imported into Star-CCM+ 4.02.007 for meshing. The CAD file describes the inner surface of the CTMFD glassware, and is depicted in Figure 41. It has a bulb with a total height of 26.5 mm and a diameter of 13 mm, an inner elbow radius of 71.056 mm, a tube inner diameter of 4 mm, and is shown in Figure 42.




**Figure 42: Model Dimensions (mm), Front**

The straight parts of the arms in the CAD model are set at 60° angles from the centerline. Alternate views for the model can be seen in Figure 43 and Figure 44. They give the views from the top and side, respectively. Much of what they depict can be inferred from Figure 42.




**Figure 43: Model Dimensions (mm), Top**



**Figure 44: Model Dimensions (mm), Side**

Meshing in Star-CCM+ 4.02.007 with the parameters given in Table 7 produced a geometry with 347,520 polyhedral cells, which can be seen in Figure 45. This file was


saved and eventually imported into Star-CCM+ 5.02.009, which has various improvements over earlier versions, especially in the realm of execution speed.



**Figure 45: CFD Mesh**

The simulation modeled a relatively simple transient case. For this simulation, phase changes and turbulence were disabled; flow was assumed to be laminar. The initial location of the air-acetone interface was placed at a radius of 2.5 cm by giving the

top of the arms in the CTMFD a fill fraction of 1 for air, and all other locations a fill fraction of 1 for acetone. This results in an initial fill similar to that presented in Figure 46, where “Phase 1” would be air. An air pressure boundary was chosen at the top, while the sides were set to be walls with the no-slip condition enforced.



**Figure 46: Initial Fill Example**

The physics models are given in Table 8 and Table 9. This CFD model of a CTMFD serves as a framework for performing various CFD simulations. By changing

the relevant parameters and physics models, it can be used for more simulations than the one performed here.

The goal of the simulation was to simulate a simple ramp up from stationary to an operational speed, and to observe the time needed to reach equilibrium at the full, steady speed. Using a Java macro, the simulation settled for 0.2 s at the beginning, and then steadily ramped up in speed until it hit 180 rps at  $t=2.0$  s. At that point, the CTMFD maintained a steady rotational rate. Output files were saved at intervals of 0.1 s of simulated time out to a maximum of 10.0 s, at which point the simulation ended.

**Table 7: Meshing Information**

Models	Surface Remesher Polyhedral Mesher Prism Layer Mesher
Reference Values	Base Size = 1 mm 4 Prism Layers Prism Layer Stretching Ratio = 1.5 Prism Layer Thickness = 33.3% of Base 36 Points/Circle Surface Growth Rate = 1.3 Surface Proximity: 2 Points in gap, 0 m search floor Relative Minimum Size = 25% of Base Relative Target Size = 35% of Base Polyhedral Density and Growth Factor both 1.0 Polyhedral Blending Factor = 1.0

The values given in Table 7 govern the meshing for this model in Star-CCM+. Polyhedral meshing was chosen because it has advantages over simpler mesh types (i.e., tetrahedral or trimmed); a model will need far fewer polyhedral cells for similar results.



The base size defines the size of cells in the coarse mesh, and the value of 1 mm was thought to provide an adequate resultant mesh; cells may be smaller as the need arises from geometric concerns, etc. The surface remesher was activated to improve the mesh quality and conformance to the original CAD model, and the prism layer mesher was enabled to improve the quality of turbulence modeling, if enabled in the future. It creates small layers of cells near the surfaces of the geometry [32].

The physics models are given in Table 8. Since the simulation is a three-dimensional, time-dependent, multiphase problem, the relevant models for that must be enabled. Laminar flow was assumed. The Eulerian Multiphase model used in conjunction with the Volume of Fluid model is for immiscible fluids where the mesh can resolve their interfaces [32], and requires the Segregated Flow models. Surface tension modeling was enabled, as was gravity and a rotating reference frame. The two fluids that were modeled were air and acetone, both modeled as incompressible using their built-in fluid characteristics. The surface tension value for acetone was not built-in, and was defined as 0.02272 N/m [21]. The initial distribution of air and acetone was defined by two field functions, *inair* (giving the volume fraction of air in a cell) and *inwater* (giving the volume fraction of acetone in a cell); both are given in Table 9.

**Table 8: Physics Conditions**

<p>Models</p>	<p>Cell Quality Remediation  Eulerian Multiphase Flow</p> <ul style="list-style-type: none"> <li>• Air, constant density = 1.18415 kg/m<sup>3</sup></li> <li>• Acetone, constant density = 786.741 kg/m<sup>3</sup></li> </ul> <p>Gravity  Implicit Unsteady  Laminar  Multiphase EOS  Multiphase Mixtures</p> <ul style="list-style-type: none"> <li>• Volume-Weighted Viscosity and Thermal Conductivity</li> <li>• Mass-Weighted Specific Heat</li> </ul> <p>Segregated Flow (2<sup>nd</sup> order convection)  Segregated Fluid Isothermal, continuum temperature is 300 K  Surface Tension  Three Dimensional  Volume of Fluid Model, 2<sup>nd</sup> order convection</p>
<p>Reference Values</p>	<p>Gravity: -9.81 m/s<sup>2</sup> in the z-direction  Altitude=0  Valid Temperatures between 100 K and 5000 K  Ref. Pressure = 101,325 Pa</p>
<p>Initial Conditions</p>	<p>Pressure = 101,325 Pa  Temperature = 300 K  Stationary  Volume Fraction based on inair and inwater field functions</p>

**Table 9: Other Conditions**

Solvers	Implicit Unsteady Timestep = 2.0E-4 s, 2 <sup>nd</sup> order temporal discretization Rigid Body Motion defaults Segregated Flow defaults Segregated VOF defaults Segregated Energy defaults
Stopping Criteria	Maximum Inner Iterations = 15 10 s physical time
Reports: CurrentTime	Dimensions: Time Definition: \$Time Units: s
Field function inair	dimensionless scalar defined as $((($Centroid[0]) * ($Centroid[0]) + ($Centroid[1]) * ($Centroid[1])) < 0.000625) ? ((($Centroid[2]) > 0.025) ? 1 : 0) : 0$
Field function inwater	dimensionless scalar defined as $(Sinair > 0) ? 0 : 1$

In Table 9, there are various parameters used in the CFD simulation that were not shown in Table 7 or Table 8. It includes the definitions of the inair and inwater field functions that determine the initial fluid distribution, as well as the CurrentTime report used by the Java macro to help conduct the simulation. The solvers used by the enabled models largely used their default parameters (relaxation factors, etc.). The Implicit Unsteady solver used a 2<sup>nd</sup> order temporal discretization scheme with a 0.2 ms timestep; this gives 12.96° of rotation per timestep at the full 180 rps. The maximum number of inner iterations in the calculations was 15. Those parameters resulted in residuals on the order of 10<sup>-3</sup> to 10<sup>-4</sup>, and the full 10 seconds of simulated time took nearly two weeks to compute across 11 CPU cores.

The important datum is the centerline pressure in the bulb. This value was extracted from three axial locations in the centerline of the bulb: one at the top of the cylindrical section where the upper dome begins, one 6.75 mm below the top of the cylindrical section, placing it dead center in the bulb, and one 13.5 mm below the top of the cylindrical section, at the bottom where it meets the lower dome. As the simulation was run, its state was saved at 0.1 s (simulated time) intervals for later data extraction; a macro was executed on each save file to help extract the data. Currently, only the mid-level (6.75 mm) point is used for analysis.

The centerline pressure values were examined over the time period of interest, and a determination was made as to how long it takes the pressure to settle down to a roughly constant value. This does not mean that the flows have themselves settled down, only that they have settled enough for the centerline pressure to reach its steady state value.

Both of the Java macros used in this effort (one to run the simulation, another to assist with data extraction) are given in Appendix C.

## **4.2. CFD RESULTS**

Using a macro for assistance, the relevant values were captured from the simulation after completion. The simulation was operated by another Java macro to adjust the rotation rate as a function of simulated time; the main User Interface in Star-CCM+ was not otherwise amenable to fluctuating rotation rates.

The extracted values for the pressure at the midpoint are given in Table 10 for the period before and during the speed ramp-up. It lists the calculated pressure as well as

the drop from the reference (atmospheric) to the centerline pressure; both the CFD results and the results of the application of Eq. (42) are shown for comparison.

**Table 10: CFD Ramp-Up**

Time	Rotation Rate	CFD Pressure	$\Delta P$ CFD	Pressure Eq. (42)	$\Delta P$ Eq. (42)
0	0	1.01E+05	0.00E+00	1.01E+05	0.00E+00
0.1	0	1.02E+05	-4.00E+02	1.01E+05	0.00E+00
0.2	0	1.02E+05	-4.00E+02	1.01E+05	0.00E+00
0.3002	10	1.01E+05	5.29E+02	1.00E+05	9.71E+02
0.4002	20	9.80E+04	3.28E+03	9.74E+04	3.88E+03
0.5002	30	9.34E+04	7.89E+03	9.26E+04	8.74E+03
0.6002	40	8.70E+04	1.43E+04	8.58E+04	1.55E+04
0.7002	50	7.86E+04	2.27E+04	7.71E+04	2.43E+04
0.8002	60	6.84E+04	3.29E+04	6.64E+04	3.49E+04
0.9002	70	5.63E+04	4.51E+04	5.38E+04	4.76E+04
1.0002	80	4.22E+04	5.91E+04	3.92E+04	6.21E+04
1.1002	90	2.63E+04	7.50E+04	2.27E+04	7.86E+04
1.2002	100	8.48E+03	9.28E+04	4.26E+03	9.71E+04
1.3002	110	-1.12E+04	1.13E+05	-1.61E+04	1.17E+05
1.4002	120	-3.27E+04	1.34E+05	-3.84E+04	1.40E+05
1.5002	130	-5.60E+04	1.57E+05	-6.27E+04	1.64E+05
1.6002	140	-8.11E+04	1.82E+05	-8.89E+04	1.90E+05
1.7002	150	-1.08E+05	2.09E+05	-1.17E+05	2.18E+05
1.8002	160	-1.37E+05	2.38E+05	-1.47E+05	2.48E+05
1.9002	170	-1.67E+05	2.68E+05	-1.79E+05	2.81E+05
2.0002	180	-1.99E+05	3.01E+05	-2.13E+05	3.14E+05

The ramp-up period was from 0.2 s to 2.0 s; that period is contained in Table 10. After that, the rotation rate was held constant and the solution was allowed to settle on equilibrium values. The results for the beginning of the equilibration period, 2 s to 6 s, are given in Table 11. As can be seen, the values quickly converge to a steady-state solution.

**Table 11: Post-Ramp Values**


Time	Rotation Rate	CFD Pressure	$\Delta P$ CFD	Pressure Eq. (42)	$\Delta P$ Eq. (42)
2.1002	180	-2.01E+05	3.02E+05	-2.13E+05	3.14E+05
2.2002	180	-2.02E+05	3.03E+05	-2.13E+05	3.14E+05
2.3002	180	-2.03E+05	3.04E+05	-2.13E+05	3.14E+05
2.4002	180	-2.03E+05	3.04E+05	-2.13E+05	3.14E+05
2.5002	180	-2.03E+05	3.05E+05	-2.13E+05	3.14E+05
2.6002	180	-2.03E+05	3.05E+05	-2.13E+05	3.14E+05
2.7002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
2.8002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
2.9002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.0002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.1002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.2002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.3002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.4002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.5002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.6002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.7002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.8002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
3.9002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.0002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.1002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.2002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.3002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.4002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.5002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.6002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.7002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.8002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
4.9002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.0002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.1002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.2002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.3002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.4002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.5002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.6002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.7002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.8002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
5.9002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
6.0002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05

**Table 12: Long-Term Values**

Time	Rotation Rate	CFD Pressure	$\Delta P$ CFD	Pressure Eq. (42)	$\Delta P$ Eq. (42)
6.1002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
6.2002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
6.3002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
6.4002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
6.5002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
6.6002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
6.7002	180	-2.04E+05	3.05E+05	-2.13E+05	3.14E+05
6.8002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
6.9002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.0002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.1002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.2002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.3002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.4002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.5002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.6002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.7002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.8002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
7.9002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
8.0002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
8.1002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
8.2002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
8.3002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
8.4002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
8.5002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
8.6002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
8.7002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
8.8002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
8.9002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
9.0002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
9.1002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
9.2002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
9.3002	180	-2.04E+05	3.06E+05	-2.13E+05	3.14E+05
9.4002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
9.5002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
9.6002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
9.7002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
9.8002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
9.9002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05
10.0002	180	-2.05E+05	3.06E+05	-2.13E+05	3.14E+05

The post-ramp values given in Table 11 do not end at the end of the simulation; that occurs at 10 s. Continuing on to the final value, Table 12 gives the long-term approach in the results. The deviations from steady-state tend to be small. After 10 s, it was assumed that any further changes in the centerline pressure would be negligible, and that it would represent a steady-state condition.


The values given in Table 10, Table 11, and Table 12 can be charted to graphically show the time dependence of the difference between atmospheric and CTMFD centerline pressures. The comparison to values extracted from Eq. (42) are shown in Figure 47 and Figure 48.



**Figure 47: CFD Pressure Drop**




The pressure differences determined by the simple CFD simulation and the equation, as shown in Figure 47, are very close to each other. The equation assumed that the rotation rate was steady, not fluctuating, and yet gave remarkably close values to the CFD calculations. To make this clearer, one can examine Figure 48. It gives the pressure determined by the CFD calculations as a fraction of its steady-state (10 s) value and as a fraction of the pressure drop determined by Eq. (42). Even during the ramp period, the CFD-determined pressure drop closely followed the pressure drop from Eq. (42); outside of the very early stages of the ramp, it was well within 10% of the equation's value.




**Figure 48: CFD ΔP Fractions**

The fractional comparison is given in Figure 48. The figure shows two views of the CFD-determined centerline pressure difference from atmospheric. One is the fraction of the pressure difference as determined by Eq. (42) at the given time. The other is the fraction of the pressure difference at the given time compared to the long-term (10 s) value. From the figure, it can be seen that the centerline pressure in the CFD calculation approaches its steady-state value well within one second after the end of the ramp. It also shows that the centerline pressure during ramp-up closely tracks the values given by Eq. (42) for the speed at the given time. The steady-state values for the lab-frame velocity magnitude and pressure field are shown in Figure 49 and Figure 50; they show the distribution of those values using cutaway views of the simulated test section.



**Figure 49: Lab-Frame Velocity Distribution**

In Figure 49, a cutaway view of the CFD model can be seen with the steady-state velocity distribution. It is presented in the lab frame; within the rotating reference frame, the velocity magnitudes are close to zero, as is expected. A similar cutaway view is presented in Figure 50 for the pressure field. It shows a relatively constant pressure in the upper arms; this region is filled with low-density air, so the result is believable. Below that, the relatively high-density acetone shows a large radial pressure gradient, which is steeper going out to toward the elbows. Near the center, the gradient is much milder.



**Figure 50: Pressure Distribution**

It would appear from the simulation that the air density makes a slight difference as to the final centerline pressure. The difference between the simple calculation given

in Eq. (42) and the simulation is on the order of 2-3% at steady state, using ambient pressure as a reference.

It is also notable that the pressures immediately after the speed has finished ramping up to its maximum value are at 98.3% of their steady state value. After just 0.2 s post-ramp, the pressures cross the 99% mark, reaching 99.2% of their steady-state values. At 0.4 s post-ramp, the pressures are at 99.5% of the steady-state value. They slowly, with minor oscillations, approach the full steady-state value after that. At 8.0 s after the speed has finished ramping up (10.0 s in the simulation) from 0 to 180 rps (in 1.8 s), the pressures are considered to be at their steady-state values and these numbers are used for the earlier comparisons.

## 5. CONCLUSIONS

This research was intended to increase the current knowledge of the behavior of CTMFD systems. A multi-pronged approach was taken; this research applied theoretical, computational, and experimental techniques to combat the lack of knowledge

The first major goal was to design, construct, and operate an experimental facility for CTMFD system evaluation. Such a facility was successfully built, and it is operational.

A second goal was to explore the use of laser-induced cavitation as an experimental technique in general, with an emphasis on CTMFD systems. This appears to be a valid technique, as the experimental operations were successful at achieving laser-induced cavitation in a seeded fluid.

The third goal involved exploring the energetics of a CTMFD system. The application of theory suggested the result would be a curve based on the pressure in the fluid. While the experiment as-is successfully determines the broad range of energies that may work, the results are currently too noisy to confidently establish curve parameters.

The final major goal was the development of a CFD framework for CTMFD modeling. This was achieved; a trial run has provided an insight into the rapid approach to steady-state pressures a CTMFD may experience.

While the data collected in the current experimental runs are too noisy for the proper development of an empirical model, they do suggest that future runs with improved techniques would be able to achieve that goal. In addition, the CFD framework developed here can be used to cross-compare experimental results with computer simulations as well as with the theoretical models developed here.

### **5.1. KEY FINDINGS**

The experiment and simulation demonstrated the ability of the facilities to test CTMFD systems and the potential to extract their operational characteristics. The experiment showed a certain viability for the technique of laser-induced cavitation in a seeded fluid, and demonstrated some of the associated limitations as well. Some of the key conclusions are listed:

- CTMFD pressures come to their steady-state values relatively fast, according to a CFD simulation
- Triggering a CTMFD has critical phenomena that occur on less than ms timescales; the growth of small bubbles to the full vapor column is fast and violent
- There is a clear threshold for the time-dependence on the energy deposition rate; if it happens too slowly, then it is phenomenologically different from a much faster or instant deposition

### **5.2. FUTURE WORK**

There are certain issues that need to be resolved before quantitative results can be obtained from this research:

- Resolution of the issues with glassware curvature at the laser entrance; the optically flat glassware should be used in future tests
- Full characterization of the seeding material, including particle size distributions, time to settle out of solution, opacity, thermal conductivity, heat capacity, interface energy with the surrounding fluid, etc.
- Reduction of the vibrations in the experiment, which may have large influences on the outcomes
- Finding a more effective way to clean the test sections
- General reduction in the noise/scatter of the data
- Further CFD simulations to compare with theory and experimental data

In addition, the systems developed can be used to collect data for other fluids and conditions, not just acetone near room temperature. Dyes may be explored as opposed to particulate seeds. Finally, tests with radioactive sources should be conducted as well to characterize the system's responses to different types of radiation.

## REFERENCES

- [1] Trevena, D. H. *Cavitation and Tension in Liquids*. Bristol, UK: IOP Publishing, 1987.
- [2] Briggs, Lyman J. *The Limiting Negative Pressure of Acetic Acid, Benzene, Aniline, Carbon Tetrachloride, and Chloroform*. *Journal of Chemical Physics* 19.7 (1951): 970-972.
- [3] Zheng, Q., D. J. Durben, G. H. Wolf, C. A. Angell. *Liquids at Large Negative Pressures: Water at the Homogeneous Nucleation Limit*. *Science* 254.5033 (1991): 829-832.
- [4] Scholander, P. F., H. T. Hammel, Edda D. Bradstreet, E. A. Hemmingsen. *Sap Pressure in Vascular Plants: Negative Pressure can be Measured in Plants*. *Science* 148.3668 (1965): 339-346.
- [5] Taleyarkhan, Rusi, J. Lapinskas, Y. Xu. *Tensioned Metastable Fluids and Nanoscale Interactions with External Stimuli—Theoretical-cum-Experimental Assessments and Nuclear Engineering Applications*. *Nuclear Engineering and Design* 238.7 (2008): 1820-1827.
- [6] Brennen, Christopher E. *Cavitation and Bubble Dynamics*. New York: Oxford University Press, Inc., 1995.
- [7] Leighton, T. G. *The Acoustic Bubble*. London: Academic Press Limited, 1994.
- [8] Neppiras, E. A. *Acoustic Cavitation*. *Physics Reports* 61.3 (1980): 159-251.
- [9] Collier, John G., Thome, John R. *Convective Boiling and Condensation*. 3<sup>rd</sup> ed. New York: Oxford University Press, Inc., 1996.
- [10] U.S. Food and Drug Administration. *Risk of Burns from Eruptions of Hot Water Overheated in Microwave Ovens*. Last Updated 25 April 2012, Retrieved 19 Oct 2012, <http://www.fda.gov/Radiation-EmittingProducts/RadiationEmittingProductsandProcedures/HomeBusinessandEntertainment/ucm142506.htm>
- [11] Fisher, John C. *The Fracture of Liquids*. *Journal of Applied Physics* 19.11 (1948): 1062-1067.
- [12] Lienhard, J.H., Karimi, A. *Homogeneous Nucleation and the Spinodal Line*. *Journal of Heat Transfer* 103.1 (1981): 61-64.



- [13] Poole, Peter H., Francesco Sciortino, Ulrich Essmann, H. Eugene Stanley. *Spinodal of Liquid Water*. *Physical Review E* 48.5 (1993): 3799-3817
- [14] Holbrook, N. Michele, Michael J. Burns, Christopher B. Field. *Negative Xylem Pressures in Plants: A Test of the Balancing Pressure Technique*. *Science* 270.5239 (1995): 1193-1194.
- [15] Glaser, Donald A. *Some Effects of Ionizing Radiation on the Formation of Bubbles in Liquids*. *Physical Review* 87.4 (1952): 665.
- [16] Seitz, Frederick. *On the Theory of the Bubble Chamber*. *Physics of Fluids* 1.1 (1958): 2-13.
- [17] E. Behnke, J. I. Collar, P. S. Cooper, K. Crum, M. Crisler, M. Hu, I. Levine, D. Nakazawa, H. Nguyen, B. Odom, E. Ramberg, J. Rasmussen, N. Riley, A. Sonnenschein, M. Szydagis, R. Tschirhart. *Spin-Dependent WIMP Limits from a Bubble Chamber*. *Science* 319.5865 (2008): 933-936.
- [18] Knoll, Glenn F. *Radiation Detection and Measurement*. 3<sup>rd</sup> ed. Hoboken, NJ: John Wiley & Sons, Inc., 2000.
- [19] Bertolotti, M., D. Sette, F. Wanderlingh. *On the Possibility of High Energy Particle Detectors Based on Ultrasonic Cavitation*. *Nuclear Instruments and Methods* 35.1 (1965): 109-112.
- [20] Briggs, Lyman J. *Limiting Negative Pressure of Water*. *Journal of Applied Physics* 21.7 (1950): 721-722.
- [21] W. M. Haynes, ed. *CRC Handbook of Chemistry and Physics*. 93<sup>rd</sup> Edition (Internet Version 2013), CRC Press/Taylor and Francis, Boca Raton, FL.
- [22] National Institute of Standards and Technology. *Acetone*. Retrieved 5 Oct 2012, <http://webbook.nist.gov/cgi/cbook.cgi?ID=C67641&Units=SI&Mask=4#Thermo-Phase>
- [23] Sigma-Aldrich. *Carbon, Mesoporous Nanopowder, <500 nm Particle Size (DLS), >99.95% Trace Metals Basis*. CAS 1333-86-4. Retrieved 18 Oct 2012, <http://www.sigmaaldrich.com/catalog/product/aldrich/699632?lang=en&region=US>
- [24] Huang, Jing, K. Padmanabhan, O. M. Collins. *The Sampling Theorem with Constant Amplitude Variable Width Pulses*, *Circuits and Systems I: Regular Papers*, *IEEE Transactions on*, 58.6 (2011): 1178-1190.

- [25] Barr, Michael. *Pulse Width Modulation*, Embedded Systems Programming (2001): 103-104. Accessible at <http://www.barrgroup.com/Embedded-Systems/How-To/PWM-Pulse-Width-Modulation>
- [26] Ruilang Smarhome Limited, *Types of Dimmer*. Retrieved 19 Oct 2012, <http://www.dimming.org/Technical/detail/705.html>
- [27] Axelson, Jan. *Serial Port Complete*. Madison, WI: Lakeview Research, 1998.
- [28] Tissue, Bryan M. *Beer-Lambert Law*. Virginia Tech, 2003, Retrieved 19 Oct 2012, <http://www.files.chem.vt.edu/chem-ed/spec/beerslaw.html>
- [29] Newport Corporation. *Gaussian Beam Optics Tutorial*. Retrieved 7 Oct 2012, <http://www.newport.com/servicesupport/tutorials/default.aspx?id=112>
- [30] Coherent, Inc. *Coherent CUBE™ Laser System Operator's Manual*. Rev. AB. Santa Clara, CA: Coherent, 2005. Accessible at [http://www.coherent.com/downloads/Cube\\_RevAB.pdf](http://www.coherent.com/downloads/Cube_RevAB.pdf)
- [31] National Semiconductor Corporation. *LM556 Dual Timer*. Santa Clara, CA: National Semiconductor, March 2000. Texas Instruments Literature Number: SNAS549. Accessible at <http://www.ti.com/lit/ds/symlink/lm556.pdf>
- [32] CD-adapco. *User Guide: Star-CCM+ Version 5.02*. Melville, NY: CD-adapco, 2009.

**APPENDIX A**  
**ELECTRIC CIRCUIT SCHEMATICS**

This Appendix contains the electrical schematics for the circuits designed and built as part of this research effort.

## A.1 CONTAINMENT BOX INTERLOCK





Figure 51: Containment Box Interlock Schematic

In Figure 51, the electrical schematic for the interlock on the containment box is given. The components labeled in the figure have values given in Table 13.

**Table 13: Containment Box Interlock Components**

C1: 0.047 $\mu$ F	F1: 10 A	S1: R13-28D-06-R
C2: 0.047 $\mu$ F	F2: 2.5 A	S2: GSW01-R
C3: 0.047 $\mu$ F	F3: 1.5 A	S3: GPB006-WH-R
C4: 0.047 $\mu$ F		S4: V3L-1465-D8
C5: 6800 $\mu$ F	R1: 47 $\Omega$	S5: V3L-1465-D8
C6: 3300 $\mu$ F	R2: 4.7k $\Omega$ 5W	
C7: 1000 $\mu$ F	R3: 4.7k $\Omega$ 5W	T1: QC-5126
	R4: 47 $\Omega$	
D1: 5100H1	R5: 10 $\Omega$	U1: L7812CV
D2: 1N5822G	R6: 10 $\Omega$	
D3, D4, D5, D6: KBU6J	R7: 10 $\Omega$	W1: 3110GL-B4W-B19-P53
D7: 5100H7	R8: 10 $\Omega$	
D8: 1N5822G	R9: 10k $\Omega$	Y1: K10P-11D15-12
D9: 1N5822G	R10: 750 $\Omega$ ½ W	Y2: LB2-12DS-R
D10: 1N5822G	R11: 33 $\Omega$ 5 W	
D11: 5102H5-5V	R12: 33 $\Omega$ 5 W	
D12: 80SQ045	R13: 1k $\Omega$ ½ W	
D13: 1N5822G	R14: 10k $\Omega$	
D14: 1N5822G	R15: 10k $\Omega$	

## A.2 SPEED SENSOR




**Figure 52: Speed Sensor Schematic**

In Figure 52, the electrical schematic for the speed sensor circuit is shown. The components shown in it are detailed in Table 14.

**Table 14: Speed Sensor Components**

C1: 560 pF	R1: 470 $\Omega$
D1: 1N5822G	R2: 5k $\Omega$
D2: HLMP-1700-B0002	R3: 470 $\Omega$
D3: HLMP-1790-A0002	R4: 220 $\Omega$
D4: BPV22NF(L)	R5: 3.9k $\Omega$
D5: L-34F3CS	R6: 3.9k $\Omega$
U1: LF353N	R7: 10 $\Omega$
	R8: 10 $\Omega$
	R9: 220 $\Omega$
	R10: 220 $\Omega$
	R11: 1M $\Omega$
	R12: 560 $\Omega$

### A.3 SPEED SENSOR ADAPTER



**Figure 53: Speed Sensor Adapter Schematic**




The electrical schematic for the speed sensor adapter is given in Figure 53. The corresponding component details are given in Table 15.

**Table 15: Speed Sensor Adapter Components**

C1: 10 pF	R1: 470k $\Omega$
C2: 10 pF	R2: 220 $\Omega$
	R3: 10k $\Omega$
D1: 50SQ100	R4: 1M $\Omega$
D2: 50SQ100	R5: 470k $\Omega$
	R6: 1M $\Omega$
U1: MC34071A	R7: 1M $\Omega$

## A.4 CAVITATION SENSOR




**Figure 54: Cavitation Sensor Schematic**

The electrical schematic for the cavitation sensor is given in Figure 54. Its corresponding components are listed in Table 16.

**Table 16: Cavitation Sensor Components**

C1: 560 pF	R3: 470 $\Omega$
C2: 560 pF	R4: 1k $\Omega$
D1: 50SQ100	R5: 8.2k $\Omega$
D2: HLMP-1700-B0002	R6: 8.2k $\Omega$
D3: HLMP-1790-A0002	R7: 33 $\Omega$
D4: Radioshack #276-0307 5mm 660nm 1.7V 20mA 3000mcd 12deg clear-lens LED	R8: 33 $\Omega$
D5: 50SQ100	R9: 220 $\Omega$
D6: 1N4615	R10: 10 $\Omega$
U1: MC34071A	R11: 10 $\Omega$
Q1: CdS Photocell – small one from Radioshack #276-1657 assortment (P1201?)	R12: 1.5k $\Omega$
R1: 1k $\Omega$	R13: 47k $\Omega$
R2: 150k $\Omega$	R14: 3.3k $\Omega$
	R15: 1.5k $\Omega$
	R16: 10k $\Omega$
	R17: 10k $\Omega$
	R18: 10k $\Omega$

## A.5 SIGNAL INVERTER



**Figure 55: Signal Inverter Schematic**

The electrical schematic for the signal inverter is given in Figure 55. The values for its components are given in Table 17.

**Table 17: Signal Inverter Components**

C1: 10 $\mu$ F	R1: 1 $\Omega$
C2: 10 $\mu$ F	R2: 1 $\Omega$
	R3: 15k $\Omega$
D1: GP15M	R4: 15k $\Omega$
D2: GP15M	R5: 10k $\Omega$
D3: GP15M	R6: 4.7k $\Omega$
D4: GP15M	R7: 10k $\Omega$
	R8: 10k $\Omega$
U1: MC34071AP	R9: 100k $\Omega$
	R10: 1k $\Omega$

## **A.6 SPEED CONTROLLER ELECTRONICS**

An overview drawing of the subassemblies contained in the Speed Controller Electronics Unit is given in Figure 56. The Master Power subassembly is given in Figure 57, the Fault Detector subassembly is given in Figure 58, the Isolator subassembly is given in Figure 59, the Phase Detector subassembly is given in Figure 60, the Trigger subassembly is given in Figure 61, and the Waveform Adapter subassembly is given in Figure 62. The components used are listed in Table 18 and Table 19.

# OVERVIEW

## FAULT PROTECTION AND PHASE CONTROLLER

JUNE 2012






Figure 56: Speed Controller Electronics Overview




**Figure 57: Master Power Subassembly**



**Figure 58: Fault Detector Subassembly**





**Figure 59: Isolator Subassembly**




Figure 60: Phase Detector Subassembly




Figure 61: Trigger Subassembly




Figure 62: Waveform Adapter Subassembly

**Table 18: Speed Controller Components, Part 1**

C1: 0.01 $\mu$ F	D2: 6A8-T	D35: 1N4615
C2: 0.01 $\mu$ F	D3: 6A8-T	D36: 1N4005
C3: 0.01 $\mu$ F	D4: 6A8-T	D37: STPS3150RL
C4: 0.01 $\mu$ F	D5: 6A8-T	D38: 6A8-T
C5: 0.22 $\mu$ F	D6: 1N4615	D39: 6A8-T
C6: 330 $\mu$ F	D7: 1N4615	D40: 6A8-T
C7: 0.22 $\mu$ F	D8: 6A8-T	D41: 6A8-T
C8: 47 $\mu$ F	D9: 1N4004	D42: S6020L
C9: 33 $\mu$ F	D10: 1N4742A	D43: S6020L
C10: 0.022 $\mu$ F	D11: 1N4742A	D44: 6A8-T
C11: 0.1 $\mu$ F	D12: 6A8-T	F1: 10A SLO-BLO
C12: 330 $\mu$ F	D13: BZV85-CV2,113	F2: 10A SLO-BLO
C13: 22 $\mu$ F	D14: BZV85-CV2,113	L1: 100 $\mu$ H
C14: 470 $\mu$ F	D15: 5101H1	P1: DUAL BINDING POST
C15: 470 $\mu$ F	D16: 1091M5-125VAC	Q1: KSP45
C16: 4.7 $\mu$ F	D17: 6A8-T	Q2: 2N3417
C17: 47 $\mu$ F	D18: 6A8-T	Q3: BC557
C18: 47 $\mu$ F	D19: GBPC3506W-E4/51	Q4: KSP45
C19: 0.22 $\mu$ F	D20: W10G	Q5: KSP45
C20: 0.22 $\mu$ F	D21: STPS3150RL	Q6: 2SA1381ESTU
C21: 0.1 $\mu$ F	D22: STPS3150RL	Q7: KSP45
C22: 0.22 $\mu$ F	D23: 6A8-T	Q8: KSP45
C23: 0.22 $\mu$ F	D24: STPS3150RL	Q9: KSH45H11ITU
C24: 0.22 $\mu$ F	D25: STPS3150RL	Q10: 2N3417
C25: 0.22 $\mu$ F	D26: 1N4615	Q11: KSH45H11ITU
C26: 4.7 $\mu$ F	D27: STPS3150RL	Q12: KSA1625K
C27: 47 nF	D28: STPS3150RL	Q13: KSP45
C28: 0.1 $\mu$ F	D29: 1N4615	Q14: KSP45
C29: 47 nF	D30: STPS3150RL	
C30: 0.1 $\mu$ F	D31: BZX55B16	
C31: 10 $\mu$ F	D32: BZX55B16	
D1: 1091M5-125VAC	D33: BZX55B16	
	D34: BZX55B16	

**Table 19: Speed Controller Components, Part 2**

R1: 10 MΩ	R34: 1 MΩ	R67: 150 kΩ 2W
R2: 100 Ω	R35: 10 Ω	R68: 2.2 kΩ
R3: 4.7 MΩ	R36: 1 MΩ	R69: 47 kΩ
R4: 33 kΩ	R37: 220 kΩ	R70: 3.3 kΩ
R5: 4.7 MΩ	R38: 15 kΩ 1%	R71: 330 kΩ
R6: 4.7 MΩ	R39: 200 kΩ 1%	R72: 100 kΩ
R7: 10 Ω	R40: 1 MΩ	R73: 47 kΩ 1W
R8: 33 kΩ	R41: 1 MΩ	R74: 1 MΩ
R9: 100 kΩ	R42: 10 MΩ 1%	R75: 15 Ω
R10: 300 kΩ	R43: 470 kΩ 1%	R76: 15 kΩ 5W
R11: 200 kΩ	R44: 10 MΩ 1%	R77: 100 kΩ 1W
R12: 100 kΩ	R45: 470 kΩ 1%	R78: 15 kΩ 5W
R13: 330 kΩ	R46: 15 kΩ	R79: 330 kΩ
R14: 47 Ω	R47: 4.7 kΩ	R80: 100 Ω
R15: 100 kΩ	R48: 15 kΩ	R81: 5.6 kΩ 5W
R16: 200 kΩ	R49: 1.5 kΩ	R82: 5.6 kΩ 5W
R17: 150 Ω	R50: 4.7 kΩ	
R18: 47 Ω	R51: 4.7 kΩ	S1: S821-RO
R19: 2.2 MΩ	R52: 220 Ω	S2: 103-R13-135C-02-EV
R20: 1 MΩ	R53: 27 kΩ 0.1%	
R21: 10 MΩ	R54: 9.1 Ω	T1: 164H36
R22: 2.2 MΩ	R55: 10 kΩ	
R23: 470 kΩ	R56: 10 kΩ	U1: LM7812
R24: 470 kΩ	R57: 15 kΩ	U2: LM7912
R25: 100 kΩ	R58: 2.2 kΩ	U3: MC34071APG
R26: 470 kΩ	R59: 15 kΩ	U4: MC34071APG
R27: 6.2 kΩ 5W	R60: 1 MΩ	U5: TLE2141ACP
R28: 75 kΩ 1W	R61: 2.2 kΩ	
R29: 16 kΩ 5W	R62: 1 MΩ	W1: OA80AP-11-2WB
R30: 1.6 kΩ	R63: 150 kΩ 0.1%	
R31: 470 kΩ	R64: 10 kΩ	Y1: KUP-14D15-110
R32: 100 kΩ	R65: 330 kΩ	
R33: 10 Ω	R66: 22 kΩ	

## **A.7 RS-232 ISOLATOR AND POWER SUPPLY**

An overview of the RS-232 Isolator and Power supply is given in Figure 63. The subassemblies it describes are given in Figure 64, Figure 65, Figure 66, Figure 67, and Figure 68; the buffer subassemblies are identical, and only differ in their connections to the interface pins. The list of components is given in Table 20 and Table 21.

# OVERVIEW

## SERIAL PORT BUFFER AND POWER

JUNE 2011






Figure 63: Serial Port Isolator Overview







**Figure 64: Power Supply Subassembly**




**Figure 65: Buffer A-B Subassembly**



**Figure 66: Buffer C-D Subassembly**



**Figure 67: Buffer E-F Subassembly**



**Figure 68: Buffer G-H Subassembly**

**Table 20: Serial Port Isolator Components, Part 1**


C1: 3300 $\mu$ F	D1: GBPC3506W-E4/51	P9: DUAL BINDING POST
C2: 3300 $\mu$ F	D2: 50SQ100	P10: DUAL BINDING POST
C3: 3300 $\mu$ F	D3: 1N5225B	
C4: 3300 $\mu$ F	D4: 1N5225B	R1: 1.8K $\Omega$ 1W
C5: 470 $\mu$ F	D5: 50SQ100	R2: 5.6K $\Omega$
C6: 470 $\mu$ F	D6: 50SQ100	R3: 2.2M $\Omega$
C7: 68 $\mu$ F	D7: 50SQ100	R4: 2.2M $\Omega$
C8: 68 $\mu$ F	D8: 5101H1	R5: 5.6K $\Omega$
C9: 0.22 $\mu$ F		R6: 1M $\Omega$
C10: 0.22 $\mu$ F	F1: 2.5 A	R7: 1M $\Omega$
C11: 0.22 $\mu$ F	F2: 1 A	R8: 33K $\Omega$
C12: 0.22 $\mu$ F	F3: 1 A	R9: 220 $\Omega$
C13: 0.22 $\mu$ F		R10: 2.4M $\Omega$
C14: 0.22 $\mu$ F	L1: 680 $\mu$ H	R11: 30K $\Omega$
C15: 0.22 $\mu$ F	L2: 680 $\mu$ H	R12: 330K $\Omega$
C16: 0.22 $\mu$ F		R13: 160 $\Omega$
C17: 0.22 $\mu$ F	P1: TRIPLE BINDING POST	R14: 470K $\Omega$
C18: 0.22 $\mu$ F	P2: DE-9-F	R15: 33K $\Omega$
C19: 0.22 $\mu$ F	P3: DUAL BINDING POST	R16: 1K $\Omega$
C20: 0.22 $\mu$ F	P4: DUAL BINDING POST	R17: 1K $\Omega$
C21: 0.22 $\mu$ F	P5: DUAL BINDING POST	R18: 470K $\Omega$
C22: 0.22 $\mu$ F	P6: DUAL BINDING POST	R19: 33K $\Omega$
C23: 0.22 $\mu$ F	P7: DUAL BINDING POST	R20: 330K $\Omega$
C24: 0.22 $\mu$ F	P8: DUAL BINDING POST	R21: 160 $\Omega$

**Table 21: Serial Port Isolator Components, Part 2**

R22: 2.4M $\Omega$	R46: 2.4M $\Omega$	R70: 1K $\Omega$
R23: 30K $\Omega$	R47: 30K $\Omega$	R71: 1K $\Omega$
R24: 220 $\Omega$	R48: 330K $\Omega$	R72: 470K $\Omega$
R25: 33K $\Omega$	R49: 160 $\Omega$	R73: 33K $\Omega$
R26: 33K $\Omega$	R50: 470K $\Omega$	R74: 330K $\Omega$
R27: 220 $\Omega$	R51: 33K $\Omega$	R75: 160 $\Omega$
R28: 2.4M $\Omega$	R52: 1K $\Omega$	R76: 2.4M $\Omega$
R29: 30K $\Omega$	R53: 1K $\Omega$	R77: 30K $\Omega$
R30: 330K $\Omega$	R54: 470K $\Omega$	R78: 220 $\Omega$
R31: 160 $\Omega$	R55: 33K $\Omega$	R79: 33K $\Omega$
R32: 470K $\Omega$	R56: 330K $\Omega$	
R33: 33K $\Omega$	R57: 160 $\Omega$	S1: S301T-RO
R34: 1K $\Omega$	R58: 2.4M $\Omega$	
R35: 1K $\Omega$	R59: 30K $\Omega$	T1: VPT30-3330
R36: 470K $\Omega$	R60: 220 $\Omega$	
R37: 33K $\Omega$	R61: 33K $\Omega$	U1: LM7812
R38: 330K $\Omega$	R62: 33K $\Omega$	U2: LM7912
R39: 160 $\Omega$	R63: 220 $\Omega$	U3: OPA2132PAG4
R40: 2.4M $\Omega$	R64: 2.4M $\Omega$	U4: OPA2132PAG4
R41: 30K $\Omega$	R65: 30K $\Omega$	U5: OPA2132PAG4
R42: 220 $\Omega$	R66: 330K $\Omega$	U6: OPA2132PAG4
R43: 33K $\Omega$	R67: 160 $\Omega$	
R44: 33K $\Omega$	R68: 470K $\Omega$	W1: AD0624LB-A70GL-LF
R45: 220 $\Omega$	R69: 33K $\Omega$	

## A.8 LASER INTERLOCK SYSTEM

An overview of the laser interlock system is given in Figure 69. The subassemblies are shown in Figure 70, Figure 71, Figure 72, Figure 73, and Figure 74. The components for the system are listed in Table 22.



**Figure 69: Laser Interlock System Overview**






Figure 70: Interlock Light 1 Subassembly







Figure 71: Interlock Light 2 Subassembly



**Figure 72: Interlock Light Flasher Controller Subassembly**



**Figure 73: Interlock 12V Supply Subassembly**



**DOOR AND  
BUTTONS**

**Figure 74: Interlock Door and Buttons Subassembly**

**Table 22: Laser Interlock System Components**


C1: 220 $\mu$ F	F1: 7A	R19: 750 $\Omega$
C2: 1000 $\mu$ F	F2: 7A	R20: 47 $\Omega$ 10 W
C3: 220 $\mu$ F	F3: 1.25A	R21: 470K $\Omega$
C4: 1000 $\mu$ F	F4: 10A	R22: 18 $\Omega$
D1: 10A07	Q1: NTE128	R23: 18 $\Omega$
D2: 10A07	Q2: NTE128	R24: 750 $\Omega$
D3: 1N4004	Q3: NTE128	R25: 750 $\Omega$
D4: 1091M7-12V	Q4: NTE128	R26: 470K $\Omega$
D5: 1N4004	Q5: NTE128	R27: 470K $\Omega$
D6: 10A07	Q6: NTE128	S1: H2011U2F205NQ
D7: 10A07	R1: 180 $\Omega$	S2: McMaster # 75759K21
D8: 1N5927BG	R2: 68 $\Omega$	S3: McMaster # 6785K21
D9: 10A07	R3: 4.7 $\Omega$ 10 W – 30J4R7E	S4: McMaster # 6785K21
D10: 10A07	R4: 2K $\Omega$ 50 W – RH0502K000FE02	S5: Magnetic/Reed Switch 505-101-WS
D11: 1N4004	R5: 10 $\Omega$	S6: Magnetic/Reed Switch 505-101-WS
D12: 1091M7-12V	R6: 470K $\Omega$	T1: 186D10
D13: 1N4004	R7: 180 $\Omega$	U1: ETN-120-AFT-75
D14: 10A07	R8: 68 $\Omega$	U2: ETN-120-AFT-75
D15: 10A07	R9: 4.7 $\Omega$ 10 W – 30J4R7E	W1: 30-60W INCANDESCENT BULB
D16: 1N5927BG	R10: 2K $\Omega$ 50 W – RH0502K000FE02	W2: 30-60W INCANDESCENT BULB
D17: DFB2520	R11: 10 $\Omega$	Y1: HJ2-L-T-DC12V
D18: 1N4004	R12: 470K $\Omega$	Y2: HJ2-L-T-DC12V
D19: 1N4004	R13: 470K $\Omega$	Y3: HJ2-L-T-DC12V
D20: 1091M7-12V	R14: 470K $\Omega$	Y4: HJ2-L-T-DC12V
D21: 1N4004	R15: 18 $\Omega$	Y5: HJ2-L-T-DC12V
D22: 1N4004	R16: 390 $\Omega$	
D23: 1N4004	R17: 470K $\Omega$	
D24: 1N4004	R18: 68 $\Omega$	
D25: 1091M1-125VAC		

## A.9 PULSE GENERATOR

The electrical schematic for the Pulse Generator is given in Figure 75. The components for it are listed in Table 23.

**Table 23: Pulse Generator Components**

C1: 10 $\mu$ F	R1: 1 $\Omega$
C2: 47 $\mu$ F	R2: 1 M $\Omega$
C3: 0.022 $\mu$ F	R3: 1 M $\Omega$
C4: 0.001 $\mu$ F	R4: 1 k $\Omega$
C5: 220 pF	R5: 68 $\Omega$
C6: 100 pF	R6: 10 k $\Omega$
C7: 10 $\mu$ F	R7: 10 k $\Omega$
C8: 100 pF	R8: 100 k $\Omega$
C9: 0.001 $\mu$ F	R9: 10 k $\Omega$
	R10: 10 k $\Omega$
D1: STPS5L40RL	R11: 27 k $\Omega$
D2: STPS5L40RL	R12: 100 k $\Omega$ audio taper
D3: STPS5L40RL	R13: 1 k $\Omega$
D4: 1N4614	R14: 1 k $\Omega$
D5: BAT43	R15: 1 k $\Omega$
D6: BAT43	R16: 39 $\Omega$
D7: BAT43	R17: 100 k $\Omega$
	R18: 1 k $\Omega$
U1: LM7805	R19: 1.5 k $\Omega$
U2: TLE2141AC	R20: 4.7 k $\Omega$
U3: NE556	R21: 12 k $\Omega$
	R22: 3.3 k $\Omega$
	R23: 1 k $\Omega$



**Figure 75: Pulse Generator Schematic**

**APPENDIX B**  
**SPEEDCONTROL SOURCE CODE**



A number of separate Visual Basic™ files were developed as part of the source code and User's Guide for the SpeedControl software. With the exception of the icons and certain resource files, they are all listed in this Appendix. A total of 21 files are included here.

## B.1 ASSEMBLYINFO.VB

```
Imports System.Resources

Imports System
Imports System.Reflection
Imports System.Runtime.InteropServices

' General Information about an assembly is controlled through the following
' set of attributes. Change these attribute values to modify the information
' associated with an assembly.

' Review the values of the assembly attributes

<Assembly: AssemblyTitle("CTMFD Speed and Laser Control Application")>
<Assembly: AssemblyDescription("Control Application for the Speed and Laser in
the NHTS Lab CTMFD Facility")>
<Assembly: AssemblyCompany("Texas Engineering Experiment Station")>
<Assembly: AssemblyProduct("Speed and Laser Controller")>
<Assembly: AssemblyCopyright("Copyright © Texas A&M University 2011")>
<Assembly: AssemblyTrademark("Texas A&M University")>

<Assembly: ComVisible(False)>

' The following GUID is for the ID of the typelib if this project is exposed to
COM
<Assembly: Guid("083d8e3a-fda9-449a-a320-245cafcla9e3")>

' Version information for an assembly consists of the following four values:
'
'     Major Version
'     Minor Version
'     Build Number
'     Revision
'
' You can specify all the values or you can default the Build and Revision
Numbers
' by using the '*' as shown below:
' <Assembly: AssemblyVersion("1.0.*")>

<Assembly: AssemblyVersion("1.0.*")>
<Assembly: AssemblyFileVersion("1.0.1.3")>

<Assembly: NeutralResourcesLanguageAttribute("en-US")>
```

## B.2 FIREPULSE.DESIGNER.VB

```
<Global.Microsoft.VisualBasic.CompilerServices.DesignerGenerated()> _
Partial Class FirePulse
    Inherits System.Windows.Forms.Form

    'Form overrides dispose to clean up the component list.
    <System.Diagnostics.DebuggerNonUserCode()> _
    Protected Overrides Sub Dispose(ByVal disposing As Boolean)
        Try
            If disposing AndAlso components IsNot Nothing Then
                components.Dispose()
            End If
        Finally
            MyBase.Dispose(disposing)
        End Try
    End Sub

    'Required by the Windows Form Designer
    Private components As System.ComponentModel.IContainer

    'NOTE: The following procedure is required by the Windows Form Designer
    'It can be modified using the Windows Form Designer.
    'Do not modify it using the code editor.
    <System.Diagnostics.DebuggerStepThrough()> _
    Private Sub InitializeComponent()
        Dim resources As System.ComponentModel.ComponentResourceManager = New
System.ComponentModel.ComponentResourceManager(GetType(FirePulse))
        Me.CommentBox = New System.Windows.Forms.TextBox
        Me.CancelPulseButton = New System.Windows.Forms.Button
        Me.FireButton = New System.Windows.Forms.Button
        Me.Label1 = New System.Windows.Forms.Label
        Me.Label2 = New System.Windows.Forms.Label
        Me.Label3 = New System.Windows.Forms.Label
        Me.SetValuesButton = New System.Windows.Forms.Button
        Me.DurationDisplay = New System.Windows.Forms.Label
        Me.PowerDisplay = New System.Windows.Forms.Label
        Me.DurationSetBox = New System.Windows.Forms.TextBox
        Me.PowerSetBox = New System.Windows.Forms.TextBox
        Me.SuspendLayout()
        '
        'CommentBox
        '
        Me.CommentBox.Location = New System.Drawing.Point(12, 25)
        Me.CommentBox.MaximumSize = New System.Drawing.Size(289, 74)
        Me.CommentBox.MinimumSize = New System.Drawing.Size(289, 74)
        Me.CommentBox.Multiline = True
        Me.CommentBox.Name = "CommentBox"
        Me.CommentBox.ScrollBars = System.Windows.Forms.ScrollBars.Vertical
        Me.CommentBox.Size = New System.Drawing.Size(289, 74)
        Me.CommentBox.TabIndex = 5
        Me.CommentBox.Text = "(Leave a comment)"
        '
        'CancelPulseButton
        '
        Me.CancelPulseButton.Location = New System.Drawing.Point(226, 194)
        Me.CancelPulseButton.MaximumSize = New System.Drawing.Size(75, 23)
        Me.CancelPulseButton.MinimumSize = New System.Drawing.Size(75, 23)
        Me.CancelPulseButton.Name = "CancelPulseButton"
```

```

Me.CancelPulseButton.Size = New System.Drawing.Size(75, 23)
Me.CancelPulseButton.TabIndex = 4
Me.CancelPulseButton.Text = "Cancel"
Me.CancelPulseButton.UseVisualStyleBackColor = True
'
'FireButton
'
Me.FireButton.Location = New System.Drawing.Point(12, 194)
Me.FireButton.MaximumSize = New System.Drawing.Size(75, 23)
Me.FireButton.MinimumSize = New System.Drawing.Size(75, 23)
Me.FireButton.Name = "FireButton"
Me.FireButton.Size = New System.Drawing.Size(75, 23)
Me.FireButton.TabIndex = 3
Me.FireButton.Text = "FIRE!"
Me.FireButton.UseVisualStyleBackColor = True
'
'Label1
'
Me.Label1.AutoSize = True
Me.Label1.Location = New System.Drawing.Point(9, 9)
Me.Label1.MaximumSize = New System.Drawing.Size(54, 13)
Me.Label1.MinimumSize = New System.Drawing.Size(54, 13)
Me.Label1.Name = "Label1"
Me.Label1.Size = New System.Drawing.Size(54, 13)
Me.Label1.TabIndex = 6
Me.Label1.Text = "Comment:"
'
'Label2
'
Me.Label2.AutoSize = True
Me.Label2.Location = New System.Drawing.Point(18, 121)
Me.Label2.MaximumSize = New System.Drawing.Size(71, 13)
Me.Label2.MinimumSize = New System.Drawing.Size(71, 13)
Me.Label2.Name = "Label2"
Me.Label2.Size = New System.Drawing.Size(71, 13)
Me.Label2.TabIndex = 7
Me.Label2.Text = "Est. Duration:"
'
'Label3
'
Me.Label3.AutoSize = True
Me.Label3.Location = New System.Drawing.Point(49, 149)
Me.Label3.MaximumSize = New System.Drawing.Size(40, 13)
Me.Label3.MinimumSize = New System.Drawing.Size(40, 13)
Me.Label3.Name = "Label3"
Me.Label3.Size = New System.Drawing.Size(40, 13)
Me.Label3.TabIndex = 8
Me.Label3.Text = "Power:"
'
'SetValuesButton
'
Me.SetValuesButton.Location = New System.Drawing.Point(120, 194)
Me.SetValuesButton.MaximumSize = New System.Drawing.Size(75, 23)
Me.SetValuesButton.MinimumSize = New System.Drawing.Size(75, 23)
Me.SetValuesButton.Name = "SetValuesButton"
Me.SetValuesButton.Size = New System.Drawing.Size(75, 23)
Me.SetValuesButton.TabIndex = 9
Me.SetValuesButton.Text = "Set Values"
Me.SetValuesButton.UseVisualStyleBackColor = True

```

```

    '
    'DurationDisplay
    '
    Me.DurationDisplay.AutoSize = True
    Me.DurationDisplay.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
    Me.DurationDisplay.Location = New System.Drawing.Point(95, 121)
    Me.DurationDisplay.MaximumSize = New System.Drawing.Size(100, 15)
    Me.DurationDisplay.MinimumSize = New System.Drawing.Size(100, 15)
    Me.DurationDisplay.Name = "DurationDisplay"
    Me.DurationDisplay.Size = New System.Drawing.Size(100, 15)
    Me.DurationDisplay.TabIndex = 10
    Me.DurationDisplay.Text = "0.0001"
    '
    'PowerDisplay
    '
    Me.PowerDisplay.AutoSize = True
    Me.PowerDisplay.BorderStyle = System.Windows.Forms.BorderStyle.Fixed3D
    Me.PowerDisplay.Location = New System.Drawing.Point(95, 149)
    Me.PowerDisplay.MaximumSize = New System.Drawing.Size(100, 15)
    Me.PowerDisplay.MinimumSize = New System.Drawing.Size(100, 15)
    Me.PowerDisplay.Name = "PowerDisplay"
    Me.PowerDisplay.Size = New System.Drawing.Size(100, 15)
    Me.PowerDisplay.TabIndex = 11
    Me.PowerDisplay.Text = "100"
    '
    'DurationSetBox
    '
    Me.DurationSetBox.Location = New System.Drawing.Point(201, 118)
    Me.DurationSetBox.MaximumSize = New System.Drawing.Size(100, 20)
    Me.DurationSetBox.MaxLength = 12
    Me.DurationSetBox.MinimumSize = New System.Drawing.Size(100, 20)
    Me.DurationSetBox.Name = "DurationSetBox"
    Me.DurationSetBox.Size = New System.Drawing.Size(100, 20)
    Me.DurationSetBox.TabIndex = 12
    Me.DurationSetBox.Text = "0.0001"
    '
    'PowerSetBox
    '
    Me.PowerSetBox.Location = New System.Drawing.Point(201, 146)
    Me.PowerSetBox.MaximumSize = New System.Drawing.Size(100, 20)
    Me.PowerSetBox.MaxLength = 9
    Me.PowerSetBox.MinimumSize = New System.Drawing.Size(100, 20)
    Me.PowerSetBox.Name = "PowerSetBox"
    Me.PowerSetBox.Size = New System.Drawing.Size(100, 20)
    Me.PowerSetBox.TabIndex = 13
    Me.PowerSetBox.Text = "100"
    '
    'FirePulse
    '
    Me.AutoScaleDimensions = New System.Drawing.SizeF(6.0!, 13.0!)
    Me.AutoScaleMode = System.Windows.Forms.AutoScaleMode.Font
    Me.ClientSize = New System.Drawing.Size(315, 237)
    Me.Controls.Add(Me.PowerSetBox)
    Me.Controls.Add(Me.DurationSetBox)
    Me.Controls.Add(Me.PowerDisplay)
    Me.Controls.Add(Me.DurationDisplay)
    Me.Controls.Add(Me.SetValuesButton)
    Me.Controls.Add(Me.Label3)

```

```

Me.Controls.Add(Me.Label2)
Me.Controls.Add(Me.Label1)
Me.Controls.Add(Me.CommentBox)
Me.Controls.Add(Me.CancelPulseButton)
Me.Controls.Add(Me.FireButton)
Me.FormBorderStyle = System.Windows.Forms.FormBorderStyle.FixedDialog
Me.Icon = CType(resources.GetObject("$this.Icon"), System.Drawing.Icon)
Me.MaximizeBox = False
Me.MaximumSize = New System.Drawing.Size(321, 263)
Me.MinimizeBox = False
Me.MinimumSize = New System.Drawing.Size(321, 263)
Me.Name = "FirePulse"
Me.ShowIcon = False
Me.SizeGripStyle = System.Windows.Forms.SizeGripStyle.Hide
Me.Text = "Fire a Laser Pulse"
Me.ResumeLayout(False)
Me.PerformLayout()

End Sub
Friend WithEvents CommentBox As System.Windows.Forms.TextBox
Friend WithEvents CancelPulseButton As System.Windows.Forms.Button
Friend WithEvents FireButton As System.Windows.Forms.Button
Friend WithEvents Label1 As System.Windows.Forms.Label
Friend WithEvents Label2 As System.Windows.Forms.Label
Friend WithEvents Label3 As System.Windows.Forms.Label
Friend WithEvents SetValueButton As System.Windows.Forms.Button
Friend WithEvents DurationDisplay As System.Windows.Forms.Label
Friend WithEvents PowerDisplay As System.Windows.Forms.Label
Friend WithEvents DurationSetBox As System.Windows.Forms.TextBox
Friend WithEvents PowerSetBox As System.Windows.Forms.TextBox
End Class

```

### B.3 FIREPULSE.VB

```

Public Class FirePulse
    'Code for the FirePulse form that shows when the User wants to Fire a
    Manually-Issued Laser Pulse

    Private Sub FirePulse_FormClosing(ByVal sender As Object, ByVal e As
System.Windows.Forms.FormClosingEventArgs) Handles Me.FormClosing
        'Stuff to do when the form is closing

        If e.CloseReason <> CloseReason.None Then
            e.Cancel = True
        End If

    End Sub

    Private Sub CancelPulseButton_Click(ByVal sender As System.Object, ByVal e
As System.EventArgs) Handles CancelPulseButton.Click
        'User clicked Cancel

        'set the default comment

```

```

    CommentBox.Text = "(Leave a Comment)"
    CommentBox.Select(0, CommentBox.TextLength)
    CommentBox.Focus()

    DurationSetBox.Text = DurationDisplay.Text
    PowerSetBox.Text = PowerDisplay.Text

    Me.Hide()
    Application.DoEvents()

End Sub

Private Sub FirePulse_Shown(ByVal sender As Object, ByVal e As
System.EventArgs) Handles Me.Shown
    'handles stuff when the form is shown

    'set the default comment
    CommentBox.Text = "(Insert Comment Here)"
    CommentBox.Select(0, CommentBox.TextLength)
    CommentBox.Focus()

    DurationSetBox.Text = DurationDisplay.Text
    PowerSetBox.Text = PowerDisplay.Text

    Application.DoEvents()

End Sub

Private Sub SetValueButton_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles SetValueButton.Click
    'updates the values from the set boxes

    Try

        Dim ChangedPulseDuration As Boolean = False
        Dim NewPulseDuration As Double = 0
        Dim ChangedPulsePower As Boolean = False
        Dim NewPulsePower As Double = 0
        Dim EnteredDurationValue As Double = -1
        Dim EnteredPowerValue As Double = -1

        'stop autopulsing
        RunBox.StopAutomaticPulsing()

        'test the values for convertibility
        Try
            EnteredDurationValue = Val(DurationSetBox.Text)
        Catch TooMuchSpeed As OverflowException
            'bad value for duration
            MsgBox("Illegal Value for the new Estimated Duration:" &
vbNewLine & DurationSetBox.Text, , "Overflow")
            EnteredDurationValue = -1
        End Try

    Try

```

```

        EnteredPowerValue = Val(PowerSetBox.Text)
    Catch TooMuchSpeed As OverflowException
        'bad value for duration
        MsgBox("Illegal Value for the Next Laser Power:" & vbNewLine &
PowerSetBox.Text, , "Overflow")
        EnteredPowerValue = -1
    End Try

    'sanity check
    If EnteredDurationValue >= 0 Then
        'it works so far
        NewPulseDuration = EnteredDurationValue
        If EnteredPowerValue > 0 Then
            'both work
            NewPulsePower = EnteredPowerValue
            SyncLock Windowsill.RunBoxLock
                'load laser control values
                If Windowsill.EstimatedLaserPulseDuration <>
NewPulseDuration Then
                    ChangedPulseDuration = True
                    Windowsill.EstimatedLaserPulseDuration =
NewPulseDuration
                End If
                If Windowsill.NextLaserPulsePower <> NewPulsePower Then
                    ChangedPulsePower = True
                    Windowsill.NextLaserPulsePower = NewPulsePower
                End If
            End SyncLock
        Else
            MsgBox("Next Laser Pulse Power must be >0")
        End If
    Else
        MsgBox("Estimated Pulse Duration values must be >=0")
    End If

    'log the changes
    If ChangedPulseDuration = True Then
        Lumberjack.SendToLog("Estimated Laser Pulse Duration changed to
" & Str(NewPulseDuration))
    End If
    If ChangedPulsePower = True Then
        Lumberjack.SendToLog("Changed Next Laser Pulse Power to " &
Str(NewPulsePower))
    End If
    Application.DoEvents()

    Catch TooBig As OverflowException
        'something overflowed
        Lumberjack.SendToLog("Recoverable Exception in " &
Thread.CurrentThread.Name & ": " & TooBig.Message & vbNewLine & "Details: " &
vbNewLine & TooBig.ToString)
        MsgBox("An Overflow Exception has occurred in " &
Thread.CurrentThread.Name & ", but execution will continue. Details: " &
vbNewLine & TooBig.ToString, , "OUCH!")
    Catch BigException As Exception
        'something got really screwed up
        Lumberjack.SendToLog("Exception in " & Thread.CurrentThread.Name &
": " & BigException.Message & vbNewLine & "Details: " & vbNewLine &
BigException.ToString)

```

```

        MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End Try

End Sub

```

```

Private Sub FireButton_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles FireButton.Click
    'FIRE!
    'Issues a manual-type pulse to the laser

    Dim PulsePower As Double = 0
    Dim PulseDuration As Double = 0
    Dim PulseComment As String = ""
    Dim PulseInProgress As Boolean = False

    'stop autopulsing
    RunBox.StopAutomaticPulsing()

    'get data to log
    PulseComment = CommentBox.Text
    SyncLock Windowsill.RunBoxLock
        PulsePower = Windowsill.NextLaserPulsePower
        PulseDuration = Windowsill.EstimatedLaserPulseDuration
    End SyncLock

    'prepare the values for when the box is next shown
    Me.Hide()
    PowerSetBox.Text = PowerDisplay.Text
    DurationSetBox.Text = DurationDisplay.Text
    CommentBox.Text = "(Leave a Comment)"
    CommentBox.Select(0, CommentBox.TextLength)
    CommentBox.Focus()

    'log the event
    Lumberjack.SendToLog("The User has Ordered a Manual Laser Pulse with a
Pulse Power of " & PulsePower.ToString & " and an Estimated Pulse Duration of "
& PulseDuration.ToString & " with the following Comment: " & PulseComment)

    'Issue the pulse to the laser controller
    SyncLock Windowsill.RunBoxLock
        PulseInProgress = Windowsill.FireManualPulse
        Windowsill.FireManualPulse = True
    End SyncLock

    'log overlapping manual pulse events
    If PulseInProgress = True Then
        Lumberjack.SendToLog("Manually-Issued Laser Pulse Already in
Progress! A Second Pulse WILL NOT Follow.")
    End If

    Application.DoEvents()

```



End Sub

End Class

## B.4 HELPBOX.DESIGNER.VB

```
<Global.Microsoft.VisualBasic.CompilerServices.DesignerGenerated()> _
Partial Class HelpBox
    Inherits System.Windows.Forms.Form

    'Form overrides dispose to clean up the component list.
    <System.Diagnostics.DebuggerNonUserCode()> _
    Protected Overrides Sub Dispose(ByVal disposing As Boolean)
        Try
            If disposing AndAlso components IsNot Nothing Then
                components.Dispose()
            End If
        Finally
            MyBase.Dispose(disposing)
        End Try
    End Sub

    'Required by the Windows Form Designer
    Private components As System.ComponentModel.IContainer

    'NOTE: The following procedure is required by the Windows Form Designer
    'It can be modified using the Windows Form Designer.
    'Do not modify it using the code editor.
    <System.Diagnostics.DebuggerStepThrough()> _
    Private Sub InitializeComponent()
        Dim resources As System.ComponentModel.ComponentResourceManager = New
System.ComponentModel.ComponentResourceManager(GetType(HelpBox))
        Me.GuideTextBox = New System.Windows.Forms.TextBox
        Me.Button1 = New System.Windows.Forms.Button
        Me.SuspendLayout()
        '
        'GuideTextBox
        '
        Me.GuideTextBox.AcceptsReturn = True
        Me.GuideTextBox.AcceptsTab = True
        Me.GuideTextBox.BackColor = System.Drawing.SystemColors.Window
        Me.GuideTextBox.Font = New System.Drawing.Font("Microsoft Sans Serif",
10.0!, System.Drawing.FontStyle.Regular, System.Drawing.GraphicsUnit.Point,
CType(0, Byte))
        Me.GuideTextBox.Location = New System.Drawing.Point(12, 12)
        Me.GuideTextBox.MaximumSize = New System.Drawing.Size(568, 313)
        Me.GuideTextBox.MinimumSize = New System.Drawing.Size(568, 313)
        Me.GuideTextBox.Multiline = True
        Me.GuideTextBox.Name = "GuideTextBox"
        Me.GuideTextBox.ReadOnly = True
        Me.GuideTextBox.ScrollBars = System.Windows.Forms.ScrollBars.Vertical
        Me.GuideTextBox.Size = New System.Drawing.Size(568, 313)
        Me.GuideTextBox.TabIndex = 0
        Me.GuideTextBox.Text = "The User's Guide goes here. " &
Global.Microsoft.VisualBasic.ChrW(13) & Global.Microsoft.VisualBasic.ChrW(10) &
```

```

Global.Microsoft.VisualBasic.ChrW(13) & Global.Microsoft.VisualBasic.ChrW(10) &
"Jackass."
    ,
    'Button1
    ,
    Me.Button1.Location = New System.Drawing.Point(505, 331)
    Me.Button1.MaximumSize = New System.Drawing.Size(75, 23)
    Me.Button1.MinimumSize = New System.Drawing.Size(75, 23)
    Me.Button1.Name = "Button1"
    Me.Button1.Size = New System.Drawing.Size(75, 23)
    Me.Button1.TabIndex = 1
    Me.Button1.Text = "D'oh!"
    Me.Button1.UseVisualStyleBackColor = True
    ,
    'HelpBox
    ,
    Me.AutoScaleDimensions = New System.Drawing.SizeF(6.0!, 13.0!)
    Me.AutoScaleMode = System.Windows.Forms.AutoScaleMode.Font
    Me.ClientSize = New System.Drawing.Size(594, 375)
    Me.Controls.Add(Me.Button1)
    Me.Controls.Add(Me.GuideTextBox)
    Me.FormBorderStyle = System.Windows.Forms.FormBorderStyle.FixedDialog
    Me.Icon = CType(resources.GetObject("$this.Icon"), System.Drawing.Icon)
    Me.MaximizeBox = False
    Me.MaximumSize = New System.Drawing.Size(600, 400)
    Me.MinimizeBox = False
    Me.MinimumSize = New System.Drawing.Size(600, 400)
    Me.Name = "HelpBox"
    Me.ShowIcon = False
    Me.SizeGripStyle = System.Windows.Forms.SizeGripStyle.Hide
    Me.Text = "Help! I'm stuck in a computer!"
    Me.ResumeLayout(False)
    Me.PerformLayout()

End Sub
Friend WithEvents GuideTextBox As System.Windows.Forms.TextBox
Friend WithEvents Button1 As System.Windows.Forms.Button
End Class

```

## B.5 HELPBOX.VB

```

Public Class HelpBox
    'Code for the HelpBox form -- the form that shows when the User needs Help

    Private Sub Button1_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles Button1.Click
        'Hide the help box

        Me.Hide()

End Sub

```

```

Private Sub HelpBox_Load(ByVal sender As Object, ByVal e As
System.EventArgs) Handles Me.Load
    'Stuff for when the box is first loaded

    Dim GuideString As String = ""

    'MsgBox("You " & vbNewLine & " IDIOT")

    'Create the head text
    GuideString = My.Application.Info.CompanyName & " " &
My.Application.Info.ProductName & " v. " & My.Application.Info.Version.Major &
"." & My.Application.Info.Version.Minor & vbNewLine
    GuideString = GuideString & "Build " &
My.Application.Info.Version.Build & ", Revision " &
My.Application.Info.Version.Revision & vbNewLine
    GuideString = GuideString &
FileVersionInfo.GetVersionInfo(Reflection.Assembly.GetExecutingAssembly().Locat
ion).OriginalFilename & vbNewLine
    GuideString = GuideString & "File Version: " &
FileVersionInfo.GetVersionInfo(Reflection.Assembly.GetExecutingAssembly().Locat
ion).FileVersion & vbNewLine
    GuideString = GuideString & My.Application.Info.Copyright & vbNewLine &
vbNewLine & vbNewLine & vbNewLine

    'load the user's guide
    GuideString = GuideString & My.Resources.UserGuide.ToString

    'put it all in the text box
    GuideTextBox.Text = GuideString

    'set the initial location of the cursor
    GuideTextBox.SelectionStart = 0
    GuideTextBox.SelectionLength = 0

End Sub

End Class

```

## B.6 INSERTCOMMENT.DESIGNER.VB

```

<Global.Microsoft.VisualBasic.CompilerServices.DesignerGenerated()> _
Partial Class InsertComment
    Inherits System.Windows.Forms.Form

    'Form overrides dispose to clean up the component list.
    <System.Diagnostics.DebuggerNonUserCode()> _
    Protected Overrides Sub Dispose(ByVal disposing As Boolean)
        Try
            If disposing AndAlso components IsNot Nothing Then
                components.Dispose()
            End If
        Finally
            MyBase.Dispose(disposing)
        End Try
    End Sub

```

```

'Required by the Windows Form Designer
Private components As System.ComponentModel.IContainer

'NOTE: The following procedure is required by the Windows Form Designer
'It can be modified using the Windows Form Designer.
'Do not modify it using the code editor.
<System.Diagnostics.DebuggerStepThrough()> _
Private Sub InitializeComponent()
    Dim resources As System.ComponentModel.ComponentResourceManager = New
System.ComponentModel.ComponentResourceManager(GetType(InsertComment))
    Me.CommentOKButton = New System.Windows.Forms.Button
    Me.CommentCancelButton = New System.Windows.Forms.Button
    Me.CommentBox = New System.Windows.Forms.TextBox
    Me.SuspendLayout()
    '
    'CommentOKButton
    '
    Me.CommentOKButton.Location = New System.Drawing.Point(12, 231)
    Me.CommentOKButton.MaximumSize = New System.Drawing.Size(75, 23)
    Me.CommentOKButton.MinimumSize = New System.Drawing.Size(75, 23)
    Me.CommentOKButton.Name = "CommentOKButton"
    Me.CommentOKButton.Size = New System.Drawing.Size(75, 23)
    Me.CommentOKButton.TabIndex = 0
    Me.CommentOKButton.Text = "OK"
    Me.CommentOKButton.UseVisualStyleBackColor = True
    '
    'CommentCancelButton
    '
    Me.CommentCancelButton.Location = New System.Drawing.Point(205, 231)
    Me.CommentCancelButton.MaximumSize = New System.Drawing.Size(75, 23)
    Me.CommentCancelButton.MinimumSize = New System.Drawing.Size(75, 23)
    Me.CommentCancelButton.Name = "CommentCancelButton"
    Me.CommentCancelButton.Size = New System.Drawing.Size(75, 23)
    Me.CommentCancelButton.TabIndex = 1
    Me.CommentCancelButton.Text = "Cancel"
    Me.CommentCancelButton.UseVisualStyleBackColor = True
    '
    'CommentBox
    '
    Me.CommentBox.Location = New System.Drawing.Point(12, 12)
    Me.CommentBox.MaximumSize = New System.Drawing.Size(268, 213)
    Me.CommentBox.MinimumSize = New System.Drawing.Size(268, 213)
    Me.CommentBox.Multiline = True
    Me.CommentBox.Name = "CommentBox"
    Me.CommentBox.ScrollBars = System.Windows.Forms.ScrollBars.Vertical
    Me.CommentBox.Size = New System.Drawing.Size(268, 213)
    Me.CommentBox.TabIndex = 2
    '
    'InsertComment
    '
    Me.AutoScaleDimensions = New System.Drawing.SizeF(6.0!, 13.0!)
    Me.AutoScaleMode = System.Windows.Forms.AutoScaleMode.Font
    Me.ClientSize = New System.Drawing.Size(294, 275)
    Me.Controls.Add(Me.CommentBox)
    Me.Controls.Add(Me.CommentCancelButton)
    Me.Controls.Add(Me.CommentOKButton)
    Me.FormBorderStyle = System.Windows.Forms.FormBorderStyle.FixedDialog
    Me.Icon = CType(resources.GetObject("$this.Icon"), System.Drawing.Icon)

```

```

    Me.MaximizeBox = False
    Me.MaximumSize = New System.Drawing.Size(300, 300)
    Me.MinimizeBox = False
    Me.MinimumSize = New System.Drawing.Size(300, 300)
    Me.Name = "InsertComment"
    Me.ShowIcon = False
    Me.SizeGripStyle = System.Windows.Forms.SizeGripStyle.Hide
    Me.Text = "Insert a Comment"
    Me.ResumeLayout(False)
    Me.PerformLayout()

End Sub
Friend WithEvents CommentOKButton As System.Windows.Forms.Button
Friend WithEvents CommentCancelButton As System.Windows.Forms.Button
Friend WithEvents CommentBox As System.Windows.Forms.TextBox
End Class

```

## B.7 INSERTCOMMENT.VB

```

Public Class InsertComment
    'Code for the InsertComment form that shows when the User wants to insert a
    Comment into the Log

```

```

    Private Sub CommentCancelButton_Click(ByVal sender As System.Object, ByVal
e As System.EventArgs) Handles CommentCancelButton.Click
        'User Clicked Cancel Button

        'set the default comment
        CommentBox.Text = "(Insert Comment Here)"
        CommentBox.Select(0, CommentBox.TextLength)
        CommentBox.Focus()
        Me.Hide()

```

```

End Sub

```

```

    Private Sub CommentOKButton_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles CommentOKButton.Click
        'User Clicked OK button

        'Send the Comment to the Log
        Lumberjack.SendToLog("User Comment: " & CommentBox.Text)
        'set the default comment
        CommentBox.Text = "(Insert Comment Here)"
        CommentBox.Select(0, CommentBox.TextLength)
        CommentBox.Focus()
        Me.Hide()

```

```

End Sub

```

```

    Private Sub InsertComment_Shown(ByVal sender As Object, ByVal e As
System.EventArgs) Handles Me.Shown

```

```

'Form is Shown

'set the default comment
CommentBox.Text = "(Insert Comment Here)"
CommentBox.Select(0, CommentBox.TextLength)
CommentBox.Focus()
Application.DoEvents()

End Sub

```

```
End Class
```

## B.8 LONGSHOREMAN.VB

```
Option Explicit On
Option Strict On
```

```
Friend NotInheritable Class Longshoreman
```

```

'This class deals with managing the second serial port
'Its thread only runs if there is a second port in use
'However, it maintains the Laser Control Mode variable for the program
'
'

```

```

Friend Shared LaserPorter As New Thread(AddressOf
Longshoreman.SecondPortManager)
Friend Shared LaserControlMode As Long = 0
Friend Shared WithEvents COMPort2 As New System.IO.Ports.SerialPort
Friend Shared LaserPortLock As New Object

```

```

Private Shared Sub SecondPortManager()
'Only used in dual-port mode
'in dual-port mode, the laser is connected to a second serial port
'instead of piggy-backing on the speed controller port

```

```

Dim LocalExecutionStatus As Long
Dim LocalProgramExit As Boolean
Dim Proceed As Boolean
Dim LocalPortName As String
Dim LocalPortSpeed As Integer
Dim LocalPortDataBits As Integer
Dim LocalPortStopBits As System.IO.Ports.StopBits
Dim LocalPortFlowControl As System.IO.Ports.Handshake
Dim LocalPortEncoding As System.Text.Encoding
Dim LocalPortOpen As Boolean = False
Dim LocalRXString As String = ""
Dim LocalTXString As String = ""
Dim LocalRXChar(0) As Char
Dim CharactersRead As Integer = 0
Dim CharactersRemain As Boolean = False
Dim PreviousCharacterNewline As Boolean = False
Dim LastRXTimeTicks As Long = 0
Dim RXTimeoutToLogTicks As Long = 2500000

```

```

Dim BytesToSend() As Byte
Dim NumberBytes As Integer = 0
Dim SendRefObj As Object = CObj(0)
Dim ShortString As String = ""
Dim FoundLimit As Boolean = False
Dim SendLength As Integer = 0
Dim WriteNumber As Long = 0
Dim ClearForLaser As Boolean = False
Dim LaserEOL As String = ""
Dim RecentTX As Boolean = False

Try
    'much of this mirrors stuff that happens elsewhere in other Program
modes
    Thread.CurrentThread.Name = "LaserPorter"
    Proceed = False
    LocalRXChar(0) = CChar("")
    'wait for the speed control port to open
    Do
        'get speed control port status
        SyncLock Windowsill.RunBoxLock
            Proceed = Windowsill.SpeedControlReady
        End SyncLock
        'check for program exit condition
        SyncLock CentralClass.ProgramExitLock
            LocalProgramExit = CentralClass.ExitProgram
        End SyncLock
        If LocalProgramExit = True Then Proceed = True
        Application.DoEvents()
        System.Threading.Thread.Sleep(3500)
    Loop While Proceed = False

    'get port settings and try to open the port
    SyncLock CentralClass.FileOpsLock
        LocalPortName = CentralClass.LaserPort
        LocalPortSpeed = CentralClass.ComPortBaudRate
        LocalPortDataBits = CentralClass.ComPortDataBits
        LocalPortStopBits = CentralClass.ComPortStopBits
        LocalPortFlowControl = CentralClass.ComPortFlowControl
        LocalPortEncoding = CentralClass.ComPortEncoding
        LaserEOL = CentralClass.LaserNewlineString
    End SyncLock

    Proceed = False
    'open the port
    Do

        Try
            'log it
            Lumberjack.SendToLog("Attempting to open Laser Port (" &
LocalPortName & ") with the following settings: " & LocalPortSpeed.ToString &
" baud, " & LocalPortDataBits.ToString & " data bits, " &
LocalPortStopBits.ToString & " stop bits, flow control=" &
LocalPortFlowControl.ToString & ", and " & LocalPortEncoding.ToString & "
Encoding.")

            'set up and open the port
            SyncLock Longshoreman.LaserPortLock
                Longshoreman.COMPort2.PortName = LocalPortName
                Longshoreman.COMPort2.BaudRate = LocalPortSpeed

```

```

        Longshoreman.COMPort2.DataBits = LocalPortDataBits
        Longshoreman.COMPort2.StopBits = LocalPortStopBits
        Longshoreman.COMPort2.Handshake = LocalPortFlowControl
        Longshoreman.COMPort2.Encoding = LocalPortEncoding
        'set the read and write buffer size in bytes
        Longshoreman.COMPort2.ReadBufferSize = 16384
        Longshoreman.COMPort2.WriteBufferSize = 16384
        'open the port
        Longshoreman.COMPort2.Open()
        LocalPortOpen = Longshoreman.COMPort2.IsOpen
    End SyncLock
    'log the results
    If LocalPortOpen = True Then
        'success
        Lumberjack.SendToLog("Success in Opening the Laser Port
(" & LocalPortName & ")")
        'proceed with the program
        Proceed = True
    Else
        'some failure without an exception getting caught
        Lumberjack.SendToLog("Failure in Opening the Laser Port
(" & LocalPortName & ")")
        'see if user wants to try again
        If MsgBox("Failure in attempt to open the laser port "
& LocalPortName & vbNewLine & "Retry?", MsgBoxStyle.YesNo, "Laser Port
Problem") = MsgBoxResult.Yes Then
            'user wants to retry
            Lumberjack.SendToLog("Will retry opening laser
port")
        Else
            'user wants to abort
            Proceed = True
            Lumberjack.SendToLog("Abort opening laser port,
ending program")

            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
        End If
    End If
End If

    Catch SerialException As Exception
        Lumberjack.SendToLog("Exception in attempt to open the
laser port " & LocalPortName & ": " & vbNewLine & SerialException.Message)
        If MsgBox("Exception in attempt to open the laser port " &
LocalPortName & ": " & vbNewLine & SerialException.Message & vbNewLine &
"Retry?", MsgBoxStyle.YesNo, "Laser Port Problem") = MsgBoxResult.Yes Then
            'user wants to retry
            Lumberjack.SendToLog("Will retry opening laser port")
        Else
            'user wants to abort
            Proceed = True
            Lumberjack.SendToLog("Abort opening laser port, ending
program")

            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
        End If
    End If

End Try

```



```

        'Check to see if the program should exit
        SyncLock CentralClass.ProgramExitLock
            If CentralClass.ExitProgram = True Then
                Proceed = True
                LocalProgramExit = True
            End If
        End SyncLock
    Loop While Proceed = False

    'signal that the program is ready
    SyncLock Windowsill.RunBoxLock
        Windowsill.LaserPortReady = True
    End SyncLock

    'main part of the program
    'it doesn't care if the program is in early shutdown or pure
operation
    'so it does the same loop until the correct shutdown stage is
reached
    Do
        SyncLock CentralClass.ProgramExitLock
            LocalExecutionStatus = CentralClass.ExecutionStage
        End SyncLock
        System.Threading.Thread.Sleep(65)
        Application.DoEvents()
    '
    'get data from the port
    SyncLock Longshoreman.LaserPortLock
        LocalPortOpen = Longshoreman.COMPort2.IsOpen
    End SyncLock

    If LocalPortOpen = True Then
        'grab the characters buffered by the serialport one at a
time
        Do
            'read one character from the port, if there are any
            SyncLock Longshoreman.LaserPortLock
                If Longshoreman.COMPort2.BytesToRead > 0 Then
                    CharactersRead =
Longshoreman.COMPort2.Read(LocalRXChar, 0, 1)
                    'remember the last rx read time
                    LastRXTimeTicks = Now.Ticks
                Else
                    'no characters read
                    CharactersRead = 0
                End If
            End SyncLock
            If CharactersRead > 0 Then
                'characters were actually read, process the data
                'check for cr or lf
                If (LocalRXChar(0).ToString = vbCr) Or
(LocalRXChar(0).ToString = vbLf) Then
                    'current character is a newline sort of thing
                    If PreviousCharacterNewline = True Then
                        'previous character was a newline sort of
character
                    'so is the current line

```

```

'log it all and clear the
previouscharacternewline condition
PreviousCharacterNewline = False
LocalRXString = LocalRXString &

LocalRXChar(0).ToString
'send it all to the runbox
SyncLock Windowsill.RunBoxLock
    Windowsill.LaserRX = Windowsill.LaserRX
& LocalRXString
End SyncLock
'log it
Lumberjack.SendToLog("RX From Laser: " &
LocalRXString)
'clear the string
LocalRXString = ""
Else
'previous character was NOT a newline
character
'but the current line is
'append it to the local rx string, but wait
before logging
PreviousCharacterNewline = True
LocalRXString = LocalRXString &
LocalRXChar(0)
End If
ElseIf PreviousCharacterNewline = True Then
'previous but not current character was a
newline
'send the previous data where they all belong
'send it all to the runbox
SyncLock Windowsill.RunBoxLock
    Windowsill.LaserRX = Windowsill.LaserRX &
LocalRXString
End SyncLock
'log it
Lumberjack.SendToLog("RX From Laser: " &
LocalRXString)
'clear the local rx string and put the current
character in it
LocalRXString = LocalRXChar(0).ToString
PreviousCharacterNewline = False
Else
'neither the current nor the last character
were newlines
'append the received character to the local rx
string
LocalRXString = LocalRXString &
LocalRXChar(0).ToString
End If
'
End If

'check for remaining characters
SyncLock Longshoreman.LaserPortLock
    If Longshoreman.COMPort2.BytesToRead > 0 Then
        'data remains
        CharactersRemain = True
    Else
        CharactersRemain = False
    End If

```

```

        'no data left
    End If
    End SyncLock
    Loop While CharactersRemain = True
End If

'check for time to dump the rx data to the log
'only if it hasn't received anything in the timeout period
If (Now.Ticks - LastRXTimeTicks) > RXTimeoutToLogTicks Then
    'last rx time was more than one timeout ago
    'if there's data to log, log it
    If LocalRXString <> "" Then
        'stuff to log
        'send it all to the runbox
        SyncLock Windowsill.RunBoxLock
            Windowsill.LaserRX = Windowsill.LaserRX &
LocalRXString
        End SyncLock
        'log it
LocalRXString)
        Lumberjack.SendToLog("RX From Laser: " &
            'clear the string
            LocalRXString = ""
        End If
    End If
End If

'write block

'tell fire control to hold off momentarily
SyncLock Stevedore.SpeedPortLock
    Stevedore.ClearToFireLaser = False
End SyncLock

'send data to port here
'get any data
RecentTX = False
SyncLock Windowsill.RunBoxLock
    LocalTXString = LocalTXString & Windowsill.CommandToLaser
    'got the data, clear the shared variable
    Windowsill.CommandToLaser = ""
End SyncLock
'only send when the output buffer is empty to ensure it goes in
the correct order
If LocalTXString <> "" Then
    'set the transmission flag for later use
    RecentTX = True
    'check for an empty buffer
    SyncLock Longshoreman.LaserPortLock
        If Longshoreman.COMPort2.BytesToWrite = 0 Then
            'empty buffer, write data
            'localportencoding
            If LocalPortEncoding.GetByteCount(LocalTXString) >
Longshoreman.COMPort2.WriteBufferSize Then
                'too many characters
                'split the write in half in a loop until it
fits
                FoundLimit = False
                SendLength = LocalTXString.Length
                Do

```

```

        SendLength = CInt(SendLength / 2)
        'see if the max bytes from that can be
buffered
        If
LocalPortEncoding.GetMaxByteCount(SendLength) <
Longshoreman.COMPort2.WriteBufferSize Then
            'it works
            FoundLimit = True
            ElseIf SendLength < 10 Then
                'it should be longer, something is
really wrong
                'proceed anyway
                FoundLimit = True
            End If
            Loop While FoundLimit = False
            'get the string to send
            ShortString = LocalTXString.Substring(0,
SendLength)
            'and remove it from the local tx string
            LocalTXString = LocalTXString.Remove(0,
SendLength)
            'encode the string
            BytesToSend =
LocalPortEncoding.GetBytes(ShortString)
            NumberBytes = BytesToSend.Length
            'now it's ready to write
            Else
                'everything can fit in the buffer immediately
                'encode the string
                BytesToSend =
LocalPortEncoding.GetBytes(LocalTXString)
                NumberBytes = BytesToSend.Length
                'clear the local string
                LocalTXString = ""
                'ready to send
            End If
            'write it to the serial port output asynchronously
            SendRefObj = CObj(WriteNumber)

Longshoreman.COMPort2.BaseStream.BeginWrite(BytesToSend, 0, NumberBytes,
AddressOf Longshoreman.FinishedComPort2Send, SendRefObj)
                WriteNumber += 1
            End If
        End SyncLock
    End If

    'Update Laser Fire Control
    ClearForLaser = True
    'check for request to fire
    If ClearForLaser = True Then
        SyncLock Windowsill.RunBoxLock
            If Windowsill.LaserTXDataCritical = False Then
                'laser not in firing sequence, laser is not clear
to fire
                ClearForLaser = False
            End If
        End SyncLock
    End If
    'check saved data

```

```

        If LocalTXString <> "" Then
            'there's saved data to be transmitted, laser is not clear
to fire
            ClearForLaser = False
        End If
        'check available data
        If ClearForLaser = True Then
            SyncLock Windowsill.RunBoxLock
                If Windowsill.CommandToLaser <> "" Then
                    'there's data left to be loaded and transmitted,
laser is not clear to fire
                    ClearForLaser = False
                End If
            End SyncLock
        End If
        'check buffered data
        If ClearForLaser = True Then
            SyncLock Longshoreman.LaserPortLock
                If Longshoreman.COMPort2.BytesToWrite <> 0 Then
                    'there's buffered data in transmission, laser is
not clear to fire
                    ClearForLaser = False
                End If
            End SyncLock
        End If
        If RecentTX = True Then
            'don't signal a clear line just yet
            ClearForLaser = False
        End If
        'send value to fire control
        SyncLock Stevedore.SpeedPortLock
            Stevedore.ClearToFireLaser = ClearForLaser
        End SyncLock

    Loop While LocalExecutionStatus < 1020

    'signal fire control to that the laser is not clear to fire
    SyncLock Stevedore.SpeedPortLock
        Stevedore.ClearToFireLaser = False
    End SyncLock

    'close the port
    Try
        'if the port was opened, close it
        If LocalPortOpen = True Then
            'log it
            Lumberjack.SendToLog("Attempting to Close the Laser Port ("
& LocalPortName & ")")
            'send final string to the laser port, if there is one
            'get any data
            SyncLock Windowsill.RunBoxLock
                LocalTXString = LocalTXString &
Windowsill.CommandToLaser
                Windowsill.CommandToLaser = ""
            End SyncLock
            'transmit any data
            LocalTXString = LocalTXString & LaserEOL

        Try

```

```

        'perform the write
        SyncLock Longshoreman.LaserPortLock
            Longshoreman.COMPort2.Write(LocalTXString)
        End SyncLock
    Catch FinishedWriteException As Exception
        'log the issue
        Lumberjack.SendToLog("Exception in final write on " &
LocalPortName & ": " & FinishedWriteException.Message)
    End Try

    System.Threading.Thread.Sleep(250)
    'get all the data from the port, then close it
    SyncLock Longshoreman.LaserPortLock
        If Longshoreman.COMPort2.IsOpen = True Then
            LocalRXString = LocalRXString &
Longshoreman.COMPort2.ReadExisting()
            'the port is open, close it
            Longshoreman.COMPort2.Close()
            Longshoreman.COMPort2.Dispose()
        End If
        LocalPortOpen = Longshoreman.COMPort2.IsOpen
    End SyncLock
    System.Threading.Thread.Sleep(1000)
    'log success/failure to close the port
    If LocalPortOpen = True Then
        'port is still open, log an error
        Lumberjack.SendToLog("Laser Port (" & LocalPortName &
") did not close successfully")
    Else
        'port closed
        Lumberjack.SendToLog("Successfully Closed the Laser
Port (" & LocalPortName & ")")
    End If
    End If

    Catch SerialPortClosureProblem As Exception
        'log it
        Lumberjack.SendToLog("Exception while attempting to close the
Laser Port (" & LocalPortName & "): " & vbNewLine &
SerialPortClosureProblem.Message)
    End Try

    'send the output where it belongs
    If LocalRXString <> "" Then
        'log the final rx string
        Lumberjack.SendToLog("Final Text Received from the Laser: " &
LocalRXString)
        'mirror it on the runbox
        SyncLock Windowsill.RunBoxLock
            Windowsill.LaserRX = Windowsill.LaserRX & LocalRXString
        End SyncLock
        'clear the string
        LocalRXString = ""
    End If

    System.Threading.Thread.Sleep(3000)
    'log termination
    Lumberjack.SendToLog("Laser Port Module Stopping")

```

```

        Catch ThreadNeededKilling As ThreadAbortException
            'the thread was aborted
            Application.ExitThread()
        Catch BigException As Exception
            'something got really screwed up
            Lumberjack.SendToLog("Exception in " & Thread.CurrentThread.Name &
": " & BigException.Message & vbNewLine & "Details: " & vbNewLine &
BigException.ToString)
            MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
        End Try

        Application.ExitThread()

    End Sub

```

```

    Private Shared Sub FinishedComPort2Send(ByVal TXResult As
System.IAsyncResult)
        'gets called in asynchronous writes to the laser port
        'when they finish transmitting data

        Try
            SyncLock Longshoreman.LaserPortLock
                'end the (completed) write
                Longshoreman.COMPort2.BaseStream.EndWrite(TXResult)
            End SyncLock
        Catch ex As Exception
            'something went wrong
            'log the error
            Lumberjack.SendToLog("Exception in the result of transmission to
laser: " & ex.Message)
            Lumberjack.SendToLog("Exception Data: " &
TXResult.AsyncState.ToString())
        End Try

    End Sub

```

```

End Class

```

## **B.9 LUMBERJACK.VB**

```

Option Explicit On

```

```

Option Strict On

```

```

Friend NotInheritable Class Lumberjack

```

```

    'This class contains the logging system

```

```

    'It executes in a thread, here the BostonLogger

```

```

'Before the thread is launched, the OutputLogFile needs to be opened for
writing
'This must be done by an outside routine, not here
,
,
Friend Shared BostonLogger As New Thread(AddressOf Lumberjack.LogWriter)
Friend Shared OutputLogFile As System.IO.TextWriter
Friend Shared LogFileLock As New Object
Private Shared NextOutputString As String = ""
Private Shared TimberLock As New Object
Private Shared LogDividerString As String =
"=====

Private Shared Function BannerInfo() As String
'hands the startup info to the logger

Dim NextString As String = ""
Dim DividerString As String = Lumberjack.LogDividerString

SyncLock CentralClass.FileOpsLock
'startup banner
NextString = vbNewLine & vbNewLine & DividerString & vbNewLine
NextString = NextString & My.Application.Info.CompanyName & " " &
My.Application.Info.ProductName & " v. " & My.Application.Info.Version.Major &
"." & My.Application.Info.Version.Minor & vbNewLine
NextString = NextString & "Build " &
My.Application.Info.Version.Build & ", Revision " &
My.Application.Info.Version.Revision & vbNewLine
NextString = NextString &
FileVersionInfo.GetVersionInfo(Reflection.Assembly.GetExecutingAssembly().Locat
ion).OriginalFilename & " File Version: " &
FileVersionInfo.GetVersionInfo(Reflection.Assembly.GetExecutingAssembly().Locat
ion).FileVersion & vbNewLine
NextString = NextString & DividerString & vbNewLine
'give the filename
NextString = NextString & "Log File: " & vbNewLine &
System.IO.Path.GetFullPath(CentralClass.Filename) & vbNewLine
'give append/replace flag
If CentralClass.AppendFile = True Then
NextString = NextString & "Appending any existing file." &
vbNewLine
Else
NextString = NextString & "Replacing any existing file." &
vbNewLine
End If
'reflect status of advanced timing features
NextString = NextString & "Advanced Timing Features: "
If CentralClass.AdvancedTiming = True Then
NextString = NextString & "Enabled" & vbNewLine
Else
NextString = NextString & "Disabled" & vbNewLine
End If
'give selected ports, speed, and start time
NextString = NextString & "Speed Controller Port: " &
CentralClass.SpeedPort & vbNewLine
NextString = NextString & "Laser Port: " & CentralClass.LaserPort
& vbNewLine

```



```

        NextString = NextString & "Port Speed: " &
CentralClass.ComPortBaudRate & " baud" & vbNewLine
        NextString = NextString & "Program Startup: " &
CentralClass.ProgramStartTime & vbNewLine
        NextString = NextString & DividerString
        NextString = NextString & Lumberjack.LogStamp & "Begin Logging"
    End SyncLock

    BannerInfo = NextString

End Function

Private Shared Sub SawmillEcho(ByVal Logged As String)

    'This directs the data logged back out to the runbox mirror

    SyncLock Windowsill.RunBoxLock
        'echo the data to the RunBox
        Windowsill.LogWritten = Windowsill.LogWritten & Logged
    End SyncLock

End Sub

Private Shared Function LogStamp() As String

    'gives a new line and the formatted time stamp for the log

    LogStamp = vbNewLine & "[" & Format(Now(), "MM/dd/yyyy HH:mm:ss.ff") &
"]: "

End Function

Public Shared Sub SendToLog(ByVal ToLog As String)

    'sends the input string to the log file
    SyncLock Lumberjack.TimberLock
        Lumberjack.NextOutputString = Lumberjack.NextOutputString &
LogStamp() & ToLog
    End SyncLock

    'evidently the thread.interrupt method is dangerous, so it's commented
out here

    'Try
    '    'if the logger is asleep, wake it
    '    If Lumberjack.BostonLogger.ThreadState =
Threading.ThreadState.WaitSleepJoin Then
    '        Lumberjack.BostonLogger.Interrupt()
    '    End If
    'Catch SomethingUnexpected As Exception
    '    Beep()
    '    'No exceptions are actually expected to ever appear here
    '    'If they do, they probably can't be logged

```

```

'End Try

End Sub

Private Shared Sub LogWriter()
    'this is meant to run in its own thread and send the log queue to the
log file
    'it echoes it to the runbox form as well through the SawmillEcho sub

    Dim NextString As String = ""
    Dim LocalProgramExit As Boolean = False
    Dim DeltaTicks As Long
    Dim LastFlush As Long
    Dim LocalExecutionStage As Long
    Dim LocalTimeoutCounter As Long
    Dim LocalTimeoutDelay As Long
    Dim MaxCharacterTransfer As Integer = 32767
    Dim CharactersToTransfer As Integer = 0
    Dim DividerString As String = Lumberjack.LogDividerString

    'trap otherwise unhandled exceptions, kill the thread if any pop up
Try
    'startup stuff
    Thread.CurrentThread.Name = "Boston_Logger"
    'set the flush frequency to ~10 seconds
    DeltaTicks = 100000000
    'set timeout to ~1000 seconds
    LocalTimeoutDelay = 10000000000
    NextString = BannerInfo()
    SyncLock Lumberjack.TimberLock
        'purge the next output string, if it already has data
        If Lumberjack.NextOutputString <> "" Then
            'don't get more characters than the i/o can handle
            If NextString.Length + Lumberjack.NextOutputString.Length >
MaxCharacterTransfer Then
                'too long for a single operation
                'only do one, hold the rest over for the main loop
                'next if-then is really only a formality
                If NextString.Length < MaxCharacterTransfer Then
                    'we can append it, so do so
                    CharactersToTransfer = MaxCharacterTransfer -
NextString.Length
                    NextString = NextString &
Lumberjack.NextOutputString.Substring(0, CharactersToTransfer)
                    'remove the transferred characters
                    Lumberjack.NextOutputString =
Lumberjack.NextOutputString.Remove(0, CharactersToTransfer)
                End If
            Else
                'short enough for a single operation
                NextString = NextString & Lumberjack.NextOutputString
                Lumberjack.NextOutputString = ""
            End If
        End If
    End SyncLock

    'now write the startup material to the log file

```

```

SyncLock Lumberjack.LogFileLock
    Try
        Lumberjack.OutputLogFile.Write(NextString)
        LastFlush = Now.Ticks
        Lumberjack.OutputLogFile.Flush()
    Catch ex As Exception
        MsgBox("An exception has occurred in " &
Thread.CurrentThread.Name & " and the program will shut down" & vbNewLine &
ex.Message, , "OUCH!")
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
        SyncLock Lumberjack.TimberLock
            Lumberjack.NextOutputString =
Lumberjack.NextOutputString & Lumberjack.LogStamp & "System Error: " &
ex.Message
        End SyncLock
    End Try
End SyncLock

'copy the initial logging to the runbox
Lumberjack.SawmillEcho(NextString)

'clear the output string
NextString = ""

'now loop for the main operation
Do
    'check for new data
    SyncLock Lumberjack.TimberLock

        'check for new data
        If Lumberjack.NextOutputString <> "" Then
            'don't get more characters than the i/o can handle
            If Lumberjack.NextOutputString.Length >
MaxCharacterTransfer Then
                'too long for a single operation
                'only do one, leave the rest
                CharactersToTransfer = MaxCharacterTransfer
                NextString =
Lumberjack.NextOutputString.Substring(0, CharactersToTransfer)
                'remove the transferred characters
                Lumberjack.NextOutputString =
Lumberjack.NextOutputString.Remove(0, CharactersToTransfer)
            Else
                'short enough for a single operation
                NextString = NextString &
Lumberjack.NextOutputString
                Lumberjack.NextOutputString = ""
            End If
        End If
    End SyncLock

    'write any new data to the disk and RunBox
    If NextString <> "" Then
        SyncLock Lumberjack.LogFileLock
            'write the data
            Try
                Lumberjack.OutputLogFile.Write(NextString)

```

```

        'check to see if it's time to flush the cache
        If (Now.Ticks - LastFlush) > DeltaTicks Then
            'time to flush
            LastFlush = Now.Ticks
            Lumberjack.OutputLogFile.Flush()
        End If
        Catch ex As Exception
            MsgBox("An exception has occurred in " &
Thread.CurrentThread.Name & " and the program will shut down" & vbNewLine &
ex.Message, , "OUCH!")
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
            SyncLock Lumberjack.TimberLock
                Lumberjack.NextOutputString =
Lumberjack.NextOutputString & Lumberjack.LogStamp & "System Error: " &
ex.Message
            End SyncLock
        End Try
    End SyncLock
    Lumberjack.SawmillEcho(NextString)
    'clear the string
    NextString = ""
End If

    'wait
    Try
        'this was 55 ms, but that expected a thread.interrupt
method, which has turned out to be dangerous
        'so the sleep period was shortened instead
        System.Threading.Thread.Sleep(35)
    Catch ex As ThreadInterruptedException
        'sleep was interrupted
    Exit Try
    End Try
    Application.DoEvents()
    'get exit status
    SyncLock CentralClass.ProgramExitLock
        LocalProgramExit = CentralClass.ExitProgram
    End SyncLock

    Loop While LocalProgramExit = False

    'put shutdown matter here
    LocalTimeoutCounter = Now.Ticks

    Do
        'wait for the correct time to shut all the way down
        'in the meantime, continue to log, but do not echo to runbox if
its exit level has been reached
        'check for new data
        SyncLock Lumberjack.TimberLock
            'check for new data
            If Lumberjack.NextOutputString <> "" Then
                'don't get more characters than the i/o can handle
                If Lumberjack.NextOutputString.Length >
MaxCharacterTransfer Then
                    'too long for a single operation
                    'only do one, leave the rest

```

```

        CharactersToTransfer = MaxCharacterTransfer
        NextString =
Lumberjack.NextOutputString.Substring(0, CharactersToTransfer)
        'remove the transferred characters
        Lumberjack.NextOutputString =
Lumberjack.NextOutputString.Remove(0, CharactersToTransfer)
        Else
            'short enough for a single operation
            NextString = NextString &
Lumberjack.NextOutputString
            Lumberjack.NextOutputString = ""
        End If
    End If
End SyncLock
'write any new data to the disk
If NextString <> "" Then
    SyncLock Lumberjack.LogFileLock
        'write the data
        Try
            Lumberjack.OutputLogFile.Write(NextString)
        Catch ex As Exception
            MsgBox("An exception has occurred in " &
Thread.CurrentThread.Name & " and the program will shut down" & vbNewLine &
ex.Message, , "OUCH!")
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
            SyncLock Lumberjack.TimberLock
                Lumberjack.NextOutputString =
Lumberjack.NextOutputString & Lumberjack.LogStamp & "System Error: " &
ex.Message
            End SyncLock
        End Try
    End SyncLock
    If LocalExecutionStage < 1050 Then
        'User Interface should still be running
        Lumberjack.SawmillEcho(NextString)
    End If
    'clear the string
    NextString = ""
End If
Try
    System.Threading.Thread.Sleep(55)
Catch ex As ThreadInterruptedException
    'sleep was interrupted
    Exit Try
End Try
Application.DoEvents()
SyncLock CentralClass.ProgramExitLock
    'get the program execution stage
    LocalExecutionStage = CentralClass.ExecutionStage
End SyncLock
'nominally, loop until the proper shutdown stage is reached
before exiting
    'but if it takes too long then exit after a timeout
    Loop While ((Now.Ticks - LocalTimeoutCounter) < LocalTimeoutDelay)
And (LocalExecutionStage < 1100)

'Final Shutdown Stage for Logging

```

```

'proceed to exit
Do
    'loop until all the log material is gathered

    'check for new data
    SyncLock Lumberjack.TimberLock
        'check for new data
        If Lumberjack.NextOutputString <> "" Then
            'don't get more characters than the i/o can handle
            If Lumberjack.NextOutputString.Length >
MaxCharacterTransfer Then
                'too long for a single operation
                'only do one, leave the rest
                CharactersToTransfer = MaxCharacterTransfer
                NextString =
Lumberjack.NextOutputString.Substring(0, CharactersToTransfer)
                'remove the transferred characters
                Lumberjack.NextOutputString =
Lumberjack.NextOutputString.Remove(0, CharactersToTransfer)
            Else
                'short enough for a single operation
                NextString = NextString &
Lumberjack.NextOutputString
                Lumberjack.NextOutputString = ""
            End If
        End If
    End SyncLock

    'write gathered data
    If NextString <> "" Then
        SyncLock Lumberjack.LogFileLock
            'write the data
            Try
                Lumberjack.OutputLogFile.Write(NextString)
            Catch ex As Exception
                MsgBox("An exception has occurred in " &
Thread.CurrentThread.Name & " and the program will shut down" & vbNewLine &
ex.Message, , "OUCH!")

                SyncLock CentralClass.ProgramExitLock
                    CentralClass.ExitProgram = True
                End SyncLock
                SyncLock Lumberjack.TimberLock
                    Lumberjack.NextOutputString =
Lumberjack.NextOutputString & Lumberjack.LogStamp & "System Error: " &
ex.Message

                End SyncLock
            End Try
        End SyncLock
        'clear the string
        NextString = ""
    End If

    'see if there's additional data
    SyncLock Lumberjack.TimberLock
        'get number of remaining characters
        CharactersToTransfer = Lumberjack.NextOutputString.Length
    End SyncLock

Loop While CharactersToTransfer > 0

```

```

        NextString = NextString & Lumberjack.LogStamp & "End Logging" &
vbNewLine & DividerString & vbNewLine
        'write any new data to the disk
        If NextString <> "" Then
            SyncLock Lumberjack.LogFileLock
                'write the data
                Try
                    Lumberjack.OutputLogFile.Write(NextString)
                Catch ex As Exception
                    MsgBox("An exception has occurred in " &
Thread.CurrentThread.Name & " and the program will shut down" & vbNewLine &
ex.Message, , "OUCH!")
                    SyncLock CentralClass.ProgramExitLock
                        CentralClass.ExitProgram = True
                    End SyncLock
                    SyncLock Lumberjack.TimberLock
                        Lumberjack.NextOutputString =
Lumberjack.NextOutputString & Lumberjack.LogStamp & "System Error: " &
ex.Message
                    End SyncLock
                End Try
            End SyncLock
            'clear the string
            NextString = ""
        End If
        SyncLock Lumberjack.LogFileLock
            Try
                'time to flush
                Lumberjack.OutputLogFile.Flush()
                'close the file
                Lumberjack.OutputLogFile.Close()
            Catch ex As Exception
                MsgBox("An exception has occurred in " &
Thread.CurrentThread.Name & " and the program will shut down" & vbNewLine &
ex.Message, , "OUCH!")
                SyncLock CentralClass.ProgramExitLock
                    CentralClass.ExitProgram = True
                End SyncLock
                SyncLock Lumberjack.TimberLock
                    Lumberjack.NextOutputString =
Lumberjack.NextOutputString & Lumberjack.LogStamp & "System Error: " &
ex.Message
                End SyncLock
            End Try
        End SyncLock

        Catch ThreadNeededKilling As ThreadAbortException
            'the thread was aborted
            Application.ExitThread()
        Catch BigException As Exception
            'something got really screwed up
            MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
        End Try
    End Try

```

```

        Application.ExitThread()
    End Sub

End Class

```

## B.10 MAINCODE.VB

```

Option Explicit On
Option Strict On

'Imports System.Security.AccessControl

Module MainCode

    Public Declare Function QueryPerformanceCounter Lib "kernel32" (ByRef
lpPerformanceCount As Long) As Long
    Public Declare Function QueryPerformanceFrequency Lib "kernel32" (ByRef
lpFrequency As Long) As Long

    Private Declare Function timeBeginPeriod Lib "winmm.dll" (ByVal uPeriod As
UInt32) As UInt32
    Private Declare Function timeEndPeriod Lib "winmm.dll" (ByVal uPeriod As
UInt32) As UInt32
    Private Declare Function timeGetTime Lib "winmm.dll" () As UInt32

    Private uPeriod As UInt32 = CUInt(1)

Sub Main()

    'Declarations
    Dim ComPortName As String = ""
    Dim LocalExit As Boolean = False
    Dim a As Long = 0
    Dim FileValid As Boolean = True
    Dim ThreadsLaunched As Boolean = False
    Dim LocalLaserControlMode As Long
    'Dim OutputLogFileACL As FileSecurity
    '

    'Initialization

    'set the system timer to update at 1 ms intervals (normally 15.6),
which is the max
    'the following timeBeginPeriod API call MUST have a corresponding
timeEndPeriod API call!!!!!!!!!!!!!!
    timeBeginPeriod(uPeriod)
    'it will appear at the end of the program

    Application.EnableVisualStyles()

```



```

SyncLock CentralClass.FileOpsLock
    'record the starting time
    If TimeZone.CurrentTimeZone.IsDaylightSavingTime(Now()) = True Then
        'daylight saving time
        CentralClass.ProgramStartTime = Format(Now(), "MMMM d, yyyy
HH:mm:ss ") & TimeZone.CurrentTimeZone.DaylightName
    Else
        'standard time
        CentralClass.ProgramStartTime = Format(Now(), "MMMM d, yyyy
HH:mm:ss ") & TimeZone.CurrentTimeZone.StandardName
    End If

End SyncLock

'set the process priority
Process.GetCurrentProcess.PriorityClass =
ProcessPriorityClass.AboveNormal
Thread.CurrentThread.Name = "Launcher"

HelpBox.Hide()

SyncLock Windowsill.RunBoxLock
    Windowsill.SpeedControlReady = False
    Windowsill.LaserPortReady = False
End SyncLock

SyncLock CentralClass.ProgramExitLock
    CentralClass.ExitProgram = False
    CentralClass.ExecutionStage = 0
End SyncLock

StartupForm.Panell.BorderStyle = BorderStyle.Fixed3D
For Each ComPortName In My.Computer.Ports.SerialPortNames
    'Adds the computer's serial ports to port list
    StartupForm.ControllerPortComboBox.Items.Add(ComPortName)
    StartupForm.LaserPortComboBox.Items.Add(ComPortName)
Next

Do
    StartupForm.ShowDialog()
    SyncLock CentralClass.ProgramExitLock
        LocalExit = CentralClass.ExitProgram
    End SyncLock
    If LocalExit = True Then
        'The User has chosen to Exit the application
        Beep()
        Exit Do
    Else
        'proceed with the program
        FileValid = True
        'check for valid filename
        SyncLock CentralClass.FileOpsLock
            'check for valid name
            Try
                System.IO.Path.GetFullPath(CentralClass.Filename)
            Catch ex As Exception

```

```

        'invalid filename
        FileValid = False
        'alert the user
        Beep()
        MsgBox("The file " & CentralClass.Filename & " has
resulted in an exception: " & vbNewLine & ex.Message)
        End Try

        'check if file, not directory, and for a good location
        If FileValid = True Then
            Try
                'see if file exists; if it does, make sure it's not
a directory or read-only
                If System.IO.File.Exists(CentralClass.Filename) =
True Then

                    'it exists; check for directory status
                    Try
                        If
(System.IO.File.GetAttributes(CentralClass.Filename) And
System.IO.FileAttributes.Directory) = System.IO.FileAttributes.Directory Then
                            'it's a directory
                            FileValid = False
                            Beep()
                            MsgBox(CentralClass.Filename & " is a
directory. Please choose something else.")
                        End If
                        Catch ex1 As Exception
                            'invalid filename or something
                            FileValid = False
                            'alert the user
                            Beep()
                            MsgBox("The file " & CentralClass.Filename
& " has resulted in an exception: " & vbNewLine & ex1.Message)
                        End Try

                        'check for read-only
                        Try
                            If
(System.IO.File.GetAttributes(CentralClass.Filename) And
System.IO.FileAttributes.ReadOnly) = System.IO.FileAttributes.ReadOnly Then
                                'it's read-only
                                FileValid = False
                                Beep()
                                MsgBox(CentralClass.Filename & " is a
read-only file. Please choose something else.")
                            End If
                            Catch ex1 As Exception
                                'invalid filename or something
                                FileValid = False
                                'alert the user
                                Beep()
                                MsgBox("The file " & CentralClass.Filename
& " has resulted in an exception: " & vbNewLine & ex1.Message)
                            End Try

                                'check for write and modify permissions
                                'maybe we'll just do this later by actually
opening the file

```

```

        'Try
        ' 'get the ACL
        '   OutputLogFileACL =
File.GetAccessControl(CentralClass.Filename, AccessControlSections.All)
        '
'MsgBox(OutputLogFileACL.GetAccessRules(True, True,
GetType(System.Security.Principal.NTAccount)))
        '   'If (OutputLogFileACL.GetAccessRules(True,
True, GetType(FileSystemRights)) And FileSystemRights.Write) <>
FileSystemRights.Write Then
        '   'no write permission
        '   FileValid = False
        '   Beep()
        '   Dim accessrules =
OutputLogFileACL.GetAccessRules(True, True,
GetType(System.Security.Principal.NTAccount))
        '   accessrules()
        '   For Each rule As
System.Security.AccessControl.FileSystemAccessRule In accessRules
        '       MsgBox(rule.IdentityReference.Value)
        '
MsgBox(rule.AccessControlType.ToString())
        '
MsgBox(rule.FileSystemRights.ToString())
        '   Next

        '   MsgBox(CentralClass.Filename & " is not
writable by you. Please choose something else.")
        '   'End If
'Catch ex1 As Exception
        '   'invalid filename or something
        '   FileValid = False
        '   'alert the user
        '   Beep()
        '   MsgBox("The file " & CentralClass.Filename
& " has resulted in an exception: " & vbNewLine & ex1.Message)
'End Try

'see if the user REALLY wants to modify the
file
        If FileValid = True Then
            Beep()
            If (CentralClass.AppendFile = True) Then
                'for append
                If MsgBox("The file " & vbNewLine &
CentralClass.Filename & vbNewLine & "already exists. Do you really want to
append it?", MsgBoxStyle.YesNo, "Pin a tail on a donkey?") <> MsgBoxResult.Yes
Then
                    'chose not to add on to it
                    FileValid = False
                End If
            Else
                'for replace
                If MsgBox("The file " & vbNewLine &
CentralClass.Filename & vbNewLine & "already exists. Do you really want to
replace it? " & vbNewLine & vbNewLine & "THIS WILL ERASE ALL DATA CURRENTLY IN
THE FILE", MsgBoxStyle.YesNo, "Wash your brains?") <> MsgBoxResult.Yes Then
                    'chose not to add on to it
                    FileValid = False
                End If
            End If
        End If
    End Try
End Sub

```

```

                End If
            End If
        End If

        Else
            'the file does not already exist, see if the
directory does
            Try
                If
System.IO.Directory.Exists(System.IO.Path.GetDirectoryName(CentralClass.FileName
e)) = False Then
                    'path does not exist
                    FileValid = False
                    Beep()
                    MsgBox(CentralClass.Filename & " does
not have a valid path. Please choose something else.")
                End If
                Catch ex1 As Exception
                    'invalid filename or something
                    FileValid = False
                    'alert the user
                    Beep()
                    MsgBox("The file " & CentralClass.Filename
& " has resulted in an exception: " & vbNewLine & ex1.Message)
                End Try
            End If

            Catch ex As Exception
                'invalid filename
                FileValid = False
                'alert the user
                Beep()
                MsgBox("The file " & CentralClass.Filename & " has
resulted in an exception: " & vbNewLine & ex.Message)
            End Try

        End If

        'prevent the creation of blank files due to no speed port
selection
        SyncLock CentralClass.FileOpsLock
            If CentralClass.SpeedPort = "(none)" Then
                FileValid = False
                Exit Do
            End If
        End SyncLock

        'Now see if we can open the file for editing
        If FileValid = True Then
            SyncLock Lumberjack.LogFileLock
                'try opening the file for writing

                Try
                    Lumberjack.OutputLogFile =
System.IO.TextWriter.Synchronized(My.Computer.FileSystem.OpenTextFileWriter(Cen
tralClass.Filename, CentralClass.AppendFile))
                Catch ex As Exception
                    'something did not work

```

```

        FileValid = False
        'alert the user
        Beep()
        MsgBox("The file " & CentralClass.Filename & "
has resulted in an exception: " & vbCrLf & ex.Message)
        End Try

        End SyncLock

        End If

        End SyncLock
    End If
Loop While FileValid = False

HelpBox.Hide()

'just an end program box
'TestEnder.Show()
Application.DoEvents()

Thread.CurrentThread.Priority = ThreadPriority.AboveNormal
'Get ready to launch the other threads
SyncLock CentralClass.ProgramExitLock
    LocalExit = CentralClass.ExitProgram
End SyncLock

'check for a selected speed controller port, and see if there is a
laser port
If LocalExit = False Then
    SyncLock CentralClass.FileOpsLock
        'see if a port was chosen for the speed controller
        If CentralClass.SpeedPort = "(none)" Then
            'no controller port, proceed to exit program
            Beep()
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
                LocalExit = True
            End SyncLock
            MsgBox("You have not selected a serial port. The Program
will not continue.", , "Uh huh")
        End If
        'see what the user selected for the laser port
        If CentralClass.LaserPort = "(none)" Then
            'no port at all for laser
            LocalLaserControlMode = 0
        Else
            'A port was selected, see what it is
            If CentralClass.LaserPort = CentralClass.SpeedPort Then
                'The laser and speed controller share the same serial
port
                LocalLaserControlMode = 1
            Else
                'The laser has its own independent serial port
                LocalLaserControlMode = 2
            End If
        End If
    End SyncLock
End If
End If

```

```

SyncLock Longshoreman.LaserPortLock
    Longshoreman.LaserControlMode = LocalLaserControlMode
End SyncLock

If LocalExit = False Then
    'launch the threads, otherwise continue straight to shutdown

    'start the logger thread
    SyncLock CentralClass.ProgramExitLock
        'Program Status=Launching Threads
        CentralClass.ExecutionStage = 10
    End SyncLock
    Lumberjack.BostonLogger.Start()
    ThreadsLaunched = True
    Thread.Sleep(55)
    Application.DoEvents()
    'echo laser port mode to log
    If LocalLaserControlMode = 0 Then
        'No laser port
        Lumberjack.SendToLog("Starting Up in Speed Control Only Mode")
    ElseIf LocalLaserControlMode = 1 Then
        'laser port is shared with speed controller port
        Lumberjack.SendToLog("Starting Up in Shared Speed and Laser
Port Mode")
    ElseIf LocalLaserControlMode = 2 Then
        'laser port is separate from the speed controller port
        Lumberjack.SendToLog("Starting Up in Dual Port Mode")
    Else
        'what mode is this?
        Lumberjack.SendToLog("What Laser Control Mode is associated
with a value of " & Convert.ToString(LocalLaserControlMode) & "?")
    End If

    'start the user interface thread
    SyncLock CentralClass.ProgramExitLock
        'Program Status=Launching Threads
        CentralClass.ExecutionStage = 20
    End SyncLock
    Lumberjack.SendToLog("Starting the User Interface Module")
    Windowsill.Gooey.Start()
    Thread.Sleep(55)
    Application.DoEvents()

    'start the speed controller thread
    SyncLock CentralClass.ProgramExitLock
        'Program Status=Launching Threads
        CentralClass.ExecutionStage = 30
    End SyncLock
    Lumberjack.SendToLog("Starting the Controller Port Module")
    Stevedore.Col_Sanders.Priority = ThreadPriority.AboveNormal
    Stevedore.Col_Sanders.Start()
    Thread.Sleep(55)
    Application.DoEvents()

    'start the laser port thread, if necessary
    If LocalLaserControlMode = 2 Then
        'laser on a separate port

```

```

        SyncLock CentralClass.ProgramExitLock
            'Program Status=Launching Threads
            CentralClass.ExecutionStage = 40
        End SyncLock
        Lumberjack.SendToLog("Starting the Laser Port Module")
        Longshoreman.LaserPorter.Start()
        Thread.Sleep(55)
        Application.DoEvents()
    End If
    Thread.Sleep(55)
    Application.DoEvents()

End If

SyncLock CentralClass.ProgramExitLock
    LocalExit = CentralClass.ExitProgram
    If LocalExit = False Then
        CentralClass.ExecutionStage = 100
        'Program Status=Threads Launched, Running
    End If
End SyncLock
If LocalExit = False Then
    'Log the completion of startup procedures
    Lumberjack.SendToLog("All modules launched, entering Running Mode")
End If

'Now sleep until shutdown
Do
    'make sure threads are still alive
    'check logger
    If Lumberjack.BostonLogger.IsAlive = False Then
        'The Logger Died! End program
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End If
    'check speed controller
    If Stevedore.Col_Sanders.IsAlive = False Then
        'The Speed Controller Died! End program
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End If
    'check user interface
    If Windowsill.Gooey.IsAlive = False Then
        'The User Interface Died! End program
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End If
    'check secondary serial port, if in that mode
    If LocalLaserControlMode = 2 Then
        If Longshoreman.LaserPorter.IsAlive = False Then
            'The Laser Port Died! End program
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
        End If
    End If
End Do

```

```

        SyncLock CentralClass.ProgramExitLock
            LocalExit = CentralClass.ExitProgram
            If LocalExit = True Then
                'Set Program Status to Beginning Shutdown
                CentralClass.ExecutionStage = 1000
            End If
        End SyncLock
        Thread.Sleep(55)
        Application.DoEvents()
    Loop While LocalExit = False

'shutdown stuff
'make sure that the program status is Beginning Shutdown
SyncLock CentralClass.ProgramExitLock
    CentralClass.ExecutionStage = 1000
End SyncLock

If ThreadsLaunched = True Then
    'threads were launched, log the shutdown
    Lumberjack.SendToLog("Program Shutdown in Progress")
End If

'shut down the speed controller
Application.DoEvents()
Thread.Sleep(55)
If ThreadsLaunched = True Then
    'enter imminent controller shutdown into log
    Lumberjack.SendToLog("Initiate Speed Control Port Termination")
End If
SyncLock CentralClass.ProgramExitLock
    CentralClass.ExecutionStage = 1010
    'stage that tells the speed controller to finish
End SyncLock
Application.DoEvents()
'now give the thread a few seconds to finish
Thread.Sleep(55)
Try
    If Stevedore.Col_Sanders.Join(60000) = False Then
        'it did not finish in time
        'it had a full minute (60000 ms)
        'kill it
        Stevedore.Col_Sanders.Abort()
        'log the issue
        If ThreadsLaunched = True Then
            Lumberjack.SendToLog("The Speed Control Port Thread
Shutdown timed out. The thread was aborted.")
        End If
    End If
Catch ex As Exception
    'thread hadn't been started
End Try
Application.DoEvents()
Thread.Sleep(55)

'shut down the laser port

```



```

Application.DoEvents()
Thread.Sleep(55)
If (ThreadsLaunched = True) And (LocalLaserControlMode = 2) Then
    'enter imminent laser port shutdown into log
    Lumberjack.SendToLog("Initiate Laser Port Termination")
End If
SyncLock CentralClass.ProgramExitLock
    CentralClass.ExecutionStage = 1020
    'stage that tells the laser port module to finish
End SyncLock
Application.DoEvents()
Thread.Sleep(55)
'now give the thread a few seconds to finish
Try
    If Longshoreman.LaserPorter.Join(60000) = False Then
        'it did not finish in time
        'it had a full minute (60000 ms)
        'kill it
        Longshoreman.LaserPorter.Abort()
        'log the issue
        If ThreadsLaunched = True Then
            Lumberjack.SendToLog("The Laser Port Thread Shutdown timed
out. The thread was aborted.")
        End If
    End If
Catch ex As Exception
    'thread hadn't been started
End Try
Application.DoEvents()
Thread.Sleep(55)

'shut down the user interface
Application.DoEvents()
Thread.Sleep(55)
If ThreadsLaunched = True Then
    'enter imminent UI shutdown into log
    Lumberjack.SendToLog("Initiate User Interface Termination")
End If
SyncLock CentralClass.ProgramExitLock
    CentralClass.ExecutionStage = 1050
    'stage that tells the user interface to finish
End SyncLock
Application.DoEvents()
Thread.Sleep(55)
'now give the thread a few seconds to finish
Try
    If Windowsill.Gooey.Join(5000) = False Then
        'it did not finish in time
        'kill it
        Windowsill.Gooey.Abort()
        'log the issue
        If ThreadsLaunched = True Then
            Lumberjack.SendToLog("The User Interface Thread Shutdown
timed out. The thread was aborted.")
        End If
    End If
Catch ex As Exception
    'thread hadn't been started

```

```

End Try
Application.DoEvents()
Thread.Sleep(100)

'shut down the logger
Application.DoEvents()
Thread.Sleep(100)
If ThreadsLaunched = True Then
    'enter imminent logger shutdown into log
    Lumberjack.SendToLog("Initiate Logger Termination")
End If
SyncLock CentralClass.ProgramExitLock
    CentralClass.ExecutionStage = 1100
    'stage that tells the logger to finish
End SyncLock
Application.DoEvents()
Thread.Sleep(55)
'now give the thread a few seconds to finish
Try
    If Lumberjack.BostonLogger.Join(5000) = False Then
        'it did not finish in time
        'log the issue
        If ThreadsLaunched = True Then
            Lumberjack.SendToLog("The Logger Thread Shutdown timed out.
The thread will be aborted.")
        End If
        Application.DoEvents()
        Thread.Sleep(250)
        Application.DoEvents()
        'kill it
        Lumberjack.BostonLogger.Abort()
    End If
Catch ex As Exception
    'thread hadn't been started
End Try
Application.DoEvents()
Thread.Sleep(55)

Application.DoEvents()
Thread.Sleep(100)

'Close any resources that are still open (files, ports, forms)

'Close and Dispose all forms

'Dispose the FirePulse box
Try
    FirePulse.Hide()
    FirePulse.Dispose()
Catch ex As ObjectDisposedException
End Try

'Dispose the Helpbox
Try
    HelpBox.Hide()
    HelpBox.Dispose()

```

```

Catch ex As ObjectDisposedException
End Try

'Dispose the InsertComment box
Try
    InsertComment.Hide()
    InsertComment.Dispose()
Catch ex As ObjectDisposedException
End Try

'Dispose the Runbox
Try
    RunBox.Hide()
    RunBox.Dispose()
Catch ex As ObjectDisposedException
End Try

'Dispose the SendLaserCommand box
Try
    SendLaserCommand.Hide()
    SendLaserCommand.Dispose()
Catch ex As ObjectDisposedException
End Try

'Dispose the StartupForm
Try
    StartupForm.Hide()
    StartupForm.Dispose()
Catch ex As ObjectDisposedException
End Try

'Dispose the TestEnder box
'Try
'    TestEnder.Hide()
'    TestEnder.Dispose()
'Catch ex As ObjectDisposedException
'End Try

Application.DoEvents()

'Force-Close the log file
Try
    Lumberjack.OutputLogFile.Flush()
    Lumberjack.OutputLogFile.Close()
    Lumberjack.OutputLogFile.Dispose()
Catch ex1 As ArgumentNullException
    'never initialized the output file
Catch ex2 As ObjectDisposedException
    'already closed
Catch ex3 As NullReferenceException
    'file never opened?
Catch ex As Exception
    'something else
    MsgBox("An exception occurred. " & vbNewLine & ex.Message, ,
"Argh!")
End Try

'Force-Close Serial Port 1 (Controller Port and possibly includes the
laser port)

```

```

Try
    If Stevedore.COMPort1.IsOpen = True Then
        Stevedore.COMPort1.DiscardOutBuffer()
    End If
    Stevedore.COMPort1.Close()
    Stevedore.COMPort1.Dispose()
Catch ex1 As InvalidOperationException
    'port is not open
Catch ex As Exception
    'something else
    MsgBox("An exception occurred. " & vbNewLine & ex.Message, ,
"Argh!")
End Try

'Force-Close Serial Port 2 (laser port, if any and on a separate port)
Try
    If Longshoreman.COMPort2.IsOpen = True Then
        Longshoreman.COMPort2.DiscardOutBuffer()
    End If
    Longshoreman.COMPort2.Close()
    Longshoreman.COMPort2.Dispose()
Catch ex1 As InvalidOperationException
    'port is not open
Catch ex As Exception
    'something else
    MsgBox("An exception occurred. " & vbNewLine & ex.Message, ,
"Argh!")
End Try

'THIS IS THE CORRESPONDING API CALL TO THE timeBeginPeriod CALL AT THE
BEGINNING OF THE PROGRAM
timeEndPeriod(uPeriod)

Application.DoEvents()
Thread.Sleep(1000)

'Then leave the program
Application.Exit()

End Sub

```

```
End Module
```

```
Friend NotInheritable Class CentralClass
```

```

'Application-wide variables
'The following blocks each have their own undefined new object
'That object must be used for synclocking that particular block
'Otherwise, synchronization issues will readily occur
,
,
'File and Startup variables
Friend Shared Filename As String = ""
Friend Shared AppendFile As Boolean = True
Friend Shared AdvancedTiming As Boolean = False

```

```

    Friend Shared SpeedPort As String = ""
    Friend Shared LaserPort As String = ""
    Friend Shared ComPortBaudRate As Integer = 9600
    Friend Shared ComPortParity As System.IO.Ports.Parity =
System.IO.Ports.Parity.None
    Friend Shared ComPortFlowControl As System.IO.Ports.Handshake =
System.IO.Ports.Handshake.None
    Friend Shared ComPortStopBits As System.IO.Ports.StopBits =
System.IO.Ports.StopBits.One
    Friend Shared ComPortDataBits As Integer = 8
    Friend Shared ComPortEncoding As System.Text.Encoding =
System.Text.Encoding.ASCII
    Friend Shared LaserNewlineString As String = vbCr
    Friend Shared ProgramStartTime As String = ""
    Friend Shared FileOpsLock As New Object
    '
    '
    'Program Control/Exit
    Friend Shared ExecutionStage As Long = 0
    Friend Shared ExitProgram As Boolean = False
    Friend Shared ProgramExitLock As New Object
    '
    '

```

End Class

## B.11 RUNBOX.DESIGNER.VB

```

<Global.Microsoft.VisualBasic.CompilerServices.DesignerGenerated()> _
Partial Class RunBox
    Inherits System.Windows.Forms.Form

    'Form overrides dispose to clean up the component list.
    <System.Diagnostics.DebuggerNonUserCode()> _
    Protected Overrides Sub Dispose(ByVal disposing As Boolean)
        Try
            If disposing AndAlso components IsNot Nothing Then
                components.Dispose()
            End If
        Finally
            MyBase.Dispose(disposing)
        End Try
    End Sub

    'Required by the Windows Form Designer
    Private components As System.ComponentModel.IContainer

    'NOTE: The following procedure is required by the Windows Form Designer
    'It can be modified using the Windows Form Designer.
    'Do not modify it using the code editor.
    <System.Diagnostics.DebuggerStepThrough()> _
    Private Sub InitializeComponent()
        Dim resources As System.ComponentModel.ComponentResourceManager = New
System.ComponentModel.ComponentResourceManager(GetType(RunBox))
        Me.TimeBox = New System.Windows.Forms.Label

```

```

Me.DateBox = New System.Windows.Forms.Label
Me.Label13 = New System.Windows.Forms.Label
Me.Label14 = New System.Windows.Forms.Label
Me.Label15 = New System.Windows.Forms.Label
Me.CurrentSpeedBox = New System.Windows.Forms.Label
Me.Label17 = New System.Windows.Forms.Label
Me.OutputFileBox = New System.Windows.Forms.Label
Me.Label19 = New System.Windows.Forms.Label
Me.CavitationBox = New System.Windows.Forms.Label
Me.Label11 = New System.Windows.Forms.Label
Me.SpeedInRangeBox = New System.Windows.Forms.Label
Me.Label13 = New System.Windows.Forms.Label
Me.CurrentStatusBox = New System.Windows.Forms.Label
Me.GroupBox1 = New System.Windows.Forms.GroupBox
Me.Label18 = New System.Windows.Forms.Label
Me.RestartDelayShowBox = New System.Windows.Forms.Label
Me.RestartDelayInputBox = New System.Windows.Forms.TextBox
Me.Label17 = New System.Windows.Forms.Label
Me.SetSpeedShowBox = New System.Windows.Forms.Label
Me.SetSpeedInputBox = New System.Windows.Forms.TextBox
Me.Label15 = New System.Windows.Forms.Label
Me.ButtonSetSpeed = New System.Windows.Forms.Button
Me.OnCavitationStopAndRestart = New System.Windows.Forms.RadioButton
Me.OnCavitationStop = New System.Windows.Forms.RadioButton
Me.ButtonStopSpeed = New System.Windows.Forms.Button
Me.ButtonStartSpeed = New System.Windows.Forms.Button
Me.OnCavitationContinue = New System.Windows.Forms.RadioButton
Me.GroupBox2 = New System.Windows.Forms.GroupBox
Me.Label28 = New System.Windows.Forms.Label
Me.NextPulsePowerShowBox = New System.Windows.Forms.Label
Me.ButtonSetLaser = New System.Windows.Forms.Button
Me.Label26 = New System.Windows.Forms.Label
Me.EstimatedDurationShowBox = New System.Windows.Forms.Label
Me.EstimatedDurationInputBox = New System.Windows.Forms.TextBox
Me.Label23 = New System.Windows.Forms.Label
Me.LaserDelayShowBox = New System.Windows.Forms.Label
Me.LaserDelayInputBox = New System.Windows.Forms.TextBox
Me.FireLaserBox = New System.Windows.Forms.Label
Me.ButtonFireLaser = New System.Windows.Forms.Button
Me.ButtonSendLaserCommand = New System.Windows.Forms.Button
Me.Label22 = New System.Windows.Forms.Label
Me.AutomaticPulsingFalse = New System.Windows.Forms.RadioButton
Me.Label21 = New System.Windows.Forms.Label
Me.LaserRxBox = New System.Windows.Forms.TextBox
Me.AutomaticPulsingTrue = New System.Windows.Forms.RadioButton
Me.ButtonInsertComment = New System.Windows.Forms.Button
Me.ButtonEnd = New System.Windows.Forms.Button
Me.ButtonHelp = New System.Windows.Forms.Button
Me.LogTrace = New System.Windows.Forms.TextBox
Me.Label20 = New System.Windows.Forms.Label
Me.GroupBox1.SuspendLayout()
Me.GroupBox2.SuspendLayout()
Me.SuspendLayout()
'
'TimeBox
'
Me.TimeBox.AutoSize = True
Me.TimeBox.BorderStyle = System.Windows.Forms.BorderStyle.Fixed3D
Me.TimeBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat

```

```

Me.TimeBox.Location = New System.Drawing.Point(96, 9)
Me.TimeBox.MaximumSize = New System.Drawing.Size(134, 15)
Me.TimeBox.MinimumSize = New System.Drawing.Size(134, 15)
Me.TimeBox.Name = "TimeBox"
Me.TimeBox.Size = New System.Drawing.Size(134, 15)
Me.TimeBox.TabIndex = 1
Me.TimeBox.Text = "TIME"
'
'DateBox
'
Me.DateBox.AutoSize = True
Me.DateBox.BorderStyle = System.Windows.Forms.BorderStyle.Fixed3D
Me.DateBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.DateBox.Location = New System.Drawing.Point(314, 9)
Me.DateBox.MaximumSize = New System.Drawing.Size(296, 15)
Me.DateBox.MinimumSize = New System.Drawing.Size(296, 15)
Me.DateBox.Name = "DateBox"
Me.DateBox.Size = New System.Drawing.Size(296, 15)
Me.DateBox.TabIndex = 3
Me.DateBox.Text = "DATE"
'
'Label3
'
Me.Label3.AutoSize = True
Me.Label3.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label3.Location = New System.Drawing.Point(57, 9)
Me.Label3.MinimumSize = New System.Drawing.Size(33, 13)
Me.Label3.Name = "Label3"
Me.Label3.Size = New System.Drawing.Size(33, 13)
Me.Label3.TabIndex = 0
Me.Label3.Text = "Time:"
'
'Label4
'
Me.Label4.AutoSize = True
Me.Label4.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label4.Location = New System.Drawing.Point(275, 9)
Me.Label4.MinimumSize = New System.Drawing.Size(33, 13)
Me.Label4.Name = "Label4"
Me.Label4.Size = New System.Drawing.Size(33, 13)
Me.Label4.TabIndex = 2
Me.Label4.Text = "Date:"
'
'Label5
'
Me.Label5.AutoSize = True
Me.Label5.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label5.Location = New System.Drawing.Point(12, 24)
Me.Label5.MinimumSize = New System.Drawing.Size(78, 13)
Me.Label5.Name = "Label5"
Me.Label5.Size = New System.Drawing.Size(78, 13)
Me.Label5.TabIndex = 4
Me.Label5.Text = "Current Speed:"
'
'CurrentSpeedBox
'
Me.CurrentSpeedBox.AutoSize = True
Me.CurrentSpeedBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D

```

```

Me.CurrentSpeedBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.CurrentSpeedBox.Location = New System.Drawing.Point(96, 24)
Me.CurrentSpeedBox.MaximumSize = New System.Drawing.Size(134, 15)
Me.CurrentSpeedBox.MinimumSize = New System.Drawing.Size(134, 15)
Me.CurrentSpeedBox.Name = "CurrentSpeedBox"
Me.CurrentSpeedBox.Size = New System.Drawing.Size(134, 15)
Me.CurrentSpeedBox.TabIndex = 5
Me.CurrentSpeedBox.Text = "SPEED"
,
'Label7
,
Me.Label7.AutoSize = True
Me.Label7.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label7.Location = New System.Drawing.Point(247, 24)
Me.Label7.MinimumSize = New System.Drawing.Size(61, 13)
Me.Label7.Name = "Label7"
Me.Label7.Size = New System.Drawing.Size(61, 13)
Me.Label7.TabIndex = 6
Me.Label7.Text = "Output File:"
,
'OutputFileBox
,
Me.OutputFileBox.AutoEllipsis = True
Me.OutputFileBox.AutoSize = True
Me.OutputFileBox.BorderStyle = System.Windows.Forms.BorderStyle.Fixed3D
Me.OutputFileBox.Cursor = System.Windows.Forms.Cursors.Default
Me.OutputFileBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.OutputFileBox.Location = New System.Drawing.Point(314, 24)
Me.OutputFileBox.MaximumSize = New System.Drawing.Size(296, 15)
Me.OutputFileBox.MinimumSize = New System.Drawing.Size(296, 15)
Me.OutputFileBox.Name = "OutputFileBox"
Me.OutputFileBox.Size = New System.Drawing.Size(296, 15)
Me.OutputFileBox.TabIndex = 7
Me.OutputFileBox.Text = "FILE"
,
'Label9
,
Me.Label9.AutoSize = True
Me.Label9.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label9.Location = New System.Drawing.Point(391, 54)
Me.Label9.MinimumSize = New System.Drawing.Size(104, 13)
Me.Label9.Name = "Label9"
Me.Label9.Size = New System.Drawing.Size(104, 13)
Me.Label9.TabIndex = 12
Me.Label9.Text = "Cavitation Detected:"
,
'CavitationBox
,
Me.CavitationBox.AutoSize = True
Me.CavitationBox.BackColor = System.Drawing.Color.Navy
Me.CavitationBox.BorderStyle =
System.Windows.Forms.BorderStyle.FixedSingle
Me.CavitationBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.CavitationBox.Font = New System.Drawing.Font("Microsoft Sans Serif",
8.25!, System.Drawing.FontStyle.Bold, System.Drawing.GraphicsUnit.Point,
CType(0, Byte))
Me.CavitationBox.ForeColor = System.Drawing.Color.Yellow
Me.CavitationBox.Location = New System.Drawing.Point(501, 54)
Me.CavitationBox.MaximumSize = New System.Drawing.Size(40, 15)

```



```

Me.CavitationBox.MinimumSize = New System.Drawing.Size(40, 15)
Me.CavitationBox.Name = "CavitationBox"
Me.CavitationBox.Size = New System.Drawing.Size(40, 15)
Me.CavitationBox.TabIndex = 13
Me.CavitationBox.Text = "NO"
'
'Label11
'
Me.Label11.AutoSize = True
Me.Label11.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label11.Location = New System.Drawing.Point(97, 54)
Me.Label11.MinimumSize = New System.Drawing.Size(87, 13)
Me.Label11.Name = "Label11"
Me.Label11.Size = New System.Drawing.Size(87, 13)
Me.Label11.TabIndex = 10
Me.Label11.Text = "Speed in Range:"
'
'SpeedInRangeBox
'
Me.SpeedInRangeBox.AutoSize = True
Me.SpeedInRangeBox.BackColor = System.Drawing.Color.Navy
Me.SpeedInRangeBox.BorderStyle =
System.Windows.Forms.BorderStyle.FixedSingle
Me.SpeedInRangeBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.SpeedInRangeBox.Font = New System.Drawing.Font("Microsoft Sans
Serif", 8.25!, System.Drawing.FontStyle.Bold,
System.Drawing.GraphicsUnit.Point, CType(0, Byte))
Me.SpeedInRangeBox.ForeColor = System.Drawing.Color.Yellow
Me.SpeedInRangeBox.Location = New System.Drawing.Point(190, 54)
Me.SpeedInRangeBox.MaximumSize = New System.Drawing.Size(40, 15)
Me.SpeedInRangeBox.MinimumSize = New System.Drawing.Size(40, 15)
Me.SpeedInRangeBox.Name = "SpeedInRangeBox"
Me.SpeedInRangeBox.Size = New System.Drawing.Size(40, 15)
Me.SpeedInRangeBox.TabIndex = 11
Me.SpeedInRangeBox.Text = "NO"
'
'Label13
'
Me.Label13.AutoSize = True
Me.Label13.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label13.Location = New System.Drawing.Point(50, 41)
Me.Label13.MinimumSize = New System.Drawing.Size(40, 13)
Me.Label13.Name = "Label13"
Me.Label13.Size = New System.Drawing.Size(40, 13)
Me.Label13.TabIndex = 8
Me.Label13.Text = "Status:"
'
'CurrentStatusBox
'
Me.CurrentStatusBox.AutoSize = True
Me.CurrentStatusBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
Me.CurrentStatusBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.CurrentStatusBox.Location = New System.Drawing.Point(96, 39)
Me.CurrentStatusBox.MaximumSize = New System.Drawing.Size(514, 15)
Me.CurrentStatusBox.MinimumSize = New System.Drawing.Size(514, 15)
Me.CurrentStatusBox.Name = "CurrentStatusBox"
Me.CurrentStatusBox.Size = New System.Drawing.Size(514, 15)
Me.CurrentStatusBox.TabIndex = 9

```

```

Me.CurrentStatusBox.Text = "STATUS"
'
'GroupBox1
'
Me.GroupBox1.Controls.Add(Me.Label18)
Me.GroupBox1.Controls.Add(Me.RestartDelayShowBox)
Me.GroupBox1.Controls.Add(Me.RestartDelayInputBox)
Me.GroupBox1.Controls.Add(Me.Label17)
Me.GroupBox1.Controls.Add(Me.SetSpeedShowBox)
Me.GroupBox1.Controls.Add(Me.SetSpeedInputBox)
Me.GroupBox1.Controls.Add(Me.Label15)
Me.GroupBox1.Controls.Add(Me.ButtonSetSpeed)
Me.GroupBox1.Controls.Add(Me.OnCavitationStopAndRestart)
Me.GroupBox1.Controls.Add(Me.OnCavitationStop)
Me.GroupBox1.Controls.Add(Me.ButtonStopSpeed)
Me.GroupBox1.Controls.Add(Me.ButtonStartSpeed)
Me.GroupBox1.Controls.Add(Me.OnCavitationContinue)
Me.GroupBox1.Location = New System.Drawing.Point(12, 72)
Me.GroupBox1.MaximumSize = New System.Drawing.Size(296, 147)
Me.GroupBox1.MinimumSize = New System.Drawing.Size(296, 147)
Me.GroupBox1.Name = "GroupBox1"
Me.GroupBox1.Size = New System.Drawing.Size(296, 147)
Me.GroupBox1.TabIndex = 14
Me.GroupBox1.TabStop = False
Me.GroupBox1.Text = "Speed Controls"
'
'Label18
'
Me.Label18.AutoSize = True
Me.Label18.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label18.Location = New System.Drawing.Point(64, 91)
Me.Label18.MaximumSize = New System.Drawing.Size(74, 13)
Me.Label18.MinimumSize = New System.Drawing.Size(74, 13)
Me.Label18.Name = "Label18"
Me.Label18.Size = New System.Drawing.Size(74, 13)
Me.Label18.TabIndex = 7
Me.Label18.Text = "Restart Delay:"
'
'RestartDelayShowBox
'
Me.RestartDelayShowBox.AutoSize = True
Me.RestartDelayShowBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
Me.RestartDelayShowBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.RestartDelayShowBox.Location = New System.Drawing.Point(215, 91)
Me.RestartDelayShowBox.MaximumSize = New System.Drawing.Size(65, 15)
Me.RestartDelayShowBox.MinimumSize = New System.Drawing.Size(65, 15)
Me.RestartDelayShowBox.Name = "RestartDelayShowBox"
Me.RestartDelayShowBox.Size = New System.Drawing.Size(65, 15)
Me.RestartDelayShowBox.TabIndex = 9
Me.RestartDelayShowBox.Text = "00000"
'
'RestartDelayInputBox
'
Me.RestartDelayInputBox.Location = New System.Drawing.Point(144, 88)
Me.RestartDelayInputBox.MaximumSize = New System.Drawing.Size(65, 20)
Me.RestartDelayInputBox.MaxLength = 9
Me.RestartDelayInputBox.MinimumSize = New System.Drawing.Size(65, 20)
Me.RestartDelayInputBox.Name = "RestartDelayInputBox"

```

```

Me.RestartDelayInputBox.Size = New System.Drawing.Size(65, 20)
Me.RestartDelayInputBox.TabIndex = 8
Me.RestartDelayInputBox.Text = "00000"
'
'Label17
'
Me.Label17.AutoSize = True
Me.Label17.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label17.Location = New System.Drawing.Point(13, 21)
Me.Label17.MaximumSize = New System.Drawing.Size(60, 13)
Me.Label17.MinimumSize = New System.Drawing.Size(60, 13)
Me.Label17.Name = "Label17"
Me.Label17.Size = New System.Drawing.Size(60, 13)
Me.Label17.TabIndex = 0
Me.Label17.Text = "Set Speed:"
'
'SetSpeedShowBox
'
Me.SetSpeedShowBox.AutoSize = True
Me.SetSpeedShowBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
Me.SetSpeedShowBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.SetSpeedShowBox.Location = New System.Drawing.Point(16, 67)
Me.SetSpeedShowBox.MaximumSize = New System.Drawing.Size(65, 15)
Me.SetSpeedShowBox.MinimumSize = New System.Drawing.Size(65, 15)
Me.SetSpeedShowBox.Name = "SetSpeedShowBox"
Me.SetSpeedShowBox.Size = New System.Drawing.Size(65, 15)
Me.SetSpeedShowBox.TabIndex = 2
Me.SetSpeedShowBox.Text = "123456789"
'
'SetSpeedInputBox
'
Me.SetSpeedInputBox.Location = New System.Drawing.Point(16, 41)
Me.SetSpeedInputBox.MaximumSize = New System.Drawing.Size(65, 20)
Me.SetSpeedInputBox.MaxLength = 9
Me.SetSpeedInputBox.MinimumSize = New System.Drawing.Size(65, 20)
Me.SetSpeedInputBox.Name = "SetSpeedInputBox"
Me.SetSpeedInputBox.Size = New System.Drawing.Size(65, 20)
Me.SetSpeedInputBox.TabIndex = 1
Me.SetSpeedInputBox.Text = "00000"
'
'Label15
'
Me.Label15.AutoSize = True
Me.Label15.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label15.Location = New System.Drawing.Point(89, 21)
Me.Label15.MaximumSize = New System.Drawing.Size(74, 13)
Me.Label15.MinimumSize = New System.Drawing.Size(74, 13)
Me.Label15.Name = "Label15"
Me.Label15.Size = New System.Drawing.Size(74, 13)
Me.Label15.TabIndex = 3
Me.Label15.Text = "On Cavitation:"
'
'ButtonSetSpeed
'
Me.ButtonSetSpeed.Location = New System.Drawing.Point(6, 118)
Me.ButtonSetSpeed.MaximumSize = New System.Drawing.Size(75, 23)
Me.ButtonSetSpeed.MinimumSize = New System.Drawing.Size(75, 23)
Me.ButtonSetSpeed.Name = "ButtonSetSpeed"

```

```

Me.ButtonSetSpeed.Size = New System.Drawing.Size(75, 23)
Me.ButtonSetSpeed.TabIndex = 10
Me.ButtonSetSpeed.Text = "Set"
Me.ButtonSetSpeed.UseVisualStyleBackColor = True
'
'OnCavitationStopAndRestart
'
Me.OnCavitationStopAndRestart.AutoSize = True
Me.OnCavitationStopAndRestart.Checked = True
Me.OnCavitationStopAndRestart.Location = New System.Drawing.Point(169,
65)
Me.OnCavitationStopAndRestart.MaximumSize = New
System.Drawing.Size(115, 17)
Me.OnCavitationStopAndRestart.MinimumSize = New
System.Drawing.Size(115, 17)
Me.OnCavitationStopAndRestart.Name = "OnCavitationStopAndRestart"
Me.OnCavitationStopAndRestart.Size = New System.Drawing.Size(115, 17)
Me.OnCavitationStopAndRestart.TabIndex = 6
Me.OnCavitationStopAndRestart.TabStop = True
Me.OnCavitationStopAndRestart.Text = "Stop + Restart"
Me.OnCavitationStopAndRestart.UseVisualStyleBackColor = True
'
'OnCavitationStop
'
Me.OnCavitationStop.AutoSize = True
Me.OnCavitationStop.Location = New System.Drawing.Point(169, 42)
Me.OnCavitationStop.MaximumSize = New System.Drawing.Size(115, 17)
Me.OnCavitationStop.MinimumSize = New System.Drawing.Size(115, 17)
Me.OnCavitationStop.Name = "OnCavitationStop"
Me.OnCavitationStop.Size = New System.Drawing.Size(115, 17)
Me.OnCavitationStop.TabIndex = 5
Me.OnCavitationStop.Text = "Stop"
Me.OnCavitationStop.UseVisualStyleBackColor = True
'
'ButtonStopSpeed
'
Me.ButtonStopSpeed.Enabled = False
Me.ButtonStopSpeed.Location = New System.Drawing.Point(215, 118)
Me.ButtonStopSpeed.MaximumSize = New System.Drawing.Size(75, 23)
Me.ButtonStopSpeed.MinimumSize = New System.Drawing.Size(75, 23)
Me.ButtonStopSpeed.Name = "ButtonStopSpeed"
Me.ButtonStopSpeed.Size = New System.Drawing.Size(75, 23)
Me.ButtonStopSpeed.TabIndex = 12
Me.ButtonStopSpeed.Text = "Stop"
Me.ButtonStopSpeed.UseVisualStyleBackColor = True
'
'ButtonStartSpeed
'
Me.ButtonStartSpeed.Location = New System.Drawing.Point(134, 118)
Me.ButtonStartSpeed.MaximumSize = New System.Drawing.Size(75, 23)
Me.ButtonStartSpeed.MinimumSize = New System.Drawing.Size(75, 23)
Me.ButtonStartSpeed.Name = "ButtonStartSpeed"
Me.ButtonStartSpeed.Size = New System.Drawing.Size(75, 23)
Me.ButtonStartSpeed.TabIndex = 11
Me.ButtonStartSpeed.Text = "Start"
Me.ButtonStartSpeed.UseVisualStyleBackColor = True
'
'OnCavitationContinue
'

```

```

Me.OnCavitationContinue.AutoSize = True
Me.OnCavitationContinue.Location = New System.Drawing.Point(169, 19)
Me.OnCavitationContinue.MaximumSize = New System.Drawing.Size(115, 17)
Me.OnCavitationContinue.MinimumSize = New System.Drawing.Size(115, 17)
Me.OnCavitationContinue.Name = "OnCavitationContinue"
Me.OnCavitationContinue.Size = New System.Drawing.Size(115, 17)
Me.OnCavitationContinue.TabIndex = 4
Me.OnCavitationContinue.Text = "Continue"
Me.OnCavitationContinue.UseVisualStyleBackColor = True
'
'GroupBox2
'
Me.GroupBox2.Controls.Add(Me.Label28)
Me.GroupBox2.Controls.Add(Me.NextPulsePowerShowBox)
Me.GroupBox2.Controls.Add(Me.ButtonSetLaser)
Me.GroupBox2.Controls.Add(Me.Label26)
Me.GroupBox2.Controls.Add(Me.EstimatedDurationShowBox)
Me.GroupBox2.Controls.Add(Me.EstimatedDurationInputBox)
Me.GroupBox2.Controls.Add(Me.Label23)
Me.GroupBox2.Controls.Add(Me.LaserDelayShowBox)
Me.GroupBox2.Controls.Add(Me.LaserDelayInputBox)
Me.GroupBox2.Controls.Add(Me.FireLaserBox)
Me.GroupBox2.Controls.Add(Me.ButtonFireLaser)
Me.GroupBox2.Controls.Add(Me.ButtonSendLaserCommand)
Me.GroupBox2.Controls.Add(Me.Label22)
Me.GroupBox2.Controls.Add(Me.AutomaticPulsingFalse)
Me.GroupBox2.Controls.Add(Me.Label21)
Me.GroupBox2.Controls.Add(Me.LaserRxBox)
Me.GroupBox2.Controls.Add(Me.AutomaticPulsingTrue)
Me.GroupBox2.Location = New System.Drawing.Point(314, 72)
Me.GroupBox2.MaximumSize = New System.Drawing.Size(296, 293)
Me.GroupBox2.MinimumSize = New System.Drawing.Size(296, 293)
Me.GroupBox2.Name = "GroupBox2"
Me.GroupBox2.Size = New System.Drawing.Size(296, 293)
Me.GroupBox2.TabIndex = 15
Me.GroupBox2.TabStop = False
Me.GroupBox2.Text = "Laser Controls"
'
'Label28
'
Me.Label28.AutoSize = True
Me.Label28.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label28.Location = New System.Drawing.Point(73, 44)
Me.Label28.MaximumSize = New System.Drawing.Size(40, 39)
Me.Label28.MinimumSize = New System.Drawing.Size(40, 39)
Me.Label28.Name = "Label28"
Me.Label28.Size = New System.Drawing.Size(40, 39)
Me.Label28.TabIndex = 4
Me.Label28.Text = "Next Pulse Power:"
'
'NextPulsePowerShowBox
'
Me.NextPulsePowerShowBox.AutoSize = True
Me.NextPulsePowerShowBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
Me.NextPulsePowerShowBox.FlatStyle =
System.Windows.Forms.FlatStyle.Flat
Me.NextPulsePowerShowBox.Location = New System.Drawing.Point(69, 91)
Me.NextPulsePowerShowBox.MaximumSize = New System.Drawing.Size(65, 15)

```

```

Me.NextPulsePowerShowBox.MinimumSize = New System.Drawing.Size(65, 15)
Me.NextPulsePowerShowBox.Name = "NextPulsePowerShowBox"
Me.NextPulsePowerShowBox.Size = New System.Drawing.Size(65, 15)
Me.NextPulsePowerShowBox.TabIndex = 5
Me.NextPulsePowerShowBox.Text = "000001100"
'
'ButtonSetLaser
'
Me.ButtonSetLaser.Location = New System.Drawing.Point(6, 86)
Me.ButtonSetLaser.MaximumSize = New System.Drawing.Size(57, 23)
Me.ButtonSetLaser.MinimumSize = New System.Drawing.Size(57, 23)
Me.ButtonSetLaser.Name = "ButtonSetLaser"
Me.ButtonSetLaser.Size = New System.Drawing.Size(57, 23)
Me.ButtonSetLaser.TabIndex = 12
Me.ButtonSetLaser.Text = "Set"
Me.ButtonSetLaser.UseVisualStyleBackColor = True
'
'Label26
'
Me.Label26.AutoSize = True
Me.Label26.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label26.Location = New System.Drawing.Point(137, 37)
Me.Label26.MaximumSize = New System.Drawing.Size(56, 26)
Me.Label26.MinimumSize = New System.Drawing.Size(56, 26)
Me.Label26.Name = "Label26"
Me.Label26.Size = New System.Drawing.Size(56, 26)
Me.Label26.TabIndex = 6
Me.Label26.Text = "Estimated Duration:"
'
'EstimatedDurationShowBox
'
Me.EstimatedDurationShowBox.AutoSize = True
Me.EstimatedDurationShowBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
Me.EstimatedDurationShowBox.FlatStyle =
System.Windows.Forms.FlatStyle.Flat
Me.EstimatedDurationShowBox.Location = New System.Drawing.Point(140,
91)
Me.EstimatedDurationShowBox.MaximumSize = New System.Drawing.Size(65,
15)
Me.EstimatedDurationShowBox.MinimumSize = New System.Drawing.Size(65,
15)
Me.EstimatedDurationShowBox.Name = "EstimatedDurationShowBox"
Me.EstimatedDurationShowBox.Size = New System.Drawing.Size(65, 15)
Me.EstimatedDurationShowBox.TabIndex = 8
Me.EstimatedDurationShowBox.Text = "00000"
'
'EstimatedDurationInputBox
'
Me.EstimatedDurationInputBox.Location = New System.Drawing.Point(140,
65)
Me.EstimatedDurationInputBox.MaximumSize = New System.Drawing.Size(65,
20)
Me.EstimatedDurationInputBox.MaxLength = 9
Me.EstimatedDurationInputBox.MinimumSize = New System.Drawing.Size(65,
20)
Me.EstimatedDurationInputBox.Name = "EstimatedDurationInputBox"
Me.EstimatedDurationInputBox.Size = New System.Drawing.Size(65, 20)
Me.EstimatedDurationInputBox.TabIndex = 7

```

```

Me.EstimatedDurationInputBox.Text = "00000"
,
'Label23
,
Me.Label23.AutoSize = True
Me.Label23.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label23.Location = New System.Drawing.Point(218, 44)
Me.Label23.MaximumSize = New System.Drawing.Size(37, 13)
Me.Label23.MinimumSize = New System.Drawing.Size(37, 13)
Me.Label23.Name = "Label23"
Me.Label23.Size = New System.Drawing.Size(37, 13)
Me.Label23.TabIndex = 9
Me.Label23.Text = "Delay:"
,
'LaserDelayShowBox
,
Me.LaserDelayShowBox.AutoSize = True
Me.LaserDelayShowBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
Me.LaserDelayShowBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.LaserDelayShowBox.Location = New System.Drawing.Point(220, 91)
Me.LaserDelayShowBox.MaximumSize = New System.Drawing.Size(65, 15)
Me.LaserDelayShowBox.MinimumSize = New System.Drawing.Size(65, 15)
Me.LaserDelayShowBox.Name = "LaserDelayShowBox"
Me.LaserDelayShowBox.Size = New System.Drawing.Size(65, 15)
Me.LaserDelayShowBox.TabIndex = 11
Me.LaserDelayShowBox.Text = "00000"
,
'LaserDelayInputBox
,
Me.LaserDelayInputBox.Location = New System.Drawing.Point(220, 65)
Me.LaserDelayInputBox.MaximumSize = New System.Drawing.Size(65, 20)
Me.LaserDelayInputBox.MaxLength = 9
Me.LaserDelayInputBox.MinimumSize = New System.Drawing.Size(65, 20)
Me.LaserDelayInputBox.Name = "LaserDelayInputBox"
Me.LaserDelayInputBox.Size = New System.Drawing.Size(65, 20)
Me.LaserDelayInputBox.TabIndex = 10
Me.LaserDelayInputBox.Text = "00000"
,
'FireLaserBox
,
Me.FireLaserBox.AutoSize = True
Me.FireLaserBox.BackColor = System.Drawing.Color.Crimson
Me.FireLaserBox.BorderStyle = System.Windows.Forms.BorderStyle.Fixed3D
Me.FireLaserBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.FireLaserBox.Font = New System.Drawing.Font("Microsoft Sans Serif",
8.25!, System.Drawing.FontStyle.Bold, System.Drawing.GraphicsUnit.Point,
CType(0, Byte))
Me.FireLaserBox.ForeColor = System.Drawing.Color.Yellow
Me.FireLaserBox.Location = New System.Drawing.Point(6, 44)
Me.FireLaserBox.MaximumSize = New System.Drawing.Size(60, 30)
Me.FireLaserBox.MinimumSize = New System.Drawing.Size(60, 30)
Me.FireLaserBox.Name = "FireLaserBox"
Me.FireLaserBox.Size = New System.Drawing.Size(60, 30)
Me.FireLaserBox.TabIndex = 3
Me.FireLaserBox.Text = "FIRE LASER!"
Me.FireLaserBox.TextAlign =
System.Drawing.ContentAlignment.MiddleCenter
,

```

```

'ButtonFireLaser
'
Me.ButtonFireLaser.Location = New System.Drawing.Point(6, 118)
Me.ButtonFireLaser.Name = "ButtonFireLaser"
Me.ButtonFireLaser.Size = New System.Drawing.Size(128, 23)
Me.ButtonFireLaser.TabIndex = 13
Me.ButtonFireLaser.Text = "Fire Pulse..."
Me.ButtonFireLaser.UseVisualStyleBackColor = True
'
'ButtonSendLaserCommand
'
Me.ButtonSendLaserCommand.Location = New System.Drawing.Point(140, 118)
Me.ButtonSendLaserCommand.Name = "ButtonSendLaserCommand"
Me.ButtonSendLaserCommand.Size = New System.Drawing.Size(150, 23)
Me.ButtonSendLaserCommand.TabIndex = 14
Me.ButtonSendLaserCommand.Text = "Send Command to Laser"
Me.ButtonSendLaserCommand.UseVisualStyleBackColor = True
'
'Label22
'
Me.Label22.AutoSize = True
Me.Label22.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label22.Location = New System.Drawing.Point(6, 21)
Me.Label22.MaximumSize = New System.Drawing.Size(110, 13)
Me.Label22.MinimumSize = New System.Drawing.Size(110, 13)
Me.Label22.Name = "Label22"
Me.Label22.Size = New System.Drawing.Size(110, 13)
Me.Label22.TabIndex = 0
Me.Label22.Text = "Automatic Pulsing:"
'
'AutomaticPulsingFalse
'
Me.AutomaticPulsingFalse.AutoSize = True
Me.AutomaticPulsingFalse.Checked = True
Me.AutomaticPulsingFalse.Location = New System.Drawing.Point(221, 19)
Me.AutomaticPulsingFalse.MaximumSize = New System.Drawing.Size(39, 17)
Me.AutomaticPulsingFalse.MinimumSize = New System.Drawing.Size(39, 17)
Me.AutomaticPulsingFalse.Name = "AutomaticPulsingFalse"
Me.AutomaticPulsingFalse.Size = New System.Drawing.Size(39, 17)
Me.AutomaticPulsingFalse.TabIndex = 2
Me.AutomaticPulsingFalse.TabStop = True
Me.AutomaticPulsingFalse.Text = "No"
Me.AutomaticPulsingFalse.UseVisualStyleBackColor = True
'
'Label21
'
Me.Label21.AutoSize = True
Me.Label21.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label21.Location = New System.Drawing.Point(6, 150)
Me.Label21.MaximumSize = New System.Drawing.Size(128, 13)
Me.Label21.MinimumSize = New System.Drawing.Size(128, 13)
Me.Label21.Name = "Label21"
Me.Label21.Size = New System.Drawing.Size(128, 13)
Me.Label21.TabIndex = 15
Me.Label21.Text = "Received from Laser:"
'
'LaserRxBox
'
Me.LaserRxBox.AcceptsReturn = True

```



```

    Me.LaserRxBox.BackColor = System.Drawing.SystemColors.Window
    Me.LaserRxBox.Font = New System.Drawing.Font("Lucida Console", 9.0!,
System.Drawing.FontStyle.Regular, System.Drawing.GraphicsUnit.Point, CType(0,
Byte))
    Me.LaserRxBox.Location = New System.Drawing.Point(6, 166)
    Me.LaserRxBox.MaximumSize = New System.Drawing.Size(284, 121)
    Me.LaserRxBox.MaxLength = 8192
    Me.LaserRxBox.MinimumSize = New System.Drawing.Size(284, 121)
    Me.LaserRxBox.Multiline = True
    Me.LaserRxBox.Name = "LaserRxBox"
    Me.LaserRxBox.ReadOnly = True
    Me.LaserRxBox.ScrollBars = System.Windows.Forms.ScrollBars.Vertical
    Me.LaserRxBox.Size = New System.Drawing.Size(284, 121)
    Me.LaserRxBox.TabIndex = 16
    Me.LaserRxBox.Text = "Text Received from the Laser: " &
Global.Microsoft.VisualBasic.ChrW(13) & Global.Microsoft.VisualBasic.ChrW(10) &
Global.Microsoft.VisualBasic.ChrW(13) & Global.Microsoft.VisualBasic.ChrW(10)
    ,
    'AutomaticPulsingTrue
    ,
    Me.AutomaticPulsingTrue.AutoSize = True
    Me.AutomaticPulsingTrue.Location = New System.Drawing.Point(140, 17)
    Me.AutomaticPulsingTrue.MaximumSize = New System.Drawing.Size(43, 17)
    Me.AutomaticPulsingTrue.MinimumSize = New System.Drawing.Size(43, 17)
    Me.AutomaticPulsingTrue.Name = "AutomaticPulsingTrue"
    Me.AutomaticPulsingTrue.Size = New System.Drawing.Size(43, 17)
    Me.AutomaticPulsingTrue.TabIndex = 1
    Me.AutomaticPulsingTrue.Text = "Yes"
    Me.AutomaticPulsingTrue.UseVisualStyleBackColor = True
    ,
    'ButtonInsertComment
    ,
    Me.ButtonInsertComment.Location = New System.Drawing.Point(314, 371)
    Me.ButtonInsertComment.MaximumSize = New System.Drawing.Size(134, 23)
    Me.ButtonInsertComment.MinimumSize = New System.Drawing.Size(134, 23)
    Me.ButtonInsertComment.Name = "ButtonInsertComment"
    Me.ButtonInsertComment.Size = New System.Drawing.Size(134, 23)
    Me.ButtonInsertComment.TabIndex = 18
    Me.ButtonInsertComment.Text = "Insert Comment"
    Me.ButtonInsertComment.UseVisualStyleBackColor = True
    ,
    'ButtonEnd
    ,
    Me.ButtonEnd.Location = New System.Drawing.Point(535, 371)
    Me.ButtonEnd.MaximumSize = New System.Drawing.Size(75, 23)
    Me.ButtonEnd.MinimumSize = New System.Drawing.Size(75, 23)
    Me.ButtonEnd.Name = "ButtonEnd"
    Me.ButtonEnd.Size = New System.Drawing.Size(75, 23)
    Me.ButtonEnd.TabIndex = 20
    Me.ButtonEnd.Text = "End"
    Me.ButtonEnd.UseVisualStyleBackColor = True
    ,
    'ButtonHelp
    ,
    Me.ButtonHelp.Location = New System.Drawing.Point(454, 371)
    Me.ButtonHelp.MaximumSize = New System.Drawing.Size(75, 23)
    Me.ButtonHelp.MinimumSize = New System.Drawing.Size(75, 23)
    Me.ButtonHelp.Name = "ButtonHelp"
    Me.ButtonHelp.Size = New System.Drawing.Size(75, 23)

```

```

Me.ButtonHelp.TabIndex = 19
Me.ButtonHelp.Text = "Help"
Me.ButtonHelp.UseVisualStyleBackColor = True
'
'LogTrace
'
Me.LogTrace.AcceptsReturn = True
Me.LogTrace.BackColor = System.Drawing.SystemColors.Window
Me.LogTrace.Font = New System.Drawing.Font("Lucida Console", 9.0!,
System.Drawing.FontStyle.Regular, System.Drawing.GraphicsUnit.Point, CType(0,
Byte))
Me.LogTrace.Location = New System.Drawing.Point(12, 238)
Me.LogTrace.MaximumSize = New System.Drawing.Size(296, 156)
Me.LogTrace.MaxLength = 8192
Me.LogTrace.MinimumSize = New System.Drawing.Size(296, 156)
Me.LogTrace.Multiline = True
Me.LogTrace.Name = "LogTrace"
Me.LogTrace.ReadOnly = True
Me.LogTrace.ScrollBars = System.Windows.Forms.ScrollBars.Vertical
Me.LogTrace.Size = New System.Drawing.Size(296, 156)
Me.LogTrace.TabIndex = 17
Me.LogTrace.Text = "Output Log Follows: " &
Global.Microsoft.VisualBasic.ChrW(13) & Global.Microsoft.VisualBasic.ChrW(10) &
Global.Microsoft.VisualBasic.ChrW(13) & Global.Microsoft.VisualBasic.ChrW(10)
'
'Label20
'
Me.Label20.AutoSize = True
Me.Label20.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.Label20.Location = New System.Drawing.Point(12, 222)
Me.Label20.MaximumSize = New System.Drawing.Size(60, 13)
Me.Label20.MinimumSize = New System.Drawing.Size(60, 13)
Me.Label20.Name = "Label20"
Me.Label20.Size = New System.Drawing.Size(60, 13)
Me.Label20.TabIndex = 16
Me.Label20.Text = "Output:"
'
'RunBox
'
Me.AutoScaleDimensions = New System.Drawing.SizeF(6.0!, 13.0!)
Me.AutoScaleMode = System.Windows.Forms.AutoScaleMode.Font
Me.ClientSize = New System.Drawing.Size(622, 410)
Me.Controls.Add(Me.Label20)
Me.Controls.Add(Me.LogTrace)
Me.Controls.Add(Me.ButtonHelp)
Me.Controls.Add(Me.ButtonInsertComment)
Me.Controls.Add(Me.ButtonEnd)
Me.Controls.Add(Me.GroupBox2)
Me.Controls.Add(Me.GroupBox1)
Me.Controls.Add(Me.Label13)
Me.Controls.Add(Me.CurrentStatusBox)
Me.Controls.Add(Me.Label11)
Me.Controls.Add(Me.SpeedInRangeBox)
Me.Controls.Add(Me.Label9)
Me.Controls.Add(Me.CavitationBox)
Me.Controls.Add(Me.Label7)
Me.Controls.Add(Me.OutputFileBox)
Me.Controls.Add(Me.Label5)
Me.Controls.Add(Me.CurrentSpeedBox)

```

```

Me.Controls.Add(Me.Label4)
Me.Controls.Add(Me.Label3)
Me.Controls.Add(Me.DateBox)
Me.Controls.Add(Me.TimeBox)
Me.ForeColor = System.Drawing.SystemColors.WindowText
Me.FormBorderStyle = System.Windows.Forms.FormBorderStyle.Fixed3D
Me.Icon = CType(resources.GetObject("$this.Icon"), System.Drawing.Icon)
Me.MaximizeBox = False
Me.MaximumSize = New System.Drawing.Size(632, 440)
Me.MinimizeBox = False
Me.MinimumSize = New System.Drawing.Size(632, 440)
Me.Name = "RunBox"
Me.SizeGripStyle = System.Windows.Forms.SizeGripStyle.Hide
Me.Text = "RUN RUN RUN!!!"
Me.GroupBox1.ResumeLayout(False)
Me.GroupBox1.PerformLayout()
Me.GroupBox2.ResumeLayout(False)
Me.GroupBox2.PerformLayout()
Me.ResumeLayout(False)
Me.PerformLayout()

End Sub

Friend WithEvents TimeBox As System.Windows.Forms.Label
Friend WithEvents DateBox As System.Windows.Forms.Label
Friend WithEvents Label3 As System.Windows.Forms.Label
Friend WithEvents Label4 As System.Windows.Forms.Label
Friend WithEvents Label5 As System.Windows.Forms.Label
Friend WithEvents CurrentSpeedBox As System.Windows.Forms.Label
Friend WithEvents Label7 As System.Windows.Forms.Label
Friend WithEvents OutputFileBox As System.Windows.Forms.Label
Friend WithEvents Label9 As System.Windows.Forms.Label
Friend WithEvents CavitationBox As System.Windows.Forms.Label
Friend WithEvents Label11 As System.Windows.Forms.Label
Friend WithEvents SpeedInRangeBox As System.Windows.Forms.Label
Friend WithEvents Label13 As System.Windows.Forms.Label
Friend WithEvents CurrentStatusBox As System.Windows.Forms.Label
Friend WithEvents GroupBox1 As System.Windows.Forms.GroupBox
Friend WithEvents GroupBox2 As System.Windows.Forms.GroupBox
Friend WithEvents OnCavitationContinue As System.Windows.Forms.RadioButton
Friend WithEvents OnCavitationStop As System.Windows.Forms.RadioButton
Friend WithEvents ButtonInsertComment As System.Windows.Forms.Button
Friend WithEvents ButtonEnd As System.Windows.Forms.Button
Friend WithEvents ButtonHelp As System.Windows.Forms.Button
Friend WithEvents LogTrace As System.Windows.Forms.TextBox
Friend WithEvents ButtonStopSpeed As System.Windows.Forms.Button
Friend WithEvents ButtonStartSpeed As System.Windows.Forms.Button
Friend WithEvents ButtonSetSpeed As System.Windows.Forms.Button
Friend WithEvents OnCavitationStopAndRestart As
System.Windows.Forms.RadioButton
Friend WithEvents AutomaticPulsingTrue As System.Windows.Forms.RadioButton
Friend WithEvents SetSpeedInputBox As System.Windows.Forms.TextBox
Friend WithEvents Label15 As System.Windows.Forms.Label
Friend WithEvents Label17 As System.Windows.Forms.Label
Friend WithEvents SetSpeedShowBox As System.Windows.Forms.Label
Friend WithEvents Label18 As System.Windows.Forms.Label
Friend WithEvents RestartDelayShowBox As System.Windows.Forms.Label
Friend WithEvents RestartDelayInputBox As System.Windows.Forms.TextBox
Friend WithEvents Label20 As System.Windows.Forms.Label
Friend WithEvents Label22 As System.Windows.Forms.Label

```

```

Friend WithEvents AutomaticPulsingFalse As System.Windows.Forms.RadioButton
Friend WithEvents Label21 As System.Windows.Forms.Label
Friend WithEvents LaserRxBox As System.Windows.Forms.TextBox
Friend WithEvents ButtonFireLaser As System.Windows.Forms.Button
Friend WithEvents ButtonSendLaserCommand As System.Windows.Forms.Button
Friend WithEvents FireLaserBox As System.Windows.Forms.Label
Friend WithEvents ButtonSetLaser As System.Windows.Forms.Button
Friend WithEvents Label26 As System.Windows.Forms.Label
Friend WithEvents EstimatedDurationShowBox As System.Windows.Forms.Label
Friend WithEvents EstimatedDurationInputBox As System.Windows.Forms.TextBox
Friend WithEvents Label23 As System.Windows.Forms.Label
Friend WithEvents LaserDelayShowBox As System.Windows.Forms.Label
Friend WithEvents LaserDelayInputBox As System.Windows.Forms.TextBox
Friend WithEvents Label28 As System.Windows.Forms.Label
Friend WithEvents NextPulsePowerShowBox As System.Windows.Forms.Label
End Class

```

## B.12 RUNBOX.VB

```

Public Class RunBox
    'Code for the RunBox form -- The primary interface between the Code and the
    User that is shown during normal operation

```

```

    Private Sub RunBox_FormClosing(ByVal sender As Object, ByVal e As
System.Windows.Forms.FormClosingEventArgs) Handles Me.FormClosing
        'Stuff to do when the form is closing

```

```

        If e.CloseReason <> CloseReason.None Then
            e.Cancel = True
        End If

```

```

    End Sub

```

```

    Private Sub RunBox_Load(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles MyBase.Load

```

```

        'Stuff to do when the form is loaded
        'set the defaults

```

```

        'set the title

```

```

        Me.Text = My.Application.Info.ProductName & " v. " &
My.Application.Info.Version.Major & "." & My.Application.Info.Version.Minor &
"." & My.Application.Info.Version.Build & "." &
My.Application.Info.Version.Revision

```

```

        'set default values for the speed control side

```

```

        OnCavitationStop.Checked = True
        RestartDelayInputBox.Text = "5"
        RestartDelayShowBox.Text = "5"
        SetSpeedInputBox.Text = "0"
        SetSpeedShowBox.Text = "0"

```

```

        'set default values for the laser control side

```

```

        NextPulsePowerShowBox.Text = "1"

```

```

EstimatedDurationInputBox.Text = "0.00001"
EstimatedDurationShowBox.Text = "0.00001"
LaserDelayInputBox.Text = "2.5"
LaserDelayShowBox.Text = "2.5"
AutomaticPulsingFalse.Checked = True

'send the values to the shared variables
SyncLock Windowsill.RunBoxLock
    'load laser control values
    Windowsill.NextLaserPulsePower = Val(NextPulsePowerShowBox.Text)
    Windowsill.EstimatedLaserPulseDuration =
Val (EstimatedDurationShowBox.Text)
    Windowsill.DelayBetweenPulses = Val(LaserDelayShowBox.Text)
    Windowsill.AutomaticPulsing = AutomaticPulsingTrue.Checked
    'load speed control values
    Windowsill.RunButtonClicked = False
    Windowsill.DesiredSpeed = Val(SetSpeedShowBox.Text)
    Windowsill.RestartDelayTime = Val(RestartDelayShowBox.Text)
    If OnCavitationContinue.Checked = True Then
        'continue on cavitation
        Windowsill.CavitationAction = 0
    ElseIf OnCavitationStop.Checked = True Then
        'stop
        Windowsill.CavitationAction = 1
    ElseIf OnCavitationStopAndRestart.Checked = True Then
        'stop and restart
        Windowsill.CavitationAction = 2
    Else
        '?'
        Windowsill.CavitationAction = 3
    End If
End SyncLock

End Sub

Private Sub ButtonInsertComment_Click(ByVal sender As System.Object, ByVal
e As System.EventArgs) Handles ButtonInsertComment.Click
    'User wants to Insert a Comment into the Logfile

    InsertComment.Show()
    InsertComment.BringToFront()

End Sub

Private Sub ButtonHelp_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles ButtonHelp.Click
    'User thinks help may be available
    'HAHAHAHAHAHA

    HelpBox.Show()
    HelpBox.BringToFront()

End Sub

```

```

Private Sub ButtonEnd_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles ButtonEnd.Click
    'User click on the END button

    Dim LocalExit As Boolean

    'make sure a shutdown is not already in progress
    SyncLock CentralClass.ProgramExitLock
        LocalExit = CentralClass.ExitProgram
    End SyncLock
    If LocalExit = False Then
        'make sure User wants to Exit
        If MsgBox("Do you really want to End the Program?",
MsgBoxStyle.YesNo, "End it all?") = MsgBoxResult.Yes Then
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
            Lumberjack.SendToLog("Program Shutdown Initiated by User")
        End If
    End If
    Application.DoEvents()

End Sub

```

```

Private Sub ButtonFireLaser_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles ButtonFireLaser.Click
    'fire a user-defined pulse from the laser
    Dim FormerState As Boolean

    'first disable automatic pulsing
    SyncLock Windowsill.RunBoxLock
        FormerState = Windowsill.AutomaticPulsing
        Windowsill.AutomaticPulsing = False
        Me.AutomaticPulsingFalse.Checked = True
    End SyncLock
    'log the event
    If FormerState = True Then
        Lumberjack.SendToLog("Disable Automatic Laser Pulsing")
    End If

    'then show the pulse box
    FirePulse.Show()
    FirePulse.BringToFront()
    Application.DoEvents()

End Sub

```

```

Private Sub ButtonSendLaserCommand_Click(ByVal sender As System.Object,
ByVal e As System.EventArgs) Handles ButtonSendLaserCommand.Click
    'Send a text command to the laser
    Dim FormerState As Boolean

    'first disable automatic pulsing
    SyncLock Windowsill.RunBoxLock

```

```

        FormerState = Windowsill.AutomaticPulsing
        Windowsill.AutomaticPulsing = False
        Me.AutomaticPulsingFalse.Checked = True
    End SyncLock
    'log the event
    If FormerState = True Then
        Lumberjack.SendToLog("Disable Automatic Laser Pulsing")
    End If

    'then show the command box
    SendLaserCommand.Show()
    SendLaserCommand.BringToFront()
    Application.DoEvents()

End Sub

```

```

Private Sub AutomaticPulsingFalse_Click(ByVal sender As Object, ByVal e As
System.EventArgs) Handles AutomaticPulsingFalse.Click
    'immediately disabele automatic pulsing
    Dim FormerState As Boolean

    SyncLock Windowsill.RunBoxLock
        FormerState = Windowsill.AutomaticPulsing
        Windowsill.AutomaticPulsing = False
        Me.AutomaticPulsingFalse.Checked = True
    End SyncLock
    'log the event
    If FormerState = True Then
        Lumberjack.SendToLog("Disable Automatic Laser Pulsing")
    End If
    Application.DoEvents()

End Sub

```

```

Private Sub ButtonStartSpeed_Click(ByVal sender As System.Object, ByVal e
As System.EventArgs) Handles ButtonStartSpeed.Click
    'user pushed start

    'alert the program
    SyncLock Windowsill.RunBoxLock
        Windowsill.RunButtonClicked = True
    End SyncLock

    'disable the start button
    Me.ButtonStartSpeed.Enabled = False
    'enable the stop button
    Me.ButtonStopSpeed.Enabled = True
    'log the event
    Lumberjack.SendToLog("Start Automatically Controlling the Speed")
    Application.DoEvents()

End Sub

```

```

Private Sub ButtonStopSpeed_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles ButtonStopSpeed.Click
    'something pushed stop

    Dim OldStatus As Boolean
    Dim ShuttingDown As Boolean

    'alert the program
    SyncLock Windowsill.RunBoxLock
        OldStatus = Windowsill.RunButtonClicked
        Windowsill.RunButtonClicked = False
    End SyncLock

    'disable the stop button
    Me.ButtonStopSpeed.Enabled = False
    'enable the start button, unless shutting down
    Me.ButtonStartSpeed.Enabled = True
    'get shutdown status
    SyncLock CentralClass.ProgramExitLock
        ShuttingDown = CentralClass.ExitProgram
    End SyncLock
    If ShuttingDown = True Then
        'disable button if shutting down
        Me.ButtonStartSpeed.Enabled = False
    End If
    Application.DoEvents()
    'log the event, unless nothing changed
    If OldStatus = True Then
        Lumberjack.SendToLog("Stop Automatically Controlling the Speed")
    End If
    'stop autopulsing
    Call StopAutomaticPulsing()

End Sub

Friend Sub StopAutomaticPulsing()
    'call from main thread

    Call AutomaticPulsingFalse_Click(Me, EventArgs.Empty)

End Sub

Friend Sub PressStopButton()
    'call from main thread

    Call ButtonStopSpeed_Click(Me, EventArgs.Empty)

End Sub

Private Sub ButtonSetSpeed_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles ButtonSetSpeed.Click
    'sets the speed control values

```



```

Try

Dim DesiredSpeedChanged As Boolean = False
Dim NewDesiredSpeed As Double = 0
Dim RestartDelayTimeChanged As Boolean = False
Dim NewDelayTime As Double = 0
Dim CavitationActionChanged As Boolean = False
Dim NewCavitationAction As Long = 0
Dim UpdateSpeed As Boolean = False
Dim UpdateDelay As Boolean = False
Dim DelayHolder As Double = -1

'load delay time value
Try
    DelayHolder = Val(RestartDelayInputBox.Text)
    UpdateDelay = True
Catch BadDelayValue As OverflowException
    'bad value for new delay time
    UpdateDelay = False
    DelayHolder = -1
    MsgBox("Illegal Value for the new Delay Time" & vbNewLine &
RestartDelayInputBox.Text, , "Overflow")
End Try

'send the values to the shared variables
If DelayHolder >= 0 Then
    NewDelayTime = DelayHolder
    'load speed control values
    Try
        NewDesiredSpeed = Val(SetSpeedInputBox.Text)
        UpdateSpeed = True
    Catch TooMuchSpeed As OverflowException
        'bad value for speed
        UpdateSpeed = False
        MsgBox("Illegal Value for the new Speed" & vbNewLine &
SetSpeedInputBox.Text, , "Overflow")
    End Try

    'cavitation action
    If OnCavitationContinue.Checked = True Then
        'continue on cavitation
        NewCavitationAction = 0
    ElseIf OnCavitationStop.Checked = True Then
        'stop
        NewCavitationAction = 1
    ElseIf OnCavitationStopAndRestart.Checked = True Then
        'stop and restart
        NewCavitationAction = 2
    Else
        '?'
        NewCavitationAction = 3
    End If
    SyncLock Windowsill.RunBoxLock
        'commit changes
        If NewCavitationAction <> Windowsill.CavitationAction Then
            'action on cavitation changed
            Windowsill.CavitationAction = NewCavitationAction
            CavitationActionChanged = True
        End If
    End SyncLock
End If

```

```

        End If
        If UpdateSpeed = True Then
            If NewDesiredSpeed <> Windowsill.DesiredSpeed Then
                'desired speed changed
                Windowsill.DesiredSpeed = NewDesiredSpeed
                DesiredSpeedChanged = True
            End If
        End If
        If UpdateDelay = True Then
            If NewDelayTime <> Windowsill.RestartDelayTime Then
                'restart delay changed
                Windowsill.RestartDelayTime = NewDelayTime
                RestartDelayTimeChanged = True
            End If
        End If
    End SyncLock
Else
    Beep()
    MsgBox("Restart Delays must be >=0, no values changed")
End If

'now log any changes
If DesiredSpeedChanged = True Then
    Lumberjack.SendToLog("Desired Control Speed changed to " &
Str(NewDesiredSpeed))
End If
If RestartDelayTimeChanged = True Then
    Lumberjack.SendToLog("Restart Delay Time changed to " &
Str(NewDelayTime))
End If
If CavitationActionChanged = True Then
    If NewCavitationAction = 0 Then
        Lumberjack.SendToLog("Action on cavitation changed to
Continue")
    ElseIf NewCavitationAction = 1 Then
        Lumberjack.SendToLog("Action on cavitation changed to
Stop")
    ElseIf NewCavitationAction = 2 Then
        Lumberjack.SendToLog("Action on cavitation changed to Stop
+ Restart")
    Else
        Lumberjack.SendToLog("Action on cavitation changed to
?????")
    End If
End If

Application.DoEvents()

Catch TooBig As OverflowException
    'something overflowed
    Lumberjack.SendToLog("Recoverable Exception in " &
Thread.CurrentThread.Name & ": " & TooBig.Message & vbNewLine & "Details: " &
vbNewLine & TooBig.ToString)
    MsgBox("An Overflow Exception has occurred in " &
Thread.CurrentThread.Name & ", but execution will continue. Details: " &
vbNewLine & TooBig.ToString, , "OUCH!")
Catch BigException As Exception
    'something got really screwed up

```

```

        Lumberjack.SendToLog("Exception in " & Thread.CurrentThread.Name &
": " & BigException.Message & vbNewLine & "Details: " & vbNewLine &
BigException.ToString)
        MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End Try

End Sub

```

```

Private Sub ButtonSetLaser_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles ButtonSetLaser.Click
    'sets the laser control values

    Try

        Dim ChangedPulseDuration As Boolean = False
        Dim NewPulseDuration As Double = 0
        Dim ChangedPulseDelay As Boolean = False
        Dim NewPulseDelay As Double = 0
        Dim ChangedAutoPulsing As Boolean = False
        Dim NewAutoPulsing As Boolean = False
        Dim DurationHolder As Double = -1
        Dim DelayHolder As Double = -1

        'test the values
        Try
            DurationHolder = Val(EstimatedDurationInputBox.Text)
            Catch TooMuchSpeed As OverflowException
                'bad value for duration
                MsgBox("Illegal Value for the new Estimated Duration:" &
vbNewLine & EstimatedDurationInputBox.Text, , "Overflow")
                DurationHolder = -1
            End Try

        Try
            DelayHolder = Val(LaserDelayInputBox.Text)
            Catch TooMuchSpeed As OverflowException
                'bad value for duration
                MsgBox("Illegal Value for the new Delay Between Pulses:" &
vbNewLine & LaserDelayInputBox.Text, , "Overflow")
                DelayHolder = -1
            End Try

        'sanity check
        If DurationHolder >= 0 Then
            'it works so far
            NewPulseDuration = DurationHolder
            If DelayHolder > 0 Then
                'both work
                NewPulseDelay = DelayHolder
                NewAutoPulsing = AutomaticPulsingTrue.Checked
                SyncLock Windowsill.RunBoxLock
                    'load laser control values

```

```

        If Windowsill.EstimatedLaserPulseDuration <>
NewPulseDuration Then
            ChangedPulseDuration = True
            Windowsill.EstimatedLaserPulseDuration =
NewPulseDuration
        End If
        If Windowsill.DelayBetweenPulses <> NewPulseDelay Then
            ChangedPulseDelay = True
            Windowsill.DelayBetweenPulses = NewPulseDelay
        End If
        If WindowsillAutomaticPulsing <> NewAutoPulsing Then
            ChangedAutoPulsing = True
            WindowsillAutomaticPulsing = NewAutoPulsing
        End If
    End SyncLock
Else
    MsgBox("Delay between laser pulses must be >0")
End If
Else
    MsgBox("Estimated Pulse Duration values must be >=0")
End If

'log the changes
If ChangedPulseDuration = True Then
    Lumberjack.SendToLog("Estimated Laser Pulse Duration changed to
" & Str(NewPulseDuration))
End If
If ChangedPulseDelay = True Then
    Lumberjack.SendToLog("Changed Delay between Laser Pulses to " &
Str(NewPulseDelay))
End If
If ChangedAutoPulsing = True Then
    If NewAutoPulsing = True Then
        Lumberjack.SendToLog("Changed to Automatic Laser Pulsing")
    Else
        Lumberjack.SendToLog("Changed to Manual Laser Pulsing")
    End If
End If
Application.DoEvents()

Catch TooBig As OverflowException
    'something overflowed
    Lumberjack.SendToLog("Recoverable Exception in " &
Thread.CurrentThread.Name & ": " & TooBig.Message & vbNewLine & "Details: " &
vbNewLine & TooBig.ToString)
    MsgBox("An Overflow Exception has occurred in " &
Thread.CurrentThread.Name & ", but execution will continue. Details: " &
vbNewLine & TooBig.ToString, , "OUCH!")
    Catch BigException As Exception
        'something got really screwed up
        Lumberjack.SendToLog("Exception in " & Thread.CurrentThread.Name &
": " & BigException.Message & vbNewLine & "Details: " & vbNewLine &
BigException.ToString)
        MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock

```

```

        End Try

    End Sub

End Class

```

### B.13 SENDLASERCOMMAND.DESIGNER.VB

```

<Global.Microsoft.VisualBasic.CompilerServices.DesignerGenerated()> _
Partial Class SendLaserCommand
    Inherits System.Windows.Forms.Form

    'Form overrides dispose to clean up the component list.
    <System.Diagnostics.DebuggerNonUserCode()> _
    Protected Overrides Sub Dispose(ByVal disposing As Boolean)
        Try
            If disposing AndAlso components IsNot Nothing Then
                components.Dispose()
            End If
        Finally
            MyBase.Dispose(disposing)
        End Try
    End Sub

    'Required by the Windows Form Designer
    Private components As System.ComponentModel.IContainer

    'NOTE: The following procedure is required by the Windows Form Designer
    'It can be modified using the Windows Form Designer.
    'Do not modify it using the code editor.
    <System.Diagnostics.DebuggerStepThrough()> _
    Private Sub InitializeComponent()
        Dim resources As System.ComponentModel.ComponentResourceManager = New
System.ComponentModel.ComponentResourceManager(GetType(SendLaserCommand))
        Me.CommandText = New System.Windows.Forms.TextBox
        Me.CancelCommandButton = New System.Windows.Forms.Button
        Me.SendCommandButton = New System.Windows.Forms.Button
        Me.CommandNoteBox = New System.Windows.Forms.Label
        Me.NewlineButton = New System.Windows.Forms.Button
        Me.SuspendLayout()
        '
        'CommandText
        '
        Me.CommandText.AcceptsReturn = True
        Me.CommandText.Location = New System.Drawing.Point(12, 12)
        Me.CommandText.MaximumSize = New System.Drawing.Size(270, 206)
        Me.CommandText.MinimumSize = New System.Drawing.Size(270, 206)
        Me.CommandText.Multiline = True
        Me.CommandText.Name = "CommandText"
        Me.CommandText.ScrollBars = System.Windows.Forms.ScrollBars.Vertical
        Me.CommandText.Size = New System.Drawing.Size(270, 206)
        Me.CommandText.TabIndex = 0
        '
        'CancelCommandButton
        '
    End Sub

```

```

Me.CancelCommandButton.Location = New System.Drawing.Point(207, 224)
Me.CancelCommandButton.MaximumSize = New System.Drawing.Size(75, 23)
Me.CancelCommandButton.MinimumSize = New System.Drawing.Size(75, 23)
Me.CancelCommandButton.Name = "CancelCommandButton"
Me.CancelCommandButton.Size = New System.Drawing.Size(75, 23)
Me.CancelCommandButton.TabIndex = 2
Me.CancelCommandButton.Text = "Cancel"
Me.CancelCommandButton.UseVisualStyleBackColor = True
'
'SendCommandButton
'
Me.SendCommandButton.Location = New System.Drawing.Point(12, 224)
Me.SendCommandButton.MaximumSize = New System.Drawing.Size(75, 23)
Me.SendCommandButton.MinimumSize = New System.Drawing.Size(75, 23)
Me.SendCommandButton.Name = "SendCommandButton"
Me.SendCommandButton.Size = New System.Drawing.Size(75, 23)
Me.SendCommandButton.TabIndex = 1
Me.SendCommandButton.Text = "OK"
Me.SendCommandButton.UseVisualStyleBackColor = True
'
'CommandNoteBox
'
Me.CommandNoteBox.AutoSize = True
Me.CommandNoteBox.BorderStyle =
System.Windows.Forms.BorderStyle.Fixed3D
Me.CommandNoteBox.FlatStyle = System.Windows.Forms.FlatStyle.Flat
Me.CommandNoteBox.Location = New System.Drawing.Point(12, 250)
Me.CommandNoteBox.MaximumSize = New System.Drawing.Size(270, 15)
Me.CommandNoteBox.MinimumSize = New System.Drawing.Size(270, 15)
Me.CommandNoteBox.Name = "CommandNoteBox"
Me.CommandNoteBox.Size = New System.Drawing.Size(270, 15)
Me.CommandNoteBox.TabIndex = 3
'
'NewlineButton
'
Me.NewlineButton.Location = New System.Drawing.Point(99, 224)
Me.NewlineButton.MaximumSize = New System.Drawing.Size(96, 23)
Me.NewlineButton.MinimumSize = New System.Drawing.Size(96, 23)
Me.NewlineButton.Name = "NewlineButton"
Me.NewlineButton.Size = New System.Drawing.Size(96, 23)
Me.NewlineButton.TabIndex = 4
Me.NewlineButton.Text = "Insert EOL"
Me.NewlineButton.UseVisualStyleBackColor = True
'
'SendLaserCommand
'
Me.AutoScaleDimensions = New System.Drawing.SizeF(6.0!, 13.0!)
Me.AutoScaleMode = System.Windows.Forms.AutoScaleMode.Font
Me.ClientSize = New System.Drawing.Size(294, 268)
Me.Controls.Add(Me.NewlineButton)
Me.Controls.Add(Me.CommandNoteBox)
Me.Controls.Add(Me.CommandText)
Me.Controls.Add(Me.CancelCommandButton)
Me.Controls.Add(Me.SendCommandButton)
Me.FormBorderStyle = System.Windows.Forms.FormBorderStyle.FixedDialog
Me.Icon = CType(resources.GetObject("$this.Icon"), System.Drawing.Icon)
Me.MaximizeBox = False
Me.MaximumSize = New System.Drawing.Size(300, 300)
Me.MinimizeBox = False

```

```

    Me.MinimumSize = New System.Drawing.Size(300, 300)
    Me.Name = "SendLaserCommand"
    Me.ShowIcon = False
    Me.SizeGripStyle = System.Windows.Forms.SizeGripStyle.Hide
    Me.Text = "Send Command to Laser"
    Me.ResumeLayout(False)
    Me.PerformLayout()

End Sub
Friend WithEvents CommandText As System.Windows.Forms.TextBox
Friend WithEvents CancelCommandButton As System.Windows.Forms.Button
Friend WithEvents SendCommandButton As System.Windows.Forms.Button
Friend WithEvents CommandNoteBox As System.Windows.Forms.Label
Friend WithEvents NewlineButton As System.Windows.Forms.Button
End Class

```

## B.14 SENDLASERCOMMAND.VB

```

Public Class SendLaserCommand
    'Code for the SendLaserCommand form -- the form that shows when the User
    wishes to manually send a string of text to the laser

    Private Shared SendingCommand As Boolean = False
    Private Shared SendLockObj As New Object

    Private Sub SendLaserCommand_FormClosing(ByVal sender As Object, ByVal e As
System.Windows.Forms.FormClosingEventArgs) Handles Me.FormClosing
        'Stuff to do when the form is closing

        If e.CloseReason <> CloseReason.None Then
            e.Cancel = True
        End If
    End Sub

    Private Sub CancelCommandButton_Click(ByVal sender As System.Object, ByVal
e As System.EventArgs) Handles CancelCommandButton.Click
        'cancel any action and close the box

        CommandText.Text = ""
        CommandNoteBox.Text = ""
        Me.Hide()
    End Sub

    Private Sub SendCommandButton_Click(ByVal sender As System.Object, ByVal e
As System.EventArgs) Handles SendCommandButton.Click
        'send any text to the laser

```

```

Dim TextToSend As String = ""
Dim DatalineLockdown As Boolean = False
Dim InUse As Boolean = False

'only one send at a time
SyncLock SendLockObj
    InUse = SendingCommand
    If SendingCommand = False Then
        'indicate that the thing is in use
        SendingCommand = True
    End If
End SyncLock

If InUse = False Then
    'we can proceed; there is not an overlapping attempt
    'get the command and clear the box
    TextToSend = CommandText.Text
    CommandText.Text = ""
    CommandNoteBox.Text = ""
    Me.Hide()

    SyncLock Windowsill.RunBoxLock
        'only xmit if the line is clear
        DatalineLockdown = Windowsill.LaserTXDataCritical
        If DatalineLockdown = False Then
            'copy the text
            Windowsill.CommandToLaser = Windowsill.CommandToLaser &
TextToSend
        End If
    End SyncLock

    'If the line was not clear, restore the box and show the note
    If DatalineLockdown = True Then
        'restore the box
        Me.Show()
        'show an explanatory note
        CommandNoteBox.Text = "Could Not Proceed, Try Again"
        'restore the command text
        CommandText.Text = TextToSend
        CommandText.Select(CommandText.TextLength, 0)
        CommandText.ScrollToCaret()
        Beep()
    Else
        'the line was open, log the transmission
        Lumberjack.SendToLog("The Following User-Issued Command Will Be
Sent To The Laser: " & TextToSend)
    End If

    'unblock the line
    SyncLock SendLockObj
        SendingCommand = False
    End SyncLock

End If

End Sub

```



```

Private Sub NewlineButton_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles NewlineButton.Click
    'inserts a newline character specific to the laser at the caret
location

    Dim EOLString As String
    Dim EditString As String
    Dim CursorLocation As Integer
    Dim SelectedLength As Integer

    'get the newline sequence
    SyncLock CentralClass.FileOpsLock
        EOLString = CentralClass.LaserNewlineString
    End SyncLock

    SyncLock SendLockObj
        'only proceed if a send is not currently being issued
        'lock down the text box
        CommandText.ReadOnly = True
        'get the text
        EditString = CommandText.Text
        'get the caret or selection begin location and selection length
        CursorLocation = CommandText.SelectionStart
        SelectedLength = CommandText.SelectionLength
        'insert the eol sequence
        CommandText.Text = EditString.Insert(CursorLocation, EOLString)
        'shift the selection
        CommandText.SelectionStart = CursorLocation + 1
        CommandText.SelectionLength = SelectedLength
        'unlock the box
        CommandText.ReadOnly = False
    End SyncLock

End Sub

End Class

```

## B.15 STARTUPFORM.DESIGNER.VB

```

<Global.Microsoft.VisualBasic.CompilerServices.DesignerGenerated()> _
Partial Class StartupForm
    Inherits System.Windows.Forms.Form

    'Form overrides dispose to clean up the component list.
    <System.Diagnostics.DebuggerNonUserCode()> _
    Protected Overrides Sub Dispose(ByVal disposing As Boolean)
        Try
            If disposing AndAlso components IsNot Nothing Then
                components.Dispose()
            End If
        Finally
            MyBase.Dispose(disposing)
        End Try
    End Sub

```

```

'Required by the Windows Form Designer
Private components As System.ComponentModel.IContainer

'NOTE: The following procedure is required by the Windows Form Designer
'It can be modified using the Windows Form Designer.
'Do not modify it using the code editor.
<System.Diagnostics.DebuggerStepThrough()> _
Private Sub InitializeComponent()
    Dim resources As System.ComponentModel.ComponentResourceManager = New
System.ComponentModel.ComponentResourceManager(GetType(StartupForm))
    Me.OKButton = New System.Windows.Forms.Button
    Me.ProgramHelpButton = New System.Windows.Forms.Button
    Me.ExitButton = New System.Windows.Forms.Button
    Me.FileNameBox = New System.Windows.Forms.TextBox
    Me.RadioButtonAppend = New System.Windows.Forms.RadioButton
    Me.RadioButtonReplace = New System.Windows.Forms.RadioButton
    Me.BrowseButton = New System.Windows.Forms.Button
    Me.Panel1 = New System.Windows.Forms.Panel
    Me.Label1 = New System.Windows.Forms.Label
    Me.Label2 = New System.Windows.Forms.Label
    Me.Label3 = New System.Windows.Forms.Label
    Me.ControllerPortComboBox = New System.Windows.Forms.ComboBox
    Me.LaserPortComboBox = New System.Windows.Forms.ComboBox
    Me.PortSpeedComboBox = New System.Windows.Forms.ComboBox
    Me.Label4 = New System.Windows.Forms.Label
    Me.TimingCheckBox = New System.Windows.Forms.CheckBox
    Me.Panel1.SuspendLayout()
    Me.SuspendLayout()
    '
    'OKButton
    '
    Me.OKButton.Location = New System.Drawing.Point(46, 256)
    Me.OKButton.MaximumSize = New System.Drawing.Size(128, 40)
    Me.OKButton.MinimumSize = New System.Drawing.Size(128, 40)
    Me.OKButton.Name = "OKButton"
    Me.OKButton.Size = New System.Drawing.Size(128, 40)
    Me.OKButton.TabIndex = 7
    Me.OKButton.Text = "OK"
    Me.OKButton.UseVisualStyleBackColor = True
    '
    'ProgramHelpButton
    '
    Me.ProgramHelpButton.Location = New System.Drawing.Point(211, 256)
    Me.ProgramHelpButton.MaximumSize = New System.Drawing.Size(128, 40)
    Me.ProgramHelpButton.MinimumSize = New System.Drawing.Size(128, 40)
    Me.ProgramHelpButton.Name = "ProgramHelpButton"
    Me.ProgramHelpButton.Size = New System.Drawing.Size(128, 40)
    Me.ProgramHelpButton.TabIndex = 8
    Me.ProgramHelpButton.Text = "Help"
    Me.ProgramHelpButton.UseVisualStyleBackColor = True
    '
    'ExitButton
    '
    Me.ExitButton.Location = New System.Drawing.Point(368, 256)
    Me.ExitButton.MaximumSize = New System.Drawing.Size(128, 40)
    Me.ExitButton.MinimumSize = New System.Drawing.Size(128, 40)
    Me.ExitButton.Name = "ExitButton"
    Me.ExitButton.Size = New System.Drawing.Size(128, 40)

```

```

Me.ExitButton.TabIndex = 9
Me.ExitButton.Text = "Exit"
Me.ExitButton.UseVisualStyleBackColor = True
'
'FilenameBox
'
Me.FilenameBox.Location = New System.Drawing.Point(22, 95)
Me.FilenameBox.MaximumSize = New System.Drawing.Size(406, 20)
Me.FilenameBox.MinimumSize = New System.Drawing.Size(406, 20)
Me.FilenameBox.Name = "FilenameBox"
Me.FilenameBox.Size = New System.Drawing.Size(406, 20)
Me.FilenameBox.TabIndex = 4
Me.FilenameBox.Text = "output.txt"
'
'RadioButtonAppend
'
Me.RadioButtonAppend.AutoSize = True
Me.RadioButtonAppend.Checked = True
Me.RadioButtonAppend.Location = New System.Drawing.Point(194, 51)
Me.RadioButtonAppend.MaximumSize = New System.Drawing.Size(62, 17)
Me.RadioButtonAppend.MinimumSize = New System.Drawing.Size(62, 17)
Me.RadioButtonAppend.Name = "RadioButtonAppend"
Me.RadioButtonAppend.Size = New System.Drawing.Size(62, 17)
Me.RadioButtonAppend.TabIndex = 2
Me.RadioButtonAppend.TabStop = True
Me.RadioButtonAppend.Text = "Append"
Me.RadioButtonAppend.UseVisualStyleBackColor = True
'
'RadioButtonReplace
'
Me.RadioButtonReplace.AutoSize = True
Me.RadioButtonReplace.Location = New System.Drawing.Point(363, 51)
Me.RadioButtonReplace.MaximumSize = New System.Drawing.Size(65, 17)
Me.RadioButtonReplace.MinimumSize = New System.Drawing.Size(65, 17)
Me.RadioButtonReplace.Name = "RadioButtonReplace"
Me.RadioButtonReplace.Size = New System.Drawing.Size(65, 17)
Me.RadioButtonReplace.TabIndex = 3
Me.RadioButtonReplace.Text = "Replace"
Me.RadioButtonReplace.UseVisualStyleBackColor = True
'
'BrowseButton
'
Me.BrowseButton.Location = New System.Drawing.Point(22, 46)
Me.BrowseButton.MaximumSize = New System.Drawing.Size(86, 26)
Me.BrowseButton.MinimumSize = New System.Drawing.Size(86, 26)
Me.BrowseButton.Name = "BrowseButton"
Me.BrowseButton.Size = New System.Drawing.Size(86, 26)
Me.BrowseButton.TabIndex = 1
Me.BrowseButton.Text = "Browse..."
Me.BrowseButton.UseVisualStyleBackColor = True
'
'Panell
'
Me.Panell.Controls.Add(Me.Label1)
Me.Panell.Controls.Add(Me.BrowseButton)
Me.Panell.Controls.Add(Me.RadioButtonReplace)
Me.Panell.Controls.Add(Me.RadioButtonAppend)
Me.Panell.Controls.Add(Me.FilenameBox)
Me.Panell.Location = New System.Drawing.Point(46, 97)

```

```

Me.Panel1.MaximumSize = New System.Drawing.Size(450, 128)
Me.Panel1.MinimumSize = New System.Drawing.Size(450, 128)
Me.Panel1.Name = "Panel1"
Me.Panel1.Size = New System.Drawing.Size(450, 128)
Me.Panel1.TabIndex = 6
'
'Label1
'
Me.Label1.AutoSize = True
Me.Label1.Font = New System.Drawing.Font("Microsoft Sans Serif", 16.0!,
System.Drawing.FontStyle.Regular, System.Drawing.GraphicsUnit.Point, CType(0,
Byte))
Me.Label1.Location = New System.Drawing.Point(181, 11)
Me.Label1.MaximumSize = New System.Drawing.Size(89, 26)
Me.Label1.MinimumSize = New System.Drawing.Size(89, 26)
Me.Label1.Name = "Label1"
Me.Label1.Size = New System.Drawing.Size(89, 26)
Me.Label1.TabIndex = 0
Me.Label1.Text = "Log File"
'
'Label2
'
Me.Label2.AutoSize = True
Me.Label2.Font = New System.Drawing.Font("Microsoft Sans Serif", 12.0!,
System.Drawing.FontStyle.Regular, System.Drawing.GraphicsUnit.Point, CType(0,
Byte))
Me.Label2.Location = New System.Drawing.Point(42, 24)
Me.Label2.MaximumSize = New System.Drawing.Size(128, 20)
Me.Label2.MinimumSize = New System.Drawing.Size(120, 20)
Me.Label2.Name = "Label2"
Me.Label2.Size = New System.Drawing.Size(120, 20)
Me.Label2.TabIndex = 0
Me.Label2.Text = "Controller Port"
'
'Label3
'
Me.Label3.AutoSize = True
Me.Label3.Font = New System.Drawing.Font("Microsoft Sans Serif", 12.0!,
System.Drawing.FontStyle.Regular, System.Drawing.GraphicsUnit.Point, CType(0,
Byte))
Me.Label3.Location = New System.Drawing.Point(207, 24)
Me.Label3.MaximumSize = New System.Drawing.Size(82, 20)
Me.Label3.MinimumSize = New System.Drawing.Size(82, 20)
Me.Label3.Name = "Label3"
Me.Label3.Size = New System.Drawing.Size(82, 20)
Me.Label3.TabIndex = 2
Me.Label3.Text = "Laser Port"
'
'ControllerPortComboBox
'
Me.ControllerPortComboBox.DropDownStyle =
System.Windows.Forms.ComboBoxStyle.DropDownList
Me.ControllerPortComboBox.FormattingEnabled = True
Me.ControllerPortComboBox.Items.AddRange(New Object() {"(none)"})
Me.ControllerPortComboBox.Location = New System.Drawing.Point(46, 47)
Me.ControllerPortComboBox.MaximumSize = New System.Drawing.Size(128, 0)
Me.ControllerPortComboBox.MinimumSize = New System.Drawing.Size(128, 0)
Me.ControllerPortComboBox.Name = "ControllerPortComboBox"
Me.ControllerPortComboBox.Size = New System.Drawing.Size(128, 21)

```

```

Me.ControllerPortComboBox.TabIndex = 1
'
'LaserPortComboBox
'
Me.LaserPortComboBox.DropDownStyle =
System.Windows.Forms.ComboBoxStyle.DropDownList
Me.LaserPortComboBox.FormattingEnabled = True
Me.LaserPortComboBox.Items.AddRange(New Object() {"(none)"})
Me.LaserPortComboBox.Location = New System.Drawing.Point(211, 47)
Me.LaserPortComboBox.MaximumSize = New System.Drawing.Size(128, 0)
Me.LaserPortComboBox.MinimumSize = New System.Drawing.Size(128, 0)
Me.LaserPortComboBox.Name = "LaserPortComboBox"
Me.LaserPortComboBox.Size = New System.Drawing.Size(128, 21)
Me.LaserPortComboBox.TabIndex = 3
'
'PortSpeedComboBox
'
Me.PortSpeedComboBox.DropDownStyle =
System.Windows.Forms.ComboBoxStyle.DropDownList
Me.PortSpeedComboBox.FormattingEnabled = True
Me.PortSpeedComboBox.Items.AddRange(New Object() {"19200"})
Me.PortSpeedComboBox.Location = New System.Drawing.Point(368, 47)
Me.PortSpeedComboBox.MaximumSize = New System.Drawing.Size(128, 0)
Me.PortSpeedComboBox.MinimumSize = New System.Drawing.Size(128, 0)
Me.PortSpeedComboBox.Name = "PortSpeedComboBox"
Me.PortSpeedComboBox.Size = New System.Drawing.Size(128, 21)
Me.PortSpeedComboBox.TabIndex = 5
'
'Label4
'
Me.Label4.AutoSize = True
Me.Label4.Font = New System.Drawing.Font("Microsoft Sans Serif", 12.0!,
System.Drawing.FontStyle.Regular, System.Drawing.GraphicsUnit.Point, CType(0,
Byte))
Me.Label4.Location = New System.Drawing.Point(364, 24)
Me.Label4.MaximumSize = New System.Drawing.Size(89, 20)
Me.Label4.MinimumSize = New System.Drawing.Size(89, 20)
Me.Label4.Name = "Label4"
Me.Label4.Size = New System.Drawing.Size(89, 20)
Me.Label4.TabIndex = 4
Me.Label4.Text = "Port Speed"
'
'TimingCheckBox
'
Me.TimingCheckBox.AutoSize = True
Me.TimingCheckBox.Checked = True
Me.TimingCheckBox.CheckState = System.Windows.Forms.CheckState.Checked
Me.TimingCheckBox.Location = New System.Drawing.Point(46, 74)
Me.TimingCheckBox.Name = "TimingCheckBox"
Me.TimingCheckBox.Size = New System.Drawing.Size(131, 17)
Me.TimingCheckBox.TabIndex = 10
Me.TimingCheckBox.Text = "Use Advanced Timing"
Me.TimingCheckBox.UseVisualStyleBackColor = True
'
'StartupForm
'
Me.AutoScaleDimensions = New System.Drawing.SizeF(6.0!, 13.0!)
Me.AutoScaleMode = System.Windows.Forms.AutoScaleMode.Font
Me.ClientSize = New System.Drawing.Size(540, 347)

```

```

Me.Controls.Add(Me.TimingCheckBox)
Me.Controls.Add(Me.PortSpeedComboBox)
Me.Controls.Add(Me.Label4)
Me.Controls.Add(Me.LaserPortComboBox)
Me.Controls.Add(Me.ControllerPortComboBox)
Me.Controls.Add(Me.Label3)
Me.Controls.Add(Me.Label2)
Me.Controls.Add(Me.Panell)
Me.Controls.Add(Me.ExitButton)
Me.Controls.Add(Me.ProgramHelpButton)
Me.Controls.Add(Me.OKButton)
Me.FormBorderStyle = System.Windows.Forms.FormBorderStyle.Fixed3D
Me.Icon = CType(resources.GetObject("$this.Icon"), System.Drawing.Icon)
Me.MaximizeBox = False
Me.MaximumSize = New System.Drawing.Size(550, 376)
Me.MinimumSize = New System.Drawing.Size(550, 376)
Me.Name = "StartupForm"
Me.SizeGripStyle = System.Windows.Forms.SizeGripStyle.Hide
Me.Text = "Speed Controller Port and Logfile"
Me.Panell.ResumeLayout(False)
Me.Panell.PerformLayout()
Me.ResumeLayout(False)
Me.PerformLayout()

End Sub
Friend WithEvents OKButton As System.Windows.Forms.Button
Friend WithEvents ProgramHelpButton As System.Windows.Forms.Button
Friend WithEvents ExitButton As System.Windows.Forms.Button
Friend WithEvents FileNameBox As System.Windows.Forms.TextBox
Friend WithEvents RadioButtonAppend As System.Windows.Forms.RadioButton
Friend WithEvents RadioButtonReplace As System.Windows.Forms.RadioButton
Friend WithEvents BrowseButton As System.Windows.Forms.Button
Friend WithEvents Panell As System.Windows.Forms.Panel
Friend WithEvents Label1 As System.Windows.Forms.Label
Friend WithEvents Label2 As System.Windows.Forms.Label
Friend WithEvents Label3 As System.Windows.Forms.Label
Friend WithEvents ControllerPortComboBox As System.Windows.Forms.ComboBox
Friend WithEvents LaserPortComboBox As System.Windows.Forms.ComboBox
Friend WithEvents PortSpeedComboBox As System.Windows.Forms.ComboBox
Friend WithEvents Label4 As System.Windows.Forms.Label
Friend WithEvents TimingCheckBox As System.Windows.Forms.CheckBox
End Class

```

## B.16 STARTUPFORM.VB

```

Public Class StartupForm
    'Code for the StartupForm -- the first form seen by the User on Program
    Startup

    Private Sub BrowseButton_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles BrowseButton.Click
        'The User has clicked on the Browse button in the startup form
        'Shows a file dialog to save the output log file

        'Create the SaveFileDialog

```

```

    Dim LogFileDialog1 As New SaveFileDialog
    'Set the windows title
    LogFileDialog1.Title = "Output Log File"
    'Set the File Filters, defaulting to text
    LogFileDialog1.Filter = "Text File (*.txt)|*.txt|All Files (*.*)|*.*"
    LogFileDialog1.FilterIndex = 1
    'Set the initial directory to My Documents
    LogFileDialog1.InitialDirectory =
Environment.GetFolderPath(Environment.SpecialFolder.MyDocuments)
    'Automatically add an extension matching the filter
    LogFileDialog1.DefaultExt = ""
    LogFileDialog1.AddExtension = True
    LogFileDialog1.CheckFileExists = False
    LogFileDialog1.OverwritePrompt = False
    LogFileDialog1.CheckPathExists = True
    'Show the dialog
    LogFileDialog1.ShowDialog()
    'Copy the filename to the filename textbox
    If LogFileDialog1.FileName <> "" Then
        FileNameBox.Text = LogFileDialog1.FileName
    End If
    Application.DoEvents()

End Sub

    Private Sub ExitButton_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles ExitButton.Click
    'Exit Button has been clicked, shut down

    'This should already be the case, but to be sure set the Exit flag
    SyncLock CentralClass.ProgramExitLock
        CentralClass.ExitProgram = True
    End SyncLock
    Me.Hide()

End Sub

    Private Sub OKButton_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles OKButton.Click
    'OK Button has been clicked, do final checks and continue

    Dim CurrentSender As New System.Object
    Dim SecondArg As New
System.Windows.Forms.FormClosingEventArgs(CloseReason.None, False)

    'Set the Exit flag to False to continue execution
    SyncLock CentralClass.ProgramExitLock
        CentralClass.ExitProgram = False
    End SyncLock
    StartupForm_FormClosing(CurrentSender, SecondArg)

    Me.Hide()

End Sub

```

```

Private Sub StartupForm_FormClosing(ByVal sender As Object, ByVal e As
System.Windows.Forms.FormClosingEventArgs) Handles Me.FormClosing
    'Stuff to run when the form is closing
    'loads the form's data into the main class

    SyncLock CentralClass.FileOpsLock
        'set the filename
        CentralClass.Filename = FilenameBox.Text
        'set the append/replace flag
        If RadioButtonAppend.Checked = True Then
            CentralClass.AppendFile = True
        ElseIf RadioButtonReplace.Checked = True Then
            CentralClass.AppendFile = False
        End If
        'set the port speed
        CentralClass.ComPortBaudRate =
CInt((Val(PortSpeedComboBox.SelectedItem)))
        'set the ports
        CentralClass.LaserPort = LaserPortComboBox.SelectedItem.ToString
        CentralClass.SpeedPort =
ControllerPortComboBox.SelectedItem.ToString
        'set the timing feature
        CentralClass.AdvancedTiming = TimingCheckBox.Checked
    End SyncLock

End Sub

Private Sub StartupForm_Load(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles MyBase.Load
    'Startup events for when the form is loaded

    'Default Selections in the combobox
    ControllerPortComboBox.SelectedIndex = 0
    LaserPortComboBox.SelectedIndex = 0
    PortSpeedComboBox.SelectedIndex = 0
    'default file and location
    FilenameBox.Text =
Environment.GetFolderPath(Environment.SpecialFolder.Desktop) & "\output.txt"

End Sub

Private Sub ProgramHelpButton_Click(ByVal sender As System.Object, ByVal e
As System.EventArgs) Handles ProgramHelpButton.Click
    'The User wants help
    'HAHAHAHAHAHAHAHAHAHA

    'MsgBox("Yeah, right.")
    HelpBox.Show()

End Sub

```



```

    Private Sub StartupForm_Shown(ByVal sender As Object, ByVal e As
System.EventArgs) Handles Me.Shown
        'Runs every time the form is shown, not just the first time it is
loaded

        'Set the Exit flag so that if the form unexpectedly closes the program
ends
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock

    End Sub

End Class

```

## B.17 STEVEDORE.VB

```

Option Explicit On
Option Strict On

Friend NotInheritable Class Stevedore

    'This class handles the primary serial port
    'It controls the speed
    'It also generates the signals for laser control
    'If the mode is correct, those signals will be sent to the primary serial
port
    'However, if two-port mode is being used, the signals will be sent
    'to the other port handler and will be dealt with there
    ,
    ,
    Friend Shared Col_Sanders As New Thread(AddressOf Stevedore.Colonel)
    ,
    ,
    'Serial Port 1 (Speed Port, possibly with Laser Control)
    Friend Shared WithEvents COMPort1 As New System.IO.Ports.SerialPort
    Friend Shared ClearToFireLaser As Boolean = False
    Friend Shared SpeedPortLock As New Object
    ,
    ,
    'Speed Control Port Reader Internal Statics
    Private Shared LastRXTimeTicksSaved As Long = 0
    Private Shared TempRXString As String = ""
    Private Shared NewlineRX As Boolean = False
    Private Shared MainPortReaderLock As New Object
    ,
    ,
    'Speed Control Port Writer Internal Statics
    Private Shared SavedTXString As String = ""
    Private Shared SavedWriteNumber As Integer = 0
    Private Shared MainPortWriterLock As New Object

    Private Shared Sub Colonel()

```

```

'This is the single most important part of the program
'It handles the speed controller serial port
'It maintains the correct speed depending on program state
'Issues the laser fire trigger
'Determines the speed
'And eats up CPU cycles like a fat guy on weed
,
'Individual pins on the serial port should be connected as follows:
,
'Laser Fire Signal:  RTS
'Laser Fire Ground:  GND
'Speed Controller Signal:  DTR
'Speed Controller Ground:  GND
'Speed Sensor Signal:  DSR
'Speed Sensor Ground:  GND
'Cavitation Sensor Signal:  CD
'Cavitation Sensor Ground:  GND
,
'If the Laser Data Port is connected to the Speed Control Port (Program
Mode 1)
'Connect the additional pins as follows:
,
'Data TO Laser Signal:  TXD
'Data TO Laser Ground:  GND
'Data FROM Laser Signal:  RXD
'Data FROM Laser Ground:  GND
,
'For the Control Pins (NOT TXD, RXD, GND):
'A POSITIVE Voltage is shown as the Boolean 'TRUE' in the SerialPort
Holding and Enable values
'A NEGATIVE Voltage is, likewise, a Boolean 'FALSE'
'The hardware default should be a NEGATIVE voltage on every pin
,
'The Advanced Timing Feature is a trick to try to get a more accurate
measurement of the speed
'The speed is measured by counting changes in a control line on the
serial port
'However, if the OS preempts the measurement for a long period, some of
those changes might be missed
'And the speed would therefore get an artificially low measurement
'So, enabling the Advanced Timing Feature looks for overly large chunks
of missing time
'The chunks must be more than twice the average loop duration, and
larger than the period for a half-cycle for the speed
'If it finds such a timeperiod, it will remove that period from the
speed calculations (and consider it a sort of 'dead time')
'It will replace that long time with the time it takes for an average
Main Loop to execute

'Declarations
Dim LocalExecutionStage As Long = 0
Dim ContinueExecution As Boolean = True
Dim LocalTXString As String = ""
Dim LocalRXString As String = ""
Dim LastTime As Long = 0
Dim Tock As Long = 0
Dim Freq As Long = 0

```

```

Dim LastTimeCheckedRead As Long = 0
Dim LastTimeCheckedWrite As Long = 0
Dim LastTimeUpdated As Long = 0
Dim SendData As Boolean = False
Dim TimeBetweenReads As Long = 0
Dim TimeBetweenWriteChecks As Long = 0
Dim TimeBetweenUpdates As Long = 0
Dim Proceed As Boolean = False
Dim LocalPortName As String = ""
Dim LocalPortSpeed As Integer = 0
Dim LocalPortDataBits As Integer = 0
Dim LocalPortStopBits As System.IO.Ports.StopBits =
System.IO.Ports.StopBits.One
Dim LocalPortFlowControl As System.IO.Ports.Handshake =
System.IO.Ports.Handshake.None
Dim LocalPortEncoding As System.Text.Encoding =
System.Text.Encoding.UTF8
Dim LocalPortOpen As Boolean = False
Dim PortUseString As String = ""
Dim LocalProgramMode As Long = 0
Dim SpeedPulsesUp As Double = 0
Dim SpeedPulsesDown As Double = 0
Dim CalculatedSpeed As Double = 0
Dim TargetSpeed As Double = 0
Dim SpeedError As Double = 0.02
Dim TargetSpeedAcquired As Boolean = False
Dim TargetSpeedAcquiredDelayTime As Long = 0
Dim TargetSpeedAcquiredCounterTocks As Long = 0
Dim CavitationDetected As Boolean = False
Dim CavitationDetectedPrevious As Boolean = False
Dim LocalCavitationAction As Long = 1
Dim FiredLaser As Boolean = False
Dim NextLaserPower As Double = 0
Dim SpeedRestartTimeLeft As Double = 0
Dim SpeedRestartStatus As Long = 0
Dim AutoPulsing As Boolean = False
Dim StopAutopulsing As Boolean = False
Dim TimeBetweenPulses As Double = 100
Dim PulseTimer As Long = 0
Dim StopTimeoutTicks As Long = 100000000
Dim TimeoutBeginTicks As Long = 0
Dim CavitationPinPositive As Boolean = False
Dim CavitationPinPositivePrevious As Boolean = False
Dim CavitationStartTime As Long = 0
Dim CavitationTimeoutTicks As Long = 1000000
Dim CavitationTimeoutTocks As Long = 0
Dim SpeedDetectorPinPositive As Boolean = False
Dim SpeedDetectorPinPositivePrevious As Boolean = False
Dim HalfLifeTicks As Long = 2500000
Dim DecayConstant As Double = -0.1
Dim SpeedLambda As Double = 0
Dim RemainingFraction As Double = 1
Dim TotalTimeTocks As Double = 0
Dim MeasuredOutputPinPositiveFraction As Double = 0
Dim PositiveTimeTocks As Double = 0
Dim SpeedControlPinPositive As Boolean = False
Dim LaserFirePinPositive As Boolean = False
Dim LocalRunButtonClicked As Boolean = False
Dim LocalRestartDelayTime As Double = 1

```

```

Dim FormerRestartStatus As Long = 0
Dim DesiredSpeedPinPositiveFraction As Double = 0
Dim StopSpeedValue As Double = 0.1
Dim LastRecordedSpeed As Double = -100
Dim LastRecordedSpeedTime As Long = 0
Dim MaxTimeBetweenSpeedRecordingTicks As Long = 100000000
Dim MaxDeltaSpeedRecording As Double = 5
Dim SpeedDeltaFraction As Double = 0
Dim LaserFireStage As Integer = 0
Dim LocalFireManualPulse As Boolean = False
Dim NextLaserString As String = ""
Dim LaserCommandClearanceTimeTocks As Long = 0
Dim LocalPulseDuration As Double = 0
Dim LastLaserPulseTimeTocks As Long = 0
Dim FireNumber As Long = 0
Dim AutoPulseWaitCounter As Long = 0
Dim LaserPowerLimit As Double = 100
Dim LaserSequenceTimeout As Long = 120
Dim PulseSequenceTimer As Long = 0
Dim SpinnerStopTimeoutCounter As Long = 0
Dim LaserEOL As String = ""
Dim PowerCommand As String = "CAL="
Dim CommandSeparation As Long = 3500000
Dim CommandSeparationTimer As Long = 0
Dim PulseReps As Integer = 0
Dim MaxPulseReps As Integer = 3
Dim LaserInitComplete As Boolean = True

Dim AdvancedTimingFeature As Boolean = False
Dim UsedAdvancedTiming As Boolean = False
Dim LoopStartTocks As Long = 0
Dim LoopEndTocks As Long = 0
Dim DeltaTocks As Long = 0
Dim AdvancedDeltaTocks As Long = 0
Dim LiveTocks As Long = 0
Dim AllTocks As Long = 0
Dim RecentTocks As Double = 0
Dim RecentLoops As Double = 0
Dim RecentDecayFactor As Double = 0
Dim MaxDetectableSpeedHalfLife As Double = 1

Dim RemainingLiveFraction As Double = 0
Dim LoggedLiveTocks As Long = 0
Dim LoggedTotalTocks As Long = 0
Dim RestartDelayTimerTocks As Long = 0
Dim SpeedZeroCutoff As Double = 0.001

Dim TotalLoops As Long = 0
Dim AdvancedTimingCounts As Long = 0

Dim SpeedDeltaCoefficient As Double = 0.0025 'change rate, pin positive
fraction * seconds / rotation - change
Dim SpeedDeltaLimiter As Double = 2.0 'max change rate, pin positive
fraction / second

Dim Look_Ahead_Time As Double = 0.5
Dim LookAheadTocks As Long
Dim Regression_Delta As Double
Dim Regression_xbar As Double

```

```

Dim Regression_ybar As Double
Dim Regression_s_xx As Double
Dim Regression_s_xy As Double
Dim Regression_s_yy As Double
Dim Regression_Beta0 As Double
Dim Regression_Beta1 As Double
Dim Regression_Counter As Integer = 0
Dim Regression_nmax As Integer = 5
Dim Regression_x_Tocks() As Long
Dim Regression_x() As Double
Dim Regression_y() As Double

Dim PredictedSpeed As Double = 0
Dim DeltaSpeed As Double = 0
Dim CrossoverSpeed As Double = 8

Dim JumpCount As Long = 0
Dim JumpSlope As Double = 2500
Dim JumpSlopeTock As Double = 0
Dim LastJumpTock As Long = 0
Dim TimeBetweenJumps As Double = 1.0
Dim TocksBetweenJumps As Long = 0
Dim JumpValue As Double = 0.0000025

Dim RC As Double = 0      'Resistor x Capacitor, 1/s, set later on
Dim Capacitor As Double = 0
Dim PinDeviation As Double = 0
Dim SpeedOverride As Boolean = False
Dim FastResume As Double = 0.75 'the fraction of the initial Capacitor
value to use when resuming in pulse sequences

```

Try

```

'Startup Routine
Thread.CurrentThread.Name = "Kernel_Sanders"
'get the program/port mode
SyncLock Longshoreman.LaserPortLock
    LocalProgramMode = Longshoreman.LaserControlMode
End SyncLock

'set the port use string
If LocalProgramMode = 1 Then
    'shared laser and speed control port
    PortUseString = "Speed Controller/Laser Port"
Else
    'port only used for speed control
    PortUseString = "Speed Controller Port"
End If

'get advanced timing features and laser EOL
SyncLock CentralClass.FileOpsLock
    AdvancedTimingFeature = CentralClass.AdvancedTiming
    LaserEOL = CentralClass.LaserNewlineString
End SyncLock

'set variable defaults and check for the performance counter
ContinueExecution = True

```

```

If QueryPerformanceCounter(Tock) = 0 Then
ContinueExecution = False
MsgBox("Find a computer with a performance timer.")
'No performance counter, can't run
'log the result and set the shutdown flag
Lumberjack.SendToLog("Computer does not have a performance
timer. Execution cannot continue, shutting down the Program")
SyncLock CentralClass.ProgramExitLock
CentralClass.ExitProgram = True
End SyncLock
End If
'get the performance counter's frequency (per second)
QueryPerformanceFrequency(Freq)

'Set the Target Speed Acquired Countdown, default is one second in
tocks
TargetSpeedAcquiredDelayTime = Freq * (1)

'set early values
If ContinueExecution = True Then
QueryPerformanceCounter(LastTimeCheckedRead)
QueryPerformanceCounter(LastTimeCheckedWrite)
'set the RC-time constant to match the experimental setup
RC = 150000 * (0.0000047 + 0.00001)
'Capacitor expresses the stored fraction from 0 to 1 estimated
to exist in the electronics
Capacitor = 0
'set time between reads to 1/50 second
TimeBetweenReads = CLng(Freq / 50)
'set update frequency to 30/sec
TimeBetweenUpdates = CLng(Freq / 30)
'set write check frequency to 60/sec
TimeBetweenWriteChecks = CLng(Freq / 60)
'set the decay value in units of 1/tocks (Tocks, NOT Ticks; 1
Tock=1/Freq seconds)
DecayConstant = -(Math.Log(2) / (HalfLifeTicks * Freq /
10000000))

'set the conversion factor
'the divide by two is because it will be used to average the
speed from two different sources
'the sources are summed up then multiplied by the conversion
factor
SpeedLambda = (-Freq) * DecayConstant / 2
'the speed is determined by taking the rate of pulses coming in
and 'smearing' them out
'using an exponential decay scheme
'set the cavitation detection timeout period
CavitationTimeoutTocks = CLng(CavitationTimeoutTicks * Freq /
10000000)

'amount of time to look ahead and predict the speed
LookAheadTocks = CLng(Look_Ahead_Time * Freq)
'set the critical jump slope
JumpSlopeTock = JumpSlope / Freq
'set the minimum time between jumps
TocksBetweenJumps = CLng(TimeBetweenJumps * Freq)
'determine the delta for use in the Deming Regression
computation
'Deming Regression is a linear least-squares technique to fit
data to a line and uses the following relationships:

```

```

'
' y ~ b0 + b1 * x
'
' xbar = (1/n) * SUM{ x_i }
'
' ybar = (1/n) * SUM{ y_i }
'
' s_xx = (1/[n-1]) * SUM{ ( x_i - xbar )^2 }
'
' s_yy = (1/[n-1]) * SUM{ ( y_i - ybar )^2 }
'
' s_xy = (1/[n-1]) * SUM{ ( x_i - xbar ) * ( y_i - ybar ) }
'
' d = sigma_y^2 / sigma_x^2 --> delta uses the error in the
x and y samples themselves, not the variances of the sets of x and y points
'
' betal = ( s_yy - [d * s_xx] + SQRT{ (s_yy - [d * s_xx])^2 +
(4 * d * s_xy^2) } ) / ( 2 * s_xy )
' which is a solution to
' -s_xy * betal^2 + (s_yy - d * s_xx) * betal + d * s_xy = 0
'
' beta0 = ybar - (betal * xbar)
'

'for now, use delta=1 (orthogonal regression) (delta is d
above)
Regression_Delta = 1
'the delta is defined as d = variance_y / variance_x
'where the variance is based on the error in the sample itself
'using the error propagation formula, the delta here would be
expressed as
'
' d = Speed^2 * DecayConstant^2 * exp[2 * DecayConstant * {Avg.
Loop Tocks}] / ( 1 - exp[2 * DecayConstant * {Avg. Loop Tocks}] )
'
'which is not only dependent on speed, but also tends to
produce results on the order of 2E-12
'if delta --> infinity, then the Deming Regression becomes
standard OLS regression and beta = cov(x,y) / var(x)
'where the variance and covariance are determined from the
recorded data set undergoing regression analysis
'if delta --> 0, then beta = var(y) / cov(x,y)
'An earlier attempt used a dummy loop to estimate loop time and
a speed of 1, and that earlier code is commented out below:
'
'
'
'QueryPerformanceCounter(Tock)
'LastTime = Tock
''do a few things in a loop to simulate the real loop; the next
few lines through the Do loop are deliberate junk
'RecentDecayFactor = -10
'TotalLoops = 0
'Do
'
' TotalLoops += 1
' SyncLock Stevedore.SpeedPortLock
'
' just because it eats up a few cycles;
'
' RecentDecayFactor = RecentDecayFactor * Math.Exp(-3 *
Math.Log(4) + Math.Log(1.2)) + 3.14

```

```

        ' End SyncLock
        ' QueryPerformanceCounter(Tock)
        ' Application.DoEvents()
        'Loop While TotalLoops < 3
        'TotalLoops = 0
        'If Tock - LastTime <> 0 Then
        ' Regression_Delta = (DecayConstant ^ 2) * Math.Exp(2 *
DecayConstant * (Tock - LastTime)) / (1 - Math.Exp(2 * DecayConstant * (Tock -
LastTime)))
        ' Lumberjack.SendToLog("Using a Deming Variance Ratio of " &
Regression_Delta.ToString & "and a loop time estimated at " & Str(Tock -
LastTime) & " Tocks")
        'Else
        ' something won't work, exit
        ' Lumberjack.SendToLog("Something Went Wrong with the Deming
Variance Ratio Calculation")
        ' SyncLock CentralClass.ProgramExitLock
        ' CentralClass.ExitProgram = True
        ' End SyncLock
        'End If

End If

'set the array sizes for the Deming Regression routine
ReDim Regression_x_Tocks(Regression_nmax)
ReDim Regression_x(Regression_nmax)
ReDim Regression_y(Regression_nmax)
For Regression_Counter = 0 To Regression_nmax
    Regression_x_Tocks(Regression_Counter) = 0
    Regression_x(Regression_Counter) = 0
    Regression_y(Regression_Counter) = 0
Next

'wait for the right time
Proceed = False
Do
    'wait for the runbox to finish loading
    SyncLock Windowsill.RunBoxLock
        If Windowsill.RunBoxReady = True Then
            'ready to proceed
            Proceed = True
        End If
    End SyncLock
    'check for an exit program signal
    SyncLock CentralClass.ProgramExitLock
        If CentralClass.ExitProgram = True Then
            'exiting program
            Proceed = True
            ContinueExecution = False
        End If
    End SyncLock
    Thread.Sleep(55)
    Application.DoEvents()
Loop While Proceed = False

Thread.Sleep(200)
Application.DoEvents()
'then open the serial port
'get port settings and try to open the port

```



```

SyncLock CentralClass.FileOpsLock
    LocalPortName = CentralClass.SpeedPort
    LocalPortSpeed = CentralClass.ComPortBaudRate
    LocalPortDataBits = CentralClass.ComPortDataBits
    LocalPortStopBits = CentralClass.ComPortStopBits
    LocalPortFlowControl = CentralClass.ComPortFlowControl
    LocalPortEncoding = CentralClass.ComPortEncoding
End SyncLock

Proceed = False
'open the port
Do

    Try
        'log it
        Lumberjack.SendToLog("Attempting to open the " &
PortUseString & " (" & LocalPortName & ") with the following settings: " &
LocalPortSpeed.ToString & " baud, " & LocalPortDataBits.ToString & " data bits,
" & LocalPortStopBits.ToString & " stop bits, flow control=" &
LocalPortFlowControl.ToString & ", and " & LocalPortEncoding.ToString & "
Encoding.")

        'set up and open the port
SyncLock Stevedore.SpeedPortLock
    Stevedore.COMPort1.PortName = LocalPortName
    Stevedore.COMPort1.BaudRate = LocalPortSpeed
    Stevedore.COMPort1.DataBits = LocalPortDataBits
    Stevedore.COMPort1.StopBits = LocalPortStopBits
    Stevedore.COMPort1.Handshake = LocalPortFlowControl
    Stevedore.COMPort1.Encoding = LocalPortEncoding
    'set the read and write buffer size in bytes
    Stevedore.COMPort1.ReadBufferSize = 16384
    Stevedore.COMPort1.WriteBufferSize = 16384
    'open the port
    Stevedore.COMPort1.Open()
    LocalPortOpen = Stevedore.COMPort1.IsOpen
End SyncLock
        'log the results
        If LocalPortOpen = True Then
            'success
            Lumberjack.SendToLog("Success in Opening the " &
PortUseString & " (" & LocalPortName & ")")
            'set the laser pulse and speed pins low
SyncLock Stevedore.SpeedPortLock
                Stevedore.COMPort1.DtrEnable = False
                Stevedore.COMPort1.RtsEnable = False
            End SyncLock
            'proceed with the program
            Proceed = True
        Else
            'some failure without an exception getting caught
            Lumberjack.SendToLog("Failure in Opening the " &
PortUseString & " (" & LocalPortName & ")")
            'see if user wants to try again
            If MsgBox("Failure in attempt to open the " &
PortUseString & " (" & LocalPortName & ") " & vbNewLine & "Retry?",
MsgBoxStyle.YesNo, "Port Problem") = MsgBoxResult.Yes Then
                'user wants to retry
                Lumberjack.SendToLog("Will retry opening the " &
PortUseString)
            End If
        End If
    End Try
End Do

```

```

        Else
            'user wants to abort
            Proceed = True
            Lumberjack.SendToLog("Abort opening " &
PortUseString & ", ending program")
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
        End If
    End If

    Catch SerialException As Exception
        'it didn't go
        Lumberjack.SendToLog("Exception in attempt to open the " &
PortUseString & " (" & LocalPortName & ")" & ": " & vbCrLf &
SerialException.Message)
        If MsgBox("Exception in attempt to open the " &
PortUseString & " (" & LocalPortName & ")" & ": " & vbCrLf &
SerialException.Message & vbCrLf & "Retry?", MsgBoxStyle.YesNo, "Laser Port
Problem") = MsgBoxResult.Yes Then
            'user wants to retry
            Lumberjack.SendToLog("Will retry opening the " &
PortUseString)
        Else
            'user wants to abort
            Proceed = True
            Lumberjack.SendToLog("Abort opening " & PortUseString &
", ending program")

            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
        End If
    End Try

    'Check to see if the program should exit
    SyncLock CentralClass.ProgramExitLock
        If CentralClass.ExitProgram = True Then
            Proceed = True
            ContinueExecution = False
        End If
    End SyncLock
Loop While Proceed = False

'signal that the program is ready
SyncLock Windowsill.RunBoxLock
    If ContinueExecution = True Then
        Windowsill.SpeedControlReady = True
        'signal available laser port if in the correct mode
        If (LocalProgramMode = 0) Or (LocalProgramMode = 1) Then
            'in a mode for full control by this thread
            Windowsill.LaserPortReady = True
        End If
    End If
End SyncLock

'Main Loop follows
'It is the whole point of the program

```

```

'check for an exit condition
SyncLock CentralClass.ProgramExitLock
    ContinueExecution = Not CentralClass.ExitProgram
End SyncLock

If ContinueExecution = True Then
    'start of main loop in tocks
    QueryPerformanceCounter(LoopStartTocks)
End If

Do While (ContinueExecution = True)

    'This is the main loop of the program
    'It executes continuously while the program is in execution
mode; it does not sleep
    'It monitors the speed and cavitation
    'It controls the speed and laser pulses
    'It handles RXD on the main serial port
    'And TXD as well if the laser is on it

    TotalLoops += 1

    'Clock (using Win32 Performance Counters)
    LastTime = Tock
    QueryPerformanceCounter(Tock)
    DeltaTocks = Tock - LastTime

    'advanced timing calculations here
    If AdvancedTimingFeature = True Then
        'calculate advanced timing if necessary
        If CalculatedSpeed > (1.0R / CDb1(Freq)) Then
            'nonzero speed, can proceed
            'using 1/freq above is to prevent overflows
            If (DeltaTocks > (2L * (Tock - LoopStartTocks) /
TotalLoops)) And (DeltaTocks > CLng((0.75R) * Freq / CalculatedSpeed)) Then
                'only use advanced calculation if there appears to
be a chunk of time missing; i.e., the OS took over for a bit
                'and only if it might have wiped out speed pulses;
                'the missing chunk of time must be greater than
0.75 times the pulse period
                'and must also be greater than twice the average
loop time
                '(a pulse can be wiped out at ~1/2 of the pulse
period, but is somewhat unlikely)
                'If so, the total elapsed time will be replaced by
the average loop time
                AdvancedDeltaTocks = CLng((Tock - LoopStartTocks) /
TotalLoops)
                AdvancedTimingCounts += 1
                'if not already used, mark the use of advanced
timing
                If UsedAdvancedTiming = False Then
                    'mark it as true
                    UsedAdvancedTiming = True
                    'log it
                    Lumberjack.SendToLog("Begin Use of Advanced
Timing Features")

                    'start the live time logging variables

```

```

                LoggedTotalTocks = LastTime
                LoggedLiveTocks = LiveTocks
            End If
        Else
            AdvancedDeltaTocks = DeltaTocks
        End If
    Else
        'speed is zero
        AdvancedDeltaTocks = DeltaTocks
    End If
Else
    'disabled advanced timing
    AdvancedDeltaTocks = DeltaTocks
End If

'record the live time
LiveTocks = LiveTocks + AdvancedDeltaTocks
AllTocks = AllTocks + DeltaTocks

'Calculations for the max detectable speed
RecentDecayFactor = Math.Exp(-Math.Log(2) * AdvancedDeltaTocks
/ (Freq * MaxDetectableSpeedHalfLife))
RecentLoops = (RecentLoops * RecentDecayFactor) + 1
RecentTocks = (RecentTocks * RecentDecayFactor) +
AdvancedDeltaTocks

'Put Input Event handlers here
'check the speed and cavitation sensor pins
'as well as the 'Fire Laser' and Speed Controller pins
'store the previous values
SpeedDetectorPinPositivePrevious = SpeedDetectorPinPositive
CavitationPinPositivePrevious = CavitationPinPositive
SyncLock Stevedore.SpeedPortLock
    If Stevedore.COMPort1.IsOpen = True Then
        'get the speed pin status
        SpeedDetectorPinPositive =
Stevedore.COMPort1.DsrHolding
        'get the cavitation pin status
        'positive means the instrument can receive greater
amounts of light than the negative status
        'which should happen when a vapor column appears
        CavitationPinPositive = Stevedore.COMPort1.CDHolding
        'get the speed controller pin status
        SpeedControlPinPositive = Stevedore.COMPort1.DtrEnable
        'get the laser fire pin status
        LaserFirePinPositive = Stevedore.COMPort1.RtsEnable
    Else
        'the port is not open, close the program
        ContinueExecution = False
    End If
End SyncLock
If ContinueExecution = False Then
    'signal a program exit
    SyncLock CentralClass.ProgramExitLock
        CentralClass.ExitProgram = True
    End SyncLock
End If

'process the input pin status meanings

```

```

        'if the speed pin's current state and previous state are
different, increment the appropriate counter
        If SpeedDetectorPinPositive <> SpeedDetectorPinPositivePrevious
Then
            'speed pulse received, see if pin went high
            If SpeedDetectorPinPositive = True Then
                'the pin went positive
                'increment the speedpulsesup counter
                SpeedPulsesUp += 1
            Else
                'the pin went negative
                'increment the other counter
                SpeedPulsesDown += 1
            End If
        End If
        'do some speed processing: calculate the remaining 'sum' of
pulses
        'it uses the advanced timing variable, but if advanced timing
is disabled, the advanced variable should equal the standard one
        RemainingFraction = Math.Exp(DecayConstant * CDb1(DeltaTocks))
        RemainingLiveFraction = Math.Exp(DecayConstant *
CDb1(AdvancedDeltaTocks))
        SpeedPulsesUp = SpeedPulsesUp * RemainingLiveFraction
        SpeedPulsesDown = SpeedPulsesDown * RemainingLiveFraction

        'calculate timing
        'calculate the total time
        TotalTimeTocks = (TotalTimeTocks + CDb1(DeltaTocks)) *
RemainingFraction
        If SpeedOverride = False Then
            'The speed isn't overridden, behave normally
            'LiveTimeTocks = (LiveTimeTocks + CDb1(AdvancedDeltaTocks))
* RemainingLiveFraction
        'calculate the time the output pin is positive and update
the Capacitor estimate
        If SpeedControlPinPositive = True Then
            'pin is positive, add to the time
            PositiveTimeTocks = (PositiveTimeTocks +
CDb1(DeltaTocks)) * RemainingFraction
            'bring the capacitor fraction closer to 1
            Capacitor = 1 - (1 - Capacitor) * Math.Exp(-
(CDb1(DeltaTocks) / Freq) / RC)
        Else
            'pin is negative, lose time
            PositiveTimeTocks = PositiveTimeTocks *
RemainingFraction
            'decay the capacitor fraction toward zero
            Capacitor = Capacitor * Math.Exp(-(CDb1(DeltaTocks) /
Freq) / RC)
        End If
        'calculate the fraction of the time that the speed control
output pin is positive
        If TotalTimeTocks > 0 Then
            'avoiding a divide-by-zero error
            MeasuredOutputPinPositiveFraction = PositiveTimeTocks /
TotalTimeTocks
        Else
            'total time is zero (unlikely to be negative)
            MeasuredOutputPinPositiveFraction = 0

```

```

        End If
    Else
        'the speed is overridden
        'this is off-normal operation
        'will not adjust the capacitor value here, allowing fast
resumption after the off-normal condition ends
        'sed the measured output value to the desired value to
avoid extra deviation behavior
        MeasuredOutputPinPositiveFraction =
DesiredSpeedPinPositiveFraction
    End If

    'process the cavitation status
    CavitationDetectedPrevious = CavitationDetected
    If CavitationPinPositive = True Then
        'cavitation detected? give it a timeout to make sure
        If CavitationPinPositive <> CavitationPinPositivePrevious
Then
            'new signal, start the countdown
            CavitationStartTime = Tock
        Else
            'continuing signal, see if the countdown has completed
            If Tock > (CavitationStartTime +
CavitationTimeoutTocks) Then
                'countdown has finished without sensing a non-
cavitation condition in the meantime
                CavitationDetected = True
                'log it if it's a first-time event
                If CavitationDetectedPrevious = False Then
                    'first-time event, log the detection
                    Lumberjack.SendToLog("Cavitation Detected!
Speed is " & CalculatedSpeed.ToString)
                End If
            End If
        End If
    Else
        'Cavitation not detected
        CavitationDetected = False
        'log termination of cavitation condition if it existed
        If CavitationDetectedPrevious = True Then
            'cavitation condition just stopped, log it
            Lumberjack.SendToLog("Cavitation Condition No Longer
Detected")
        End If
    End If
    If CavitationDetected = True Then
        'for Mode 1, Press Stop
        If LocalCavitationAction = 1 Then
            SyncLock Windowsill.RunBoxLock
            Windowsill.StopAction = True
            End SyncLock
        End If
        'Terminate Autopulsing on Cavitation Detection
        If AutoPulsing = True Then
            AutoPulsing = False
            StopAutopulsing = True
        End If
    End If
End If

```

```

'Output Event handlers go here
'Largely for changes in serial port control pins
'Somewhat mischaracterized; Events are unused

'update speed control output pin
SyncLock Stevedore.SpeedPortLock
    'only do it if the port is still open
    If Stevedore.COMPort1.IsOpen = True Then
        'set/make sure the pin is in the correct state for the
particular case
        If (DesiredSpeedPinPositiveFraction = 0) Or
(SpeedOverride = True) Then
            'it should be set to negative, make sure of it
            If SpeedControlPinPositive = True Then
                'it's not set to negative, set it
                Stevedore.COMPort1.DtrEnable = False
            End If
        ElseIf DesiredSpeedPinPositiveFraction = 1 Then
            'it should be set to positive, make sure
            If SpeedControlPinPositive = False Then
                'it's negative, set it positive
                Stevedore.COMPort1.DtrEnable = True
            End If
        Else
            'see if it's time to change pin states
            'if the desired fraction is equal to the measured
fraction, leave it alone
            If DesiredSpeedPinPositiveFraction >
MeasuredOutputPinPositiveFraction Then
                'it should be set to positive
                If SpeedControlPinPositive = False Then
                    'change it
                    Stevedore.COMPort1.DtrEnable = True
                End If
            ElseIf DesiredSpeedPinPositiveFraction <
MeasuredOutputPinPositiveFraction Then
                'it should be set negative
                If SpeedControlPinPositive = True Then
                    'change it
                    Stevedore.COMPort1.DtrEnable = False
                End If
            Else
                'LEAVE IT ALONE!
                'That is all
            End If
        End If
    End If
End SyncLock

'Fire Control Block
'This section handles the "Fire Laser!" pin
'and associated Laser Logic
'The firing logic goes through a number of stages
'only one stage executes in a given progression through the
block; once per major loop in this thread
'these stages control various parts of the firing sequence:
taking over the laser lines, adjusting the power, timers, issues pulses, etc.
'It gets a bit messy

```

```

SpeedOverride = False
If LocalProgramMode >= 1 Then
    'Laser Control Mode is enabled
    SyncLock Windowsill.RunBoxLock
        LaserInitComplete = Windowsill.FinishedStartup
    End SyncLock
If LocalFireManualPulse = True Then
    'the user wants to fire a pulse, follow that sequence
    'clear autopulsing values
    If AutoPulsing = True Then
        AutoPulsing = False
        StopAutopulsing = True
    End If
    If LaserFireStage = 0 Then
        PulseReps = 0
        'go to stage 100
        LaserFireStage = 100
        'start the timer
        AutoPulseWaitCounter = Tock
        PulseSequenceTimer = Tock
        'halt the speed to adjust laser power
        SpeedOverride = True
    ElseIf (LaserFireStage > 0) And (LaserFireStage < 100)
Then
        'an autopulse was interrupted, go to stage 0 up
before proceeding
        'log it
        Lumberjack.SendToLog("A Laser Pulse Operation
appears to have been interrupted at Stage " & LaserFireStage.ToString)
        LaserFireStage = 0
    ElseIf LaserFireStage = 100 Then
        'halt the speed to adjust laser power
        SpeedOverride = True
        'proceed once stopped
        If CalculatedSpeed < StopSpeedValue Then
            LaserFireStage = 150
        End If
        'check the timeout (120 seconds since beginning)
        If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
            'timed out (default is 120 seconds)
            'cancel pulsing, and log it
            Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
            LaserFireStage = 0
            LocalFireManualPulse = False
        End If
    ElseIf LaserFireStage = 150 Then
        'lock down the laser dataline and transmit the
laser pulse power
        'form the command that will adjust the laser power
        'it should use NextLaserPower, which is copied from
windowsill.nextlaserpulsepower
        'halt the speed to adjust laser power
        SpeedOverride = True
        If NextLaserPower > LaserPowerLimit Then
            'too high, cancel pulse
            NextLaserPower = 1

```



```

'log the event
Lumberjack.SendToLog("Pulse Power Has Exceeded
Limits: Cancel Manual Pulse")
'cancel the pulse
SyncLock Windowsill.RunBoxLock
    Windowsill.FireManualPulse = False
End SyncLock
'end the sequence
LocalFireManualPulse = False
LaserFireStage = 0
Else
    NextLaserString = LaserEOL
    'log the transmission
    Lumberjack.SendToLog("Automatically Generated
Command to be sent to the laser: " & NextLaserString)
    SyncLock Windowsill.RunBoxLock
        'lock down the dataline
        Windowsill.LaserTXDataCritical = True
        'send the next power command to the laser
head
        Windowsill.CommandToLaser =
Windowsill.CommandToLaser & NextLaserString
    End SyncLock
    'proceed to the next step
    NextLaserString = ""
    LaserFireStage = 200
    CommandSeparationTimer = Now.Ticks
End If
'check the timeout (x seconds since beginning
stage)
If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
    'timed out (default is 120 seconds)
    'cancel pulsing, and log it
    Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
    LaserFireStage = 0
    LocalFireManualPulse = False
End If
ElseIf LaserFireStage = 200 Then
    'wait for the buffered command to complete its
transmission
    'see if the shared buffer has cleared
    'halt the speed to adjust laser power
    SpeedOverride = True
    SyncLock Windowsill.RunBoxLock
        NextLaserString = Windowsill.CommandToLaser
    End SyncLock
    If NextLaserString = "" Then
        'it's been loaded past the shared buffer, see
if the system is ready
        SyncLock Stevedore.SpeedPortLock
            If Stevedore.ClearToFireLaser = True Then
                If Now.Ticks - CommandSeparationTimer >
CommandSeparation Then
                    'proceed to the next stage
                    NextLaserString = PowerCommand &
NextLaserPower.ToString & LaserEOL
                    'log the transmission

```

```

Generated Command to be sent to the laser: Lumberjack.SendToLog("Automatically
" & NextLaserString)
SyncLock Windowsill.RunBoxLock
'lock down the dataline
Windowsill.LaserTXDataCritical
= True
' send the next power command to
the laser head
Windowsill.CommandToLaser =
Windowsill.CommandToLaser & NextLaserString
End SyncLock
'proceed to the next step
NextLaserString = ""
LaserFireStage = 250
LaserCommandClearanceTimeTocks =
Tock
End If
Else
'update the timer so that the laser has
some time to process the pre-command eol
CommandSeparationTimer = Now.Ticks
End If
End SyncLock
Else
'update the timer so that the laser has some
time to process the pre-command eol
CommandSeparationTimer = Now.Ticks
End If
'check the timeout (120 seconds since beginning)
If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
'timed out (default is 120 seconds)
'cancel pulsing, and log it
Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
LaserFireStage = 0
LocalFireManualPulse = False
End If
ElseIf LaserFireStage = 250 Then
'transmission
'wait for the buffered command to complete its
'see if the shared buffer has cleared
'halt the speed to adjust laser power
SpeedOverride = True
SyncLock Windowsill.RunBoxLock
NextLaserString = Windowsill.CommandToLaser
End SyncLock
If NextLaserString = "" Then
'if the system is ready
'it's been loaded past the shared buffer, see
SyncLock Stevedore.SpeedPortLock
If Stevedore.ClearToFireLaser = True Then
'proceed to the next stage
LaserFireStage = 300
LaserCommandClearanceTimeTocks = Tock
End If
End SyncLock
End If
'check the timeout (120 seconds since beginning)

```

```

                                If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
                                'timed out (default is 120 seconds)
                                'cancel pulsing, and log it
                                Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
                                LaserFireStage = 0
                                LocalFireManualPulse = False
                                End If
                                ElseIf LaserFireStage = 300 Then
                                'halt the speed to adjust laser power
                                SpeedOverride = True
                                'this step is a timer to ensure the laser has
processed the command (4 seconds) fully
                                If (Cdbl(Tock - LaserCommandClearanceTimeTocks) /
Cdbl(Freq)) > 4 Then
                                'proceed
                                LaserFireStage = 350
                                'compensate for an expected overreaction; the
speed will come back online after this
                                Capacitor = Capacitor * FastResume
                                End If
                                'check the timeout (120 seconds since beginning)
                                If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
                                'timed out (default is 120 seconds)
                                'cancel pulsing, and log it
                                Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
                                LaserFireStage = 0
                                LocalFireManualPulse = False
                                End If
                                ElseIf LaserFireStage = 350 Then
                                'start the spinup counter and move to the next
stage
                                LaserFireStage = 400
                                LaserCommandClearanceTimeTocks = Tock
                                'check the timeout (120 seconds since beginning)
                                If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
                                'timed out (default is 120 seconds)
                                'cancel pulsing, and log it
                                Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
                                LaserFireStage = 0
                                LocalFireManualPulse = False
                                End If
                                ElseIf LaserFireStage = 400 Then
                                'wait 20 seconds as the speed goes back to where it
was before being overridden
                                If (Cdbl(Tock - LaserCommandClearanceTimeTocks) /
Cdbl(Freq)) > 20 Then
                                'proceed
                                LaserFireStage = 450
                                End If
                                'check the timeout (x seconds since beginning)
                                If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
                                'timed out (default is 120 seconds)

```

```

        'cancel pulsing, and log it
        Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
        LaserFireStage = 0
        LocalFireManualPulse = False
    End If
ElseIf LaserFireStage = 450 Then
    'start the delay between pulses
    AutoPulseWaitCounter = Tock
    'proceed to the next stage
    LaserFireStage = 500
ElseIf LaserFireStage = 500 Then
    'wait for delay to complete
    If CDb1(Tock - AutoPulseWaitCounter) / CDb1(Freq) >
TimeBetweenPulses Then
        'delay has finished, proceed
        LaserFireStage = 550
        AutoPulseWaitCounter = Tock
    End If
    'check the timeout (x seconds since beginning)
    If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)
        'cancel pulsing, and log it
        Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
        LaserFireStage = 0
        LocalFireManualPulse = False
    End If
ElseIf LaserFireStage = 550 Then
    'FIRE!
    FireNumber += 1
    'log the event
    Lumberjack.SendToLog("Firing Laser with a Pulse
Power of " & NextLaserPower.ToString & " and an estimated duration of " &
LocalPulseDuration.ToString)
    Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
    Lumberjack.SendToLog("FIRE " & FireNumber.ToString
& "!")
    'Fire the Laser: Raise the RTS signal
    SyncLock Stevedore.SpeedPortLock
        Stevedore.COMPort1.RtsEnable = True
    End SyncLock
    'raise the fired laser flags
    FiredLaser = True
    'update the last fire time
    LastLaserPulseTimeTocks = Tock
    'proceed to the next stage
    LaserFireStage = 600
    'check the timeout (x seconds since beginning)
    If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)
        'cancel pulsing, and log it
        Lumberjack.SendToLog("Manual Pulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating Pulse")
        LaserFireStage = 0
        LocalFireManualPulse = False

```

```

End If
ElseIf LaserFireStage = 600 Then
'complete the firing sequence
'lower the fired laser flag
SyncLock Stevedore.SpeedPortLock
    Stevedore.COMPort1.RtsEnable = False
End SyncLock
'release the laser dataline
SyncLock Windowsill.RunBoxLock
    Windowsill.LaserTXDataCritical = False
    Windowsill.FireManualPulse = False
End SyncLock
'end the sequence
LocalFireManualPulse = False
LaserFireStage = 0
Else
'Unknown stage
'log the event and clear it
Lumberjack.SendToLog("Unknown Fire Control Stage:
Manual Pulse Stage " & LaserFireStage.ToString)
LocalFireManualPulse = False
LaserFireStage = 0
End If

ElseIf AutoPulsing = True Then
'automatic fire control sequence
If LocalRunButtonClicked = False Then
'not controlling the speed, do not fire
If LaserFireStage <> 0 Then
'interrupting a pulse, log it
Lumberjack.SendToLog("A Laser Pulse Operation
appears to have been interrupted at Stage " & LaserFireStage.ToString)
LaserFireStage = 0
End If
LaserFireStage = 0
ElseIf LaserFireStage = 0 Then
'go to the first stage
LaserFireStage = 5
ElseIf LaserFireStage >= 100 Then
'a manual pulse was interrupted, go to stage 0
first
'log it
Lumberjack.SendToLog("A Laser Pulse Operation
appears to have been interrupted at Stage " & LaserFireStage.ToString)
LaserFireStage = 0
ElseIf LaserFireStage = 5 Then
'get things started and go on
'start the timer
AutoPulseWaitCounter = Tock
PulseSequenceTimer = Tock
'go to the next step
LaserFireStage = 10
'halt the speed to adjust laser power
SpeedOverride = True
'set the number of pulse repetitions to 0
PulseReps = 0
ElseIf LaserFireStage = 10 Then
'check to see if the conditions are right to
proceed

```

```

'or if it's timed out
If (CavitationDetected = False) And
(CalculatedSpeed < StopSpeedValue) Then
    'conditions are right to move on to the next
step
    LaserFireStage = 15
End If
'halt the speed to adjust laser power
SpeedOverride = True
'check for a timeout
If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
    'timed out (default is 120 seconds)
    'cancel autopulsing, and log it
    Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
    LaserFireStage = 0
    StopAutopulsing = True
    AutoPulsing = False
End If
ElseIf LaserFireStage = 15 Then
    'lock down the laser dataline and transmit the
laser pulse power
    'form the command that will adjust the laser power
    'it should use NextLaserPower, which is copied from
windowsill.nextlaserpulsepower
    'halt the speed to adjust laser power
    SpeedOverride = True
    If NextLaserPower > LaserPowerLimit Then
        'too high, end autopulsing
        NextLaserPower = 1
        StopAutopulsing = True
        AutoPulsing = False
        'log the event
        Lumberjack.SendToLog("Autopulsing Power Has
Exceeded Limits: End Autopulsing")
        LaserFireStage = 0
    Else
        NextLaserString = LaserEOL
        'log the transmission
        Lumberjack.SendToLog("Automatically Generated
Command to be sent to the laser: " & NextLaserString)
        SyncLock Windowsill.RunBoxLock
            'lock down the dataline
            Windowsill.LaserTXDataCritical = True
            'send the next power command to the laser
head
            Windowsill.CommandToLaser =
Windowsill.CommandToLaser & NextLaserString
        End SyncLock
        'proceed to the next step
        NextLaserString = ""
        LaserFireStage = 20
        CommandSeparationTimer = Now.Ticks
    End If
    'check for a timeout
    If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)

```

```

'cancel autopulsing, and log it
Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
LaserFireStage = 0
StopAutopulsing = True
AutoPulsing = False
End If
ElseIf LaserFireStage = 20 Then
'wait for the buffered command to complete its
transmission
'see if the shared buffer has cleared
'halt the speed to adjust laser power
SpeedOverride = True
SyncLock Windowsill.RunBoxLock
NextLaserString = Windowsill.CommandToLaser
End SyncLock
If NextLaserString = "" Then
'it's been loaded past the shared buffer, see
if the system is ready
SyncLock Stevedore.SpeedPortLock
If Stevedore.ClearToFireLaser = True Then
'check for a completed delay from the
last command
If Now.Ticks - CommandSeparationTimer >
CommandSeparation Then
'issue the next laser command
'and proceed to the next stage
NextLaserString = PowerCommand &
NextLaserPower.ToString & LaserEOL
'log the transmission
Lumberjack.SendToLog("Automatically
Generated Command to be sent to the laser: " & NextLaserString)
SyncLock Windowsill.RunBoxLock
'send the next power command to
the laser head
Windowsill.CommandToLaser =
Windowsill.CommandToLaser & NextLaserString
End SyncLock
'proceed to the next step
NextLaserString = ""
LaserFireStage = 25
LaserCommandClearanceTimeTocks =
Tock
End If
Else
'update the timer so that the laser has
some time to process the pre-command eol
CommandSeparationTimer = Now.Ticks
End If
End SyncLock
Else
'update the timer so that the laser has some
time to process the pre-command eol
CommandSeparationTimer = Now.Ticks
End If
'check for a timeout
If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
'timed out (default is 120 seconds)

```

```

'cancel autopulsing, and log it
Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
LaserFireStage = 0
StopAutopulsing = True
AutoPulsing = False
End If
ElseIf LaserFireStage = 25 Then
'halt the speed to adjust laser power
SpeedOverride = True
'wait for the buffered command to complete its
transmission
'see if the shared buffer has cleared
SyncLock Windowsill.RunBoxLock
NextLaserString = Windowsill.CommandToLaser
End SyncLock
If NextLaserString = "" Then
'it's been loaded past the shared buffer, see
if the system is ready
SyncLock Stevedore.SpeedPortLock
If Stevedore.ClearToFireLaser = True Then
'proceed to the next stage
LaserFireStage = 30
LaserCommandClearanceTimeTocks = Tock
End If
End SyncLock
End If
'check for a timeout
If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
'timed out (default is 120 seconds)
'cancel autopulsing, and log it
Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
LaserFireStage = 0
StopAutopulsing = True
AutoPulsing = False
End If
ElseIf LaserFireStage = 30 Then
'halt the speed to adjust laser power
SpeedOverride = True
'this step is just a short timer to ensure the
laser has processed the command (4 seconds)
If (Cdbl(Tock - LaserCommandClearanceTimeTocks) /
Cdbl(Freq)) > 4 Then
'proceed
LaserFireStage = 35
'compensate for an expected overreaction; the
speed will come back online after this
Capacitor = Capacitor * FastResume
End If
'check for a timeout
If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
'timed out (default is 120 seconds)
'cancel autopulsing, and log it
Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
LaserFireStage = 0

```



```

        StopAutopulsing = True
        AutoPulsing = False
    End If
ElseIf LaserFireStage = 35 Then
    'start the delay between pulses
    AutoPulseWaitCounter = Tock
    'proceed to the next stage
    LaserFireStage = 40
    'check for a timeout
    If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)
        'cancel autopulsing, and log it
        Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
        LaserFireStage = 0
        StopAutopulsing = True
        AutoPulsing = False
    End If
ElseIf LaserFireStage = 40 Then
    'wait for delay to complete
    If CDbl(Tock - AutoPulseWaitCounter) / CDbl(Freq) >
TimeBetweenPulses Then
        'delay has finished, proceed
        LaserFireStage = 45
        AutoPulseWaitCounter = Tock
    End If
    'check for a timeout
    If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)
        'cancel autopulsing, and log it
        Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
        LaserFireStage = 0
        StopAutopulsing = True
        AutoPulsing = False
    End If
ElseIf LaserFireStage = 45 Then
    'FIRE!!!
    'or something
    If CavitationDetected = True Then
        'stop autopulsing on cavitation detection
        LaserFireStage = 0
        StopAutopulsing = True
        AutoPulsing = False
        'unblock the datalink
        SyncLock Windowsill.RunBoxLock
            Windowsill.LaserTXDataCritical = False
        End SyncLock
        'log it
        Lumberjack.SendToLog("Cavitation Detected: End
Autopulsing")
    ElseIf (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)
        'cancel autopulsing, and log it
        Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")

```

```

        LaserFireStage = 0
        StopAutopulsing = True
        AutoPulsing = False
    ElseIf (TargetSpeedAcquired = True) And
(CavitationPinPositive = False) Then
        'ready to fire, find the correct theta:
        If (SpeedDetectorPinPositive = True) And
SpeedDetectorPinPositivePrevious = False Then
            'found the correct theta (just after the
detector pin goes positive)
                'FIRE LASER!!!!
                'FIRE!
                FireNumber += 1
                PulseReps += 1
                'log the event
                Lumberjack.SendToLog("Firing Laser with a
Pulse Power of " & NextLaserPower.ToString & " and an estimated duration of " &
LocalPulseDuration.ToString)
                Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
                Lumberjack.SendToLog("FIRE " &
FireNumber.ToString & "!")
                'Fire the Laser: Raise the RTS signal
                SyncLock Stevedore.SpeedPortLock
                    Stevedore.COMPort1.RtsEnable = True
                End SyncLock
                'raise the fired laser flags
                FiredLaser = True
                'update the last fire time
                LastLaserPulseTimeTocks = Tock
                'proceed to the next stage
                LaserFireStage = 50
            End If
        End If
    ElseIf LaserFireStage = 50 Then
        'complete the firing sequence
        'lower the fire laser signal
        SyncLock Stevedore.SpeedPortLock
            Stevedore.COMPort1.RtsEnable = False
        End SyncLock
        'Autopulse mode fires a cluster of pulses with a
common energy, and only shifts the energy value between clusters
        If PulseReps >= MaxPulseReps Then
            'the cluster of pulses has completed, move on
            'release the laser dataline
            SyncLock Windowsill.RunBoxLock
                Windowsill.LaserTXDataCritical = False
            End SyncLock
            'update the pulse energy
            NextLaserPower = NextLaserPower + 1
            If NextLaserPower > LaserPowerLimit Then
                'too high, end autopulsing
                NextLaserPower = 1
                StopAutopulsing = True
                AutoPulsing = False
                'log the event
                Lumberjack.SendToLog("Autopulsing Power Has
Exceeded Limits: End Autopulsing")
            End If
        End If
    End If

```

```

SyncLock Windowsill.RunBoxLock
    Windowsill.NextLaserPulsePower =
NextLaserPower

    End SyncLock
    'end the sequence
    LaserFireStage = 55
    AutoPulseWaitCounter = Tock
Else
    'the cluster of pulses has not completed,
repeat the pulse from the delay between them
    LaserFireStage = 35
    'check for a timeout
    If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)
        'cancel autopulsing, and log it
        Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
        LaserFireStage = 0
        StopAutopulsing = True
        AutoPulsing = False
    End If
End If
ElseIf LaserFireStage = 55 Then
    'end the sequence
    'this is just a post-cluster timer to give the
cavitation a chance to develop before the next sequence is applied
    'wait for delay to complete
    If CDbl(Tock - AutoPulseWaitCounter) / CDbl(Freq) >
TimeBetweenPulses Then
        'delay has finished, so has the sequence
        LaserFireStage = 0
        AutoPulseWaitCounter = Tock
    End If
    'check for a timeout
    If (Tock - PulseSequenceTimer) / Freq >
LaserSequenceTimeout Then
        'timed out (default is 120 seconds)
        'cancel autopulsing, and log it
        Lumberjack.SendToLog("AutoPulse Timeout in
Stage " & LaserFireStage.ToString & "; terminating AutoPulse Mode")
        LaserFireStage = 0
        StopAutopulsing = True
        AutoPulsing = False
    End If
Else
    'Unknown stage
    'log the event and clear it
    Lumberjack.SendToLog("Unknown Fire Control Stage:
Autopulse Stage " & LaserFireStage.ToString)
    LaserFireStage = 0
End If
Else
    'fire control disabled
    If LaserFireStage <> 0 Then
        'fire control was disabled in firing operations
        'log the pulse cancellation
        Lumberjack.SendToLog("Current Laser Pulse Operation
Cancelled at Stage " & LaserFireStage.ToString)
    End If
End If

```

```

        LaserFireStage = 0
    End If
End If
Else
    'fire control disabled
    LaserFireStage = 0
End If
If LaserFireStage = 0 Then
    'make sure the laser is not being told to fire at this
point
    SyncLock Stevedore.SpeedPortLock
        If Stevedore.COMPort1.RtsEnable = True Then
            'lower the laser fire signal
            Stevedore.COMPort1.RtsEnable = False
        End If
    End SyncLock
    'make sure the laser datalink is unblocked
    If LaserInitComplete = True Then
        SyncLock Windowsill.RunBoxLock
            Windowsill.LaserTXDataCritical = False
        End SyncLock
    End If
End If

'Timed events go here
'check for updated speed settings here?
'update calculated speed
'etc.

'update logged speed if the conditions are met
'those include time and speed change
If (Tock - LastRecordedSpeedTime) / Freq >
(MaxTimeBetweenSpeedRecordingTicks / 10000000) Then
    'it's time to log the speed
    Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
    'update the speed recording time and value
    LastRecordedSpeed = CalculatedSpeed
    LastRecordedSpeedTime = Tock
    'log the live fraction, if applicable
    If UsedAdvancedTiming = True Then
        'advanced timing has been applied
        Lumberjack.SendToLog("Current Live Fraction: " &
(CDbl(LiveTocks - LoggedLiveTocks) / CDbl(Tock - LoggedTotalTocks)).ToString)
        'update the logged times
        LoggedLiveTocks = LiveTocks
        LoggedTotalTocks = Tock
    End If
ElseIf CalculatedSpeed > StopSpeedValue Then
    'it is not stopped
    'check for standard delta
    If Math.Abs(CalculatedSpeed - LastRecordedSpeed) >
MaxDeltaSpeedRecording Then
        'Speed is different enough to update in the log
        Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
        'update the speed recording time and value
        LastRecordedSpeed = CalculatedSpeed
    End If
End If

```

```

        LastRecordedSpeedTime = Tock
        'log the live fraction, if applicable
        If UsedAdvancedTiming = True Then
            'advanced timing has been applied
            Lumberjack.SendToLog("Current Live Fraction: " &
(CDbl(LiveTocks - LoggedLiveTocks) / CDbl(Tock - LoggedTotalTocks)).ToString)
            'update the logged times
            LoggedLiveTocks = LiveTocks
            LoggedTotalTocks = Tock
        End If
    ElseIf (TargetSpeed > 0) And (LocalRunButtonClicked = True)
Then
        'see if it has crossed in to the fine-tune region or if
it changed enough within it
        If Math.Abs((CalculatedSpeed - TargetSpeed) /
TargetSpeed) <= 1.25 * SpeedError Then
            'in fine-tune region
            'see if it crossed into the fine-tune region
            If Math.Abs((LastRecordedSpeed - TargetSpeed) /
TargetSpeed) > 1.25 * SpeedError Then
                'it crossed into the fine-tune region, log it
                Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
                'update the speed recording time and value
                LastRecordedSpeed = CalculatedSpeed
                LastRecordedSpeedTime = Tock
                'log the live fraction, if applicable
                If UsedAdvancedTiming = True Then
                    'advanced timing has been applied
                    Lumberjack.SendToLog("Current Live
Fraction: " & (CDbl(LiveTocks - LoggedLiveTocks) / CDbl(Tock -
LoggedTotalTocks)).ToString)
                    'update the logged times
                    LoggedLiveTocks = LiveTocks
                    LoggedTotalTocks = Tock
                End If
            ElseIf (Math.Abs((LastRecordedSpeed -
CalculatedSpeed) / TargetSpeed) > (SpeedError / 3)) Or
(Math.Abs(LastRecordedSpeed - CalculatedSpeed) > (MaxDeltaSpeedRecording / 5))
Then
                'big enough change in the fine-tune region to
log
                'add one more requirement: minimum change
                If Math.Abs(LastRecordedSpeed -
CalculatedSpeed) > 0.5 Then
                    'this prevents microscopic changes from
being logged
                    Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
                    'update the speed recording time and value
                    LastRecordedSpeed = CalculatedSpeed
                    LastRecordedSpeedTime = Tock
                    'log the live fraction, if applicable
                    If UsedAdvancedTiming = True Then
                        'advanced timing has been applied
                        Lumberjack.SendToLog("Current Live
Fraction: " & (CDbl(LiveTocks - LoggedLiveTocks) / CDbl(Tock -
LoggedTotalTocks)).ToString)
                        'update the logged times

```

```

                LoggedLiveTocks = LiveTocks
                LoggedTotalTocks = Tock
            End If
        End If
    End If
    ElseIf Math.Abs((LastRecordedSpeed - TargetSpeed) /
TargetSpeed) <= 1.25 * SpeedError Then
        'moved outside target range
        'log it
        Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
        'update the speed recording time and value
        LastRecordedSpeed = CalculatedSpeed
        LastRecordedSpeedTime = Tock
        'log the live fraction, if applicable
        If UsedAdvancedTiming = True Then
            'advanced timing has been applied
            Lumberjack.SendToLog("Current Live Fraction: "
& (Cdbl(LiveTocks - LoggedLiveTocks) / Cdbl(Tock - LoggedTotalTocks)).ToString)
            'update the logged times
            LoggedLiveTocks = LiveTocks
            LoggedTotalTocks = Tock
        End If
    End If
End If
Else
    'it's currently stopped, see if it was before
    If LastRecordedSpeed > StopSpeedValue Then
        'wasn't stopped last time, log it
        Lumberjack.SendToLog("Speed Effectively Stopped")
        Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
        'update the speed recording time and value
        LastRecordedSpeed = CalculatedSpeed
        LastRecordedSpeedTime = Tock
        'log the live fraction, if applicable
        If UsedAdvancedTiming = True Then
            'advanced timing has been applied
            Lumberjack.SendToLog("Current Live Fraction: " &
(Cdbl(LiveTocks - LoggedLiveTocks) / Cdbl(Tock - LoggedTotalTocks)).ToString)
            'update the logged times
            LoggedLiveTocks = LiveTocks
            LoggedTotalTocks = Tock
        End If
    End If
End If

'Read the Serial Port data, if it's time
If Tock > LastTimeCheckedRead + TimeBetweenReads Then
    'check for data in the serial port
    Stevedore.MainPortReader()
    'update checked time
    LastTimeCheckedRead = Tock
End If

'Transmit data through the Speed Port (Mode 1 only)
If LocalProgramMode = 1 Then
    SendData = False

```

```

'check for write
SyncLock Stevedore.MainPortWriterLock
'see if there was a write in progress
If Stevedore.SavedTXString <> "" Then
'call the write routine
SendData = True
End If
End SyncLock
If Tock > LastTimeCheckedWrite + TimeBetweenWriteChecks
Then
'pulse the data x-mit routine
SendData = True
End If

If SendData = True Then
'write data
Stevedore.MainPortWriter()
'update time
LastTimeCheckedWrite = Tock
End If
End If

'UI, Speed calculation update: synchronize!
If Tock > LastTimeUpdated + TimeBetweenUpdates Then
'update the last update time
LastTimeUpdated = Tock

'Determine the Speed Pin Positive Fraction Deviation
'Calculates how far off the actual value is
PinDeviation = DesiredSpeedPinPositiveFraction -
MeasuredOutputPinPositiveFraction
If Math.Abs(PinDeviation) > 0.05 Then
'A significant Deviation existed in the last frame; log
it
Lumberjack.SendToLog("NOTE: The previous Frame had a
high Speed Control Deviation: " & PinDeviation.ToString)
End If

'calculate the speed
CalculatedSpeed = SpeedLambda * (SpeedPulsesUp +
SpeedPulsesDown)
'set speed to zero if below cutoff
If CalculatedSpeed < SpeedZeroCutoff Then
CalculatedSpeed = 0
End If
If CalculatedSpeed > ((Freq * RecentLoops) / (RecentTocks *
2.5)) Then
'speed is at or approaching immeasurably high values
Lumberjack.SendToLog("WARNING: CURRENT SPEED IS AT OR
NEAR IMMEASURABLY HIGH VALUES; CURRENT SPEED = " & CalculatedSpeed.ToString &
"; CURRENT LIMIT = " & (0.5 * (Freq * RecentLoops) / RecentTocks).ToString)
End If

'update the speed and time arrays
'the values get shifted to lower indices such that the most
recent is in the highest index
For Regression_Counter = 0 To Regression_nmax - 1
'time

```

```

Regression_x_Tocks(Regression_Counter) =
Regression_x_Tocks(Regression_Counter + 1)
'speed
Regression_y(Regression_Counter) =
Regression_y(Regression_Counter + 1)
Next
Regression_x_Tocks(Regression_nmax) = Tock
Regression_y(Regression_nmax) = CalculatedSpeed
'the Regression_x array is time relative to now, in seconds
(it should be decreasingly negative; the highest index should have a value of
zero)
For Regression_Counter = 0 To Regression_nmax
Regression_x(Regression_Counter) =
(Regression_x_Tocks(Regression_Counter) - Tock) / Freq
Next

'determine whether or not the speed is in range
If (TargetSpeed > 5) And (LocalRunButtonClicked = True)
Then
'target speed is in the control range, see if it's
within error bounds of the target
If Math.Abs((CalculatedSpeed - TargetSpeed) /
TargetSpeed) < SpeedError Then
'speed is inside target range, count
'the counter stores the tock when the speed entered
the range, so
If (Tock - TargetSpeedAcquiredCounterTocks) >
TargetSpeedAcquiredDelayTime Then
'it endured the countdown and is fully within
range
'log it, for entry into the range
If TargetSpeedAcquired = False Then
Lumberjack.SendToLog("Speed has entered the
Target Range; currently " & CalculatedSpeed.ToString)
End If
TargetSpeedAcquired = True
End If
Else
'speed is outside the target range
If TargetSpeedAcquired = True Then
'log the departure from the target range
Lumberjack.SendToLog("Speed has left the Target
Range; currently " & CalculatedSpeed.ToString)
End If
TargetSpeedAcquired = False
TargetSpeedAcquiredCounterTocks = Tock
End If
Else
'target speed is outside the control range or system is
not running
If TargetSpeedAcquired = True Then
'log the departure from the target range
Lumberjack.SendToLog("Speed has left the Target
Range; currently " & CalculatedSpeed.ToString)
End If
TargetSpeedAcquired = False
TargetSpeedAcquiredCounterTocks = Tock
End If

```



```

'limit the influence of the past frame's target speed pin
positive fractions
TimeBetweenUpdates) Then
    'can limit, set it to a fraction of the time of the
last frame in tocks
    'do it for both the total and positive time
    PositiveTimeTocks = PositiveTimeTocks * (0.00025 *
TimeBetweenUpdates / TotalTimeTocks)
    'don't rewrite the following equation in case rounding
errors are significant
    TotalTimeTocks = TotalTimeTocks * (0.00025 *
TimeBetweenUpdates / TotalTimeTocks)
End If

'Send Values
SyncLock Windowsill.RunBoxLock
    'speed
    Windowsill.DetectedSpeed = CalculatedSpeed
    'speed in range indicator
    Windowsill.ProperSpeed = TargetSpeedAcquired
    'cavitation
    Windowsill.Cavitation = CavitationDetected
    'laser fired indication
    If FiredLaser = True Then
        'laser was fired
        Windowsill.LaserFireIndicator = True
        'clear the flag once transmitted
        FiredLaser = False
    End If
    'Speed restart stuff
    Windowsill.RestartStatus = SpeedRestartStatus
    Windowsill.RestartTimeLeft = CLng(SpeedRestartTimeLeft)
    'autopulsing
    If StopAutopulsing = True Then
        'no autopulsing
        Windowsill.DisableAutomaticPulsing = True
        StopAutopulsing = False
    End If
    'laser stage
    Windowsill.LaserStage = LaserFireStage
End SyncLock

'Load Values
SyncLock Windowsill.RunBoxLock
    'automatic pulsing
    If (Windowsill.AutomaticPulsing = False) Or
(Windowsill.DisableAutomaticPulsing = True) Then
        'no autopulsing the laser
        AutoPulsing = False
    ElseIf StopAutopulsing = True Then
        AutoPulsing = False
    Else
        'enable autopulsing
        AutoPulsing = True
    End If
    'check for a manually-issued laser pulse
    LocalFireManualPulse = Windowsill.FireManualPulse
    'control speed

```

```

        TargetSpeed = Windowsill.DesiredSpeed
        'pulse power
        NextLaserPower = Windowsill.NextLaserPulsePower
        'time between pulses
        TimeBetweenPulses = Windowsill.DelayBetweenPulses
        'get the pulse duration
        LocalPulseDuration =
Windowsill.EstimatedLaserPulseDuration
        'run status
        LocalRunButtonClicked = Windowsill.RunButtonClicked
        'get the restart delay
        LocalRestartDelayTime = Windowsill.RestartDelayTime
        'get the action when cavitation is detected
        LocalCavitationAction = Windowsill.CavitationAction
    End SyncLock

    'Set the target speed to zero if there is a pause state
    FormerRestartStatus = SpeedRestartStatus
    'make sure that any activity gets cancelled if the status
is not correct
    If (LocalRunButtonClicked = False) Or
(LocalCavitationAction <> 2) Then
        SpeedRestartStatus = 0
    End If
    If (CavitationDetected = True) And (LocalCavitationAction =
2) Then
        'set the speed to zero and the restart status to 1
        'disable autopulsing
        'and wait for the cavitation condition to end
        TargetSpeed = 0
        SpeedRestartStatus = 1
        StopAutopulsing = True
        AutoPulsing = False
        'see if it should be logged
        If FormerRestartStatus <> SpeedRestartStatus Then
            'status changed, log it
            Lumberjack.SendToLog("Speed Halting on Cavitation,
will restart")
        End If
    ElseIf SpeedRestartStatus = 2 Then
        'COUNTDOWN!
        SpeedRestartTimeLeft = SpeedRestartTimeLeft -
(CDbl(Tock - RestartDelayTimerTocks) / CDbl(Freq))
        RestartDelayTimerTocks = Tock
        'set target speed
        TargetSpeed = 0
        'see if the Countdown has completed
        If SpeedRestartTimeLeft <= 0 Then
            'it finished
            SpeedRestartTimeLeft = 0
            'change the status
            SpeedRestartStatus = 0
            'log the end
            Lumberjack.SendToLog("Speed Restart Sequence
Completed, Resuming")
        End If
    ElseIf ((LocalCavitationAction = 2) And (SpeedRestartStatus
= 1)) And ((CavitationDetected = False) And (CalculatedSpeed <=
StopSpeedValue)) Then

```

```

'we're in stop and restart mode, cavitation was
detected and cleared, and the spinner has stopped
'move on to Phase 2
SpeedRestartStatus = 2
'start the countdown
SpeedRestartTimeLeft = LocalRestartDelayTime
RestartDelayTimerTocks = Tock
'log it
Lumberjack.SendToLog("Speed Halted and Cavitation
Cleared, will wait " & SpeedRestartTimeLeft.ToString & " s before Resuming")
'set target speed
TargetSpeed = 0
ElseIf ((LocalCavitationAction = 2) And (SpeedRestartStatus
= 1)) Then
'in a stop+restart sequence
'wait for it to stop
'maintain target speed at zero
TargetSpeed = 0
Else
'set the restart status to zero
If SpeedRestartStatus <> 0 Then
SpeedRestartStatus = 0
'log the return to normalcy
Lumberjack.SendToLog("Speed Restart Sequence
Ended")
End If
End If

'Determine the new time fraction for positive output on the
speed control pin
If (TargetSpeed = 0) Or (LocalRunButtonClicked = False)
Then
'either the control is disabled or the speed is zero
'set target fraction to zero
DesiredSpeedPinPositiveFraction = 0
ElseIf TargetSpeed < 0 Then
'a negative target speed means full speed ahead if
equal to or less than -1
'otherwise, it sets the pin positive fraction as its
negative
'i.e., if TargetSpeed = -0.25, then
DesiredSpeedPinPositiveFractio = 0.25
If TargetSpeed < -1 Then
'set target fraction to one
DesiredSpeedPinPositiveFraction = 1
Else
'set target fraction to the negative of the
targetspeed
DesiredSpeedPinPositiveFraction = -TargetSpeed
End If
Else
'calculate the new value between zero and one,
inclusive
'use an appropriate difference in the fraction; there
are limits
'
'What this section attempts to do is
'(1) Predict what the speed will be in the very near
future using a linear regression scheme

```

```

' (2) Use the predicted speed in comparison with the
desired speed to find a speed difference
' (3) Use the speed difference to come up with a
delta from the stored output fraction
' The stored output fraction is in the Capacitor
variable, and is a sort of running average
' of the output fraction on the speed pin,
simulating the phase capacitor in the electronics
' (4) Within limits, determine the new output
fraction by summing the Capacitor variable with the
' delta and a fraction of the Deviation from the
previous Frame's desired value

'Perform the Regression Calculations
Regression_xbar = 0
Regression_ybar = 0
Regression_s_xy = 0
Regression_s_xx = 0
Regression_s_yy = 0
'set the averages
For Regression_Counter = 0 To Regression_nmax
    Regression_xbar = Regression_xbar + (1 /
Cdbl(Regression_nmax + 1)) * Regression_x(Regression_Counter)
    Regression_ybar = Regression_ybar + (1 /
Cdbl(Regression_nmax + 1)) * Regression_y(Regression_Counter)
Next
'set the s-values
For Regression_Counter = 0 To Regression_nmax
    Regression_s_xy = Regression_s_xy + (1 /
Cdbl(Regression_nmax)) * (Regression_x(Regression_Counter) - Regression_xbar) *
(Regression_y(Regression_Counter) - Regression_ybar)
    Regression_s_xx = Regression_s_xx + (1 /
Cdbl(Regression_nmax)) * (Regression_x(Regression_Counter) - Regression_xbar) ^
2
    'Regression_s_yy = Regression_s_yy + (1 /
Cdbl(Regression_nmax)) * (Regression_y(Regression_Counter) - Regression_ybar) ^
2
Next
'calculate the beta-values
'If Regression_s_xy <> 0 Then
'    'no divide-by-zero
'    Regression_Betal = (Regression_s_yy -
(Regression_Delta * Regression_s_xx) + Math.Sqrt((Regression_s_yy -
(Regression_Delta * Regression_s_xx) ^ 2 + (4 * Regression_Delta *
(Regression_s_xy ^ 2)))) / (2 * Regression_s_xy)
'Else
'    Regression_Betal = 0
'    'a divide-by-zero was prevented, and is probably
the result of a constant speed=0
'End If

'DEBUGGING ALTERATION
'SINCE THE ORIGINAL DEMING REGRESSION WAS PRODUCING
OCCASIONAL WEIRD RESULTS
'FALL BACK TO SIMPLE LINEAR REGRESSION
If Regression_s_xx <> 0 Then
    'it's simple
    'no divide by zero here

```

```

Regression_s_xx          Regression_Betal = Regression_s_xy /
                          Else
                          'this might happen once
                          Regression_Betal = 0
                          End If

                          Regression_Beta0 = Regression_ybar - (Regression_Betal
* Regression_xbar)

                          'determine the predicted speed
                          'this is in the form of y = b + m*x
                          'where x is the time-value; time=0 is indexed to 'Tock'
in the Regression Calculations above
                          PredictedSpeed = Regression_Beta0 + (Regression_Betal *
Look_Ahead_Time)
                          'determine the difference in predicted speed and the
target speed
                          DeltaSpeed = TargetSpeed - PredictedSpeed
                          'calculate the resulting speed pin positive fraction
change
                          SpeedDeltaFraction = (SpeedDeltaCoefficient *
DeltaSpeed) + (SpeedDeltaCoefficient * (DeltaSpeed / CrossoverSpeed) ^ 3)
                          'limit the change
                          If SpeedDeltaFraction > SpeedDeltaLimiter *
TimeBetweenUpdates / Freq Then
                          'fraction change too high, cap it
                          SpeedDeltaFraction = SpeedDeltaLimiter *
TimeBetweenUpdates / Freq
                          ElseIf SpeedDeltaFraction < (-SpeedDeltaLimiter) *
TimeBetweenUpdates / Freq Then
                          'fraction change too negative, cap it
                          SpeedDeltaFraction = (-SpeedDeltaLimiter) *
TimeBetweenUpdates / Freq
                          End If

                          'Check for a Jump condition
                          'a Jump is when the speed makes a sudden, rapid, and
unexpected change
                          'it can happen with a constant output fraction
                          If Math.Abs(Regression_Betal) >= JumpSlope Then
                          'the slope condition is met, check for the others
                          Lumberjack.SendToLog("DEBUG MSG: Jump Condition #1
(Slope) met")
                          If ((-DeltaSpeed / TargetSpeed > SpeedError) And
(Regression_Betal > 0)) Or ((-DeltaSpeed / TargetSpeed < -SpeedError) And
(Regression_Betal < 0)) Then
                          'the Difference condition is met
                          Lumberjack.SendToLog("DEBUG MSG: Jump
Condition #2 (Difference) met")
                          If Math.Abs((CalculatedSpeed - TargetSpeed) /
TargetSpeed) <= 3.0R * SpeedError Then
                          'The Speed Condition is met
                          Lumberjack.SendToLog("DEBUG MSG: Jump
Condition #3 (Speed) met")
                          If Tock - LastJumpTock >= TocksBetweenJumps
Then

```

```

condition is met
Condition #4 (Time) met")
apply the Jump Countermeasures
Condition detected, applying Countermeasures # " & JumpCount.ToString)
- (JumpValue * Regression_Beta1 / JumpSlope)
    End If
    End If
    End If
    End If

    'get the new value if the speed is not overridden
    If SpeedOverride = False Then
        DesiredSpeedPinPositiveFraction = Capacitor +
SpeedDeltaFraction + (0.5 * PinDeviation)
    End If
    'make sure the new value is within range
    If DesiredSpeedPinPositiveFraction > 1 Then
        'it's too high, cap it at 1
        DesiredSpeedPinPositiveFraction = 1
    ElseIf DesiredSpeedPinPositiveFraction < 0 Then
        'too low, limit it to zero
        DesiredSpeedPinPositiveFraction = 0
    End If

    'DEBUG OUTPUT BLOCK
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE:
CURRENT SPEED = " & CalculatedSpeed.ToString)
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE:
PREDICT SPEED = " & PredictedSpeed.ToString)
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE: NEW
SPD PIN F = " & DesiredSpeedPinPositiveFraction.ToString)
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE:
DEMING BETA 0 = " & Regression_Beta0.ToString)
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE:
DEMING BETA 1 = " & Regression_Beta1.ToString)
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE:
DEMING S XX 1 = " & Regression_s_xx.ToString)
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE:
DEMING S YY 1 = " & Regression_s_yy.ToString)
    'Lumberjack.SendToLog("DEBUGGING OUTPUT MESSAGE:
DEMING S XY 1 = " & Regression_s_xy.ToString)

    End If

End If

'Release Control
Application.DoEvents()
SyncLock CentralClass.ProgramExitLock
ContinueExecution = Not CentralClass.ExitProgram

```

```

        End SyncLock

Loop

'get the loop end time
QueryPerformanceCounter (LoopEndTocks)

'Shutdown Routine
'perform preliminary shutdown tasks here

'press stop
SyncLock Windowsill.RunBoxLock
    Windowsill.StopAction = True
End SyncLock

'make sure the laser dataline is unblocked
SyncLock Windowsill.RunBoxLock
    Windowsill.LaserTXDataCritical = False
End SyncLock

'set speed control and laser fire pins
If LocalPortOpen = True Then
    'set the laser pulse and speed pins low
    'this SHOULD stop the spinner and end any laser pulsing
    SyncLock Stevedore.SpeedPortLock
        Stevedore.COMPort1.DtrEnable = False
        Stevedore.COMPort1.RtsEnable = False
    End SyncLock
End If

'Send Values to the Runbox
SyncLock Windowsill.RunBoxLock
    'speed
    Windowsill.DetectedSpeed = CalculatedSpeed
    'speed in range indicator
    Windowsill.ProperSpeed = False
    'cavitation
    Windowsill.Cavitation = False
    'Speed restart stuff
    Windowsill.RestartStatus = 0
    Windowsill.RestartTimeLeft = 0
    'autopulsing
    Windowsill.DisableAutomaticPulsing = True
End SyncLock

If UsedAdvancedTiming = True Then
    Lumberjack.SendToLog("Disabling Advanced Timing Feature")
    'because I'm being a lazy programmer and don't want to change
the following code
    'since accuracy no longer matters at this point in execution
    'log the live fraction, if applicable
    Lumberjack.SendToLog("Current Live Fraction: " &
(CDbl(LiveTocks - LoggedLiveTocks) / CDbl(Tock - LoggedTotalTocks)).ToString)
    'update the logged times
    LoggedLiveTocks = LiveTocks
    LoggedTotalTocks = Tock
End If

```

```

'wait for the correct shutdown state to complete
Do
    'continue monitoring and reporting the speed
    SyncLock CentralClass.ProgramExitLock
        LocalExecutionStage = CentralClass.ExecutionStage
    End SyncLock

    'Clock
    LastTime = Tock
    QueryPerformanceCounter(Tock)
    DeltaTocks = Tock - LastTime

    SpeedDetectorPinPositivePrevious = SpeedDetectorPinPositive
    CavitationPinPositivePrevious = CavitationPinPositive
    SyncLock Stevedore.SpeedPortLock
        If Stevedore.COMPort1.IsOpen = True Then
            'get the speed pin status
            SpeedDetectorPinPositive =
Stevedore.COMPort1.DsrHolding
            'get the cavitation pin status
            'positive means the instrument can receive greater
amounts of light than the negative status
            'which should happen when a vapor column appears
            CavitationPinPositive = Stevedore.COMPort1.CDHolding
            'get the speed controller pin status
            SpeedControlPinPositive = Stevedore.COMPort1.DtrEnable
            'get the laser fire pin status
            LaserFirePinPositive = Stevedore.COMPort1.RtsEnable
        Else
            'the port is not open, close the program
            ContinueExecution = False
        End If
    End SyncLock
    If ContinueExecution = False Then
        'signal a program exit
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End If

    'process the input pin status meanings
    'if the speed pin's current state and previous state are
different, increment the appropriate counter
    If SpeedDetectorPinPositive <> SpeedDetectorPinPositivePrevious
Then
        'speed pulse received, see if pin went high
        If SpeedDetectorPinPositive = True Then
            'the pin went positive
            'increment the speedpulsesup counter
            SpeedPulsesUp += 1
        Else
            'the pin went negative
            'increment the other counter
            SpeedPulsesDown += 1
        End If
    End If
    'do some speed processing: calculate the remaining 'sum' of
pulses
    RemainingFraction = Math.Exp(DecayConstant * CDb1(DeltaTocks))

```



```

SpeedPulsesUp = SpeedPulsesUp * RemainingFraction
SpeedPulsesDown = SpeedPulsesDown * RemainingFraction

'process the cavitation status
CavitationDetectedPrevious = CavitationDetected
If CavitationPinPositive = True Then
    'cavitation detected? give it a timeout to make sure
    If CavitationPinPositive <> CavitationPinPositivePrevious
Then
        'new signal, start the countdown
        CavitationStartTime = Tock
    Else
        'continuing signal, see if the countdown has completed
        If Tock > (CavitationStartTime +
CavitationTimeoutTocks) Then
            'countdown has finished without sensing a non-
cavitation condition in the meantime
            CavitationDetected = True
            'log it if it's a first-time event
            If CavitationDetectedPrevious = False Then
                'first-time event, log the detection
                Lumberjack.SendToLog("Cavitation Detected!
Speed is " & CalculatedSpeed.ToString)
            End If
        End If
    End If
Else
    'Cavitation not detected
    CavitationDetected = False
    'log termination of cavitation condition if it existed
    If CavitationDetectedPrevious = True Then
        'cavitation condition just stopped, log it
        Lumberjack.SendToLog("Cavitation Condition No Longer
Detected")
    End If
End If

'Read the Serial Port data, if it's time
If Tock > LastTimeCheckedRead + TimeBetweenReads Then
    'check for data in the serial port
    Stevedore.MainPortReader()
    'update checked time
    LastTimeCheckedRead = Tock
End If

'Transmit data through the Speed Port (Mode 1 only)
If LocalProgramMode = 1 Then
    SendData = False
    'check for write
    SyncLock Stevedore.MainPortWriterLock
        'see if there was a write in progress
        If Stevedore.SavedTXString <> "" Then
            'call the write routine
            SendData = True
        End If
    End SyncLock
    If Tock > LastTimeCheckedWrite + TimeBetweenWriteChecks
Then
        'time to pulse the x-mit routine

```

```

        SendData = True
    End If

    If SendData = True Then
        'write data
        Stevedore.MainPortWriter()
        'update time
        LastTimeCheckedWrite = Tock
    End If
End If

'calculate the speed
CalculatedSpeed = SpeedLambda * (SpeedPulsesUp +
SpeedPulsesDown)
'set speed to zero if below cutoff
If CalculatedSpeed < SpeedZeroCutoff Then
    CalculatedSpeed = 0
End If

'update logged speed if the conditions are met
'those include time and speed change
If (Tock - LastRecordedSpeedTime) / Freq >
(MaxTimeBetweenSpeedRecordingTicks / 10000000) Then
    'it's time to log the speed
    Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
    'update the speed recording time and value
    LastRecordedSpeed = CalculatedSpeed
    LastRecordedSpeedTime = Tock
ElseIf CalculatedSpeed > StopSpeedValue Then
    'it is not stopped
    'check for standard delta
    If Math.Abs(CalculatedSpeed - LastRecordedSpeed) >
MaxDeltaSpeedRecording Then
        'Speed is different enough to update in the log
        Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
        'update the speed recording time and value
        LastRecordedSpeed = CalculatedSpeed
        LastRecordedSpeedTime = Tock
    End If
Else
    'it's currently stopped, see if it was before
    If LastRecordedSpeed > StopSpeedValue Then
        'wasn't stopped last time, log it
        Lumberjack.SendToLog("Speed Effectively Stopped")
        Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
        'update the speed recording time and value
        LastRecordedSpeed = CalculatedSpeed
        LastRecordedSpeedTime = Tock
    End If
End If

'Update display
If Tock > LastTimeUpdated + TimeBetweenUpdates Then
    'update the last update time
    LastTimeUpdated = Tock
    'Send Values

```

```

SyncLock Windowsill.RunBoxLock
    'speed
    Windowsill.DetectedSpeed = CalculatedSpeed
    'speed in range indicator
    Windowsill.ProperSpeed = TargetSpeedAcquired
    'cavitation
    Windowsill.Cavitation = CavitationDetected
    'laser fired indication
    If FiredLaser = True Then
        'laser was fired
        Windowsill.LaserFireIndicator = True
        'clear the flag once transmitted
        FiredLaser = False
    End If
    'Speed restart stuff
    Windowsill.RestartStatus = SpeedRestartStatus
    Windowsill.RestartTimeLeft = CLng(SpeedRestartTimeLeft)
    'autopulsing
    If StopAutopulsing = True Then
        'no autopulsing
        Windowsill.DisableAutomaticPulsing = True
        StopAutopulsing = False
    End If
End SyncLock
End If

'Release Control
Application.DoEvents()

Loop While LocalExecutionStage < 1010

'wait for spinner to stop, or give an error message
SpinnerStopTimeoutCounter = Tock
Do
    'Clock
    LastTime = Tock
    QueryPerformanceCounter(Tock)
    DeltaTocks = Tock - LastTime

    SpeedDetectorPinPositivePrevious = SpeedDetectorPinPositive
    CavitationPinPositivePrevious = CavitationPinPositive
    SyncLock Stevedore.SpeedPortLock
        If Stevedore.COMPort1.IsOpen = True Then
            'get the speed pin status
            SpeedDetectorPinPositive =
Stevedore.COMPort1.DsrHolding
            'get the cavitation pin status
            'positive means the instrument can receive greater
amounts of light than the negative status
            'which should happen when a vapor column appears
            CavitationPinPositive = Stevedore.COMPort1.CD Holding
            'get the speed controller pin status
            SpeedControlPinPositive = Stevedore.COMPort1.DtrEnable
            'get the laser fire pin status
            LaserFirePinPositive = Stevedore.COMPort1.RtsEnable
        Else
            'the port is not open, close the program
            ContinueExecution = False
        End If
    End SyncLock
End Do

```

```

        End If
    End SyncLock
    If ContinueExecution = False Then
        'signal a program exit
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End If

    'process the input pin status meanings
    'if the speed pin's current state and previous state are
different, increment the appropriate counter
    If SpeedDetectorPinPositive <> SpeedDetectorPinPositivePrevious
Then
        'speed pulse received, see if pin went high
        If SpeedDetectorPinPositive = True Then
            'the pin went positive
            'increment the speedpulsesup counter
            SpeedPulsesUp += 1
        Else
            'the pin went negative
            'increment the other counter
            SpeedPulsesDown += 1
        End If
    End If

    'do some speed processing: calculate the remaining 'sum' of
pulses
    RemainingFraction = Math.Exp(DecayConstant * CDb1(DeltaTocks))
    SpeedPulsesUp = SpeedPulsesUp * RemainingFraction
    SpeedPulsesDown = SpeedPulsesDown * RemainingFraction

    'process the cavitation status
    CavitationDetectedPrevious = CavitationDetected
    If CavitationPinPositive = True Then
        'cavitation detected? give it a timeout to make sure
        If CavitationPinPositive <> CavitationPinPositivePrevious
Then
            'new signal, start the countdown
            CavitationStartTime = Tock
        Else
            'continuing signal, see if the countdown has completed
            If Tock > (CavitationStartTime +
CavitationTimeoutTocks) Then
                'countdown has finished without sensing a non-
cavitation condition in the meantime
                CavitationDetected = True
                'log it if it's a first-time event
                If CavitationDetectedPrevious = False Then
                    'first-time event, log the detection
                    Lumberjack.SendToLog("Cavitation Detected!
Speed is " & CalculatedSpeed.ToString)
                End If
            End If
        End If
    Else
        'Cavitation not detected
        CavitationDetected = False
        'log termination of cavitation condition if it existed
        If CavitationDetectedPrevious = True Then

```

```

'cavitation condition just stopped, log it
Lumberjack.SendToLog("Cavitation Condition No Longer
Detected")
    End If
End If

'Read the Serial Port data, if it's time
If Tock > LastTimeCheckedRead + TimeBetweenReads Then
    'check for data in the serial port
    Stevedore.MainPortReader()
    'update checked time
    LastTimeCheckedRead = Tock
End If

'Transmit data through the Speed Port (Mode 1 only)
If LocalProgramMode = 1 Then
    SendData = False
    'check for write
    SyncLock Stevedore.MainPortWriterLock
        'see if there was a write in progress
        If Stevedore.SavedTXString <> "" Then
            'call the write routine
            SendData = True
        End If
    End SyncLock
    If Tock > LastTimeCheckedWrite + TimeBetweenWriteChecks
Then
        'time to pulse the x-mit routine
        SendData = True
    End If

    If SendData = True Then
        'write data
        Stevedore.MainPortWriter()
        'update time
        LastTimeCheckedWrite = Tock
    End If
End If

'calculate the speed
CalculatedSpeed = SpeedLambda * (SpeedPulsesUp +
SpeedPulsesDown)
'set speed to zero if below cutoff
If CalculatedSpeed < SpeedZeroCutoff Then
    CalculatedSpeed = 0
End If

'update logged speed if the conditions are met
'those include time and speed change
If (Tock - LastRecordedSpeedTime) / Freq >
(MaxTimeBetweenSpeedRecordingTicks / 1000000) Then
    'it's time to log the speed
    Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
    'update the speed recording time and value
    LastRecordedSpeed = CalculatedSpeed
    LastRecordedSpeedTime = Tock
ElseIf CalculatedSpeed > StopSpeedValue Then
    'it is not stopped

```

```

        'check for standard delta
        If Math.Abs(CalculatedSpeed - LastRecordedSpeed) >
MaxDeltaSpeedRecording Then
        'Speed is different enough to update in the log
        Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
        'update the speed recording time and value
        LastRecordedSpeed = CalculatedSpeed
        LastRecordedSpeedTime = Tock
        End If
    Else
        'it's currently stopped, see if it was before
        If LastRecordedSpeed > StopSpeedValue Then
        'wasn't stopped last time, log it
        Lumberjack.SendToLog("Speed Effectively Stopped")
        Lumberjack.SendToLog("Current Speed: " &
CalculatedSpeed.ToString)
        'update the speed recording time and value
        LastRecordedSpeed = CalculatedSpeed
        LastRecordedSpeedTime = Tock
        End If
    End If

    'Update display
    If Tock > LastTimeUpdated + TimeBetweenUpdates Then
        'update the last update time
        LastTimeUpdated = Tock
        'Send Values
        SyncLock Windowsill.RunBoxLock
            'speed
            Windowsill.DetectedSpeed = CalculatedSpeed
            'speed in range indicator
            Windowsill.ProperSpeed = TargetSpeedAcquired
            'cavitation
            Windowsill.Cavitation = CavitationDetected
            'laser fired indication
            If FiredLaser = True Then
                'laser was fired
                Windowsill.LaserFireIndicator = True
                'clear the flag once transmitted
                FiredLaser = False
            End If
            'Speed restart stuff
            Windowsill.RestartStatus = SpeedRestartStatus
            Windowsill.RestartTimeLeft = CLng(SpeedRestartTimeLeft)
            'autopulsing
            If StopAutopulsing = True Then
                'no autopulsing
                Windowsill.DisableAutomaticPulsing = True
                StopAutopulsing = False
            End If
        End SyncLock
    End If

    'Release Control
    Application.DoEvents()

    If (Tock - SpinnerStopTimeoutCounter) / Freq > 30 Then
        'timeout waiting for the spinner to halt

```

```

        'log it and move on
        Lumberjack.SendToLog("Timeout waiting for spinner to halt;
speed is " & CalculatedSpeed.ToString)
        Exit Do
    End If
Loop While CalculatedSpeed > StopSpeedValue

Application.DoEvents()

'Close the Port
Try
    'if the port was opened, close it
    If LocalPortOpen = True Then
        'log it
        Lumberjack.SendToLog("Attempting to Close the " &
PortUseString & " (" & LocalPortName & ")")
        'send final string to the port, if there is one
        'get any data
        If LocalProgramMode = 1 Then
            'this thread controls the port, get final data to send
            SyncLock Stevedore.MainPortWriterLock
                'get leftover string, if any
                LocalTXString = Stevedore.SavedTXString
                Stevedore.SavedTXString = ""
            End SyncLock

            SyncLock Windowsill.RunBoxLock
                'get any last commands
                LocalTXString = LocalTXString &
Windowsill.CommandToLaser
                Windowsill.CommandToLaser = ""
            End SyncLock

            'append a newline character
            LocalTXString = LocalTXString & LaserEOL
        Else
            'laser either on another port, disconnected, or ignored
            'send a newline character
            LocalTXString = LaserEOL
        End If

        Try
            'transmit any data
            If LocalTXString <> "" Then
                SyncLock Stevedore.SpeedPortLock
                    Stevedore.COMPort1.Write(LocalTXString)
                End SyncLock
            End If
        Catch FinishedWriteException As Exception
            'log the issue
            Lumberjack.SendToLog("Exception in final write on " &
LocalPortName & ": " & FinishedWriteException.Message)
        End Try

        Thread.Sleep(250)
        'get all the data from the port, then close it
        SyncLock Stevedore.MainPortReaderLock
            'collect any text waiting to be logged
            LocalRXString = Stevedore.TempRXString

```

```

        Stevedore.TempRXString = ""
    End SyncLock

    SyncLock Stevedore.SpeedPortLock
        If Stevedore.COMPort1.IsOpen = True Then
            'get the last bit of data from the port
            LocalRXString = LocalRXString &
Stevedore.COMPort1.ReadExisting()
            'the port is open, close it
            Stevedore.COMPort1.Close()
            Stevedore.COMPort1.Dispose()
        End If
        LocalPortOpen = Stevedore.COMPort1.IsOpen
    End SyncLock
    Thread.Sleep(1000)
    'log success/failure to close the port
    If LocalPortOpen = True Then
        'port is still open, log an error
        Lumberjack.SendToLog(PortUseString & " (" &
LocalPortName & ") did not close successfully")
    Else
        'port closed
        Lumberjack.SendToLog("Successfully Closed the " &
PortUseString & " (" & LocalPortName & ")")
    End If
    End If

    Catch SerialPortClosureProblem As Exception
        'log it
        Lumberjack.SendToLog("Exception while attempting to close the "
& PortUseString & " (" & LocalPortName & "): " & vbNewLine &
SerialPortClosureProblem.Message)
    End Try

    'send the output where it belongs
    If LocalRXString <> "" Then
        'log the final rx string
        Lumberjack.SendToLog("Final Text Received from the " &
PortUseString & " (" & LocalPortName & "): " & LocalRXString)
        'mirror it on the runbox
        SyncLock Windowsill.RunBoxLock
            Windowsill.LaserRX = Windowsill.LaserRX & LocalRXString
        End SyncLock
        'clear the string
        LocalRXString = ""
    End If

    Thread.Sleep(3000)
    'log final comments
    Lumberjack.SendToLog(Freq.ToString & " Tocks/second")
    Lumberjack.SendToLog(LiveTocks.ToString & " Tocks Live")
    Lumberjack.SendToLog(AllTocks.ToString & " Tocks Total")
    If AllTocks <> 0 Then
        'prevent divide by zero errors
        Lumberjack.SendToLog((100 * LiveTocks / AllTocks).ToString & "
% Live Time")
    End If
    If TotalLoops <> 0 Then
        'prevent divide by zero

```



```

        Lumberjack.SendToLog((AllTocks / TotalLoops).ToString & "
Tocks/MainLoop")
    End If
    'log the live fraction, if applicable
    If UsedAdvancedTiming = True Then
        'advanced timing has been applied
        Lumberjack.SendToLog("Number of Applications of the Advanced
Timing Feature: " & AdvancedTimingCounts.ToString)
    End If
    'log termination
    Lumberjack.SendToLog("Speed Port Module Stopping")

    'now perform final shutdown tasks
    Lumberjack.SendToLog("Kernel Sanders Says " & TotalLoops & "
Loops")

    'now exit the thread

    Lumberjack.SendToLog("DEBUG MSG: LookAheadTocks = " &
LookAheadTocks.ToString)

    Catch ThreadNeededKilling As ThreadAbortException
        'the thread was aborted
        Application.ExitThread()
    Catch BigException As Exception
        'something unhandled occurred, exit the program
        Lumberjack.SendToLog("Exception in " & Thread.CurrentThread.Name &
": " & BigException.Message & vbNewLine & "Details: " & vbNewLine &
BigException.ToString)
        MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End Try

    Application.ExitThread()

End Sub

Private Shared Sub MainPortReader()
    'performs the read operations for the speed/laser port

    Dim LocalPortOpen As Boolean = False
    Dim LastRXTimeTicks As Long = 0
    Dim CharactersRead As Integer = 0
    Dim LocalRXChar(0) As Char
    Dim PreviousCharacterNewline As Boolean = False
    Dim LocalRXString As String = ""
    Dim CharactersRemain As Boolean = False
    Dim RXTimeoutToLogTicks As Long = 2500000
    Dim RXTag As String = ""

    'get variable data
    LocalRXChar(0) = CChar("")
    SyncLock Longshoreman.LaserPortLock

```

```

    If Longshoreman.LaserControlMode = 1 Then
        'laser on the speed control port
        RXTag = "RX from Laser:  "
    Else
        'laser is on another port
        RXTag = "RX from Speed Control Port:  "
    End If
End SyncLock

'load saved values
SyncLock Stevedore.MainPortReaderLock
    LastRXTimeTicks = Stevedore.LastRXTimeTicksSaved
    PreviousCharacterNewline = Stevedore.NewlineRX
    LocalRXString = Stevedore.TempRXString
End SyncLock

'get data from the port
SyncLock Stevedore.SpeedPortLock
    LocalPortOpen = Stevedore.COMPort1.IsOpen
End SyncLock

If LocalPortOpen = True Then
    'grab the characters buffered by the serialport one at a time
    Do
        'read one character from the port, if there are any
        SyncLock Stevedore.SpeedPortLock
            If Stevedore.COMPort1.BytesToRead > 0 Then
                CharactersRead = Stevedore.COMPort1.Read(LocalRXChar,
0, 1)

                'remember the last rx read time
                LastRXTimeTicks = Now.Ticks
            Else
                'no characters read
                CharactersRead = 0
            End If
        End SyncLock
        If CharactersRead > 0 Then
            'characters were actually read, process the data
            'check for cr or lf
            If (LocalRXChar(0).ToString = vbCr) Or
(LocalRXChar(0).ToString = vbLf) Then
                'current character is a newline sort of thing
                If PreviousCharacterNewline = True Then
                    'previous character was a newline sort of character
                    'so is the current line
                    'log it all and clear the previouscharacternewline
condition

                    PreviousCharacterNewline = False
                    LocalRXString = LocalRXString &
LocalRXChar(0).ToString

                    'send it all to the runbox
                    SyncLock Windowsill.RunBoxLock
                        Windowsill.LaserRX = Windowsill.LaserRX &
LocalRXString

                    End SyncLock
                    'log it
                    Lumberjack.SendToLog(RXTag & LocalRXString)
                    'clear the string
                    LocalRXString = ""
                End Do
            End If
        End If
    End Do

```

```

Else
    'previous character was NOT a newline character
    'but the current line is
    'append it to the local rx string, but wait before
logging
    PreviousCharacterNewline = True
    LocalRXString = LocalRXString & LocalRXChar(0)
End If
ElseIf PreviousCharacterNewline = True Then
    'previous but not current character was a newline
    'send the previous data where they all belong
    'send it all to the runbox
    SyncLock Windowsill.RunBoxLock
        Windowsill.LaserRX = Windowsill.LaserRX &
LocalRXString
    End SyncLock
    'log it
    Lumberjack.SendToLog(RXTag & LocalRXString)
    'clear the local rx string and put the current
character in it
    LocalRXString = LocalRXChar(0).ToString
    PreviousCharacterNewline = False
Else
    'neither the current nor the last character were
newlines
    'append the received character to the local rx string
    LocalRXString = LocalRXString & LocalRXChar(0).ToString
End If
'
End If

'check for remaining characters
SyncLock Stevedore.SpeedPortLock
    If Stevedore.COMPort1.BytesToRead > 0 Then
        'data remains
        CharactersRemain = True
    Else
        CharactersRemain = False
        'no data left
    End If
End SyncLock
Loop While CharactersRemain = True
End If

'check for time to dump the rx data to the log
'only if it hasn't received anything in the timeout period
If (Now.Ticks - LastRXTimeTicks) > RXTimeoutToLogTicks Then
    'last rx time was more than one timeout ago
    'if there's data to log, log it
    If LocalRXString <> "" Then
        'stuff to log
        'send it all to the runbox
        SyncLock Windowsill.RunBoxLock
            Windowsill.LaserRX = Windowsill.LaserRX & LocalRXString
        End SyncLock
        'log it
        Lumberjack.SendToLog(RXTag & LocalRXString)
        'clear the string
        LocalRXString = ""

```

```

        End If
    End If

    'save values
    SyncLock Stevedore.MainPortReaderLock
        Stevedore.LastRXTimeTicksSaved = LastRXTimeTicks
        Stevedore.NewlineRX = PreviousCharacterNewline
        Stevedore.TempRXString = LocalRXString
    End SyncLock

End Sub

Private Shared Sub MainPortWriter()
    'Performs the write operations when the speed controller port is shared
    with the laser

    Dim LocalTXString As String = ""
    Dim LocalPortEncoding As System.Text.Encoding
    Dim FoundLimit As Boolean = False
    Dim SendLength As Integer = 0
    Dim ShortString As String = ""
    Dim BytesToSend() As Byte
    Dim NumberBytes As Integer = 0
    Dim SendRefObj As Object = 0
    Dim WriteNumber As Integer = 0
    Dim ClearForLaser As Boolean = False
    Dim RecentTX As Boolean = False

    'load values
    SyncLock CentralClass.FileOpsLock
        LocalPortEncoding = CentralClass.ComPortEncoding
    End SyncLock
    'load saved values
    SyncLock Stevedore.MainPortReaderLock
        LocalTXString = Stevedore.SavedTXString
        WriteNumber = Stevedore.SavedWriteNumber
    End SyncLock

    'tell fire control to hold off momentarily
    SyncLock Stevedore.SpeedPortLock
        Stevedore.ClearToFireLaser = False
    End SyncLock

    'get any data
    RecentTX = False
    SyncLock Windowsill.RunBoxLock
        LocalTXString = LocalTXString & Windowsill.CommandToLaser
        'got the data, clear the shared variable
        Windowsill.CommandToLaser = ""
    End SyncLock
    'only send when the output buffer is empty to ensure it goes in the
    correct order
    If LocalTXString <> "" Then
        'set the transmission flag for later use
        RecentTX = True
        'check for an empty buffer
        SyncLock Stevedore.SpeedPortLock

```

```

        If Stevedore.COMPort1.BytesToWrite = 0 Then
            'empty buffer, write data
            'localportencoding
            If LocalPortEncoding.GetByteCount(LocalTXString) >
Stevedore.COMPort1.WriteBufferSize Then
                'too many characters
                'split the write in half in a loop until it fits
                FoundLimit = False
                SendLength = LocalTXString.Length
                Do
                    SendLength = CInt(SendLength / 2)
                    'see if the max bytes from that can be buffered
                    If LocalPortEncoding.GetMaxByteCount(SendLength) <
Stevedore.COMPort1.WriteBufferSize Then
                        'it works
                        FoundLimit = True
                    ElseIf SendLength < 10 Then
                        'it should be longer, something is really wrong
                        'proceed anyway
                        FoundLimit = True
                    End If
                Loop While FoundLimit = False
                'get the string to send
                ShortString = LocalTXString.Substring(0, SendLength)
                'and remove it from the local tx string
                LocalTXString = LocalTXString.Remove(0, SendLength)
                'encode the string
                BytesToSend = LocalPortEncoding.GetBytes(ShortString)
                NumberBytes = BytesToSend.Length
                'now it's ready to write
            Else
                'everything can fit in the buffer immediately
                'encode the string
                BytesToSend = LocalPortEncoding.GetBytes(LocalTXString)
                NumberBytes = BytesToSend.Length
                'clear the local string
                LocalTXString = ""
                'ready to send
            End If
            'write it to the serial port output asynchronously
            SendRefObj = CObj(WriteNumber)
            Stevedore.COMPort1.BaseStream.BeginWrite(BytesToSend, 0,
NumberBytes, AddressOf Stevedore.FinishedComPort1Send, SendRefObj)
            WriteNumber += 1
        End If
    End SyncLock
End If

'save values
SyncLock Stevedore.MainPortWriterLock
    Stevedore.SavedTXString = LocalTXString
    Stevedore.SavedWriteNumber = WriteNumber
End SyncLock

'Update Laser Fire Control
ClearForLaser = True
'check for request to fire
If ClearForLaser = True Then
    SyncLock Windowsill.RunBoxLock

```

```

        If Windowsill.LaserTXDataCritical = False Then
            'laser not in firing sequence, laser is not clear to fire
            ClearForLaser = False
        End If
    End SyncLock
End If
'check saved data
If ClearForLaser = True Then
    SyncLock Stevedore.MainPortWriterLock
        If Stevedore.SavedTXString <> "" Then
            'there's saved data to be transmitted, laser is not clear
to fire
                ClearForLaser = False
            End If
        End SyncLock
End If
'check available data
If ClearForLaser = True Then
    SyncLock Windowsill.RunBoxLock
        If Windowsill.CommandToLaser <> "" Then
            'there's data left to be loaded and transmitted, laser is
not clear to fire
                ClearForLaser = False
            End If
        End SyncLock
End If
'check buffered data
If ClearForLaser = True Then
    SyncLock Stevedore.SpeedPortLock
        If Stevedore.COMPort1.BytesToWrite <> 0 Then
            'there's buffered data in transmission, laser is not clear
to fire
                ClearForLaser = False
            End If
        End SyncLock
End If
If RecentTX = True Then
    'don't signal a clear line just yet
    ClearForLaser = False
End If
'send value to fire control
SyncLock Stevedore.SpeedPortLock
    Stevedore.ClearToFireLaser = ClearForLaser
End SyncLock

End Sub

```

```

Private Shared Sub FinishedComPort1Send(ByVal TXResult As
System.IAsyncResult)
    'gets called in asynchronous writes to the speed/laser port
    'when they finish transmitting data

    Try
        SyncLock Stevedore.SpeedPortLock
            'end the (completed) write
            Stevedore.COMPort1.BaseStream.EndWrite(TXResult)
        End SyncLock
    End Try

```

```

        Catch ex As Exception
            'something went wrong
            'log the error
            Lumberjack.SendToLog("Exception in the result of transmission to
laser: " & ex.Message)
            Lumberjack.SendToLog("Exception Data: " &
TXResult.AsyncState.ToString())
        End Try

    End Sub

End Class

```

## B.18 TESTENDER.DESIGNER.VB

```

<Global.Microsoft.VisualBasic.CompilerServices.DesignerGenerated()> _
Partial Class TestEnder
    Inherits System.Windows.Forms.Form

    'Form overrides dispose to clean up the component list.
    <System.Diagnostics.DebuggerNonUserCode()> _
    Protected Overrides Sub Dispose(ByVal disposing As Boolean)
        Try
            If disposing AndAlso components IsNot Nothing Then
                components.Dispose()
            End If
        Finally
            MyBase.Dispose(disposing)
        End Try
    End Sub

    'Required by the Windows Form Designer
    Private components As System.ComponentModel.IContainer

    'NOTE: The following procedure is required by the Windows Form Designer
    'It can be modified using the Windows Form Designer.
    'Do not modify it using the code editor.
    <System.Diagnostics.DebuggerStepThrough()> _
    Private Sub InitializeComponent()
        Dim resources As System.ComponentModel.ComponentResourceManager = New
System.ComponentModel.ComponentResourceManager(GetType(TestEnder))
        Me.EndButton = New System.Windows.Forms.Button
        Me.Label1 = New System.Windows.Forms.Label
        Me.SuspendLayout()
        '
        'EndButton
        '
        Me.EndButton.Location = New System.Drawing.Point(12, 32)
        Me.EndButton.Name = "EndButton"
        Me.EndButton.Size = New System.Drawing.Size(109, 23)
        Me.EndButton.TabIndex = 0
        Me.EndButton.Text = "End"
        Me.EndButton.UseVisualStyleBackColor = True
        '
        'Label1

```

```

    '
    Me.Label1.AutoSize = True
    Me.Label1.Location = New System.Drawing.Point(13, 9)
    Me.Label1.Name = "Label1"
    Me.Label1.Size = New System.Drawing.Size(106, 13)
    Me.Label1.TabIndex = 1
    Me.Label1.Text = "Click to End Program"
    '
    'TestEnder
    '
    Me.AutoScaleDimensions = New System.Drawing.SizeF(6.0!, 13.0!)
    Me.AutoScaleMode = System.Windows.Forms.AutoScaleMode.Font
    Me.ClientSize = New System.Drawing.Size(133, 67)
    Me.Controls.Add(Me.Label1)
    Me.Controls.Add(Me.EndButton)
    Me.FormBorderStyle = System.Windows.Forms.FormBorderStyle.Fixed3D
    Me.Icon = CType(resources.GetObject("$this.Icon"), System.Drawing.Icon)
    Me.MaximizeBox = False
    Me.MinimizeBox = False
    Me.Name = "TestEnder"
    Me.SizeGripStyle = System.Windows.Forms.SizeGripStyle.Hide
    Me.Text = "Exiter"
    Me.ResumeLayout(False)
    Me.PerformLayout()

End Sub
Friend WithEvents EndButton As System.Windows.Forms.Button
Friend WithEvents Label1 As System.Windows.Forms.Label
End Class

```

## B.19 TESTENDER.VB

```

Public Class TestEnder
    'A debugging-oriented form that can only initiate a program shutdown

    Private Sub Button1_Click(ByVal sender As System.Object, ByVal e As
System.EventArgs) Handles EndButton.Click
        'Ends the program

        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
        Lumberjack.SendToLog("Program Shutdown Initiated")
        Me.Hide()

    End Sub

    Private Sub TestEnder_FormClosing(ByVal sender As Object, ByVal e As
System.Windows.Forms.FormClosingEventArgs) Handles Me.FormClosing
        'Do not allow the form to be closed

        If e.CloseReason <> CloseReason.None Then
            e.Cancel = True
        End If
    End Sub

```



```

        End If

    End Sub

End Class

```

## B.20 WINDOWSILL.VB

```

Option Explicit On
Option Strict On

```

```

Friend NotInheritable Class Windowsill

```

```

    'This class houses the thread, code, and related variables that operate the
    RunBox

```

```

    '
    '
    Friend Shared Goopy As New Thread(AddressOf Windowsill.UserController)
    '
    '
    Private Shared FirstOrders As New Thread(AddressOf Windowsill.LaserInitTX)
    Private Shared InitComplete As Boolean = False
    '
    '
    Friend Shared LaserRX As String = ""
    Friend Shared CommandToLaser As String = ""
    Friend Shared LaserTXDataCritical As Boolean = False
    Friend Shared FireManualPulse As Boolean = False
    Friend Shared LogWritten As String = ""
    Friend Shared SpeedControlReady As Boolean = False
    Friend Shared LaserPortReady As Boolean = False
    Friend Shared RunBoxReady As Boolean = False
    Friend Shared DetectedSpeed As Double = 0
    Friend Shared ProperSpeed As Boolean = False
    Friend Shared Cavitation As Boolean = False
    Friend Shared LaserControlsUpdated As Boolean = False
    Friend Shared LaserFireIndicator As Boolean = False
    Friend Shared NextLaserPulsePower As Double = 0
    Friend Shared EstimatedLaserPulseDuration As Double = 0.000000001
    Friend Shared DelayBetweenPulses As Double = 1
    Friend Shared AutomaticPulsing As Boolean = False
    Friend Shared DisableAutomaticPulsing As Boolean = False
    Friend Shared SpeedControlsUpdated As Boolean = False
    Friend Shared DesiredSpeed As Double = 0
    Friend Shared RestartDelayTime As Double = 10
    Friend Shared CavitationAction As Long = 1
    Friend Shared RunButtonClicked As Boolean = False
    Friend Shared FinishedStartup As Boolean = False
    Friend Shared RestartStatus As Long = 0
    Friend Shared RestartTimeLeft As Long = 0
    Friend Shared StopAction As Boolean = False
    Friend Shared LaserStage As Long = 0
    Friend Shared RunBoxLock As New Object

```

```

Private Shared Sub UserController()
    'User Interface routine
    'Handles I/O, updates on the RunBox

    Dim LocalExit As Boolean
    Dim MaxCharacters As Long
    Dim ProgramMode As Long
    Dim StartupDone As Boolean
    Dim LocalExecutionStage As Long
    Dim LastLaserPulseTime As Long
    Dim LaserPulseFlashDurationTicks As Long
    Dim LocalLaserFired As Boolean
    Dim ShowFireLaser As Boolean
    Dim LocalLaserPulsePower As Double
    Dim DetectedCavitation As Boolean
    Dim SpeedInRange As Boolean
    Dim LocalSpeed As Double
    Dim HighlightLaserReady As Boolean
    Dim LocalDisablePulsing As Boolean
    Dim LocalSetSpeed As Double
    Dim LocalRestartDelay As Double
    Dim LocalPulseDuration As Double
    Dim LocalPulseDelay As Double
    Dim LocalRestartStatus As Long
    Dim LocalRestartTimeLeft As Long
    Dim LocalRunButtonClicked As Boolean
    Dim StatusString As String
    Dim LocalCavitationBehavior As Long
    Dim LocalStopAction As Boolean
    Dim LocalLaserStage As Long = 0
    Dim LaserEOL As String = ""
    Dim LaserInitTimeout As Long = 1200000000
    Dim LaserInitTime As Long = 0

    Try
        'Program Startup
        Thread.CurrentThread.Name = "Gooley"
        StartupDone = False
        LocalLaserFired = False
        ShowFireLaser = False
        StatusString = ""
        FirePulse.Hide()
        InsertComment.Hide()
        RunBox.Hide()
        SendLaserCommand.Hide()
        'set the duration it ticks (=100 ns/tick) that the "FIRE LASER!"
signal is shown
        LaserPulseFlashDurationTicks = 2500000
        'first, set up the RunBox
        RunBox.FireLaserBox.BackColor = System.Drawing.SystemColors.Control
        'Crimson while firing
        RunBox.FireLaserBox.ForeColor =
System.Drawing.SystemColors.ControlLight
        'Yellow while firing
        'set the maximum number of characters in the log/laser output trace
        MaxCharacters = 4096
        'now set status, date, and time
        RunBox.DateBox.Text = Format(Now(), "dddd, MMMM d, yyyy")
    
```

```

RunBox.TimeBox.Text = Format(Now(), "HH:mm:ss")
RunBox.CurrentStatusBox.Text = "Starting Up"
RunBox.CurrentSpeedBox.Text = "Not Available"
'show output log filename
SyncLock CentralClass.FileOpsLock
    RunBox.OutputFileBox.Text =
System.IO.Path.GetFullPath(CentralClass.Filename)
End SyncLock
RunBox.OutputFileBox.AutoEllipsis = True
'Append the Log Trace Box with any current log text, then clear the
shared variable
SyncLock Windowsill.RunBoxLock
    RunBox.LogTrace.AppendText(Windowsill.LogWritten)
    Windowsill.LogWritten = ""
    'set the initial state of the run button and startup
    Windowsill.RunButtonClicked = False
    Windowsill.FinishedStartup = False
End SyncLock
RunBox.LogTrace.Select(RunBox.LogTrace.TextLength, 0)
RunBox.LogTrace.ScrollToCaret()

'disable controls
RunBox.ButtonSetSpeed.Enabled = False
RunBox.ButtonStartSpeed.Enabled = False
RunBox.ButtonStopSpeed.Enabled = False
RunBox.ButtonSetLaser.Enabled = False
RunBox.ButtonFireLaser.Enabled = False
RunBox.ButtonSendLaserCommand.Enabled = False
RunBox.RestartDelayInputBox.Enabled = False
RunBox.SetSpeedInputBox.Enabled = False
RunBox.OnCavitationContinue.Enabled = False
RunBox.OnCavitationStop.Enabled = False
RunBox.OnCavitationStopAndRestart.Enabled = False
RunBox.AutomaticPulsingTrue.Enabled = False
RunBox.AutomaticPulsingFalse.Enabled = False
RunBox.LaserRxBox.Enabled = False
RunBox.EstimatedDurationInputBox.Enabled = False
RunBox.LaserDelayInputBox.Enabled = False

'get the laser eol sequence
SyncLock CentralClass.FileOpsLock
    LaserEOL = CentralClass.LaserNewlineString
End SyncLock

RunBox.Show()
LocalExit = False
Application.DoEvents()

'get the operating mode
SyncLock Longshoreman.LaserPortLock
    ProgramMode = Longshoreman.LaserControlMode
End SyncLock

'announce the readiness of the RunBox
SyncLock Windowsill.RunBoxLock
    Windowsill.RunBoxReady = True
End SyncLock

'wait for other startup tasks to complete

```

```

Do
    'check for speed control readiness
    SyncLock Windowsill.RunBoxLock
        If (Windowsill.LaserPortReady = True) And
(Windowsill.SpeedControlReady) = True Then
            'other threads ready, proceed to main loop
            StartupDone = True
            End If
        End SyncLock
        'update date
        If RunBox.DateBox.Text <> Format(Now(), "dddd, MMMM d, yyyy")
Then
            RunBox.DateBox.Text = Format(Now(), "dddd, MMMM d, yyyy")
        End If
        'update time
        If RunBox.TimeBox.Text <> Format(Now(), "HH:mm:ss") Then
            RunBox.TimeBox.Text = Format(Now(), "HH:mm:ss")
        End If
        'Append the Log Trace Box with any current log text, then clear
the shared variable
        SyncLock Windowsill.RunBoxLock
            If Windowsill.LogWritten <> "" Then
                RunBox.LogTrace.AppendText(Windowsill.LogWritten)
                Windowsill.LogWritten = ""
                'move the cursor to the end
                RunBox.LogTrace.Select(RunBox.LogTrace.TextLength, 0)
                RunBox.LogTrace.ScrollToCaret()
            End If
        End SyncLock
        'Check and see if the log trace has too many characters
        If RunBox.LogTrace.TextLength > MaxCharacters Then
            'too many characters in the log trace, eliminate enough
upstream characters to reduce its length to max
            RunBox.LogTrace.Text = RunBox.LogTrace.Text.Remove(0,
CInt(RunBox.LogTrace.TextLength - MaxCharacters))
            'move the cursor to the end
            RunBox.LogTrace.Select(RunBox.LogTrace.TextLength, 0)
            RunBox.LogTrace.ScrollToCaret()
        End If
        'Append the Laser Rx Box with any current text, then clear the
shared variable
        SyncLock Windowsill.RunBoxLock
            If Windowsill.LaserRX <> "" Then
                RunBox.LaserRxBox.AppendText(Windowsill.LaserRX)
                Windowsill.LaserRX = ""
                'move the cursor to the end
                RunBox.LaserRxBox.Select(RunBox.LogTrace.TextLength, 0)
                RunBox.LaserRxBox.ScrollToCaret()
            End If
        End SyncLock
        'Check and see if the Laser Rx Box has too many characters
        If RunBox.LaserRxBox.TextLength > MaxCharacters Then
            'too many characters in the laser rx box, eliminate enough
upstream characters to reduce its length to max
            RunBox.LaserRxBox.Text = RunBox.LaserRxBox.Text.Remove(0,
CInt(RunBox.LaserRxBox.TextLength - MaxCharacters))
            'move the cursor to the end
            RunBox.LaserRxBox.Select(RunBox.LaserRxBox.TextLength, 0)
            RunBox.LaserRxBox.ScrollToCaret()

```

```

End If
'check for program exit status
'bypass startup if shutdown condition exists
SyncLock CentralClass.ProgramExitLock
    LocalExit = CentralClass.ExitProgram
End SyncLock
If LocalExit = True Then StartupDone = True
Application.DoEvents()
Thread.Sleep(55)
Loop While StartupDone = False

'Transmit the laser init string
If ProgramMode <> 0 Then
    'start the thread to transmit the string
    SyncLock Windowsill.RunBoxLock
        Windowsill.InitComplete = False
        LaserInitTime = Now.Ticks
        Windowsill.FirstOrders.Start()
    End SyncLock
Else
    'indicate that laser init is complete
    SyncLock Windowsill.RunBoxLock
        Windowsill.InitComplete = True
    End SyncLock
End If

'make sure the laser init string completes transmission
StartupDone = False
Do
    'check for completion of transmission of the init string
    If ProgramMode <> 0 Then
        'the string should be transmitted; check on completion
        SyncLock Windowsill.RunBoxLock
            If Windowsill.InitComplete = True Then
                'laser init finished, proceed to main loop
                StartupDone = True
            End If
        End SyncLock
        If (StartupDone = False) And (Now.Ticks - LaserInitTime >
LaserInitTimeout) Then
            'too long waiting for the laser to finish init
            StartupDone = True
            Lumberjack.SendToLog("Error: Timeout in Laser
Initialization, Terminating")
            'abort program
            SyncLock CentralClass.ProgramExitLock
                CentralClass.ExitProgram = True
            End SyncLock
            LocalExit = True
        End If
    Else
        StartupDone = True
    End If
    'update date
    If RunBox.DateBox.Text <> Format(Now(), "dddd, MMMM d, yyyy")
Then
        RunBox.DateBox.Text = Format(Now(), "dddd, MMMM d, yyyy")
    End If
    'update time

```

```

    If RunBox.TimeBox.Text <> Format(Now(), "HH:mm:ss") Then
        RunBox.TimeBox.Text = Format(Now(), "HH:mm:ss")
    End If
    'Append the Log Trace Box with any current log text, then clear
the shared variable
    SyncLock Windowsill.RunBoxLock
        If Windowsill.LogWritten <> "" Then
            RunBox.LogTrace.AppendText(Windowsill.LogWritten)
            Windowsill.LogWritten = ""
            'move the cursor to the end
            RunBox.LogTrace.Select(RunBox.LogTrace.TextLength, 0)
            RunBox.LogTrace.ScrollToCaret()
        End If
    End SyncLock
    'Check and see if the log trace has too many characters
    If RunBox.LogTrace.TextLength > MaxCharacters Then
        'too many characters in the log trace, eliminate enough
upstream characters to reduce its length to max
        RunBox.LogTrace.Text = RunBox.LogTrace.Text.Remove(0,
CInt(RunBox.LogTrace.TextLength - MaxCharacters))
        'move the cursor to the end
        RunBox.LogTrace.Select(RunBox.LogTrace.TextLength, 0)
        RunBox.LogTrace.ScrollToCaret()
    End If
    'Append the Laser Rx Box with any current text, then clear the
shared variable
    SyncLock Windowsill.RunBoxLock
        If Windowsill.LaserRX <> "" Then
            RunBox.LaserRxBox.AppendText(Windowsill.LaserRX)
            Windowsill.LaserRX = ""
            'move the cursor to the end
            RunBox.LaserRxBox.Select(RunBox.LogTrace.TextLength, 0)
            RunBox.LaserRxBox.ScrollToCaret()
        End If
    End SyncLock
    'Check and see if the Laser Rx Box has too many characters
    If RunBox.LaserRxBox.TextLength > MaxCharacters Then
        'too many characters in the laser rx box, eliminate enough
upstream characters to reduce its length to max
        RunBox.LaserRxBox.Text = RunBox.LaserRxBox.Text.Remove(0,
CInt(RunBox.LaserRxBox.TextLength - MaxCharacters))
        'move the cursor to the end
        RunBox.LaserRxBox.Select(RunBox.LaserRxBox.TextLength, 0)
        RunBox.LaserRxBox.ScrollToCaret()
    End If
    'check for program exit status
    'bypass startup if shutdown condition exists
    SyncLock CentralClass.ProgramExitLock
        LocalExit = CentralClass.ExitProgram
    End SyncLock
    If LocalExit = True Then StartupDone = True
    Application.DoEvents()
    Thread.Sleep(55)
    Loop While StartupDone = False

    'finish starting up
    'only enter main mode if the program is not shutting down
    If LocalExit = False Then
        'enable applicable controls

```

```

'first, enable speed controls EXCEPT the 'stop' button
'it is only applicabe once started
RunBox.ButtonStopSpeed.Enabled = False
RunBox.OnCavitationContinue.Enabled = True
RunBox.OnCavitationStop.Enabled = True
RunBox.OnCavitationStopAndRestart.Enabled = True
RunBox.SetSpeedInputBox.Enabled = True
RunBox.RestartDelayInputBox.Enabled = True
RunBox.ButtonSetSpeed.Enabled = True
RunBox.ButtonStartSpeed.Enabled = True

'next, enable laser controls IF the mode is correct
If ProgramMode <> 0 Then
    'laser control enabled, so enable the controls

    'now enable the controls
    RunBox.AutomaticPulsingTrue.Enabled = True
    RunBox.AutomaticPulsingFalse.Enabled = True
    RunBox.LaserRxBox.Enabled = True
    RunBox.EstimatedDurationInputBox.Enabled = True
    RunBox.LaserDelayInputBox.Enabled = True
    RunBox.ButtonSetLaser.Enabled = True
    RunBox.ButtonFireLaser.Enabled = True
    RunBox.ButtonSendLaserCommand.Enabled = True
End If

SyncLock Windowsill.RunBoxLock
    LocalLaserPulsePower = Windowsill.NextLaserPulsePower
End SyncLock
'log the default selections
Lumberjack.SendToLog("Default Control Speed: " &
RunBox.SetSpeedShowBox.Text)
Lumberjack.SendToLog("Default Delay Before Restart: " &
RunBox.RestartDelayShowBox.Text)
'log default action on cavitation
If RunBox.OnCavitationContinue.Checked = True Then
    Lumberjack.SendToLog("Default Action on Cavitation:
Continue")
ElseIf RunBox.OnCavitationStop.Checked = True Then
    Lumberjack.SendToLog("Default Action on Cavitation: Stop")
ElseIf RunBox.OnCavitationStopAndRestart.Checked = True Then
    Lumberjack.SendToLog("Default Action on Cavitation: Stop
and Restart")
Else
    'Unknown state
    Lumberjack.SendToLog("Unknown Default Action on
Cavitation")
End If
'log default value of start/stop speed control
If RunBox.ButtonStartSpeed.Enabled = True Then
    Lumberjack.SendToLog("Default Speed Control State:
Started")
Else
    Lumberjack.SendToLog("Default Speed Control State:
Stopped")
End If
'log laser setup if mode <> 0
If ProgramMode <> 0 Then
    If RunBox.AutomaticPulsingTrue.Checked = True Then

```

```

Automatic")
    Lumberjack.SendToLog("Default Laser Pulse Control:
Manual")
    ElseIf RunBox.AutomaticPulsingFalse.Checked = True Then
        Lumberjack.SendToLog("Default Laser Pulse Control:
Control")
    Else
        'unknown state
        Lumberjack.SendToLog("Unknown Default Laser Pulse
Control")
    End If
    Lumberjack.SendToLog("Initial Laser Pulse Power: " &
Str(LocalLaserPulsePower))
    Lumberjack.SendToLog("Default Estimated Laser Pulse
Duration: " & RunBox.EstimatedDurationShowBox.Text)
    Lumberjack.SendToLog("Default Delay Between Laser Pulses:
" & RunBox.LaserDelayShowBox.Text)
    End If

    'log completion of user interface startup
    RunBox.CurrentStatusBox.Text = "Ready"
    Lumberjack.SendToLog("User Interface Startup Complete; Program
Ready")

    SyncLock Windowsill.RunBoxLock
        Windowsill.FinishedStartup = True
    End SyncLock

    'main loop
    Do
        SyncLock CentralClass.ProgramExitLock
            LocalExit = CentralClass.ExitProgram
        End SyncLock
        'update date
        If RunBox.DateBox.Text <> Format(Now(), "dddd, MMMM d,
yyyy") Then
            RunBox.DateBox.Text = Format(Now(), "dddd, MMMM d,
yyyy")
        End If
        'update time
        If RunBox.TimeBox.Text <> Format(Now(), "HH:mm:ss") Then
            RunBox.TimeBox.Text = Format(Now(), "HH:mm:ss")
        End If
        'Append the Log Trace Box with any current log text, then
clear the shared variable
        SyncLock Windowsill.RunBoxLock
            If Windowsill.LogWritten <> "" Then
                RunBox.LogTrace.AppendText(Windowsill.LogWritten)
                Windowsill.LogWritten = ""
                'move the cursor to the end
                RunBox.LogTrace.Select(RunBox.LogTrace.TextLength,
0)
                RunBox.LogTrace.ScrollToCaret()
            End If
        End SyncLock
        'Check and see if the log trace has too many characters
        If RunBox.LogTrace.TextLength > MaxCharacters Then
            'too many characters in the log trace, eliminate enough
upstream characters to reduce its length to max
            RunBox.LogTrace.Text = RunBox.LogTrace.Text.Remove(0,
CInt(RunBox.LogTrace.TextLength - MaxCharacters))

```



```

        'move the cursor to the end
        RunBox.LogTrace.Select (RunBox.LogTrace.TextLength, 0)
        RunBox.LogTrace.ScrollToCaret ()
    End If
    'Append the Laser Rx Box with any current text, then clear
the shared variable
    SyncLock Windowsill.RunBoxLock
        If Windowsill.LaserRX <> "" Then
            RunBox.LaserRxBox.AppendText (Windowsill.LaserRX)
            Windowsill.LaserRX = ""
            'move the cursor to the end

RunBox.LaserRxBox.Select (RunBox.LogTrace.TextLength, 0)
            RunBox.LaserRxBox.ScrollToCaret ()
        End If
    End SyncLock
    'Check and see if the Laser Rx Box has too many characters
    If RunBox.LaserRxBox.TextLength > MaxCharacters Then
        'too many characters in the laser rx box, eliminate
enough upstream characters to reduce its length to max
        RunBox.LaserRxBox.Text =
RunBox.LaserRxBox.Text.Remove (0, CInt (RunBox.LaserRxBox.TextLength -
MaxCharacters))

        'move the cursor to the end
        RunBox.LaserRxBox.Select (RunBox.LaserRxBox.TextLength,
0)

        RunBox.LaserRxBox.ScrollToCaret ()
    End If

    'Check for updated globals to show in the runbox
    SyncLock Windowsill.RunBoxLock
        'see if the speed needs to be stopped
        LocalStopAction = Windowsill.StopAction
        'check for fired laser
        If Windowsill.LaserFireIndicator = True Then
            'laser was recently fired, show it
            LastLaserPulseTime = Now.Ticks
            LocalLaserFired = True
            'clear the flag
            Windowsill.LaserFireIndicator = False
        End If
        'check for laser firing readiness
        If ProgramMode > 0 Then
            'only if there's a laser to fire
            If Windowsill.AutomaticPulsing = False Then
                'set it yellow
                HighlightLaserReady = True
                ShowFireLaser = False
            ElseIf Windowsill.ProperSpeed = True Then
                'speed in range, set to yellow
                HighlightLaserReady = True
                ShowFireLaser = True
            Else
                'not ready, set to default color
                HighlightLaserReady = False
                ShowFireLaser = False
            End If
        End If
        'check for disabling of automatic pulsing

```

```

        If Windowsill.DisableAutomaticPulsing = True Then
            'disable automatic pulsing
            LocalDisablePulsing = True
            Windowsill.AutomaticPulsing = False
            Windowsill.DisableAutomaticPulsing = False
        End If
        'get speed, speed in range, and cavitation status
        LocalSpeed = Windowsill.DetectedSpeed
        SpeedInRange = Windowsill.ProperSpeed
        DetectedCavitation = Windowsill.Cavitation
        'get setspeed, restart delay, pulse duration, pulse
delay
        LocalSetSpeed = Windowsill.DesiredSpeed
        LocalRestartDelay = Windowsill.RestartDelayTime
        LocalPulseDuration =
Windowsill.EstimatedLaserPulseDuration
        LocalPulseDelay = Windowsill.DelayBetweenPulses
        'get next pulse power
        LocalLaserPulsePower = Windowsill.NextLaserPulsePower
        'get run and restart status
        LocalRestartStatus = Windowsill.RestartStatus
        LocalRestartTimeLeft = Windowsill.RestartTimeLeft
        LocalRunButtonClicked = Windowsill.RunButtonClicked
        LocalCavitationBehavior = Windowsill.CavitationAction
        'get laser fire sequence stage
        LocalLaserStage = Windowsill.LaserStage
    End SyncLock

    'if necessary, press stop
    If LocalStopAction = True Then
        RunBox.PressStopButton()
        'clear the variable demanding the stop
        SyncLock Windowsill.RunBoxLock
            Windowsill.StopAction = False
        End SyncLock
    End If

    If LocalDisablePulsing = True Then
        'continue to disable autopulsing
        RunBox.StopAutomaticPulsing()
        LocalDisablePulsing = False
    End If

    'show updated values
    'update the speed (includes padding/trimming on right hand
side)
    If RunBox.CurrentSpeedBox.Text <> LocalSpeed.ToString("E2")
Then
        RunBox.CurrentSpeedBox.Text = LocalSpeed.ToString("E2")
    End If
    'update the setspeed
    If RunBox.SetSpeedShowBox.Text <>
LocalSetSpeed.ToString("E2") Then
        RunBox.SetSpeedShowBox.Text =
LocalSetSpeed.ToString("E2")
    End If
    'update the restart delay
    If RunBox.RestartDelayShowBox.Text <>
LocalRestartDelay.ToString("E2") Then

```

```

        RunBox.RestartDelayShowBox.Text =
LocalRestartDelay.ToString("E2")
    End If
    'update the pulse duration
    If RunBox.EstimatedDurationShowBox.Text <>
LocalPulseDuration.ToString("E2") Then
        RunBox.EstimatedDurationShowBox.Text =
LocalPulseDuration.ToString("E2")
    End If
    If FirePulse.DurationDisplay.Text <>
LocalPulseDuration.ToString("E6") Then
        FirePulse.DurationDisplay.Text =
LocalPulseDuration.ToString("E6")
    End If
    'update pulse delay
    If RunBox.LaserDelayShowBox.Text <>
LocalPulseDelay.ToString("E2") Then
        RunBox.LaserDelayShowBox.Text =
LocalPulseDelay.ToString("E2")
    End If
    'update pulse power
    If RunBox.NextPulsePowerShowBox.Text <>
LocalLaserPulsePower.ToString("E2") Then
        RunBox.NextPulsePowerShowBox.Text =
LocalLaserPulsePower.ToString("E2")
    End If
    If FirePulse.PowerDisplay.Text <>
LocalLaserPulsePower.ToString("E6") Then
        FirePulse.PowerDisplay.Text =
LocalLaserPulsePower.ToString("E6")
    End If

    'update the indicators
    If DetectedCavitation = True Then
        'cavitation has been detected
        If RunBox.CavitationBox.Text <> "YES" Then
            'update the box
            RunBox.CavitationBox.Text = "YES"
            RunBox.CavitationBox.BackColor = Color.Maroon
        End If
    Else
        'cavitation sensor shows no cavitation
        If RunBox.CavitationBox.Text <> "NO" Then
            'update the box
            RunBox.CavitationBox.Text = "NO"
            RunBox.CavitationBox.BackColor = Color.Navy
        End If
    End If
    If SpeedInRange = True Then
        'the speed is in range
        If RunBox.SpeedInRangeBox.Text <> "YES" Then
            'update the box
            RunBox.SpeedInRangeBox.Text = "YES"
            RunBox.SpeedInRangeBox.BackColor = Color.DarkGreen
        End If
    Else
        If RunBox.SpeedInRangeBox.Text <> "NO" Then
            'update the box
            RunBox.SpeedInRangeBox.Text = "NO"

```

```

        RunBox.SpeedInRangeBox.BackColor = Color.Navy
    End If
End If

'what to show in the Fire Laser! box
If HighlightLaserReady = True Then
    'speed in range, set to yellow
    If RunBox.FireLaserBox.ForeColor <> Color.Yellow Then
        RunBox.FireLaserBox.ForeColor = Color.Yellow
    End If
Else
    'not ready, set to default color
    If RunBox.FireLaserBox.ForeColor <>
System.Drawing.SystemColors.ControlLight Then
        RunBox.FireLaserBox.ForeColor =
System.Drawing.SystemColors.ControlLight
    End If
End If
'show laser fire status
If LocalLaserFired = True Then
    'laser has recently been fired
    'check timeout
    If (Now.Ticks - LastLaserPulseTime) >
LaserPulseFlashDurationTicks Then
        'timed out
        LocalLaserFired = False
        'clear the flash
        RunBox.FireLaserBox.BackColor =
System.Drawing.SystemColors.Control
    Else
        If RunBox.FireLaserBox.BackColor <> Color.Crimson
Then
            'set it to flash crimson
            RunBox.FireLaserBox.BackColor = Color.Crimson
        End If
    End If
End If

'show the current status
If LocalRunButtonClicked = True Then
    'current status is running
    StatusString = "Running"
    'append it with other tags
    'display speed in range
    If SpeedInRange = True Then
        StatusString = StatusString & ", Speed in Target
Range"
    Else
        StatusString = StatusString & ", Adjusting Speed"
    End If
    If LocalRestartStatus = 0 Then
        'running normally
        'check for laser readiness
        If ProgramMode > 0 Then
            If ShowFireLaser = True Then
                'laser control active
                StatusString = StatusString & ", Ready to
Fire Laser"
            End If

```

```

        End If
        ElseIf LocalRestartStatus = 1 Then
            'stopping
            StatusString = StatusString & ", Stopping"
        ElseIf LocalRestartStatus = 2 Then
            'paused
            StatusString = StatusString & ", Waiting for
Restart, " & LocalRestartTimeLeft & " s Remaining"
        End If
    Else
        'current status is stopped
        StatusString = "Not Running, Ready"
    End If
    If LocalLaserStage <> 0 Then
        'reflect the laser firing sequence
        StatusString = StatusString & ", Laser Pulse at Stage "
& LocalLaserStage.ToString
    End If
    'show status text
    If RunBox.CurrentStatusBox.Text <> StatusString Then
        RunBox.CurrentStatusBox.Text = StatusString
    End If

    'stop if cavitation detected in that mode
    If DetectedCavitation = True Then
        'cavitated, check the mode
        If LocalCavitationBehavior = 1 Then
            'stop
            RunBox.PressStopButton()
        End If
    End If
    Application.DoEvents()
    Thread.Sleep(55)
    Loop While LocalExit = False
End If

'shutdown routine

'disable all controls
RunBox.ButtonSetSpeed.Enabled = False
RunBox.ButtonStartSpeed.Enabled = False
RunBox.ButtonStopSpeed.Enabled = False
RunBox.ButtonSetLaser.Enabled = False
RunBox.ButtonFireLaser.Enabled = False
RunBox.ButtonSendLaserCommand.Enabled = False
RunBox.ButtonEnd.Enabled = False
RunBox.ButtonInsertComment.Enabled = False
RunBox.ButtonHelp.Enabled = False
RunBox.RestartDelayInputBox.Enabled = False
RunBox.SetSpeedInputBox.Enabled = False
RunBox.OnCavitationContinue.Enabled = False
RunBox.OnCavitationStop.Enabled = False
RunBox.OnCavitationStopAndRestart.Enabled = False
RunBox.AutomaticPulsingTrue.Enabled = False
RunBox.AutomaticPulsingFalse.Enabled = False
RunBox.EstimatedDurationInputBox.Enabled = False
RunBox.LaserDelayInputBox.Enabled = False

'reset colors and status boxes

```

```

RunBox.CurrentStatusBox.Text = "Shutting Down"
RunBox.FireLaserBox.BackColor = System.Drawing.SystemColors.Control
RunBox.FireLaserBox.ForeColor =
System.Drawing.SystemColors.ControlLight
RunBox.CavitationBox.Text = "NO"
RunBox.CavitationBox.ForeColor = Color.Yellow
RunBox.CavitationBox.BackColor = Color.Navy
RunBox.SpeedInRangeBox.Text = "NO"
RunBox.SpeedInRangeBox.ForeColor = Color.Yellow
RunBox.SpeedInRangeBox.BackColor = Color.Navy

'hide additional boxes
FirePulse.Hide()
InsertComment.Hide()
SendLaserCommand.Hide()
HelpBox.Hide()

Application.DoEvents()
'wait for the right stage
Do
    'get execution stage
    SyncLock CentralClass.ProgramExitLock
        LocalExecutionStage = CentralClass.ExecutionStage
    End SyncLock
    'update the speed
    SyncLock Windowsill.RunBoxLock
        LocalSpeed = Windowsill.DetectedSpeed
    End SyncLock
    If RunBox.CurrentSpeedBox.Text <> LocalSpeed.ToString("E2")
Then
        RunBox.CurrentSpeedBox.Text = LocalSpeed.ToString("E2")
    End If
    'update date
    If RunBox.DateBox.Text <> Format(Now(), "dddd, MMMM d, yyyy")
Then
        RunBox.DateBox.Text = Format(Now(), "dddd, MMMM d, yyyy")
    End If
    'update time
    If RunBox.TimeBox.Text <> Format(Now(), "HH:mm:ss") Then
        RunBox.TimeBox.Text = Format(Now(), "HH:mm:ss")
    End If
    'Append the Log Trace Box with any current log text, then clear
the shared variable
    SyncLock Windowsill.RunBoxLock
        If Windowsill.LogWritten <> "" Then
            RunBox.LogTrace.AppendText(Windowsill.LogWritten)
            Windowsill.LogWritten = ""
            'move the cursor to the end
            RunBox.LogTrace.Select(RunBox.LogTrace.TextLength, 0)
            RunBox.LogTrace.ScrollToCaret()
        End If
    End SyncLock
    'Check and see if the log trace has too many characters
    If RunBox.LogTrace.TextLength > MaxCharacters Then
        'too many characters in the log trace, eliminate enough
upstream characters to reduce its length to max
        RunBox.LogTrace.Text = RunBox.LogTrace.Text.Remove(0,
CInt(RunBox.LogTrace.TextLength - MaxCharacters))
        'move the cursor to the end

```

```

        RunBox.LogTrace.Select(RunBox.LogTrace.TextLength, 0)
        RunBox.LogTrace.ScrollToCaret()
    End If
    'Append the Laser Rx Box with any current text, then clear the
shared variable
    SyncLock Windowsill.RunBoxLock
        If Windowsill.LaserRX <> "" Then
            RunBox.LaserRxBox.AppendText(Windowsill.LaserRX)
            Windowsill.LaserRX = ""
            'move the cursor to the end
            RunBox.LaserRxBox.Select(RunBox.LogTrace.TextLength, 0)
            RunBox.LaserRxBox.ScrollToCaret()
        End If
    End SyncLock
    'Check and see if the Laser Rx Box has too many characters
    If RunBox.LaserRxBox.TextLength > MaxCharacters Then
        'too many characters in the laser rx box, eliminate enough
upstream characters to reduce its length to max
        RunBox.LaserRxBox.Text = RunBox.LaserRxBox.Text.Remove(0,
CInt(RunBox.LaserRxBox.TextLength - MaxCharacters))
        'move the cursor to the end
        RunBox.LaserRxBox.Select(RunBox.LaserRxBox.TextLength, 0)
        RunBox.LaserRxBox.ScrollToCaret()
    End If
    Application.DoEvents()
    Thread.Sleep(55)
    Loop While LocalExecutionStage < 1050

    'Dispose of the forms
    'Dispose the FirePulse box
    Try
        FirePulse.Hide()
        FirePulse.Dispose()
    Catch ex As ObjectDisposedException
    End Try

    'Dispose the Helpbox
    Try
        HelpBox.Hide()
        HelpBox.Dispose()
    Catch ex As ObjectDisposedException
    End Try

    'Dispose the InsertComment box
    Try
        InsertComment.Hide()
        InsertComment.Dispose()
    Catch ex As ObjectDisposedException
    End Try

    'Dispose the Runbox
    Try
        RunBox.Hide()
        RunBox.Dispose()
    Catch ex As ObjectDisposedException
    End Try

    'Dispose the SendLaserCommand box
    Try

```

```

        SendLaserCommand.Hide()
        SendLaserCommand.Dispose()
    Catch ex As ObjectDisposedException
    End Try

    Application.DoEvents()

    'final shutdown steps
    Lumberjack.SendToLog("User Interface Stopping")
    RunBox.Hide()

    'make sure the laser init thread terminates
    SyncLock Windowsill.RunBoxLock
    Try
        'terminate the laser init thread
        If Windowsill.FirstOrders.Join(100) = False Then
            Windowsill.FirstOrders.Abort()
        End If
    Catch ex As Exception
        'nothing to do here
    End Try
End SyncLock

Catch ThreadNeededKilling As ThreadAbortException
    'the thread was aborted
    Application.ExitThread()
    'make sure the laser init thread terminates
    SyncLock Windowsill.RunBoxLock
    Try
        'terminate the init thread
        Windowsill.FirstOrders.Abort()
    Catch ex As Exception
        'nothing to do here
    End Try
End SyncLock

Catch BigException As Exception
    'something got really screwed up
    Lumberjack.SendToLog("Exception in " & Thread.CurrentThread.Name &
": " & BigException.Message & vbNewLine & "Details: " & vbNewLine &
BigException.ToString)
    MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")

    SyncLock CentralClass.ProgramExitLock
        CentralClass.ExitProgram = True
    End SyncLock

    'make sure the laser init thread terminates
    SyncLock Windowsill.RunBoxLock
    Try
        'terminate the init thread
        Windowsill.FirstOrders.Abort()
    Catch ex As Exception
        'nothing to do here
    End Try
End SyncLock
End Try

```



```

Application.ExitThread()

End Sub

Private Shared Sub LaserInitTX()
    'transmits the initialization commands to the laser, one at a time
    'it is expected that this will be spun off in its own thread

    Dim FullString As String = ""
    Dim LaserInitString(0) As String
    Dim LaserEOL As String = ""
    Dim n As Integer = 0
    Dim TotalCommands As Integer = 0
    Dim WaitTime As Integer = 500
    Dim ProceedStatus As Boolean = False
    Dim LocalClearLine As Boolean = False
    Dim FirstDelay As Boolean = False

    Try

        'set the startup conditions
        Thread.CurrentThread.Name = "FireStarter"
        SyncLock Windowsill.RunBoxLock
            Windowsill.InitComplete = False
            'lock down the laser dataline
            Windowsill.LaserTXDataCritical = True
        End SyncLock

        'get the laser end-of-line character
        SyncLock CentralClass.FileOpsLock
            LaserEOL = CentralClass.LaserNewlineString
        End SyncLock

        'set the laser initialization string as a sequence of commands
        n = 0
        LaserInitString(n) = LaserEOL
        n += 1
        ReDim Preserve LaserInitString(n)
        LaserInitString(n) = "E=1" & LaserEOL
        n += 1
        ReDim Preserve LaserInitString(n)
        LaserInitString(n) = "CDRH=1" & LaserEOL
        n += 1
        ReDim Preserve LaserInitString(n)
        LaserInitString(n) = "CW=1" & LaserEOL
        n += 1
        ReDim Preserve LaserInitString(n)
        LaserInitString(n) = "P=100" & LaserEOL
        n += 1
        ReDim Preserve LaserInitString(n)
        LaserInitString(n) = "CW=0" & LaserEOL
        n += 1
        ReDim Preserve LaserInitString(n)
        LaserInitString(n) = "L=1" & LaserEOL
        n += 1
        ReDim Preserve LaserInitString(n)

```

```

LaserInitString(n) = "?HID" & LaserEOL
n += 1
ReDim Preserve LaserInitString(n)
LaserInitString(n) = "?S" & LaserEOL
n += 1
ReDim Preserve LaserInitString(n)
LaserInitString(n) = "?INT" & LaserEOL
n += 1
ReDim Preserve LaserInitString(n)
LaserInitString(n) = "?HH" & LaserEOL
n += 1
ReDim Preserve LaserInitString(n)
LaserInitString(n) = "?FL" & LaserEOL
n += 1
ReDim Preserve LaserInitString(n)
LaserInitString(n) = "CAL=4" & LaserEOL

TotalCommands = UBound(LaserInitString)

'assemble the full string
FullString = ""
For n = 0 To TotalCommands
    FullString = FullString & LaserInitString(n) & vbNewLine
Next

'log the transmission
Lumberjack.SendToLog("Transmitting the Following Laser
Initialization Sequence: " & FullString)

Application.DoEvents()

'transmit the string, one command at a time
For n = 0 To TotalCommands
    ProceedStatus = False
    FirstDelay = False
    'wait for the line to clear, then xmit command n
    Do
        If FirstDelay = False Then
            'inserts a delay from the discovery of a clear line
            'check the statuses
            'check for a clear line
            SyncLock Stevedore.SpeedPortLock
                LocalClearLine = Stevedore.ClearToFireLaser
            End SyncLock
            'then check for an empty buffer
            If LocalClearLine = True Then
                SyncLock Windowsill.RunBoxLock
                    If Windowsill.CommandToLaser = "" Then
                        'good to go
                        FirstDelay = True
                    End If
                End SyncLock
            End If
            'insert the first delay if ready
            If FirstDelay = True Then
                'play nicely, and take a nap
                Application.DoEvents()
                Thread.Sleep(WaitTime)
            End If
        End Do
    Next

```

```

        Application.DoEvents()
    End If
Else
    'passed the first delay, continue
    'check the line status
    SyncLock Stevedore.SpeedPortLock
        LocalClearLine = Stevedore.ClearToFireLaser
    End SyncLock
    SyncLock Windowsill.RunBoxLock
        If Windowsill.CommandToLaser = "" And
LocalClearLine = True Then
            ProceedStatus = True
            'transmit
            Windowsill.CommandToLaser =
Windowsill.CommandToLaser & LaserInitString(n)
            End If
        End SyncLock
    End If
    'play nicely
    Application.DoEvents()
    Thread.Sleep(1)
    Application.DoEvents()
    Loop While ProceedStatus = False
    'add a second delay post-transmission
    Application.DoEvents()
    Thread.Sleep(WaitTime)
    Application.DoEvents()
Next

    'finish up
    SyncLock Windowsill.RunBoxLock
        Windowsill.InitComplete = True
        Windowsill.LaserTXDataCritical = False
    End SyncLock

    Catch ThreadNeededKilling As ThreadAbortException
        'the thread was aborted
        Application.ExitThread()
    Catch BigException As Exception
        'something got really screwed up
        Lumberjack.SendToLog("Exception in " & Thread.CurrentThread.Name &
": " & BigException.Message & vbNewLine & "Details: " & vbNewLine &
BigException.ToString)
        MsgBox("An exception has occurred in " & Thread.CurrentThread.Name
& " and the program will shut down." & vbNewLine & BigException.Message, ,
"OUCH!")
        SyncLock CentralClass.ProgramExitLock
            CentralClass.ExitProgram = True
        End SyncLock
    End Try

    Application.ExitThread()

End Sub

End Class

```

## B.21 USERGUIDE.TXT

SpeedControl User's Guide

=====  
Contents  
=====

1. Don't Sue Me. Don't Blame Me, Either.
2. Introduction
3. Ports and Connections
4. Program Startup & Shutdown
5. Program Operation
  - A. Speed Control
  - B. Laser Control
6. Final Remarks

=====  
1. Liability  
=====

The User agrees to indemnify the Program Author against any and all damages resulting from any direct or indirect use or misuse of the program. The User shall bear any and all responsibility for the use and/or misuse of the Program.

The Program comes 'As-Is' without any warranty of any kind, express or implied, including suitability for a given purpose. Use of the Program is at the User's own risk.

The Program is \*NOT\* to be used for, with, or in conjunction with any kind of illicit, unethical, or illegal activity.

=====  
2. Introduction  
=====

The SpeedControl Program is designed to be used for the control and basic data acquisition of the Centrifugal Tensioned Metastable Fluid Detector (CTMFD) Experiment in the Nuclear Heat Transfer Systems Laboratory at Texas A&M University. It controls the rotational speed of the CTMFD apparatus, issues pulses to the laser system (if connected), and maintains a log of the Program's activities as well as certain sensor readings.

The primary interface of the Program to the Experiment is through the Computer's RS-232 serial port(s). The speed controller box, along with the applicable sensors and a laser pulse line, are connected to a primary serial

port. A laser system, if used, may be connected to the data lines of the primary serial port as well; however, the Program also allows it to be connected through a second RS-232 serial port if the Computer supports it.

The Goal of the Program is fine control of the Experiment's rotational speed and the proper issuance of Laser Pulses in order to find the minimum Laser Pulse Energy that can induce cavitation in the Experiment.

The Program requires a Computer with Windows 2000 or newer, and the .NET Framework 2.0. A modern system with at least two processing cores is highly recommended.

The Laser Control features target a 100 mW Coherent CUBE-series laser system, and may not be compatible with other power levels or systems.

=====  
3. Ports and Connections  
=====

The Program will use either one (1) or two (2) RS-232 Serial Ports on the Computer.

The Primary Serial Port should have its signal lines connected as follows:

1. GND: Common Signal Ground
2. RTS: Laser Fire Signal
3. DTR: Speed Controller Signal
4. DSR: Speed Sensor Signal
5. DCD: Cavitation Sensor Signal

If a Laser System is used it may be connected to the Primary Serial Port or to a Secondary Serial Port. In either case, its lines should be connected to the port as follows:

1. GND: Common Signal Ground
2. TXD: Data TO Laser Signal
3. RXD: Data FROM Laser Signal

All other lines on the Serial Port(s) are unused.

Aside from the Data (TXD and RXD) and Ground (GND) lines, a Positive (+) signal on the line is used internally as a Boolean 'True' and a Negative (-) signal is interpreted as a Boolean 'False' in the same manner. RS-232 standard voltages apply. The hardware default should be a Negative voltage on every line except Ground.

=====  
4. Program Startup & Shutdown  
=====

On Startup, a dialog will appear giving the User a choice of Serial Ports found in the system for use as the (Primary) Controller Port and a Laser Port. The User should select (from the list) the Serial Port that is applicable for each connection. For example, if the Speed Controller is connected to COM2, then COM2 should be selected for the Controller port. If a Laser System is

connected to that port as well, then COM2 should also be selected for the Laser Port (it does not need to be connected to the same port). If no laser system is used, then the Laser port should be indicated as 'None' in the list. The proper Port Speed must also be chosen from the list.

The User will also be able to select a Log file for use with the Program. If it exists, it may either be appended or completely overwritten, depending on the selection made by the User. It will be written as a standard text file, so the extension .TXT is highly recommended.

The User may also enable the "Advanced Timing" Feature at the Program's startup; that option will not appear later on. If the checkbox is checked, then the Program's speed measurement will potentially be affected. The Feature only comes into play if it detects chunks of missing execution time in the Program; that can be the result of preemption in a multitasking environment. As the speed is determined by counting changes in an unbuffered serial port control line, such chunks of 'dead time' may have serious effects on the calculated speed's value. If the chunks are large enough, complete cycles of changes will be lost and the speed will be underreported. The Feature combats that by finding chunks of such 'dead time' and excluding them from consideration.

When all the selections are correct and the User is ready, the User should click on the 'OK' button to proceed to the main part of the Program.

The Program may be ended by clicking on 'Exit' in the Startup form or by clicking on 'End' (and confirming the choice to exit) when the main part of the Program is running. All ports and files in use will be closed, and the Program will terminate. The Program may also terminate if it encounters an error.

=====  
5. Program Operation  
=====

Once the User proceeds to the main part of the Program, a number of options are given in the form. On the top of the main form, there is an information array. This includes the current time, day, speed, log file, and status. It also has color-coded indicators that show whether or not the speed is controlled and within bounds of the desired range as well as a cavitation indicator. Below the information array, speed controls take up space on the left, and laser controls take up space on the right. On the bottom left is a box showing the recently added data to the log file. On the bottom left there are three buttons: Insert Comment, Help, and End. Clicking on End will close the Program, once the User confirms. The Help Button brings up the User's Guide.

The Insert Comment button brings up a window that allows the User to type in a comment and insert it into the log file. Clicking on OK will send whatever is in the box immediately to the log, and will close the window. Clicking on Cancel or the Close Button will close the window without sending anything to the log.

The Speed and Laser controls are discussed in their own sections below.

5.A. Speed Control  
=====

There are a number of controls available in the Speed Controls area. On the left, the User may enter the desired speed for the Experiment. The current set speed is shown immediately below the entry box; no changes are made until the User clicks on the 'Set' button in the Speed Controls area.

The User has a choice of three things to do in the event cavitation is detected in the Experiment. The first option is to ignore it and continue running. The second option is to stop (just as if the User clicked on the Stop button while running). The third option, Stop + Restart, halts the Experiment for the amount of time set in the Restart Delay option, and then resumes to the desired speed. The Restart Delay is the amount of time, in seconds, that the Experiment will be held at zero speed until it resumes maintaining the desired speed. No changes to any of those values will be used until the User clicks on the 'Set' button.

The two buttons on the bottom right of the Speed Controls area will start and stop the Experiment. Once the 'Start' button is clicked, it should become unavailable (and 'Stop' will become available), and the Program will begin controlling the speed of the Experiment. Clicking on 'Stop' will end this; it will become unavailable while 'Start' becomes available again, and the Experiment should halt.

The User should be aware of the special values that exist for the set speed. Any valid negative value below -1 will drive the speed control output pin high when the Experiment is Started or Running. This should run the Experiment at its maximum possible speed; however, the speed will never be "In Range" when this feature is used. Values between -1 and 0 will force the fraction of time that the speed control pin is high to the negative of that value; for example, setting it to -0.25 will set the speed control pin to be in the high state 25% of the time. As with values less than or equal to -1, the speed will never be "In Range" for these values. In addition, values for the set speed between 0 and 5 (inclusive) are not considered to have stable resulting speeds. Therefore, in those ranges, the speed will not be considered "In Range" regardless of how close it is to the desired value. It should be noted that automatic laser pulses will not be issued for those speed values as a result of this.

#### 5.B. Laser Control =====

The Laser Controls area has controls for a laser system, if connected. If the Laser Port was selected as 'None' then the entire area will be unavailable. At the bottom of the area there is a box showing the text received from the laser, if any.

As with the Speed Control area, many of the settings do not take effect until the User clicks on the 'Set' button in the Laser Controls Area. The Estimated Duration and Delay values are set that way. Enabling of automatic pulsing also requires the User to click on the 'Set' button; however, if the User clicks on 'No' for Automatic Pulsing, it is immediately disabled.

The Estimated Duration value is meant to be an estimate of the duration of the laser pulse. It is not measured, and not used for any computations. It is simply stored in the log. However, it will only allow nonzero positive values to be entered.

The Delay value will also only allow positive nonzero values to be entered. It, however, is used by the Program. It defines the minimum time delay (in seconds) between the issuance of automated laser pulses.

The Next Pulse Power value is the laser power demanded of the laser for the next pulse. It will increment automatically when Automatic Pulsing is used. It can be set from the 'Fire Pulse' window.

When Automatic Pulsing is used, the Program will wait for the Experiment's speed to be controlled within range, and will automatically issue pulses to the laser system with the set delay between pulses. Each time, the pulse power will be incremented until one of four things occur: Stopping the Experiment, Disabling Automatic Pulsing, Cavitation, or an out-of bounds pulse power. Automatic Pulsing will be disabled not only if the 'No' button is clicked, but also if the User clicks on the 'Fire Pulse' or 'Send Command to Laser' buttons as well.

The 'Send Command to Laser' button brings up a window that allows the User to enter any text and send it to the laser system. If there is a current operation prohibiting it, the User will be notified and may try to send the command again. An additional button, "Insert EOL" will insert a <CR> character (ASCII code 0xD, 13 in decimal) at the caret location or immediately before the selected text. Without explicit inclusion, no end-of-line characters will be included in the transmission. WARNING -- ANY COMMAND MAY BE SENT TO THE LASER SYSTEM, INCLUDING THOSE THAT HAVE THE POTENTIAL TO CAUSE DAMAGE OR INJURY. YOU CAN \*\*REALLY\*\* SCREW UP AN EXPENSIVE PIECE OF EQUIPMENT OR CAUSE BODILY HARM IF YOU DON'T USE CARE WHEN ISSUING COMMANDS.

The 'Fire Pulse' button brings up a window that allows the User to manually issue a pulse to the laser as well as to modify the values for laser power and estimated pulse duration. As with many other Program settings, these do not take effect until the User clicks on the 'Set Values' button. The 'FIRE' button will \*NOT\* set the values. The User may also enter a Comment for the log that goes with the manually-issued pulse. Clicking on the 'FIRE' button will disable automatic pulsing and issue the manual pulse.

The Laser Control area has an indicator that reflects the current laser operation. If automatic pulsing is disabled, or, if it is enabled and the speed is in range, it will display 'FIRE LASER' in the indicator. It will flash once a pulse has been issued, whether automatically or manually.

=====  
6. Final Remarks  
=====

This Program is resource intensive. It is \*HIGHLY\* recommended that the Computer system have at least TWO CPU cores and is not running anything aside from the Program. It is multithreaded, and one of its threads will use every available CPU cycle it can. This is so that it can read and write to the serial ports thousands of times per second.

Since Windows is a preemptive multitasking system, the speed readout \*MAY\* be inaccurate. I have not closely examined this. If the thread 'misses' a cyclical change in the speed readout pin, it will not give a fully accurate measurement. A higher-performing system may reduce that vulnerability. The Advanced Timing Feature is designed to alleviate this issue; however, it may introduce its own degree of error.



The Program uses the Win32 high-resolution performance counter. On some systems, this may be erratic. Certain multi-core systems can see issues if the threads get moved from core to core. Other systems may need to disable certain power-saving features if the system's high-resolution performance counter is tied, for example, to a CPU frequency that gets adjusted.

This Program was written in Microsoft Visual Basic 2005 Express.

```
=====  
THE END  
=====
```

**APPENDIX C**  
**STAR-CCM+ JAVA MACROS**

This Appendix includes the two Java macros used to run the Star-CCM+ simulation and to assist in data extraction.

## C.1 GETOUT.JAVA

```
// STAR-CCM+ macro: getout.java
package macro;

import java.util.*;

import star.common.*;
import star.base.neo.*;
import star.vis.*;
import star.base.report.*;

import star.motion.*;
public class getout extends StarMacro {

    public void execute() {
        execute0();
    }

    private void execute0() {

        Simulation simulation_0 =
            getActiveSimulation();

        PointPart pointPart_0 =
            simulation_0.getPartManager().createPointPart(new NeoObjectVector(new
            Object[] {}), new DoubleVector(new double[] {0.0, 0.0, 0.0}));

        Region region_0 =
            simulation_0.getRegionManager().getRegion("Fluids");

        pointPart_0.getInputParts().setObjects(region_0);

        PointPart pointPart_1 =
            simulation_0.getPartManager().createPointPart(new NeoObjectVector(new
            Object[] {}), new DoubleVector(new double[] {0.0, 0.0, 0.0}));

        pointPart_1.setPresentationName("Copy of point");

        pointPart_1.copyProperties(pointPart_0);

        PointPart pointPart_2 =
            simulation_0.getPartManager().createPointPart(new NeoObjectVector(new
            Object[] {}), new DoubleVector(new double[] {0.0, 0.0, 0.0}));

        pointPart_2.setPresentationName("Copy of point");

        pointPart_2.copyProperties(pointPart_0);

        Coordinate coordinate_0 =
            pointPart_1.getPointCoordinate();

        Units units_0 =
```

```

        ((Units) simulation_0.getUnitsManager().getObject("m"));

        coordinate_0.setCoordinate(units_0, units_0, units_0, new DoubleVector(new
double[] {0.0, 0.0, -0.00675}));

        Coordinate coordinate_1 =
            pointPart_2.getPointCoordinate();

        coordinate_1.setCoordinate(units_0, units_0, units_0, new DoubleVector(new
double[] {0.0, 0.0, -0.015}));

        SumReport sumReport_0 =
            simulation_0.getReportManager().createReport(SumReport.class);

        PrimitiveFieldFunction primitiveFieldFunction_0 =
            ((PrimitiveFieldFunction)
simulation_0.getFieldFunctionManager().getFunction("Pressure"));

        sumReport_0.setScalar(primitiveFieldFunction_0);

        sumReport_0.getParts().setObjects(pointPart_1, pointPart_2, pointPart_0);

        ExpressionReport expressionReport_0 =
            ((ExpressionReport)
simulation_0.getReportManager().getReport("CurrentTime"));

        sumReport_0.printReport();

        expressionReport_0.printReport();

        // Get the rotating motion object
        RotatingMotion rotatingMotion_0 =
            ((RotatingMotion)
simulation_0.get(MotionManager.class).getObject("Rotation in Fluids"));

        simulation_0.println("omega = " +
rotatingMotion_0.getRotationRate().getValue());
    }
}

```

## C.2 RAMP\_UP.JAVA

```

// STAR-CCM+ macro: ramp_up.java
package macro;

import java.util.*;

import star.common.*;
import star.base.neo.*;
import star.base.report.*;
import star.motion.*;

public class ramp_up extends StarMacro {

    public void execute() {
        execute0();
    }
}

```

```

private void execute0() {

    // This macro is meant to adjust the rotation rate as a function of time

    // constants
    double pi_val = 3.141592653589793238;
    double rate_min = 0; // Minimum rotation rate, rad/s
    double rate_max = 180 * 2 * pi_val; // Maximum rotation rate, rad/s
    double ramp_begin_time = 0.2; // time to begin ramping
    double ramp_end_time = 2; // time to end ramping
    double sim_time_now = 0; // will be used later for the current time
    double ramp_rate = 0; // will be used later for the ramp rate
    boolean stop_crit_met = false; // stopping criteria

    // Get the current simulation
    Simulation simulation_0 =
        getActiveSimulation();

    // Get the rotating motion object
    RotatingMotion rotatingMotion_0 =
        ((RotatingMotion)
simulation_0.get(MotionManager.class).getObject("Rotation in Fluids"));

    // Get the stopping criteria
    PhysicalTimeStoppingCriterion PhyTimeSC =
        ((PhysicalTimeStoppingCriterion)
simulation_0.getSolverStoppingCriterionManager().getSolverStoppingCriterion("Ma
ximum Physical Time"));

    StepStoppingCriterion StepSC =
        ((StepStoppingCriterion)
simulation_0.getSolverStoppingCriterionManager().getSolverStoppingCriterion("Ma
ximum Steps"));

    AbortFileStoppingCriterion AbortFileSC =
        ((AbortFileStoppingCriterion)
simulation_0.getSolverStoppingCriterionManager().getSolverStoppingCriterion("St
op File"));

    // Check the status of the stopping criteria
    stop_crit_met =
        (AbortFileSC.getIsUsed() && AbortFileSC.getIsSatisfied()) ||
        (StepSC.getIsUsed() && StepSC.getIsSatisfied()) || (PhyTimeSC.getIsUsed() &&
PhyTimeSC.getIsSatisfied());

    // Connect to the time inside the simulation
    ExpressionReport TimeVal =
        ((ExpressionReport)
simulation_0.getReportManager().getReport("CurrentTime"));

    while (stop_crit_met == false) {

        // Get the current time
        sim_time_now =
            TimeVal.monitoredValue();
    }
}

```

```

// Calculate the new ramp rate
if (sim_time_now < ramp_begin_time){
    // before the beginning of the ramp
    ramp_rate = rate_min;
    simulation_0.println("Currently Before the Ramp");
} else if (sim_time_now > ramp_end_time){
    // after the end of the ramp
    ramp_rate = rate_max;
    simulation_0.println("Now After the Ramp");
} else {
    // during the ramp, ramp linearly
    ramp_rate = ((sim_time_now - ramp_begin_time) * (rate_max - rate_min) /
(ramp_end_time - ramp_begin_time)) + rate_min;
    simulation_0.println("Currently During the Ramp");
}

// Set the new rotation rate
simulation_0.println("Setting the Rotational Rate (rad/s) = " +
ramp_rate);
rotatingMotion_0.getRotationRate().setValue(ramp_rate);

// step one time step
simulation_0.getSimulationIterator().step(1, true);

// Check the status of the stopping criteria
stop_crit_met =
    (AbortFileSC.getIsUsed() && AbortFileSC.getIsSatisfied()) ||
    (StepSC.getIsUsed() && StepSC.getIsSatisfied()) || (PhyTimeSC.getIsUsed() &&
PhyTimeSC.getIsSatisfied());

}

}
}

```