

WORLD-CLASS OUTSTANDING INTERNATIONAL
PROGRAM | EXHIBITION | NETWORKING

RESOLVING INTERMITTENT VIBRATION SPIKES ON STEAM TURBINES

Rajakumar Thiagarajan
Rotating Equipment Engineer

Sankar Ganesh
Lead MDS Engineer

Ashraf Abdelrahim
Specialist - Condition Monitoring



42nd Turbomachinery
29th Pump SYMPOSIA



GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Contents

- Background
- Machine description
- Data analysis
- Initial Analysis & Recommendations
- Machine Inspection results
- Subsequent Mechanical Failure Analysis
- Conclusions
- Lessons Learned




42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Background


- Six Fresh Cooling Water Pumps:
 - 4 Steam Turbines and 2 Motor driven pumps
 - Critical pumps in LNG production
- Intermittent vibration spikes - Proactive detection on three steam turbines using expert systems
- The condition deteriorated and sporadic steam turbine trip.
- Plant vulnerable to production loss



42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Machine Description




Turbine Type:	Back pressure (5 stage)
Bearings:	Tilting pad
Seals:	Mechanical Labyrinth
Coupling:	Diaphragm
Power:	3840KW
Speed:	3602 RPM



42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Data Analysis



Overall Vibration vs. Process data

- Increasing Vibration Trend & High vibration Trip
- No correlation with the process parameters




42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Data Analysis Cont'd..

Polar Plot – 1X Amplitude & Phase Angle



Abnormal Behavior – Significant Phase Angle Change During Steady State (All Over 360°)




42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Data Analysis Cont'd..

Direct Orbit Review During Vibration Excursion



Flat Orbit & Truncated Time Waveform due to Rub




42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Data Analysis Cont'd..

Direct Orbit Overlay – Comparison of Low & High Vibration Amplitudes



Significant change in the Orbit Shape & Amplitude (Change in Balance Condition Due to Thermal Bow)




42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013



Data Analysis Cont'd..

Thermal Bow Effect of Rub



Data Analysis Cont'd..

Vibration Trend and Polar Plot – Reviewed for 2nd Steam Turbine



Similar Behavior - Intermittent vibration
Amplitude & Change in Phase Angle





42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Data Analysis Cont'd..

Vibration Trend and Polar Plot – Reviewed for 3rd Steam Turbine



Similar Behavior But Less Severity - Intermittent vibration Amplitude & Change in Phase Angle



42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013



Initial Analysis & Recommendations:

Expert Analysts at site concluded the Rubbing Issue is most likely due to

- *Carbonized oil buildup in the oil deflector / seal area.*

Recommended Action Items:

- ✓ *Inspect oil/steam seal areas for rubbing marks due to deposit built-up / carbonized oil.*



42nd Turbomachinery
29th Pump SYMPOSIA


GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Machine Inspection Results

Oil Seal Area at Non Drive End Bearing of 1st Turbine



Carbonized deposits at NDE seal area



Rubbing Marks on the shaft

Rubbing Marks at the seal area due to oil carbonization is evidenced.



42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Machine Inspection Results Cont'd..

Rotor Internals of 1st Turbine



No abnormalities noticed on the Rotor internal components.



42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Machine Inspection Results Cont'd..

Oil Seal Area at Non Drive End Bearing of 2nd & 3rd Turbine

Seal Area of 2nd Turbine



Seal Area of 3rd Turbine




- Oil Carbonization deposits and Rubbing Marks at the seal area
- Based on the inspection results of 1st Turbine, no internal checks carried out for the 2nd & 3rd Machines



42nd Turbomachinery
&
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Subsequent Mechanical Failure Analysis





Conclusions

Primary Causes:

- Low seal air pressure - Oil leakage, migration at steam gland

Contributed Causes:

- Breather clogging - Oil leakage due to vapor accumulation and high lube oil pressure inside the bearing housing
- Design issues
 - Back pressure on the common return header - Wrong elevation of breather on the Gearbox drain line
 - Oil shelter in close vicinity to the steam gland

Action Items:

- Installed Pressure Gauge
- Breather cleaning task - Equipment Strategy.
- Modify the Breather elevation



42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013

Lessons Learned

- ✓ Reduced Maintenance Cost and Down Time
 - Prognostic approach on the issues and accurate analysis through experts helped early detection of machine malfunctions.
 - Findings on one steam turbine assisted to minimize the maintenance activities on other two steam turbines.
 - Presence of online diagnostic system helped to plan the machine shutdown for the maintenance without impact on the production.

- ✓ Design issues – A lesson for future projects.
 - Absence of seal air pressure monitoring
 - Close vicinity of oil seal and steam gland
 - Wrong elevation of breather location on the Gearbox



42nd Turbomachinery
29th Pump SYMPOSIA

GEORGE R. BROWN CONVENTION CENTER
9.30 – 10.3.2013