

Bearing Issues with a Flooded Screw Compressor

John K. Whalen – TCE

Chuck Nagengast – BP

Julia Postill – TCE

Will Lowry – Texas A&M




Introduction

- Flooded screw compressor on offshore platform had thrust and journal bearing failures
- Redesigned high case thrust bearings to run with “pressurized cavity”
- Redesigned journal bearings to increase reliability

Compressor

- Vapor recovery service
- Tandem compressor design
 - Two screw compressors bolted together
 - Male rotors coupled together
- Both male rotors run at 3600 rpm
- Both female rotors run at 2175 rpm

Compressor Bearings





High pressure case

Low pressure case

LC Thrust Bearing

Active & Inactive / Male & Female - Good condition



HC Thrust Bearing Pads

Severe
failure of
active
pads
(male and
female)



Thrust bearings

- LC and HC Bearings were different design
 - Both were equalized tilting pad
- LC did not fail - HC did fail
- Recorded step increases in HC rotor position
 - February had 12-15 mils float
 - June had 30 mils float
 - July – tripped on high axial movement


Thrust Bearings

- Decision made to duplicate LC design aspects in the HC thrust bearings and upgrade bearing design
 - Main difference was LC has drain orifice control and the HC had supply orifice control
 - Upgraded HC bearings to utilize copper pads
 - Also upgraded HC to offset pivots

Thrust Bearings


- With drain orifice control the oil pressure drop is taken ***after*** the bearing is lubricated
- With supply orifice control the pressure drop is taken ***before*** the bearing is lubricated.
- Concern that there may have been some degassing of the oil as it took the pressure drop – limiting load carrying capabilities

Thrust Bearings



Oil flow controlled by inlet orifices

Thrust Bearings



Oil flow controlled by outlet orifices



Journal Bearings

- All 8 journal bearings wiped
- All bearings had same design concepts
- Oil flow through bearings contributed to lobe lubrication
- Improved reliability by increased clearance and increased oil flow (by opening flow passages in bearing bores)

Journal bearings





Journal Bearings




Journal Bearings

- Clearances ran about $\frac{3}{4}$ mils per inch
 - Decided to open closer to 1 mil per inch
- Axial oil distributions grooves had “Bleed off” notches (chamfers) to control oil flow
 - Increased number and size of these chamfers

Journal Bearings



Journal Bearings




Journal Bearings

- Oil flow through a journal bearing consists of:
 - Side Leakage
 - Chamfer flow
- Increasing clearance increases side leakage
- Increasing chamfer size and/or number increases chamfer flow

Journal Bearings

- Bearings had different oil supply and drain pressures
 - Resulted in different flows
 - Resulted in uneven flow in some bearings
 - More flow towards screws on some and more flow away from screws on others
 - Also concerns with fluctuating pressure on screw side

Compressor Oil Pressures (psig)




Journal Bearings

- Increased clearance and chamfer flow added together to increase reliability
- Bearings ran good with no reliability issues
- Unfortunately increased bearing flow resulted in increased oil flow to lobes
 - This resulted in process gas condensation issues due to lowering gas temperature coupled with low dew point gas

Journal Bearings

- Needed to come up with a “compromise” with clearance and chamfer flow
- Testing verified chamfer flow coefficients
- Journal bearing computer analysis verified:
 - Impact of clearance on total bearing flow
 - Affect of chamfer flow on bearing reliability

Test rig



Test rig




Test rig

- Tested various configurations under actual operating speed.
- Utilized actual bearings and modified for
 - Different “chamfer” configurations
 - Size and number
 - Different clearances
- Tweaked analysis
 - “side” leakage agreement with computer code
 - Chamfer flow coefficients

Journal Bearings


Effect of Clearance on Metal Temperature



Assumed load of 200 psi, no chamfer flow

Journal Bearings

Effect of Flow on Metal Temperature



Assumed load of 200 psi, 6 mils diametral clearance



Journal Bearings

- Opted to retain OEM notch configurations and increase bearing clearances
- Result is improved bearing reliability with reduced process gas condensation problems
- Demonstrated use of computerized analysis to determine best design configuration

Conclusions - Thrust

- By recognizing proven thrust bearing design concepts AND a proven LC thrust bearing design - user was able to significantly increase thrust bearing reliability
- No further thrust bearing issues since redesign installed during the summer of 2005

Conclusions – Journal

- Journal Bearing failure pointed to inadequate clearance and lack of lubrication
- Redesign to increase clearance improved reliability but introduced process gas condensation problem.
- Analysis of bearing clearance and oil flow allowed optimum bearing design.
 - No more journal bearing failures
 - Minimize condensation issues