

Abstract

37th Turbomachinery Symposium

Case Study:

VFD Induced Coupling Failure

Authors:

John Kocur, Jr. Ph.D
Machinery Specialist, ExxonMobil

Joe Corcoran
Manager Global Services & Training, Kop-Flex

A catastrophic failure of a high performance disc coupling connecting the speed increaser and LP compressor in a VFD controlled 18,300 HP motor/speed increaser/LP compressor/HP compressor train, led to months of reduced plant operation while the root cause of the failure, and corrective action, both outlined in this Case Study, were determined.

VFD Induced Coupling Failure

John A. Kocur, Jr.
Joseph P. Corcoran

Turbomachinery Symposium 2008 – Case History

Introduction

- **Background Information**
- **Failure Description**
- **Details of the RCFA**
- **Measurement Activities**
- **Controller Operation**
- **Torque Estimation**
- **Correction Activities**
- **Conclusions**

Background Information

- **VFD Induction Motor Driven Train**


- Motor: 18305 HP @ 1575 RPM
- Speed Increaser
- LP & HP Compressors @6000 RPM

- **High Speed Coupling Failure**


- After 2000 hrs of operation
 - ≈190,000,000 cycles
- Pinion – LP compressor coupling
- Safety issue due to released parts

Train Diagram

C:\Local\ARMD\Ras Gas Fuel Gas\Compressor Train.toi
John A. Kocur, Jr.
ExxonMobil Research & Engineering
01/29/06 11:15:00




Torsion Induced Failure



**Crack
Initiation**


**Spiral
Propagation**

Secondary Damage



Flailing
split
retained
hub
releasing
piece

Guard Penetrated




Turbomachinery Symposium 2008





RCFA

- **Vibration signatures prior to failure**
 - Gear radial subsynchronous vibration at 13.7 Hz
 - Coincident with 1st torsional natural frequency
- **Instrumented LS coupling for torsional measurements**
 - Torsional pulsations were identified
 - Two distinct factors involved

Torsional Measurements





Vibration Measurements



Damping Estimation

Damping estimation from the response around the natural frequency



Seems to confirm the popular assumption that trains w/ disk/diaphragm couplings have 1.6% of critical damping

VFD Sidebands

- **Sharp peak represents sidebands of the PWM frequency**

$$f_{sb} = \left| f_{pwm} - I_{odd} * f_o \right|$$


$$I_{odd} = \text{Odd Integer}$$

$$f_o = 2 * \text{Motor Speed}$$

$$f_{sb} = \text{Sideband Frequency}$$

$$f_{pwm} = 512 \text{ Hz}$$

Sideband Frequency (11x)



**Coincident
with 1st
torsional
natural
frequency**

Re-excitation of 1st Torsional NF

- **Broad peak associated with re-excitation of 1st mode**
- **Re-excitation magnitude limited by VFD controller setting**
 - Torque restrictions in place to control speed ramp and restoration rates


Where:

$$T_l = \frac{I_t * (f_d - f_a)}{t_r}$$

t_r = response time
 I_t = train inertia
 f_d = desired speed
 f_a = actual speed
 T_l = limit torque

- **Unfiltered speed signal introduced 13Hz component into controller algorithm**


VFD Model Behavior




- Initial discussions w/ vendor showed speed feedback signal to be filtered

- Further investigations revealed the existence of an unfiltered branch


Estimate of Motor Pulsating Torque




Torsional Model



Damping Estimation



Alternating Torque



Torsional Response @ Gear Shaft

Fatigue Analysis

- **Coupling Vendor**

- Constructed test rig to measure strain/stress vs. coupling torque
- Determined that pulsating torque needs to exceed 60% of rated to cause HCF

- **Predicted Torque**

- Analysis predicted that pulsating torque reached 20% of rated for measured displacement when peaks not coincident
- Response increased by 4X during speeds when sideband is coincident with 1st TNF

Conclusions

- **Re-excitation of 1st TNF not sufficient to cause failure**
 - Testing and analysis revealed this causes pulsating torque at 20% of rated
- **During coincidence with sidebands pulsating torque can reach 80% of rated**
 - Several sidebands present
 - Coincident during specific speeds
 - Can explain the time to failure

$$f_{sb} = \left| f_{pwm} - I_{odd} * f_o \right|$$

$$f_{sb} = 150 - 3 * f_o$$

Corrective Actions

- **VFD Controller**

- Vendor unable to “tune” parameters of the vector control algorithm to minimize 1st TNF excitation and sidebands to acceptable levels
- Vendor implemented volts/Hz algorithm
 - No speed feedback
- Gear vibrations less than 4 μm acceptable
- Some tuning at site to get acceptable startup vibration levels

- **New controller successful with 2 years operation**

Gear Vibrations

