USER CASE STUDY ABSTRACT 18th International Pump Users Symposium

TITLE:

Experience with Vertical-Turbine Pumps Rebowl Upgrade

ABSTRACT:

Four 580 HP cooling tower feed pumps were upgraded by retrofitting improved bowl assemblies with enclosed stainless-steel impellers.

Pumps exhibited capacity limitation up to 50% of rated and cavitation damage in original semi-open cast iron impellers, requiring continuous operation of all installed equipment, including the stand-by pump, to cover plant requirements.

Performance of the pumps was optimized by rework of new impellers and stand testing to satisfy guarantee point and improve efficiency to accommodate power limitation of existing drivers.

As a result, rated capacity was recovered, allowing one pump in stand-by, with a significant reliability improvement and considerable savings in maintenance costs, together with a lower capital investment compared to the replacement of the complete units.

AUTHORS:

César A. Morales Casanova

Rotating Equipment Specialist PDVSA – Pequiven UNF Morón, Edo. Carabobo Venezuela

Gustavo Hernández

Operations Manager Bombas FTC de Venezuela / ITT Industries Maracay, Edo. Aragua Venezuela



18th International Pump Users Symposium March 5-8, 2001. Houston, Texas

REBOWL UPGRADE OF VERTICAL-TURBINE PUMPS PROVEN EFFECTIVE

Gustavo Hernández

Operations & Service Manager Bombas Goulds de Venezuela ITT Industries César A. Morales Casanova Rotating Equipment Specialist PDVSA-Pequiven Edo. Carabobo - Venezuela

SITUATION OVERVIEW

- 30 year old Cooling Tower servicing a 680 MTD Ammonia Plant and a 750 MTD Urea Plant.
- Three 580 HP Cooling Tower Feed Pumps installed (One turbine driven and two motor driven).
- An additional pump kept as a spare.



SITUATION OVERVIEW (cont...)

- Pumps rated for 22.5 m @ 5,000 m³/hr (75 ft @ 22,000 GPM) each. (66,000 GPM total).
- Cooling Water Pumps were uprated 1997 to satisfy larger demand after a revamp of the Ammonia Plant in 1997.
- All three pumps required to operate continuously to deliver an average of 11,000 m³/hr (48,400 GPM).
- Actual limitation of 73% of rated.
- Stand-by pump required in continuous service.
 - No operational flexibility.
 - High maintenance costs.

PROCESS DIAGRAM



SITUATION OVERVIEW (Cont...)

- Pump efficiency progressively reduced due to cavitation / recirculation damage of impellers.
- Yearly overhaul required.



SITUATION ANALYSIS

Cooling water feed to the Ammonia Plant increased by 50% after revamp.

- Before: 7,400 m³/hr (32,500 GPM)
- After: 11,000 m³/hr (48,200 GPM)
- Two pumps in service / one stand-by required.
- Flow currently handled is 110% of pump rated.
- The upgrade of the Cooling Tower Feed System must include a pump rerate to cover requirements after the revamp.

SUMMARY OF UPGRADE OBJECTIVES

Restore design operating conditions (two pumps in service / one stand-by) to achieve:

- Operational flexibility.
- Equipment availability.
- Maintenance cost reduction.
- Operating cost reduction.
- Uprate the capacity to 110% of original.
- Improve reliability to expect service life extension up to three years in continuous operation.
- Cost-effective solution to comply with budgetary constraints: 4-month delivery required.

EVALUATION OF EXISTING PUMP

Qualified supplier with testing capability contracted.
Actual performance of pumps to be assessed.
Test results help determine upgrade workscope.



TEST RESULTS OF EXISTING PUMP

PUBLISHED VS TEST PERFORMANCE ORIGINAL BOWL ASSEMBLY @ 890 RPM



TEST RESULTS OF EXISTING PUMP

PUBLISHED VS TEST PERFORMANCE ORIGINAL BOWL ASSEMBLY @ 890 RPM



TEST CONCLUSIONS

- Considerable performance impairment found.
- Excessive radial clearance between impeller and suction liner is a primary cause for efficiency loss.
- Manufacturing deficiencies cause mismatching between impeller and liner profile.
- Proper adjustment of uniform clearance is difficult and time consuming.
- It is unlikely to reach new operating requirements even if the bowl assembly is fully restored.

EXISTING BOWL DEFICIENCIES

LARGE RADIAL CLEARANCE / IMPELLER-LINER PROFILE MISMATCH







PUMP UPGRADE CHOICES

	PROS - CONS	COST & LEAD TIME	
PUMP REPLACEMENT	 Field work required Larger cost & lead time 	 4 PUMPS 3 MOTORS 2 YR SPARE PARTS FOUND & PIPING TOTAL: 	\$400 K \$230 K \$70 K \$200 K \$ 900 K
		7 MONTH DELIVERY	
PUMP REBOWL	 No field work required Less cost & lead time 	 4 BOWL ASSY'S 2 YR SPARE PARTS INSTALL & TEST TOTAL: 4 MONTH DEL 	\$ 220 K \$ 60 K \$ 140 K \$ 420 K IVERY

RERATE ESTIMATE



RERATE ESTIMATE

- Available motor power : 580 HP
- Max BHP limited to 95% of available : 550 HP

Maximum head attainable:

 $Q = 5,000 \text{ m}^3/\text{hr}$; H = 22,5 m; n = 890 rpm $Ns = \frac{n\sqrt{Q}}{H^{3/4}} \quad Ns \approx 5,000 \ (US) - 100 \ (SI) \approx 87 \ \% \ (typical)$ $\eta_{pump} \approx 82 \%$ (-5 pt losses)

 $H = \frac{P\eta}{Q\rho g} \qquad H_{max} = 24,7 m \quad (81 \, ft)$ New Rated Point:

24 m @ 5,000 m³/hr (80 ft @ 22,000 GPM) Secondary Operating Point: 22,5 m @ 5,500 m³/hr (75 ft @ 24,200 GPM)

NEW BOWL ASSEMBLY



FEATURES:

- **PERFORMANCE:**
 - Q: 5,000 m³/hr (22,000 GPM)
 - H: 24,4 m (80 ft)
 - η : 87% Bowl / 80% Pump
 - P: 555 HP (580 HP Motor)
- Enclosed impeller.
- Dual wear rings.
- Impeller in SS ASTM A743 Gr. CF105MnN (Nitronic 60).
- Hard faced shaft at bearings (Chrome Oxide on 416 SS).
- Special reverse rotation (CW)

NEW BOWL ASSEMBLY INSTALLATION



WORKSCOPE:

- Keep existing pump length.
 - New Lower Column Pipe.
 - Adjust shaft length & machine coupling end for new bowl
- Install lube line for suction bell bearing.
- Hard face all shaft sleeves.
- Test pump for performance guarantee.
- Ensure 550 BHP as a maximum.
- Complete refurbishment.

NEW BOWL ASSEMBLY INSTALLATION



OLD BOWL ASSEMBLY



WORN SHAFT SLEEVE



NEW BOWL



NEW HARD FACED SHAFT

REBOWLED PUMP TESTING





PERFORMANCE TEST WITH TORQUEMETER

REBOWLED PUMP TESTING

PUBLISHED VS TEST PERFORMANCE IMPELLER Ø 21.25" @ 890 RPM



REBOWLED PUMP TESTING

PUBLISHED VS TEST PERFORMANCE IMPELLER Ø 21.25" @ 890 RPM



REBOWLED PUMP TESTING RESULTS

- Satisfactory head-flow performance.
- Complete pump BHP larger than expected:
 - Bowl published: + 16%
 - Motor rating: + 10%

Impeller rework required to adjust performance.





SURFACE FINISH IMPROVEMENT – UNDERFILE DETAILS

REWORKED IMPELLER TESTING RESULTS

PUBLISHED VS TEST PERFORMANCE IMPELLER Ø 20.75" @ 890 RPM



REWORKED IMPELLER TESTING RESULTS

PUBLISHED VS TEST PERFORMANCE IMPELLER Ø 20.75" @ 890 RPM



FINAL TEST RESULTS

Specified operating points successfully reached. 80 ft + 5% @ 22,000 GPM Rated: Secondary: 75 ft + 1% @ 24,200 GPM **BEP: Coincident with rated point** Shaft horsepower adjusted to limitations. BHP: 95 – 97% of motor rated Efficiency improved by impeller rework. Final: 83% @ BEP 75% @ BEP Before rework:

OVERALL RESULTS

- Upgrade objectives were achieved.
- Optimized operation:
 - Successful capacity uprate to 110%.
 - 2 pump running / 1 stand-by.
 - Energy savings of 3 MW-hr/year.
 - Increased operational flexibility.
- Increased reliability:
 - Performance sustained after two years in service.
 - No maintenance performed since the upgrade.
- Rebowl upgrade completed at 50% of the cost of pump replacement (savings of \$ 480K).

CONCLUSIONS

- Pump upgrade objectives were successfully achieved.
- Rebowl of existing pumps was the best choice for a cost-effective & time-saving solution.
- Extended service life achieved by component improvement.
- Stand-testing is an invaluable tool to optimize equipment operation and guarantee trouble-free operation of upgraded equipment.



- Consider to improve existing equipment for lower investment and time savings.
- Testing of modified equipment is mandatory for reliability guarantee.
- Close cooperation between manufacturers, service suppliers and users is a key for success.

THANK YOU !