



47TH TURBOMACHINERY & 34TH PUMP SYMPOSIA
HOUSTON, TEXAS | SEPTEMBER 17-20, 2018
GEORGE R. BROWN CONVENTION CENTER

Investigation and Resolution of Governing Valve Linkage Failure for Compressor Drive Steam Turbine

Kenichi Nishiyama – MCO
Mayank Jain – MCO
Elumalai Subramani – ExxonMobil



Authors



Kenichi Nishiyama

kenichi_nishiyama@compressor.mhi.co.jp

Engineer, Turbine Engineering & Design Section, Mitsubishi Heavy Industries Compressor Corporation, Hiroshima, Japan. He has 7 years of experience as a turbine engineer. Mr. Nishiyama graduated from Tokuyama College of Technology (Mechanical & Electrical Engineering).



Mayank Jain

mayank_jain@compressor.mhi.co.jp

Engineer, Turbine Engineering & Design Section, Mitsubishi Heavy Industries Compressor Corporation, Hiroshima, Japan. He has 1 year experience as a turbine engineer. Mr. Jain has B.Tech degree in Mechanical Engineering from Indian Institute of Technology (IIT), Kanpur, India.



Elumalai Subramani

elumalai.subramani@exxonmobil.com

Machinery engineer, ExxonMobil Research Engineering, Houston, Texas, USA. He has 20 years of experience in Refinery & Petrochemical plant Machinery Maintenance, Diagnosis, Commissioning and Reliability Improvement projects. He graduated from Coimbatore Institute of Technology, Tamil Nadu, India.







Contents

- Governing Linkage outline
- Rod-end bearing design
 - Static Loads
- Fracture analysis
- Possible cause
- Motion analysis and FEM analysis result
- Conclusions
- Recommendations
- Lesson Learned



Governing Linkage Outline



The rod end bearing failure occurred in 2017 after the Turbine had been in operation for 9 years.

Governing Linkage Outline

Similar trouble had happened around 2006 in other plants. Countermeasure → Bearing size up from M8 to M16

Size	Static Limit Load		Radial Static Ultimate Load	Notes
	Radial	Axial		
	(kN)		(kN)	
M16	8.33	N/A	33.34	3.5 times larger area than M8.
M8	2.69	N/A	11.76	



Similar trouble

This turbine reconfigured the bearing size to M16 in 2008.
→ The M16 bearing failed in 2017 after 9 years of operation.





Rod-end Bearing Design

Material specification:



M8 and M16 are same design

They are comprised of the same materials.


Material	PARTS	Hardness (HV)
Martensitic stainless	Ball	≥ 653
Austenitic stainless	Body	≤ 200
PTFE	Liner	N/A



Fracture Analysis



1mm
remains



Approx.
3mm

Y-Y cross section

Worn out thickness was roughly 2mm and striation pattern was observed which helped us identify high cycle fatigue fracture .




Troubleshooting

Problem	Possible Causes	Possibility
Bearing failure	High shock load	Low
	Improper strength at design stage	Low
	Corrosive fracture under severe environment	Low
	Vibratory stress	High

- Strength and shock load were verified to be within criteria.



Possible Cause




Fatigue fracture pattern and vibration analysis indicated that the 4th resonance mode falls in the Turbine operation range.




Scenario


- PTFE liner wore out due to resonance vibration (4th mode).



- Bending stress occurred due to resonance vibration.





Motion Analysis




Output data
(Sliding velocity and force)


Excitation force was estimated using motion analysis with the help of static force.



Input value
Measured Vibration on pedestal.



Bearing life estimation



1. Excited force was estimated with motion analysis.
2. Damping at resonance frequency was confirmed with hammering test.



(4th mode : 51.6Hz)
Resonance mode



MAX.	3498 r.p.m
NOR.	3331 r.p.m
MIN.	2665 r.p.m

Slip velocity (5.6 mm/sec),
Lh = 16,644 hr (1.9 years)



Under resonance condition, PTFE liner will wear out within 1.9 years of operation.

Stress Analysis





The peak stress points due to vibration at resonant frequency was found using FEA. They match the crack origin point of the failed bearing.



Recommendations

- *Plan 1:* Provide separation margin from resonant excitation frequency. -> (it is no longer operation range.)
- *Plan 2:* Improve system integrity using a redundant system.

Apply multiple rod end bearings



Recommendations

- Plan 3: Replace with Direct-drive actuator (Linkages are minimized).



Conventional Actuator
(Before Revamp)




Direct-drive Actuator
(After Revamp)



Results after maintenance

Current operation



As a result of modification (Plan 1), turbine operation speed is far away from the resonance frequency. No issues experienced after the maintenance.

Plan 2 will be carried out during next Turbine maintenance.

Plan 3 with Direct Drive Actuators.



Lessons Learned

- Bearing Life should be considered at the design stage and bearing should be replaced at every maintenance .
- Understand dynamic behavior of linkage system and enforce sufficient separation margin (Authors recommend 5% for similar situations) on damaging modes.
- Root cause analysis and Motion Analysis to know the dynamic force for multiple linkage is an useful tool in understanding the failure modes of Linkages and bearings.



Thank You...


Questions???



For Q and A

Bearing Life to be determine

Highly depends on contact stress , slip velocity & frequency



Load condition

factor 荷重方向	Constant 一定	Alternative 交番
荷重方向係数 b_1	1	0.2 ⁽¹⁾

