

Measured Seepage Losses of Canal 6.0 La Feria Irrigation District – Cameron County No. 3

By:
Eric Leigh, Extension Associate and Guy Fipps, P.E., Extension Agricultural Engineer
Department of Biological and Agricultural Engineering, Texas A&M University, College Station, TX.


April 2011

Texas Water Resources Institute Technical Report No. 373
Texas A&M University System
College Station, Texas 77843-2118

**MEASURED SEEPAGE LOSSES OF CANAL 6.0
LA FERIA IRRIGATION DISTRICT-CAMERON
COUNTY NO.3**

Rio Grande Basin Initiative
Irrigation Technology Center
Texas Water Resources Institute
Texas AgriLife Extension Service

**MEASURED SEEPAGE LOSSES
OF CANAL 6.0 -
LA FERIA IRRIGATION DISTRICT-CAMERON
COUNTY NO.3¹**



by

Eric Leigh and Guy Fipps, P.E.²
May 5, 2003

¹ A portion of this study was funded by Texas Cooperative Extension through the Rio Grande Basin Initiative administered by the Texas Water Resources Institute of the Texas A&M University System with funds provided through a grant from Cooperative State Research, Education, and Extension Service, U.S. Department of Agriculture, under Agreement No. 2001-001-45049-01149.

² Extension Associate, and Professor and Extension Agricultural Engineer, respectively, Biological and Agricultural Engineering, 2117 Texas A&M University, College Station, TX 77843-2117

TABLE OF CONTENTS

Summary

- Table 1. Seepage losses measured in Canal 6.0 of La Feria Irrigation District.
- Table 2. Seepage loss rates of Canal 6.0 given in 4 commonly used methods for characterizing water loss from canals.
- Figure 1. Map showing the locations of seepage loss tests conducted on Canal 6.0.
- Figure 2. One of six large holes observed in the brick/concrete lining of the south test segment of Canal 6.0.

Materials and Methods

Test Results

Test 1 - Canal 6.0 - North

- Figure 3. Canal 6.0 - North.
- Table 3. Data for Test 1: Canal 6.0 - North.
- Figure 4. Cross section at Staff Gauge 1 of Canal 6.0 - North.
- Figure 5. Cross section at Staff Gauge 2 of Canal 6.0 - North.

Test 2 - Canal 6.0 - South

- Table 4. Data for Test 2 - Canal 6.0 - South.
- Figure 6. Cross section at Staff Gauge 3 of Canal 6.0 - South.
- Figure 7. Cross section at Staff Gauge 4 of Canal 6.0 - South.
- Figure 8. Canal 6.0 - South.
- Figure 9. Large hole in the brick/concrete lining of Canal 6.0 - South..

Soil Descriptions

General Soil Series

Detailed Soil Units

- Table 5. Soil Series Key Codes and Permeability Ranges.
- Figure 10. Detailed soil series with test locations.

Other Test Results

- Table 6. Results of seepage loss tests conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.
- Table 7. Results of total loss tests in lined canals conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.
- Table 8. Results of total loss test in unlined canals conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.
- Table 9. Canal seepage rates reported in published studies.

Measured Water Losses in Canal 6.0 La Feria Irrigation District-Cameron County No. 3

SUMMARY

This report summarizes the results of seepage loss rate tests conducted in La Feria Irrigation District Cameron County Irrigation District No. 3 (La Feria). These tests were conducted during April 9 - 11, 2003 on Canal 6.0.

Canal 6.0 is located at the east central area of the district and runs perpendicular to and across Expressway 83 (Fig. 1). The southern and northern sections Canal 6.0 are unlined, while the middle portion is brick with a concrete topping. The brick/concrete section is approximately 5,641 ft (1.07 miles) long and varies from 12 to 13 feet in width.

Two segments of the brick/concrete section was tested (Fig. 1), referred to here as the *north* and *south* segments. Test results are summarized in Table 1. Seepage losses were measured at 1.77 and 4.61 gal/ft²/day for the north and south segments, respectively (or 153 and 369 ac-ft/mile per year). Table 2 lists seepage losses in four methods commonly used for characterizing water loss from canals. The annual water loss amounts given Tables 1 and 2 are based on an in-service life of 365 days per year.

The south segment had approximately six large holes in the canal similar to the one shown in Figure 2. This is likely the reason that the south segments seepage rate is over twice that of the north segment.

Table 1. Seepage losses measured in Canal 6.0 of La Feria Irrigation District. All segments are brick/concrete-lined. Tests 1 and 2 measured seepage losses only.

Test	Segment	Soil	Top Width (ft)	Length (ft)	Seepage Rate (gal/ft ² /day)	Total Loss in Canal (ac-ft/mile)	
						per day	per year*
1	Canal 6.0 (North)	sandy clay loam	12	600	1.77	0.41	152.92
2	Canal 6.0 (South)	sandy clay loam	12	600	4.61	1.01	369.05

*Based on 365 days per year

Table 2. Seepage loss rates of Canal 6.0 given in 4 commonly used methods for characterizing water loss from canals.

Test	ft ³ /ft ² /hour	ft/day	inches/day	gal/ft ² /day	acre-ft/mile/year
1 - North	0.013	0.33	3.84	1.77	152.92
2 - South	0.040	0.97	11.64	4.61	369.05




Figure 1. Map showing the locations of seepage loss tests conducted on Canal 6.0.



Figure 2. One of six large holes observed in the brick/concrete lining of the south test segment of Canal 6.0.

MATERIALS AND METHODS

Seepage losses were measured using the ponding method. In this method, the two ends of a canal segment are closed or sealed with earthen dams. Once sealed, water elevations were taken for approximately 48 hours. Two continuous-stage level recorders were used in each test segment to supplement the two locations where stage levels are recorded manually. Canal dimensions and water spans were also surveyed during each test. The segments did not contain valves or gates within the canal; thus, seepage loss rates were measured. Locations of the north and south test segments are shown in Figure 1.

TEST RESULTS

This section summarizes the data collected and seepage loss rates measured. For both tests, a table and charts provide test details. The charts show the surveyed canal profiles at the staff gages along with the *expected* canal shapes. The *expected* shapes were generated by fitting an equation to the measured profile data as shown in each graph. Photographs are also included which show the test segment and a close-up of the canal lining.

Descriptions of the general soil types in the area of Canal 6.0 are provided in a later section, along with a map (Fig. 10) of the detailed soil series taken from the Soil Survey for the county. Table 5 gives the key codes and corresponding soil series and permeability range for the units shown in Figure 10.

Test 1 - North



Figure 3. Canal 6.0 - North

Table 3. Data for Test 1: Canal 6.0 - North.

District:	La Feria Irrigation District Cameron County No.3	Test ID:	Canal 6.0 - North	
Canal:	Canal 6.0	Lining Type:	Concrete	
Top Width:	12 feet	Date:	April 9-11, 2003	
Test Length:	600 feet	Start Time:	3:14 pm	
Total Depth:	5 feet	Finish Time:	3:16 pm	
Location: West of Bass Rd., North of Expressway 83				
Staff Gage Readings				
Date	SG1		SG2	
	Readings	Time	Readings	Time
9-Apr	5.69	15:15	5.68	15:14
	5.67	16:13	5.67	16:12
	5.65	17:18	5.65	17:19
10-Apr	5.37	10:04	5.37	10:03
	5.32	13:02	5.32	13:03
	5.28	16:02	5.28	16:01
11-Apr	5.08	11:50	5.08	11:49
	5.04	15:11	5.04	15:16




Figure 4. Cross-section of Staff Gauge 1 of Canal 6.0 - North.




Figure 5. Cross-section of Staff Gauge 2 of Canal 6.0 - North.

Test 2 - South

Table 4. Data for Test 2: Canal 6.0 - South.				
District:	La Feria Irrigation District Cameron County No.3	Test ID:	Canal 6.0 - South	
Canal:	Canal 6.0	Lining Type:	Concrete	
Top Width:	12 feet	Date:	April 9-11, 2003	
Test Length:	600 feet	Start Time:	3:11 am	
Total Depth:	5 feet	Finish Time:	3:24 pm	
Location: West of Bass Rd, North of Expressway 83				
Staff Gage Readings				
Date	SG3		SG4	
	Readings	Time	Readings	Time
9-Apr	2.06	15:12	5.28	15:11
	1.86	16:11	5.07	16:10
	1.64	17:20	4.84	17:21
10-Apr	0.48	10:01	3.68	09:58
	0.42	13:04	3.65	13:05
	0.38	15:59	3.51	15:58
11-Apr	0.16	11:48	3.36	11:46
	0.12	15:18	3.33	15:24




Figure 6. Cross-section of Staff Gauge 3 of Canal 6.0 - South.




Figure 7. Cross-section of Staff Gauge 4 of Canal 6.0 - South.



Figure 8. Canal 6.0 - South



Figure 9. Large hole in the canal lining of Canal 6.0 - South1

SOIL DESCRIPTIONS


General Soil Series

6 - Willacy-Racombes association: Nearly level to gently sloping, well drained fine sandy loams and sandy clay loams. See figure 10 for soils map.




Detailed Soil Units



Table 5. Soil Series Key Codes and Permeability Ranges.	
Soil Unit	Permeability (in/hr)
HO - Hidalgo sandy clay loam	0.63 - 2.0
RA - Racombes sandy clay loam	0.63 - 2.0
WAA - Willacy fine sandy clay loam	2.0 - 6.3




**Cameron County Irrigation District No.3
La Feria, Texas**



Detailed Soil Map

-  Hidalgo sandy loam clay
-  Racombes sandy clay loam
-  Willacy fine sandy loam

- Test Section
-  Canal 6.0 - North
 -  Canal 6.0 - South

- Delivery Network
-  canal/concrete
 -  canal/earth
 -  pipe

**Texas Cooperative Extension
Agricultural Engineering
DMS Team - May 2003**




Figure 10. Detail Soil Series with (see Table 5 for soil permeability ranges and key codes).

OTHER TEST RESULTS

Texas Cooperative Extension has conducted approximately 50 total loss tests and seepage loss tests in the Lower Rio Grande River Basin since 1998. The results are summarized in Tables 6 – 8. Table 9 gives seepage rates versus lining type as reported in the scientific literature.

Table 6. Results of seepage loss tests conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.						
Test ID	Year	Canal Width (ft)	Canal Depth (ft)	Class*	Loss Rate	
					gal/ft ² /day	ac-ft/mi/yr
<u>Lined</u>						
16HC2	03			M		
LF1	03	12	5	M	1.77	152.9
LF2	03	10	6	M	4.61	369.1
MA4	03	12	5	S	8.85	529.7
SJ4	00	15	4	M	1.17	111.2
SJ5	02	14	5	M	1.38	145.5
UN1	01	12	6	M	2.32	214.3
UN2	01	8	3	M	2.09	132.2
<u>Unlined</u>						
BR1	03	60	11	M	3.14	794.6
MA3	03	19	5	S	13.9	1690.1
RV1	03	38	4	M	0.15	23.0
SB4	02	16	4	S	0.64	68.3
SB5	02	18	3	S	1.67	188.3
SB6	02	20	5	S	1.44	189.0
SB7	02	16	4	S	0.42	47.4
SB8	02	20	5	S	0.83	104.0

*Classification of canal: M = main, S = secondary

Table 7. Results of total loss tests in lined canals (leaking gates and valves may have contributed to measured loss rates) conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.

Test ID	Year	Canal Width (ft)	Canal Depth (ft)	Class*	Loss Rate	
					gal/ft ² /day	ac-ft/mi/yr
<u>Lined</u>						
16HC1	03	14	5	M	1.89	192.4
BV1	99	10	5	M	7.97	510.5
BV2	99	9	4	M	8.53	451.5
DL1	00	20	6	M	0.16	18.8
DL2	00	7	4	S	4.12	236.2
DO1	03	5	3	S	1.68	65.2
DO2	03	6	4	S	2.18	121.5
DO3	03	6	3	S	2.71	107.2
ED1	00	6	4	S	34.32	1519.6
ED2	00	6	4	S	21.5	858.2
ED3	00	3	2	T	10.22	308.2
ED4	00	4	3	S	18.72	567.7
ED6	99	9	4	M	8.53	451.5
HA2	00	10	4	M	2.26	135.2
HA3	98	15	2	S	0.64	45.5
ME1	98	38	7	M	1.26	281.9
ME2	98		4	M	1.88	163.5
SJ1	99	12	5	M	2.58	126.8
SJ6	03	12	3	M	1.88	1.63
SJ7	03	19	4	M	1.98	227.1
UN3	02	12	6	M	2.02	169.7

*Classification of canal: M = main, S = secondary, T = tertiary

Table 8. Results of total loss tests in unlined canals (leaking gates and valves may have contributed to measured loss rates) conducted by Texas Cooperative Extension in the Lower Rio Grande River Basin.

Test ID	Year	Canal Width (ft)	Canal Depth (ft)	Class*	Loss Rate	
					gal/ft ² /day	ac-ft/mi/yr
BV3	99	55	8	M	0.15	53.4
ED5	02	105	7	M	2.39	1213.2
MA1	99	50	10	M	1.98	227.1
MA2	99	20	5	S	4.32	371.4
SB1	00	29	7	S	1.27	215.5
SJ2	00	23	6	M	2.74	293.2
SJ3	00	30	5	S	0.95	132.6

*Classification of canal: M = main, S = secondary

Table 9. Canal seepage rate reported in published studies.

Lining/soil type	Seepage rate (gal/ft ² /day)
Unlined ¹	2.21-26.4
Portland cement ²	0.52
Compacted earth ²	0.52
Brick masonry lined ³	2.23
Earthen unlined ³	11.34
Concrete ⁴	0.74 - 4.0
Plactic ⁴	0.08-3.74
Concrete ⁴	0.06-3.22
Gunitite ⁴	0.06-0.94
Compacted earth ⁴	0.07-0.6
Clay ⁴	0.37-2.99
Loam ⁴	4.49-7.48
Sand ⁴	4.0-19.45

¹DeMaggio (1990). Technical Memorandum: San Luis unit drainage program project files. US Bureau of Reclamation, Sacramento. ²U.S. Bureau of Reclamation (1963). Lining for Irrigation Canals. ³Nayak, et al. (1996). The influence of canal seepage on groundwater in Lugert Lake irrigation area. Oklahoma Water Resources Research Institute. ⁴Nofziger (1979). Profit potential of lining watercourses in coastal commands of Orissa. Environment and Ecology 14(2):343-345.

TR-373
2011
TWRI



This material is based upon work supported by the National Institute of Food and Agriculture, U.S. Department of Agriculture, under Agreement No.2010-45049-20713 and Agreement No. 2010-34461-20677. For program information, see <http://riogrande.tamu.edu>.