



44TH **TURBOMACHINERY** & 31ST **PUMP** SYMPOSIA
HOUSTON, TEXAS | SEPTEMBER 14 – 17 2015
GEORGE R. BROWN CONVENTION CENTER

Circulating Water Pump Resonance

Monroe Voyles, Solutions Engineer

ITT Goulds Pumps
Seneca Falls, NY



Author / Presenter

Monroe Voyles III

(225) 573 2445

monroe.voyles@itt.com

Mechanical engineer with 20 years of experience; 7-chemical plant, 3-refinery, 10-pump OEMs.

B.S.M.E Louisiana State University 1994.

Professional Engineer Louisiana 2002/Texas 2014.

CAT IV Vibration Analyst (Vibration Institute 2010 & Mobius 2014)

Circulating Water Pump

- API 610-VS3 single stage
- 5 Impeller vanes
- 60,000 gpm
- 80 psig discharge
- 600 rpm
- Motor-1700 H.P.
- Two pumps; one primary and one spare



Circulating Water Pump

View Perpendicular To Discharge



View In-Line With Discharge




Problem

- Large 1X running speed vibration amplitudes at motor top
- Vibration increased significantly after an overhaul
- Pump operated for 9 years prior with low vibration amplitudes
- Spare pump did not resolve vibration issue
- Spare motor did not resolve vibration issue
- Precision alignment did not resolve vibration issue
- Field balancing reduced vibration amplitude to some degree, but not to acceptable levels.
- Depending on configuration/conditions vibration amplitudes varied from 1.0 ips rms to approximately .4 ips rms


Below Grade & Cross-Section



No
measurements
possible below
grade




Primary Accelerometer Locations





Measurement Stations For ODS/Modal

X,Y,Z data for each station




Discharge Expansion Joint

- The tie bolts were initially loose.
- Loose tie bolts allow hydraulic separation forces to be applied to the pump discharge head.
- Significant vibration changes were observed when the spare pump was started in parallel (higher discharge pressure/force)



Operating Condition Changes (animation)


- 1- Solo operation (tie bolts loose)
- 2- Start spare CWP in parallel operation; nat. freq. increased into operating speed. (note beat pattern)
- 3- While still in parallel operation the tie bolts were tightened; lower thrust force; nat. freq. lowered back below operating speed



ODS FRFs



(Frequency Response Function) (animation)

Single pump operation; all FRFs overlaid; log amplitude axis



Pump Flange and Soleplate ODS (animation)

- Soleplate and pump flange are essentially moving together.
- Stations 7 & 8 have little relative movement. Motion in the other 3 quadrants is higher than if properly grouted.
- The lower animation has no model interpolation




[Click to Animate](#)

Foundation & Soleplate Are “Springs” In The Mechanical System (animation)


The foundation and soleplate act as springs in series with the pump structure. They affect the resulting natural frequency (f_n); particularly the 1st “Trunion” mode

$$f_n = \frac{1}{2\pi} \sqrt{\frac{k}{m}}$$

k = effective stiffness
m = modal mass



Typical Resonance Response



Solution

- Bubbles indicate relative movement
- Soleplate anchor studs were tightened to improve connection and increase stiffness of the pump/foundation system
- Nuts were tightened from the discharge moving CW viewed from the top down
- As studs were tightened vibration amplitude and phase changed
- Final vibration was decreased from .4ips rms to 0.08ips rms.





Video Of Movement/Bubbles

(animation)




Stud Torqueing Sequence



Operating Deflection Shape (TIME-BASED ANIMATION)

- Stud torqueing sequence
- Waveform(1X filtered)
- Amplitude decreased 70% after soleplate anchor studs were torqued.
- Nat. freq. was raised to and then above 1X by increasing foundation/pump stiffness.




High Average/Resolution FFT

- Background or broad-band vibration energy can excite structural natural frequencies. A large number of averages and high frequency resolution attenuates noise and variability. Natural modes tend to absorb more energy and can be seen in the FFT spectrum.
- High average/resolution measurements were taken in the initial condition (solo), the spare CWP (solo), Aux CWP2 solo, and the final condition (solo operation) after the soleplate studs were torqued.
- Operating data (high average/resolution FFT) uses continuous broad band energy from sources like flow turbulence to excite natural modes. Fmax 30,000cpm & 25600 lines of resolution were used.


High Average/Resolution FFT

Broad-band vibration provided by Aux CWP2




High Average/Resolution FFT


Broad-band vibration provided by spare CWP



High Average/Resolution FFT FINAL/AFTER SOLEPLATE STUD TORQUEING



Motor Top Inline Impact FRF




Natural Frequency Data(cpm)


<u>Condition</u>	<u>In-line</u>	<u>Perp</u>
(Before) Background Aux. CWP2 solo	<u>601</u> 820	658- 1 st mode 880- 2 nd mode
(Before) Background Spare CWP solo	582 830	664-1 st mode 889-2 nd mode
(Before) Impact	581 843	656-1 st mode 881-2 nd mode
(Final) Background tight soleplate	<u>633</u> 828	683-1 st mode 894-2 nd mode

Mode Shapes (examples)


- 1st mode is the “Trunion” or pivoting mode. The column and motor are essentially a rigid body pivoting about the flange/soleplate.
- 2nd mode is a “C” shape bending mode. The column properties control the effective stiffness and natural frequency



(animations)



Overall Vibration Amplitudes



	MTI	MTP	PTI	PTP	MTA
Initial	0.379	0.178	0.216	0.0553	0.0298
Final	0.0839	0.0393	0.0474	0.0257	0.06

Lessons Learned

- The root cause of excessive vibration was a structural resonance at 1X shaft speed.
- A change in the soleplate/foundation connection likely occurred during the pump overhaul. The combination of corrosion over many years and disturbance of the soleplate during pump removal likely combined to create a “soft” interface between the pump structure and the concrete foundation.
- Reduced pump/foundation stiffness lowered the 1st or trunion mode natural frequency into the operating speed range.
- Soleplate/foundation condition should be inspected during pump removal/overhaul in the future.