

# RELIABILITY IMPROVEMENT AT PETROTRIN REFINERY - PUMPS AT NO. 8 CDU. 1997 to 2003

Presented by : Stanley Deonarine  
Head, Mechanical Eng.  
Petrotrin Refinery  
2003 October 31



# PROBLEM – TO IMPROVE PUMP RELIABILITY ON TWELVE BAD ACTORS

- ☛ Program duration – 1997 Jan to 2003 Aug.
- ☛ Mean Time Between Overhauls (MTBO) was low at 13 months for pumps and 6 months for turbines (shop overhauls only).
- ☛ Plant production was occasionally disrupted by turbine breakdowns.
- ☛ Maintenance cost was high at US\$ 9,380. per pump p.a. average.

# IDENTIFY THE BAD ACTORS

- ☛ Survey the maintenance records and cost data in the CMMS (1997 & 1998) and the SAP (1999 – 2000) for the 49 pumps at No. 8 CDU. Look for the pumps with the worst record.
- ☛ Preliminary definition : “Bad actor” - any pump handling hydrocarbons with MTBO < 24 months or maintenance cost > US\$ 7936 (TT\$ 50,000) p.a. or MTBO < 15 months regardless of cost. Preliminary number of bad actors – 17.
- ☛ Five pumps within the MTBO and cost criteria above were improved purely by quality assurance repairs without any engineering upgrade.
- ☛ Final definition : “Bad actor” - any pump which must require some engineering upgrade to improve the above. Hence, final number of bad actors – 12.

# IDENTIFY THE BAD ACTORS



# ANALYSIS METHOD

- For all major incidents e.g. fire or equipment destruction, appoint a multi-disciplinary team to investigate and develop a detailed report.
- For routine failures on the bad actors, the mechanical engineer should carry out a failure analysis.
- The engineer obtains advice as required from other members of his asset team (Process Engineer, Operations Superintendent, Maintenance Supervisor, etc).

# STEPS IN PROBLEM SOLVING

## – PROCESS RELATED

- ☞ What were the process conditions ? Adverse conditions will wreck mechanical seals
- ☞ Check suction tank for low level – problem !!
- ☞ Is NPSHA less than NPSHR ? – problem !!
- ☞ Are there light ends in the liquid ? Even small amounts can create havoc !!
- ☞ Compare actual operating conditions vs design conditions
- ☞ These causes affected one pump(TT-2407) seriously and contributed to problems on three others(TT-3100/01/58).

# STEPS IN PROBLEM SOLVING – FAILURE ANALYSIS

- ☞ Examine machine before, during/after dismantling.
- ☞ Identify all damaged/worn parts and parts with highest frequency of failure.
- ☞ Identify parts likely to be associated with the root cause – packing/sleeves, mechanical seals (faces and o-rings) and bearings/cooling systems.
- ☞ Reconcile with previous historical findings and other steps in problem solving (slides 6, 8, 9)
- ☞ Establish a pattern/mechanism of failure.
- ☞ In developing a solution, dovetail - obtain inputs from other departments and seek out a solution which addresses other problems as well.

# STEPS IN PROBLEM SOLVING - RELATED TO EQUIPMENT DESIGN

- ☞ Compare design of existing pump/turbine (40 years old) to modern design built to API standards.
- ☞ Particularly, look for design issues which lead to bearing overheating. Also, how is the bearing mounted to the shaft ? ( refer to slide 13 ). Check for fretting & looseness of parts.
- ☞ These causes affected four pumps(TT-3134/36/38/40) and twelve turbines seriously.
- ☞ Can redesign be done in-house or should it be referred to the OEM ?
- ☞ Or should a new pump/turbine be bought ?



# STEPS IN PROBLEM SOLVING – RELATED TO SHAFT SEAL DESIGN

- ✦ Examine seal faces and o-rings. Check for cracked/worn faces and embrittled o-rings. 40 year old seal designs (stellite vs carbon faces) were suffering rapid wear/overheating. These causes affected 2 LPG pumps(TT-3100/01) and a gasolene pump(TT-3158).
- ✦ On packed pumps, check for rapid grooving of sleeves. These causes affected 4 pumps (TT-3118/20/46/50). Cost of leakage – US\$4,000. per pump p.a.

# STEPS IN PROBLEM SOLVING

Process Related	Related To Shaft seal Design	Related To Equipment Design
<ol style="list-style-type: none"><li>1. Low suction tank levels.</li><li>2. <math>NPSHA &lt; NPSNR</math></li><li>3. Presence of light hydrocarbons.</li><li>4. Compare Operating vs. Design conditions.</li></ol>	<ol style="list-style-type: none"><li>1. Compare existing Design vs. Current API design.</li><li>2. Examine Seal faces &amp; O-rings. Over-heating &amp; Wear.</li><li>3. Replacement of Seals.</li></ol>	<ol style="list-style-type: none"><li>1. Compare existing Design vs. Current API design.</li><li>2. Over-heating of Bearings. Fretting and looseness.</li><li>3. Redesign – In-house or OEM or Replacement of equipment.</li></ol>

# RECOMMENDATIONS - PROCESS & SHAFT SEAL DESIGN


- ☛ At low suction pressure (2 psig), switch to another supply tank in order to avert onset of pump cavitation.
- ☛ For 4 pumps with packed glands, fit new mechanical seals (Silicon carbide vs carbon faces, alloy 718 bellows).
- ☛ For 2 LPG pumps and a gasoline pump, replace old seals by new tandem seals with outer seal in standby mode at atmospheric pressure. Multi-port flush. (Silicon carbide vs carbon faces - spring loaded).
- ☛ STATUS - All above completed except for the gasoline pump.

# RECOMMENDATIONS - EQUIPMENT DESIGN


- ☛ Replace 12 turbines (40 years old) by new machines (API-611). Design new turbines to consume excess LP (65 psig) steam instead of 450 psig steam.  
STATUS – Completed.  
OPTION CONSIDERED – upgrade of old turbines by the OEM is technically sound but the cost is about the same as for a new turbine.
- ☛ Upgrade bearing/shaft design on 4 pumps to eliminate the adaptor which fitted as a sleeve between the radial ball bearing and the shaft.  
Refer to slide 13. STATUS – 2 pumps completed.  
OPTION CONSIDERED – Purchase of upgraded pump from the OEM is technically sound but the cost is much higher.

# EXAMPLE OF EQUIPMENT REDESIGN

## UPGRADE OF PUMP BEARING/SHAFT



OLD DESIGN



MODIFIED DESIGN


**NOTE:** SHAFT WITH ENLARGED BEARING SEAT. ADAPTOR SLEEVE ELIMINATED. BEARING HOUSING IS THE SAME

# NO. 8 CDU – 12 BAD ACTOR PUMPS

TT NO.	SERVICE	MTBO (MONTHS)		MTCE COSTS TT\$, 000			
		JAN '97 - AUG '00	SEPT '00 - AUG '03	1999	2000	2001	2002
2407	Charge Booster West	11	36	164	35	0	27
3140	Heater Charge North	22	36	32	117	0	182
3138	Common Spare for Cold Crude Charge/ Heater Charge	22	18	63	249	121	26
3136	Cold Crude Charge South	14.7	36	100	93	10	0
3134	Cold Crude Charge North	14.7	36	28	3	28	41
3120	Reduced Crude South	14.7	36	39	48	157	0
3118	Reduced Crude North	14.7	36	0	84	5	7
3150	Kerosene to Storage South	14.7	36	106	0	37	0
3146	Light Gas Oil South	11	36	16	0	37	0
3158	Common Spare for Splitter Charge/ Main Reflux	11	18	0	24	40	0
3100	Depropaniser Reflux North	4.4	* 12	52	101	41	0
3101	Depropaniser Reflux South	5.5	* 12	109	40	3	17
<b>AVERAGE MTBO</b>		<b>13.4 MTHS</b>	<b>29 MTHS</b>				
<b>AVERAGE MAINTENANCE COST PER PUMP US\$,000</b>				<b>9.38</b>	<b>10.52</b>	<b>6.34</b>	<b>3.97</b>
<b>INCULDE FOR INFLATION, 5% P.A. US\$,000</b>				<b>10.88</b>	<b>11.57</b>	<b>6.66</b>	<b>3.97</b>

\* Overhauls were done early in the period. Since then, MTBO has improved to over 24 months.

## Results - Reduced Maintenance Costs For No. 8 CDU. Average Cost Per Pump



# Obsolete Turbine






# Barrier Tank on LPG Pump



# Charge Pump TT-3140



# Section of No. 8 CDU

