



46<sup>TH</sup> TURBOMACHINERY & 33<sup>RD</sup> PUMP SYMPOSIA  
HOUSTON, TEXAS | DECEMBER 11-14, 2017  
GEORGE R. BROWN CONVENTION CENTER

# Vertical Seawater Lift Pump Reversible Performance Deterioration

Ameer Khader    Alessia Sonzogni  
Luis Rojas      Eligio Lo Cascio

# Authors

- **Ameer Khader** is a Facilities Advisor at ExxonMobil Qatar. He has provided machinery engineering support for plant operations and projects at different locations: Adriatic LNG (Italy), RasGas (Qatar), Hibernia Oil Platform and Sable Gas Project (Eastern Canada). Ameer holds a BSc degree in Mechanical Engineering from Texas A&M University.
- **Alessia Sonzogni** is a Facilities Engineer at Adriatic LNG. She is responsible for process and machinery on the Terminal, guarantying plant integrity and reliability . Alessia holds a MSc degree in Chemical Engineering from Politecnico di Milano University with experiences at ETH Zurich and Campinas University (BRA).
- **Luis Rojas** is a Lead Machinery Engineer at ExxonMobil PNG. He has held several technical and managerial roles within ExxonMobil for projects and operational facilities in the US, Nigeria, and Qatar. Prior to joining ExxonMobil, he had developed his experience working for Dresser-Rand and PDVSA. Luis received his BSc and MSc degrees in Mechanical Engineering from The Ohio State University.
- **Eligio Lo cascio** is an Offshore Installation Manager at Adriatic LNG. He has extensive operations, maintenance, and engineering experience through earlier roles as Maintenance and Operations Supervisor, Procurement Manager, and Facilities Engineer. Prior to being seconded to Adriatic LNG, Eligio has worked in ExxonMobil's Procurement organization and Augusta Refinery.




# Abstract

Reversible performance deterioration of one of four parallel seawater vertical lift pumps has limited the pump's ability for continuous operation. Given the pump's flat performance characteristics curve, a systematic approach to field troubleshooting was required. Non-conventional inspections, inclusive of online video inspection, revealed performance deterioration caused by marine fouling. This case study will describe the troubleshooting steps, highlighting limitations of typical troubleshooting theories, and recovery through the use of an air lift pump.




# Problem

- SW vertical lift pump (24 m) inside a concrete basin
- Limited continuous operation due to reduced flow
- Reversible on each re-start
- Problem with 1 out of 4 pumps





# System Overview

- SW Vaporizer
- SW Service
- - - Hypochlorite




# Data Analysis

- Evaluate system – define boundary
- What data was available?
  - Decrease in motor current
  - Overall SW header flow
  - Vibration Spectrum



# Motor Current


- Motor current is the available performance measure
- Behavior limited to #2 pump
- SW header following same trend



Rate of performance degradation increase over time



# Vibration Spectrum






# Data Analysis

- Limitations?
  - Pump curve
  - Historical performance



# Pump Curve



- **Design:**

$H = 52.57 \text{ m}$

$Q = 7,250 \text{ m}^3/\text{h}$

- **Operating:**

$H = 53.8 \text{ m}$

$Q = 6,600 \text{ m}^3/\text{h}$

**Operational Changes:**



0.05 bar (0.7 psi) increase in either discharge pressure or DP across suction strainer  
→ 5800 m³/h (13% drop)

Performance calculation can not identify the problem




# Historical Pump Performance

- Historic seasonality effect across all pumps
- Change in behaviour related on pump 2
- Basin strainer gets plugged, but no performance effect



# Verification Plan

- Hypotheses table developed
  - Discharge Blockage
  - Internal Fouling
  - Suction Blockage
- Verifications based on probability and complexity





# Underwater Basin Inspection (ROV)




Significant marine fouling



Clean strainer




Mollusca/Mussels withstand forces




Mechanical cleaning required to remove mussels




# Non-Intrusive Inspections



Partially stuck check valve




Camera inspection inside pump



No attached growth on pump internals







# Non-Intrusive Inspections: Suction





# Suction Blockage Video Summary



5 hours to block strainer at  $>6000$  m<sup>3</sup>/hr water flow...Why?







# Basin Design

Jet flow through basin entrance

Flow distribution in basin affects rate of suction strainer blockage




# Way forward

- Challenges:
  - Confined space
  - Where to discharge water and loose material?
  - How to separate water from debris?
  - High head (30 m) from basin floor – need for submersible pump
  - How to collect debris from around basin corners?

**1.5 MW pump used for normal service!**



# Basin Cleaning – Air Lift Pump



- Min equipment
- No debris interaction
  - Old technology
- 1.5 m3 loose debris recovered



**Issue resolved  
on pump start up!**



# Conclusion

- Common problem for relatively simple equipment
- Recovery could become demanding
- Methodical approach to troubleshooting
- Non-conventional troubleshooting and recovery actions
- Continuous surveillance helps



# Thanks!

