

47TH TURBOMACHINERY & 34TH PUMP SYMPOSIA HOUSTON, TEXAS | SEPTEMBER 17-20, 2018 GEORGE R. BROWN CONVENTION CENTER

Correction of High Vibration on a Vertical Turbine Deep Well Pump with a Dynamic Vibration Absorber

Benjamin Bryant
Matthew Moll







Authors

Benjamin Bryant

Benjamin Bryant is a Production Manager of the Baling and Warehouse units for Celanese Corporation in Narrows, VA. Previous to this role, Ben was a Mechanical Integrity Engineer supporting the entire Narrows facility. Ben received his BS in Mechanical Engineering from North Carolina State University in 2014.

Matthew Moll

Matthew D. Moll is a Principal Rotating Equipment Engineer in the Core Technology Group for Celanese Corporation, based from Narrows VA. Previous to Celanese, Matthew was a Rotating Equipment Engineer for E. I. du Pont de Nemours and Company. Matthew received his BS in Mechanical Engineering from Virginia Polytechnic Institute and State University in 2003.

Case study on the correction of chronic high vibration on a Vertical Turbine Deep Well Pump with a Dynamic Vibration Absorber

A vertical turbine pump called #12 Well had a history of reoccurring high vibration despite multiple pump rebuilds and motor replacements. The problem was identified as a structural resonance of the motor and discharge head assembly. It was determined that a dynamic vibration absorber (DVA) would be the most effective solution. This case study presents the technique of diagnosing the resonance and the methodology of designing and calibrating a dynamic vibration absorber. Installation of the DVA reduced the overall vibration velocity amplitude by a factor of 16.

Content

- Problem Statement
- Diagnosis
- Solutions
- Design
- Calibration
- Results






Problem Statement

- A 100hp, 1780 RPM, 180 ft. deep well vertical turbine pump experienced chronic recurring high vibration.
- Despite multiple repair and rebuild attempts to the pump, motor, and foundation the issue would return within a few months of operation.
- This pump was rebuilt in early March, 2017 and experienced alert and fault level alarms (> 0.8 ips velocity overall) by late April.




 Consistently recurring high vibration despite multiple repairs and rebuilds (2013-2017)





 The velocity amplitude at 1x RPM was significantly higher than any other peak.

WELL - #12 DEEP WELL





- Reviewing the vibration data with the understanding that this pump underwent a partial rebuild only a few months prior led to the investigation of a potential resonance.
- Imbalance was ruled out for two primary reasons
 - 1. Tightening loose bolts in the body flange to concrete base increased vibration from ~0.75 ips to ~1.0 ips
 - 2. Motor was replaced at this time due to brass (cage material) found in the oil. The 2nd motor was solo run on rubber pads and produced ~0.05 ips however once mounted (uncoupled) ran ~0.75 ips

- Using a portable vibration analyzer, impact testing was conducted on the pump's motor when the pump was down. Natural frequencies detected at 1781CPM and 2200 CPM in both planes
- Having natural frequencies within 20% of the operating range allowed a small forcing frequency to be significantly amplified.
 - The closer a natural frequency is to the forcing frequency, the larger the resonating effect.



Solutions

- Moving the system's natural frequency far enough away from the pumps operating speed will drastically reduce the amplification factor.
- Since the natural frequency of a system is a function of it's stiffness and it's mass, the only way to resolve the resonating motor was to either change it's mass, or change it's stiffness.
- Increasing the mass or lowering the stiffness will lower the natural frequency while reducing mass or increasing stiffness will increase natural frequency.

Solutions Considered

- Replace pump and foundation to resolve the underlying vibration source
- Install stiffening members (e.g. I-beams)
- Add mass to the pump
- Design and install a Dynamic Vibration Absorber (DVA)

- Dynamic absorber chosen for practicality and for proximity to a second natural frequency
- A design routine published in 1998 November Edition of Sound and Vibration Magazine authored by Richard Smith "Dynamic Vibration Absorbers" was utilized for absorber engineering
- Cardboard templating came in handy too

	Units					Weight Per Foot of Rod	lb /in of 1.5" all t.	0.462
Weight of Motor	lb	1200	$W \times$	(MER)		Weight of spring	lb	22.176
Mass Effectiveness Ratio		0.9	$M_{eff} = \frac{W}{M_{eff}}$	a		Mass Effective Correction	lb	102.1527045
Mass Effectiveness Ratio	in*lb/sec^2	2.797927461		9		Mass Per Spring		25.53817613
						Support Plate		
Resonance Frequency	CPM	1780	, , 1	Sec 1R		Plate Thickness	in	0.75
Measured Velocity	in/sec	1	$dt = (\frac{1}{RPM})($	$(60{Min})({4})$		Plate Inner Diameter	in	16.5
Elapse Time - dT (1/4 Cycle)	sec	0.008426966	inch	7,		Plate Otter Diameter	in	25.25
average acceleration	in/sec^2	118.6666667	$a_{ave} = \frac{v \frac{inch}{sec}}{Time sec}$	$a_{Peak} = 1$	$.57 \times a_{ave}$	Plate Volume	in^3	215.1866432
peak acceleration	in/sec^2	186.3066667	Time sec			Weight Per Volume	lb/in^3	0.284
Weight (Force)	Ib	521.2725389	$F = M \times A$			Weight of Plate	lb	61.11300666
					Weight Plates			
Length of Spring (Rod)	in	12	Moment=	F ×L		Plate Thickness	in	0.5
Number of Springs	qty	4	# 0	f Springs		Plate Inner Diameter	in	1.56
Spring Moment	in*lb/# of springs	1563.817617	$I = \frac{\pi}{4}r^4$			Plate Otter Diameter	in	8
Spring Radius (Assume Round Rod)	in	0.697	4'		$\frac{1 Min}{50 Sec}$) $(2\pi \frac{rad}{R})$	Plate Volume	in^3	24.17704832
Spring (Inertia for Rod)	in^4	0.185361966	$\sigma = S \frac{Mc}{}$			Weight Per Volume	lb/in^3	0.284
Peak Stress in Rod	lb/in^2	23521.13333	$\sigma = S \frac{1}{I}$		oo see n	Weight of Plate	lb	6.866281723
				$K = \frac{3EI}{L^3}$				
Resonance Frequency In Radians	Rad	186.4010067		k	-			
Spring Constant (Rod)	lb/in	9654.26906		$M_{eff} = \frac{R}{\omega}$	2			





Mass Effective of Absorber


Ib / per absorber

107.2531845









WEIGHT PLATE

1 Day 1 Boarding Nate Methodard Nov 58-014 or 191

2 Stop 4 of Stoward ands, 80174 A 1910 to 157, L178 Security or 169

3 Stop 4 of Stoward ands, 80174 A 1910 to 157, L178 Security or 169, 10 Security or 169

4 Stop 1 Stoward ands, 10175 Security or 169, 10175

4 Stop 1 Stoward Public State Stoward

5 Stoward Public State Stoward

6 Stop 1 Stoward Public State Stoward

6 Stop 1 Stoward Public State Stoward

6 Stop 1 Stoward Public State Stoward

7 Stoward Public State Stoward

7 Stoward Public State Stoward

7 Stoward Public State Stoward

8 Stoward Public State Stoward

8 Stoward Public State Stoward

9 Stoward Publ

ALEXALY MITTES 1. All thread and threaded into Mounting Plate and according to be behalfed with appropriate already thread bother.

- In lineard and threaded loss bounding Flats and another.
 To be installed with personnel strength thread locker.
 Weight plate stacks to be initially set to 12 holyhi flows to be an analysis of the stack of the stac
- Weight plates must be bered to appreciately 1708 CP4 using a vibration analyses and tropoles (keep) testing blooming Plate to be pointed using SpecirCress 100 best Industrial Aurylia-Modified Albyd Enemal Paint.

Industrial Applie Modified Albyd Snamel Pales.



- The initial design to use one weight plate supported by four threaded rods was impractical due to the difficulty of tuning.
- To solve this, the weight was divided in four and individual weight plates were placed on each of the four threaded rods. This method was much easier to install and tuning was predictable with length.



Calibration

- Initial calibration was performed in the shop. An impact test was performed on each set of weights. The weights were then adjusted up or down to resonate at the frequency intended to absorb 1780 CPM.
- Final calibration was performed in the field. Using the same techniques as in the shop, the DVA required more fine tuning once installed to ensure the natural frequencies of the weights matched that at which the vibration was occurring.

Results

- Overall vibration was reduced from 0.947 inches per second to 0.058 inches per second peak velocity.
- 9 months run-time (to date) with no failures or significant changes in overall vibration



Results

