

Centrifugal Compressor High Sub-Synchronous Vibration (SSV) During Higher Load and Speed

Mohd Faizal Mohamed –
PETRONAS
Mohd Hafiz A Manan –
PETRONAS



Authors

Mohd Faizal Mohamed

Staff Rotating Engineer in Integration, Value & Assurance Division at Petronas Carigali. His responsibilities include reliability improvement, maintenance excellence, root cause failure analysis, and engineering review. He is based in Malaysia and has over 15 years of rotating machinery experience.

Mohd Hafiz B A Manan

Rotating Machinery Superintendent in Sabah Assets at Petronas Carigali. His responsibilities include equipment managing on maintenance activities, reliability improvement program and value driven maintenance. He is based in Malaysia and has 13 years of rotating machinery experience.




Executive Summary


Process fluid changes such as presence of contaminants, water and corrosive gas composition i.e., H2S can give significant impact on the degradation mechanisms of materials which require for design modification or revision in inspection, monitoring & maintenance.

Besides that, it is crucial to have information on spare rotor assembly critical speed whenever any major maintenance done for the compressor. This is essential to ensure operating regime meet sufficient separation margin on system resonances.

In this case study, presence of moisture, contaminant & H2S in process gas has been discussed that led to compressor component deterioration and damage. In addition, having situation of idling the compressor close to its critical speed also accelerated further impact & resulted in SSV issue

Equipment Overview (Centrifugal Compressor)






3rd & 4th stage*

AR ₃ — TO M ₄ — X ₃	
	1st & 2nd
AN ₃	
3 rd & 4 th stage*	TO V ₄
TO MA	
1st Q 2nd at a 20	
1st & 2nd stage	
TO AB 3 TO J4	ь,
I OW POINT	/ L


General Arrangement layout

Item	Description
Interconnection	Gear box & coupling
Process Equipment	Cooler, Scrubber, After Cooler, Glycol Contactor
Speed	Max continuous 11682 rpm
Lateral critical speed	*Concerned: 3 rd & 4 th Stage First critical 4800 rpm Second critical 17940 rpm
Bearings	Journal – tilting pads
Seals	Interstage – labyrinth Center – honeycomb

Chronology of Events




Vibration Data – Sub Synchronous



SSV only dominant once compressor load at higher speed


Overall vibration rapidly increase when speed is higher than 7000 rpm


Vibration Data – Evidence of Rub



Indication of rub

Different rotor path between running & coast down





Waterfall plot: Reverse precession indicate sign of rub


Possible Causes On Sub-Synchronous Vibration (SSV)

Multiple start-up unit were tripped on 3rd & 4th stage compressor high vibration whenever unit need to load at higher speed (>7000 rpm). From vibration plot, it was revealed that the unit was exhibiting SSV issue, whereby 1x and other vibration frequency generally exhibit low amplitude

SSV problem experienced for this compressor maybe generated from following mechanism:

- a) Hydrodynamic fluid film related issues i.e., oil whirl / whip
- b) Aerodynamic induced instability i.e., rotating stall, incipient surge
- c) Rotodynamic instability i.e., self excited
- d) Excessive clearance for internal component i.e., journal bearing

Possible Causes #1 - Instability From Hydrodynamic Fluid Film



Lubrication parameters were found satisfactory during unit in operation (within allowable range)

Metals (ppm)		
Aluminium (Al)	≤5	<1
Copper (Cu)	≤10	<1
Chromium (Cr)	≤5	<1
Iron (Fe)	≤10	<1
Lead (Pb)	≤10	<1
Tin (Sn)	≤5	<1
Silver (Ag)	≤2	<1
Flash Point (°C)		
Flash Point COC (ASTM D9	≤300	240
Insolubles		
Pentane Ins (% w/w) (ASTM		0.15
Contaminants (ppm)		
Silicon (Si)	≤10	<1
Boron (B)	≤5	<5
Sodium (Na)	≤5	4
Potassium (K)	≤5	<1
Phosphorus (P)	≤2	1
Molybdenum (Mo)	≤35	<1
Magnesium (Mg)	≤2	<1
Calcium (Ca)	≤2	2
Zinc (Zn)	≤2	2
Barium (Ba)	≤2	<1
Physical Tests		
Viscosity (cSt,100°C)	5.7	5.8
Water (ASTM D6304-A), pp	≤200	13
Viscosity (cSt,40°C)	≤36.80	33
AN (ASTM D664) mgKOH/g	≤0.20	0.02
Particle Count		
NAS 1638 Class	≤9	4
>4 Micron (particles/ml)		121
ISO 4406 Code		14/12/10
>6 Micron (particles/ml)		28
>14 Micron (particles/ml)		5
Varnish Potential		
Membrane Patch Colorimetr	≤15	8.9



Lube oil analysis is acceptable

Possible Causes #2 – Aerodynamic Induced Instability


a) Flow instability to compressor i.e., flow disturbance due to restriction in the

system.






Check valves at 2nd, 3rd & 4th stage found parted and/or passing





Possible Causes #2 (cont.) – Aerodynamic Induced Instability


b) Flow instability due to rotating stall i.e., restriction or disturbance at compressor internal component




No blockage, however severe erosion & pitting











Summary of Lab Analysis on Damaged Component

The damaged component i.e., shaft, impeller, guide vane were subjected to metallurgical analysis. Summary of finding as below:



Erosion

- Liquid droplet impingement
- Repeated impacts caused depression and metal flow
- Asperities formed between depressions
 - Asperities cracked and removed metal



Corrosion

- Areas with dark deposit accumulation
- presence of corrosion products
- Corrosion attack form crack / fatigue

Findings on Process Gas Sampling Analysis

Table 1: Physical Analysis

No	Lab	Description	Method	Unit	Result
1	##	Mercury, Hg *	ASTM D6350 - 14	μg/Sm3	32.21
2	##	Chloride, Cl ⁻	APHA 4110B	mg/L	0.62

No	Lab	Description	Method	Unit	Result
1	**	Hydrogen Sulphide, H ₂ S (in-situ)	ASTM D4810 - 06(2015)	mg/l	110
2	**	Moisture (in-situ)	ASTM D5454 - 11e1	ppm (v/v)	5110
3	**	Dew Point (in-situ)	Shaw Dew Point	°C	-2

Key observation:

- presence of Mercury
- presence of H2S content
- presence of high moisture

Design basis:

No mercury, H2S & moisture

Table 2: Gas GC Compo Analysis

No	Lab	Description	Method	Unit	Result
A a la	!	· ·	hu CC		
		Natural Gas and Similar Gaseous Mixture			
1	#	Methane, C1	GPA 2286-14	% Mole	27.7533
2	#	Ethane, C2	GPA 2286-14	% Mole	3.6707
3	#	Propane, C3	GPA 2286-14	% Mole	1.2163
4	#	Iso-Butane, IC4	GPA 2286-14	% Mole	0.3378
5	#	n-Butane, nC4	GPA 2286-14	% Mole	0.3013
6	#	Iso-Pentane, iC5	GPA 2286-14	% Mole	0.2235
7	#	n-Pentane, nC5	GPA 2286-14	% Mole	0.1911
8	#	Hexane and Heavier (Hexane Plus)	GPA 2286-14	% Mole	0.4651
9	#	Nitrogen	GPA 2286-14	% Mole	1.1009
10	#	Carbon Dioxide	GPA 2286-14	% Mole	64.7400
Extended Analysis of Natural Gas and Similar Gaseous Mixtures by GC					
1	#	Hexane, C6	GPA 2286-14	% Mole	0.2574
2	#	Heptane, C7	GPA 2286-14	% Mole	0.1088
3	#	Octane, C8	GPA 2286-14	% Mole	0.0937
4	#	Nonane, C9	GPA 2286-14	% Mole	0.0037
5	#	Decane, C10	GPA 2286-14	% Mole	0.0008
6	#	Undecane, C11	GPA 2286-14	% Mole	0.0004
7	#	Dodecane and Heavier, C12+	GPA 2286-14	% Mole	0.0003
Real	Natura	l Gas Properties Cal. from Composition *	•		
1	#	Real Gas Density	ISO 6976:2016	kg/m³	1.5303
2	#	Gross Heating Value	ISO 6976:2016	MJ/kg	10.73
3	#	Gross Heating Value	ISO 6976:2016	BTU	4613.07

Compressor major parts i.e., material for impeller, diaphragms, shaft, etc.: SS410 (not susceptible to H2S)

Possible Causes #3 — Rotodynamic Instability (Self-Excited)

Description

Installation


date

Design 1st

Critical Speed

(CS)

Actual 1st



Original Rotor – API datasheet

CONFIDENTIAL AND PROPE THIS DOCUMENT AND ALL INFORMATION CONTAINED HEREIN IS THE PROPERTY OF THE RECEIVER IN CONFIDENCE. UNAUTHORIZED DISC	PERTY OF, AND CONFIDENTIAL TO, I	COMPANY AND IS RICTLY PROHIBITED.		
Dlean Operations Dlean, NY, USA	VIB Report: RDR-0K2-100	D906R.BE Revision:		
SUBJECT: Lateral Rotor Dynamic Analysis of the 3 Compressor for Petronas Carigali Sdn Bhd.				
SUMMARY:				
This report documents the lateral rotor dynamic analysis of the The rotor exhibits acceptable sensitivity to unbalance. The first critical speed occurs at 5460 to 5980 RPM wit 21220 to 21260 RPM with minimum clearance and at 22090 to 2 have acceptable lateral separation margins based on the operating dynamics of this unit is satisfactory per API Standard 617, Sevent	th maximum clearance. The second cri 2130 RPM with maximum clearance. T ng speed range of 7788 RPM to 11682	tical speed occurs at the critical speeds		

Critical Speed	
Idling speed	 5840 rpm (during in operation)
Other information	 Spare rotor weight different about 10% 566 lbs (original) . vs 510 lbs (spare) Past record original bundle went for impeller trim / minor modification to address discharge temp issue It was suspected that the clearance used for spare rotor is towards maximum value

Original Rotor

Commissioned in

2013 and in service

until Q4 2018

4800 rpm (no

details specify for


minimum &

maximum clearance

5000 – 5100 rpm



& PUMP SYMPOSIUN





Spare Rotor

Replaced in Q4 2018 &

failed in March 2019

5460 - 5980


maximum clearance

5900 - 5920

minimum clearance

5700 – 5800 rpm


Finding on Rotor 1st Critical Speed Changes







Possible Causes #4 - Excessive Clearance of Internal Component

Excessive clearance at center seal due to rubbing









3rd & 4th stage compressor centre seal (honey comb) badly rubbed & sleeve materials loss



Surface wear

Grind spot



Shaft Rotor – damage area


Conclusion & Recommendation

No	Possible Causes	Conclusion	Recommendation
1	Hydrodyamic instability from fluid film	Not a concern	No further action. Maintain lube oil parameters & quality
2	Aerodynamic induced instability	Minor concern & less significant	Rectify passing & broken check valves
3	Aerodynamic induced instability	Concern (erosion & pitting on internal components due to process gas contaminants)	Replace affected compressor components, improve compressor materials (refer to next slide)
4	Rotor dynamic instability (self-excitation)	Main concern (idling speed vs. critical speed is <2% of separation margin	Change compressor idling speed to avoid coinciding with rotor 1st critical speed
5	Excessive clearance on internal parts/components	Main concern (consequent from no#4 and accelerated due to contaminants)	As of no#4, address source of moisture & H2S in process gas, improve compressor materials (refer to next slide)




Conclusion & Recommendation (cont.)

- Presence of moisture, contaminant & H2S led to component deterioration and damage not only to upstream facilities such as piping/scrubber but also to compressor internal components
- Such debris & contaminants unfortunately pass thru & stuck at critical area ie.
 center seal clearance creating some rubbing effect
- In addition, the situation worsen when spare compressor installed in 2018 having different rotor 1st critical speed which is 5727 rpm vs. 4800 rpm (original)
- This resulting rotor resonate whenever unit at idle speed (5840 rpm, <2% seperation margin). The rotor resonance at 1st CS with first mode shape will have largest deflection on the center leading to more exposure towards rubbing and causing severe damage to center seal
- Excessive clearance at damaged center seal behave like "third bearing" effect and causing machine experiencing stall and/or aerodynamic instability as observe from <u>sub-synchronous vibration (SSV)</u>



Conclusion & Recommendation (cont.)



Solutions Implementation

Process gas supply

- Temporary shutin flowing well with high moisture / H2S / mercury concentration [completed]
- Periodic process gas sampling & analysis [completed]

Suction scrubber

- Scrubber
 efficiency
 adequacy review
 & simulation
 [completed]
- Level control function test & periodic calibration to avoid liquid carry over [completed

Operation / Process

- Replaced passing & parted check valves
 [completed]
- Periodic
 compressor
 draining during
 start-up after
 long standby
 [completed]


Result:

Description	Unit	Result
Hydrogen Sulphide, H₂S (in-situ)	mg/l	70
Moisture (in-situ)	ppm (v/v)	15

- H2S concentration reduce from +110 mg/l to +/-70 mg/l (35% reduction)
- Moisture content reduce from 5100 ppm to 15 – 100 ppm (>90% reduction)



Solutions Implementation (cont.)



Adjust compressor idling from 5840 rpm to 6420 rpm (>15% separation margin)

[completed]


Request documentation on rotor dynamic with OEM for each bundle purchase

[completed]

Rotor Dynamic Lateral Analysis Report Rotor Dynamic Lateral Analysis Report

Serial No.: C33-058-A02

Item Name: Centrifugal Compressor



15% SM from 5400 rpm = 6210 rpm

Bundle replacement with better materials grade SS 17-4PH, NACE compliance [completed]





Compressor related rectification

Revise practice to capture actual critical speed data every start-up post maintenance work


[completed]


Solutions Implementation (cont.)












Bundle replacement using better material: 17-4PH

Summary & Lesson Learnt



- Solutions implemented
- No SSV, vibration acceptable at >8000 rpm

Running normal close to 2 years !!

- Process fluid such as gas composition recommended to be verified on periodic interval (i.e., yearly basis) for any significant changes. This input is critical to ensure any intervention required for centrifugal compressor safe operation
- Idle speed & running speed need to meet API requirement with >15% seperation margin from rotor critical speed to avoid vibration related impact
- SSV may be contributed from several factor, thus proper elimination process is deemed necessary to narrow down the root cause that create excitation force
- Out of clearance for center seal create "third bearing" effect & stall that resulted in high SSV amplitude

Thank You

